2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Solis-Cohen School

Governance DISTRICT Report Type Elementary
Address 7001 Horrocks St. Enrollment 1227
Philadelphia, Pa 19149 Grade Range '00-05'

Phone/Fax 215-728-5012 / 215-728-5982 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Solis- Turnaround Model N/A

Cohen

Building/System FCI Tiers

Easilit	y Condition Index (FCI)	Cost of Assess	sed Deficiencies	
raciiit	y condition index (FCI)	Replacer	Replacement Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	48.37%	\$25,623,700	\$52,970,972
Building	52.43 %	\$24,653,934	\$47,026,216
Grounds	16.31 %	\$969,766	\$5,944,756

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	99.88 %	\$3,130,369	\$3,134,286
Exterior Walls (Shows condition of the structural condition of the exterior facade)	10.66 %	\$357,990	\$3,358,810
Windows (Shows functionality of exterior windows)	117.03 %	\$1,918,026	\$1,638,910
Exterior Doors (Shows condition of exterior doors)	490.86 %	\$647,686	\$131,950
Interior Doors (Classroom doors)	204.45 %	\$653,025	\$319,410
Interior Walls (Paint and Finishes)	43.85 %	\$527,080	\$1,202,110
Plumbing Fixtures	82.78 %	\$1,018,469	\$1,230,320
Boilers	125.19 %	\$2,126,921	\$1,698,970
Chillers/Cooling Towers	54.07 %	\$1,204,455	\$2,227,680
Radiators/Unit Ventilators/HVAC	72.82 %	\$2,848,883	\$3,912,090
Heating/Cooling Controls	130.97 %	\$1,608,907	\$1,228,500
Electrical Service and Distribution	168.03 %	\$1,483,203	\$882,700
Lighting	55.91 %	\$1,764,359	\$3,155,880
Communications and Security (Cameras, Pa System and Fire Alarm)	78.84 %	\$931,904	\$1,182,090

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Solis-Cohen PEC School

Governance DISTRICT Report Type Elementary

Address 7001 Horrocks St. Enrollment

System requires minor

repairs

Philadelphia, Pa 19149 Grade Range '00-05'

Phone/Fax 215-728-5012 / 215-728-5982 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Solis- Turnaround Model N/A Cohen

Building/System FCI Tiers

Cost of Assessed Deficiencies Facility Condition Index (FCI) = **Replacement Value** < 15% 15 to 25% 25 to 45% > 60% 45 to 60% **Buildings** Replace Systems in Building should be Minimal Current Capital Refurbish Systems in Building should be **Funding Required** building building. considered for major considered for renovation. closing/replacement. Systems

System should be

studied to determine

repair vs. replacement.

System should be

Capital Program

replaced as part of the

System is nearing end of

should be considered for

its life expectancy and

replacement

Building and Grounds

Perform routine

maintenance on system

	FCI	Repair Costs	Replacement Cost
Overall	04.70%	\$978,076	\$20,799,850
Building	00.06 %	\$8,310	\$14,855,094
Grounds	16.31 %	\$969,766	\$5,944,756

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,335,443
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.04 %	\$337	\$759,427
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$331,550
Exterior Doors (Shows condition of exterior doors)	10.59 %	\$4,302	\$40,623
Interior Doors (Classroom doors)	04.01 %	\$3,671	\$91,462
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$408,903
Plumbing Fixtures	00.00 %	\$0	\$768,184
Boilers	00.00 %	\$0	\$454,148
Chillers/Cooling Towers	00.00 %	\$0	\$595,476
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$1,045,732
Heating/Cooling Controls	00.00 %	\$0	\$328,388
Electrical Service and Distribution	00.00 %	\$0	\$235,953
Lighting	00.00 %	\$0	\$843,591
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$315,982

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.