2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Harrington School

Governance DISTRICT Report Type Elementarymiddle

Address 5300 Baltimore Ave. Enrollment 492
Philadelphia, Pa 19143 Grade Range '00-08'

Phone/Fax 215-471-2914 / 215-471-5087 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Harrington Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)		ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	46.47%	\$16,011,229	\$34,454,153
Building	46.27 %	\$15,466,645	\$33,424,654
Grounds	52.90 %	\$544,584	\$1,029,499

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.67 %	\$887,966	\$990,206
Exterior Walls (Shows condition of the structural condition of the exterior facade)	34.02 %	\$835,006	\$2,454,515
Windows (Shows functionality of exterior windows)	150.52 %	\$1,802,775	\$1,197,665
Exterior Doors (Shows condition of exterior doors)	07.11 %	\$6,854	\$96,425
Interior Doors (Classroom doors)	73.81 %	\$172,280	\$233,415
Interior Walls (Paint and Finishes)	02.17 %	\$25,701	\$1,181,705
Plumbing Fixtures	17.61 %	\$158,356	\$899,080
Boilers	63.14 %	\$783,903	\$1,241,555
Chillers/Cooling Towers	48.83 %	\$794,940	\$1,627,920
Radiators/Unit Ventilators/HVAC	85.12 %	\$2,433,562	\$2,858,835
Heating/Cooling Controls	158.90 %	\$1,426,567	\$897,750
Electrical Service and Distribution	93.15 %	\$600,840	\$645,050
Lighting	03.39 %	\$78,070	\$2,306,220
Communications and Security (Cameras, Pa System and Fire Alarm)	21.08 %	\$182,095	\$863,835

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Harrington Annex School

Governance DISTRICT Report Type Elementarymiddle

Address 5300 Baltimore Ave. Enrollment

Philadelphia, Pa 19143 Grade Range '00-08' 215-471-2914 / 215-471-5087 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Harrington Turnaround Model N/A

Building/System FCI Tiers

Phone/Fax

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies		
raciiit	y Condition index (FCI)		Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
Buildings					
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
		Systems	•		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	45.00%	\$4,024,127	\$8,942,655
Building	45.87 %	\$3,863,085	\$8,422,299
Grounds	30.95 %	\$161,042	\$520,356

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	87.22 %	\$190,030	\$217,880
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.83 %	\$3,883	\$468,300
Windows (Shows functionality of exterior windows)	192.52 %	\$393,599	\$204,450
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$25,050
Interior Doors (Classroom doors)	250.47 %	\$141,263	\$56,400
Interior Walls (Paint and Finishes)	06.80 %	\$17,134	\$252,150
Plumbing Fixtures	51.08 %	\$241,954	\$473,700
Boilers	72.89 %	\$204,124	\$280,050
Chillers/Cooling Towers	83.52 %	\$306,695	\$367,200
Radiators/Unit Ventilators/HVAC	114.58 %	\$738,901	\$644,850
Heating/Cooling Controls	132.68 %	\$268,671	\$202,500
Electrical Service and Distribution	151.03 %	\$219,746	\$145,500
Lighting	33.13 %	\$172,368	\$520,200
Communications and Security (Cameras, Pa System and Fire Alarm)	50.42 %	\$98,253	\$194,850

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.