2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Feltonville Intermediate School

Governance DISTRICT Report Type Elementary
Address 238 E. Wyoming Ave. Enrollment 769
Philadelphia, Pa 19120 Grade Range '03-05'

Phone/Fax 215-456-3012 / 215-456-0122 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Feltonville- Turnaround Model N/A

Intermediate

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	40.01%	\$17,133,237	\$42,820,635
Building	40.57 %	\$16,925,121	\$41,721,754
Grounds	23.40 %	\$208,117	\$889,469

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.44 %	\$1,412,609	\$1,579,330
Exterior Walls (Shows condition of the structural condition of the exterior facade)	09.85 %	\$305,414	\$3,100,440
Windows (Shows functionality of exterior windows)	60.40 %	\$913,792	\$1,512,840
Exterior Doors (Shows condition of exterior doors)	149.55 %	\$182,146	\$121,800
Interior Doors (Classroom doors)	181.73 %	\$535,826	\$294,840
Interior Walls (Paint and Finishes)	05.03 %	\$55,819	\$1,109,640
Plumbing Fixtures	02.96 %	\$33,660	\$1,135,680
Boilers	00.00 %	\$0	\$1,568,280
Chillers/Cooling Towers	121.19 %	\$2,492,130	\$2,056,320
Radiators/Unit Ventilators/HVAC	164.74 %	\$5,948,957	\$3,611,160
Heating/Cooling Controls	00.00 %	\$0	\$1,134,000
Electrical Service and Distribution	00.00 %	\$0	\$814,800
Lighting	00.00 %	\$0	\$2,913,120
Communications and Security (Cameras, Pa System and Fire Alarm)	59.37 %	\$647,863	\$1,091,160

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.