2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Washington High School

Governance DISTRICT Report Type High
Address 10175 Bustleton Ave. Enrollment 1335
Philadelphia, Pa 19116 Grade Range '09-12'

Phone/Fax 215-961-2001 / 215-961-2545 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Gwhs Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	28.04%	\$55,593,064	\$198,292,258
Building	29.04 %	\$53,436,891	\$184,014,097
Grounds	15.10 %	\$2,156,173	\$14,278,161

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	06.00 %	\$457,407	\$7,617,137
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.63 %	\$93,982	\$14,947,200
Windows (Shows functionality of exterior windows)	00.67 %	\$63,517	\$9,521,920
Exterior Doors (Shows condition of exterior doors)	07.44 %	\$29,863	\$401,360
Interior Doors (Classroom doors)	60.89 %	\$792,215	\$1,300,960
Interior Walls (Paint and Finishes)	01.99 %	\$91,043	\$4,570,660
Plumbing Fixtures	61.30 %	\$2,867,714	\$4,677,920
Boilers	00.00 %	\$0	\$6,459,820
Chillers/Cooling Towers	00.00 %	\$0	\$8,470,080
Radiators/Unit Ventilators/HVAC	163.33 %	\$24,294,597	\$14,874,540
Heating/Cooling Controls	122.39 %	\$5,716,725	\$4,671,000
Electrical Service and Distribution	27.36 %	\$918,292	\$3,356,200
Lighting	34.29 %	\$4,114,778	\$11,999,280
Communications and Security (Cameras, Pa System and Fire Alarm)	16.83 %	\$756,359	\$4,494,540

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.