# **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Kirkbride School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 1501 S. 7Th St.
 Enrollment
 554

 Philadelphia, Pa 19147
 Grade Range
 '00-08'

Philadelphia, Pa 19147 Grade Range '00-08'
Phone/Fax 215-952-6214 / 215-952-6253 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Kirkbride Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	35.90%	\$10,309,506	\$28,714,480
Building	35.67 %	\$10,271,538	\$28,799,363
Grounds	14.38 %	\$37,968	\$263,957

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$611,432
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,103,870
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,026,570
Exterior Doors (Shows condition of exterior doors)	08.45 %	\$6,987	\$82,650
Interior Doors (Classroom doors)	131.15 %	\$262,382	\$200,070
Interior Walls (Paint and Finishes)	08.49 %	\$81,387	\$958,170
Plumbing Fixtures	17.43 %	\$134,343	\$770,640
Boilers	71.15 %	\$757,191	\$1,064,190
Chillers/Cooling Towers	48.34 %	\$674,495	\$1,395,360
Radiators/Unit Ventilators/HVAC	27.25 %	\$667,785	\$2,450,430
Heating/Cooling Controls	158.90 %	\$1,222,769	\$769,500
Electrical Service and Distribution	161.23 %	\$891,459	\$552,900
Lighting	36.62 %	\$723,978	\$1,976,760
Communications and Security (Cameras, Pa System and Fire Alarm)	48.71 %	\$360,660	\$740,430

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.