## **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Dobson School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 4667 Umbria St.
 Enrollment
 290

 Philadelphia, Pa 19127
 Grade Range
 '00-08'

Phone/Fax 215-487-4460 / 215-487-4804 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Dobson Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)		ed Deficiencies	
raciiit	y Condition index (FCI)	Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	37.16%	\$11,395,563	\$30,664,779
Building	36.01 %	\$10,803,655	\$30,003,427
Grounds	89.50 %	\$591,908	\$661,352

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$784,176
Exterior Walls (Shows condition of the structural condition of the exterior facade)	06.92 %	\$113,420	\$1,639,050
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$715,575
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$87,675
Interior Doors (Classroom doors)	35.24 %	\$69,571	\$197,400
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$882,525
Plumbing Fixtures	03.66 %	\$60,634	\$1,657,950
Boilers	00.00 %	\$0	\$980,175
Chillers/Cooling Towers	64.85 %	\$833,411	\$1,285,200
Radiators/Unit Ventilators/HVAC	160.38 %	\$3,619,702	\$2,256,975
Heating/Cooling Controls	158.90 %	\$1,126,235	\$708,750
Electrical Service and Distribution	155.19 %	\$790,282	\$509,250
Lighting	30.07 %	\$547,486	\$1,820,700
Communications and Security (Cameras, Pa System and Fire Alarm)	62.41 %	\$425,623	\$681,975

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.