2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Forrest School

Governance DISTRICT Report Type Elementary Address 7300 Cottage St. Enrollment 1183 Grade Range '00-06 Philadelphia, Pa 19136 215-335-5652 / 215-335-5983 Admissions Category Phone/Fax

Neighborhood Website Www.Philasd.Org/Schools/Forrest Turnaround Model N/A

Building/System FCI Tiers

| Facility Condition Index (FCI) = Cost of Assessed Deficiencies | | | | | | |
|--|-------------------------------|---|--|--|--|--|
| raciiic | y condition index (FCI) | | cement Value | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | |
| | Buildings | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | |
| Systems | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|---------|--------------|------------------|
| Overall | 47.78% | \$15,850,720 | \$33,171,769 |
| Building | 49.33 % | \$15,626,963 | \$31,675,791 |
| Grounds | 14.22 % | \$223,757 | \$1,573,143 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 08.65 % | \$71,873 | \$830,867 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 03.77 % | \$88,075 | \$2,334,558 |
| Windows (Shows functionality of exterior windows) | 39.22 % | \$446,712 | \$1,139,133 |
| Exterior Doors (Shows condition of exterior doors) | 85.86 % | \$78,743 | \$91,713 |
| Interior Doors (Classroom doors) | 174.16 % | \$386,650 | \$222,008 |
| Interior Walls (Paint and Finishes) | 12.50 % | \$132,902 | \$1,063,234 |
| Plumbing Fixtures | 46.15 % | \$394,664 | \$855,140 |
| Boilers | 87.98 % | \$1,038,883 | \$1,180,878 |
| Chillers/Cooling Towers | 77.79 % | \$1,204,455 | \$1,548,360 |
| Radiators/Unit Ventilators/HVAC | 105.16 % | \$2,859,546 | \$2,719,118 |
| Heating/Cooling Controls | 158.90 % | \$1,356,842 | \$853,875 |
| Electrical Service and Distribution | 169.49 % | \$1,039,850 | \$613,525 |
| Lighting | 69.15 % | \$1,516,837 | \$2,193,510 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 75.21 % | \$617,913 | \$821,618 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.

2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Forrest PEC School

Governance DISTRICT Report Type Elementary

Address 7300 Cottage St. Enrollment

Philadelphia, Pa 19136 Grade Range '00-06'
Phone/Fax 215-335-5652 / 215-335-5983 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Forrest Turnaround Model N/A

Building/System FCI Tiers

| Cost of Assessed Deficiencies | | | | | | |
|--|-------------------------------|---|---|--|--|--|
| Facility Condition Index (FCI) = Replacement Value | | | | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | |
| | Buildings | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | |
| Systems | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|---------|--------------|------------------|
| Overall | 01.52% | \$253,432 | \$16,677,795 |
| Building | 00.20 % | \$29,675 | \$15,104,652 |
| Grounds | 14.22 % | \$223,757 | \$1,573,143 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 01.37 % | \$13,721 | \$1,000,620 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.09 % | \$674 | \$792,676 |
| Windows (Shows functionality of exterior windows) | 00.00 % | \$0 | \$346,066 |
| Exterior Doors (Shows condition of exterior doors) | 00.00 % | \$0 | \$42,401 |
| Interior Doors (Classroom doors) | 05.29 % | \$5,049 | \$95,466 |
| Interior Walls (Paint and Finishes) | 00.00 % | \$0 | \$426,806 |
| Plumbing Fixtures | 00.00 % | \$0 | \$801,816 |
| Boilers | 00.00 % | \$0 | \$474,031 |
| Chillers/Cooling Towers | 00.00 % | \$0 | \$621,547 |
| Radiators/Unit Ventilators/HVAC | 00.00 % | \$0 | \$1,091,516 |
| Heating/Cooling Controls | 00.00 % | \$0 | \$342,765 |
| Electrical Service and Distribution | 00.00 % | \$0 | \$246,283 |
| Lighting | 00.97 % | \$8,552 | \$880,525 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 00.00 % | \$0 | \$329,816 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.