2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Allen, Ethan School

Governance DISTRICT Report Type Elementarymiddle

Address 6329 Battersby St. Enrollment 954
Philadelphia Pa 19149 Grade Range '00-08'

 Philadelphia, Pa 19149
 Grade Range
 '00-08'

 215-537-2530 / 215-537-2599
 Admissions Category
 Neighb

Phone/Fax215-537-2530 / 215-537-2599Admissions CategoryNeighborhoodWebsiteWww.Philasd.Org/Schools/EthanallenTurnaround ModelN/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	nent Value						
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	63.70%	\$22,269,670	\$34,959,480
Building	65.26 %	\$21,838,552	\$33,465,820
Grounds	25.34 %	\$431,119	\$1,701,084

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	60.34 %	\$475,847	\$788,618
Exterior Walls (Shows condition of the structural condition of the exterior facade)	02.92 %	\$71,590	\$2,453,851
Windows (Shows functionality of exterior windows)	120.14 %	\$1,438,519	\$1,197,341
Exterior Doors (Shows condition of exterior doors)	176.55 %	\$170,190	\$96,399
Interior Doors (Classroom doors)	152.05 %	\$354,803	\$233,352
Interior Walls (Paint and Finishes)	41.07 %	\$432,459	\$1,053,075
Plumbing Fixtures	54.05 %	\$485,837	\$898,837
Boilers	124.47 %	\$1,544,986	\$1,241,219
Chillers/Cooling Towers	74.01 %	\$1,204,455	\$1,627,479
Radiators/Unit Ventilators/HVAC	211.61 %	\$6,048,017	\$2,858,061
Heating/Cooling Controls	158.90 %	\$1,426,178	\$897,507
Electrical Service and Distribution	208.71 %	\$1,345,940	\$644,875
Lighting	55.49 %	\$1,279,341	\$2,305,596
Communications and Security (Cameras, Pa System and Fire Alarm)	67.51 %	\$583,039	\$863,601

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.