

LUQER MAPPER PRO

User Guide - Professional Mapping for Luthiers

1. INTRODUCTION

Luqer Mapper Pro turns instrument measurement data into a visual map, an editable instrument outline, and practical workshop exports. It is a self-contained browser app: open the HTML file in a current desktop browser such as Chrome or Edge. Its normal mapping workflow works without an internet connection.

The app uses a reference image of the instrument. You place a point, enter a measurement in millimeters, then use the point set to inspect the surface, create an optional heatmap, or export an outline.

2. INTERFACE OVERVIEW

Left sidebar - Import an image or a saved project; enter Guitar Model, Serial Number, and Additional Info; switch display and tracing tools; undo, redo, or reset.

Center workspace - The image canvas where you zoom, pan, rotate, trace the outline, and add or reposition measurement points.

Right sidebar - Logged Points. Each point is numbered, colored by its measured value, selectable, and removable.

QUICK START

- Choose **IMPORT IMAGE** and select a clear, top-down image of the instrument.
- Enter the model, serial number, and any workshop notes if they should appear in a PDF report.
- Optionally trace the perimeter before enabling a heatmap, then add measurement points and export the result.

3. NAVIGATION AND VIEW CONTROLS

Control	What it does
Mouse wheel	Zooms toward the pointer location.
Middle drag or Alt + left drag	Pans the reference image.
+ / -	Zooms in or out by a fixed amount.
FIT	Fits the image to the workspace and returns its rotation to the original orientation.
Rotate arrow	Rotates the image 90 degrees at a time.
LABELS	Shows or hides the millimeter value beside each logged point.

4. TRACING THE INSTRUMENT

Tracing defines an optional perimeter for the instrument. When there are at least three trace points, the heatmap is clipped to that closed boundary.

1. Click **TRACE: OFF** to turn tracing on. 2. Click around the instrument edge to add purple trace nodes. 3. Drag any node to refine the shape. 4. Click **TRACE: ON** to turn tracing off and close the outline.

Use **SMOOTH CURVE** to interpolate the trace into a rounded curve. This setting affects the displayed outline, the heatmap boundary, and the exported outline.

5. LOGGING MEASUREMENTS

Click a location on the image to create a pending yellow point. With the app active, type the numeric measurement (decimal values are accepted) and press **Enter** to log it in millimeters. A compatible measuring device may also be used if it sends the value as keyboard input.

To correct a location, drag its colored marker. Click an entry in Logged Points to select it, or click the X beside an entry to delete it. **UNDO** and **REDO** restore marker and trace edits.

Note: After adding a pending point, press Backspace to correct the number before pressing Enter.

6. HEATMAP

Turn **HEATMAP** on after logging measurements. With at least three points, Luger Mapper Pro computes a color field from the point values. Use the **HEATMAP OPACITY** slider to reveal more or less of the reference image beneath it.

The scale is relative to the values in the current project: blue represents the lower end of the measured range, then green and yellow move through the middle, while orange and red represent the upper end. It is a visual interpolation tool, not a substitute for additional measurements.

7. PROJECTS AND AUTO-SAVE

The app stores a browser-local working copy automatically. On a later visit, it can offer to restore that unsaved project. The saved project includes the reference image, measurements, trace, metadata, view options, heatmap opacity, and rotation.

Choose **IMPORT PROJECT** to load a Luger **.mgn** project. Choose **SAVE PROJECT** in the **EXPORT / SAVE** menu, or press **Ctrl+S** (Cmd+S on macOS), to save it. Modern browsers may let you save back to the same selected file; otherwise the app downloads a **.mgn** file.

Use **RESET ALL** only when you want to clear the current image, trace, measurements, metadata, and current-session history. The app asks for confirmation first.

8. EXPORTING

Open the **EXPORT / SAVE** menu and choose the desired action.

Option	Result
Save Project	A .mgn project file that preserves the editable working data.
Export PDF Report	A landscape report with the instrument image, numbered color-coded markers, the heatmap when it is enabled, date, model, serial, additional info, and a measurement list.
Export DXF Format	A CAD-style closed polyline made from the trace only. Measurement markers are excluded.
Export SVG Format	A vector SVG trace only. Measurement markers are excluded.

9. PRACTICAL CHECKLIST

- Use a sharp, top-down image and place trace nodes around the actual instrument edge.
- Spread measurement points across the area of interest; a sparse or uneven set makes an interpolation less representative.
- Save a **.mgn** project before experimenting with trace changes or resetting the workspace.
- Export DXF or SVG only after creating a trace; those formats do not include the image or measurement markers.