	_					
N	x1	x2	х3	x4	x5	У
1	0	0	0	0	0	0
2	0	0	0	0	1	0
3	0	0	0	1	0	0
4	0	0	0	1	1	0
5	0	0	1	0	0	1
6	0	0	1	0	1	0
7	0	0	1	1	0	1
8	0	0	1	1	1	0
9	0	1	0	0	0	0
10	0	1	0	0	1	1
11	0	1	0	1	0	0
12	0	1	0	1	1	0
13	0	1	1	0	0	0
14	0	1	1	0	1	0
15	0	1	1	1	0	0
16	0	1	1	1	1	0
17	1	0	0	0	0	0
18	1	0	0	0	1	0
19	1	0	0	1	0	1
20	1	0	0	1	1	1
21	1	0	1	0	0	0
22	1	0	1	0	1	0
23	1	0	1	1	0	0
24	1	0	1	1	1	1
25	1	1	0	0	0	0
26	1	1	0	0	1	0
27	1	1	0	1	0	0
28	1	1	0	1	1	0
29	1	1	1	0	0	0
30	1	1	1	0	1	0
31	1	1	1	1	0	0
32	1	1	1	1	1	0