
Crowding / single
Crowding / active
Passive hinge
Soft / fixed preload
Soft / force regulation
Novel / box prior
Novel / measured points
Rigid / fixed preload
Rigid / force regulation
Fault / one attempt
Fault / checked retry
Depth / single packet
Depth / raw fusion
Depth / robust fusion
5/6
3/6
6/6
2/6
6/6
11/12
11/12
10/12
12/12
0/6
6/6
6/12
1/12
9/12
0
25
50
75
100
Complete task success (%) with 95% Wilson intervals