

Product: RTL8811A/RTL8821A USB Software Package - Linux Driver

Version: v5.2.6_21981.20170407_COEX20170206-6760

Release History:

Release History:		
v4.2.0_6952.20130315		First release.
v4.2.0_7054.20130328	1.	Fix LED behavior
v4.2.2_7502.20130517	1.	Support 11AC for STA.
v4.2.3_8123.20130705	1.	Update PHY parameters to improve throughput.
v4.2.4_9533.20131209	1.	Update Phy Parameter for IOT issue
	2.	MP Driver - Packet Tx function
	3.	Fix memory leakage issue
	4.	Fix crash issue when change_band_update_ie() is called for
		2.4G->5G
	5.	Security-TKIP - Prevent starvation caused by log of
		rtw_tkip_decrypt() when binstallGrpkey ==_FALSE
	6.	avoid crash issue when quickly insert/remove driver
	7.	If AP support 802.11r, that will be send deauth with reason
		code 2 to STA. We will loop in connecting.
	8.	Improve P2P connection successful rate & IOT issue for P2P
		connection 9. IOT issue on concurrent mode 10. Support
		Linux kernel 3.10
v4.3.0_10674.20140321	1.	To fix data rate issue of AP mode
_	2.	To fix transmission power issue
		To update PHY setting when driver switches wireless band
		To fix DHCP issue
		To fix race condition issue
v4.3.14_13455.20150212_		This driver can support 8811AU and 8821AU
BTCOEX20150128-51		Support BT coexist
		Support Adaptivity
		Support efuse and mac address can read from file
		Support Sniffer feature
		Support Linux kernel 3.16.0
		Fix some 802.11 logo issue.
		Fix WPS issue
v4.3.19_15408.20151102_B		Support Linux kernel 4.0
TCOEX20150921-58		• •
100212010092100		Updata BT coexist (v58)
		Update PID,VID list
		Support ifconfig modify WiFi MAC
		Fix wpa supplicant disconnect ignore issue
		Fix UDP packet lose issue
		·
v4.3.19.1_16074.20151222	9.	Fix P2P listen state setting listen channel issue
_BTCOEX20150921-58	1.	Support Linux kernel 4.1
	2.	Fix Adaptivity IPS issue
	3.	Enhance RF setting



v4.3.19.2_16962.20160225	1.	Fix Adaptivity scan issue
_BTCOEX20150921-58	2.	Support Driver switch antenna band feature for one
		antenna module
v4.3.19.3_17177.20160325	1.	Support rtkm
_BTCOEX20150921-58	2.	Fix some scan results issue
v4.3.19.4_17413.20160414	1.	Fix MP mode IQK issue
_BTCOEX20150921-58		
v4.3.19.5_17672.20160506	1.	Fix adaptivity issue when DIG change IGI
_BTCOEX20150921-58		
v5.2.6_21981.20170407_C	1.	Support 1 antenna BT coexist
OEX20170206-6760	2.	Support TDLS
	3.	Support 8821au 1 antenna setting
	4.	Support Android 7.0
	5.	Support NAPI GRO
	6.	Update BT coexist
	7.	Update PID,VID list
	8.	Fix SoftAP mode some IOT TP issue
	9.	Fix writing-efuse may cause card-loss issue.



Description:

Realtek provides the solution for WLAN in hardware and software. The software package could be adopted for Realtek RTL8811A/RTL8821A USB WLAN series hardware on Linux based platforms.

Software Version:

RTL8811A/RTL8821A USB Linux Driver Version: v5.2.6_21981.20170407_COEX20170206-6760

- Hardware Supported:
 RTL8811AU
- RTL8821AU

Platform Supported:

- Linux (kernel 2.6.18 ~ 4.5)
- Android $1.6 \sim 2.3, 4.0 \sim 7.0$

CPU supported:

- x86
- ARM
- MIPS

