END TERM EXAMINATION

FOURTH SEMESTER [B.TECH] JUNE 2025

Paper Code: EEC-210 Subject: Electrical Machines-II

Time: 3 Hours Maximum Marks:60

Note: Attempt five questions in all including Q.No.1 which is compulsory. Select one question from each unit.

- Q1 Write short and precise answers of the following: [4x5=20]
 - a) Derive the expressions of frequency of EMF generated in an alternator.
 - b) What are the benefits of stationary armature and rotating field in synchronous generators?
 - c) Are the stator and rotor of a 3-phase induction motor electrically connected? If not, how does the current flows in armature conductors?
 - d) A 3-phase induction motor is running at a slip of 4% when the input power to the stator is 90 kW. Find the rotor copper loss, if the stator copper loss is 2 kW.
 - e) What is the damper winding; and why it is used in synchronous motors?
 - f) State the names of the various methods of starting of a 1-phase induction motor.

UNIT-I

- Q2 a) What is voltage regulation of an alternator? How it is determined by the synchronous impedance method? [5]
 - b) A 3-phase star connected synchronous generator revolves at 1000 rpm. The stator has 90 slots and 8 conductors per slot. The flux per pole is 0.5 Wb. Calculate the voltage generated, if the winding factor if 0.96.

OR

- Q3 What is armature reaction in an alternator? Explain with phasor diagrams its effect on terminal voltage of an alternator at: [10]
 - i) Unity power factor
 - ii) Zero lagging power factor
 - iii) Zero leading power factor

UNIT-II

- Q4 a) Explain and neatly draw the equivalent circuit of a 3-phase induction motor. [5]
 - b) A 50 Hz, 440 V, 3-phase, 4-pole induction motor develops half the rated torque at 1490 rpm. With the applied voltage magnitude remaining at the rated value, what should be its frequency, if the motor has to develop the same torque at 1600 rpm? Neglect the stator and rotor winding resistances, leakage reactance and iron losses.

P.T.O

		OR	
Q5	a)	Describe with neat diagram the star-delta method of starting the	3-
	b)	phase induction motors.	r===
	٠,	A 50 KVA, 400 V, 3-phase, 50 Hz squirrel cage induction most has full load slip of 5%. Its standstill impedance is 0.8	tor
		offin phase. It is started using a tanned auto-transformer to	
		maximum anowable supply current at the time of starting in 100	ne
		- calculate the fallo of Starting torque to full lead to	7, 5]
		UNIT-III	1
Q6	a)	State the principle of operation of a synchronous motor. Description	L .
	1.1	are equilibrium case will will be in on the storting	
	b]	A 3-phase synchronous motor of 8 kW has a second	-
		reactance of offin per phase find minimum	
		corresponding induced EMF for full load condition. The efficience of the machine is 0.8. Neglect the armature resistance.	
		OR	5]
Q7	a]	Describe the effect of varying excitation on armature current ar	nd
	b]	read the dia 3-pilase synchronous motor	=1
	O _j	Derive the expressions of power developed in a 3-phassynchronous motor.	se
		Experience of the control of the con	5]
20	ъ.	UNIT-IV	
28	Expla	in the double revolving field theory and show that a 1-pha	se
		tion motor is not self starting. Draw the torque-slip curves bas s theory.	ed
/		OR	O]
J 9′		short notes on:	
	i) ii)	Universal motor Induction generator	5]
	,	induction generator [5	.=

[5] [5]