Forestry

Time Limit

7min

Using A Grass Eliminator

Watch the video


Job Category	Forestry	Subject	Using a grass eliminator

I Requirements

– Recognize how to use the grass eliminator needed for weeding.

II Diagram & Requirements

1) Diagram



Job Category	Forestry	Subject	Using a grass eliminator

2) Requirements

① Combine the blade with the grass eliminator.

② Combine the washer over the blade.

③ Combine “만조(Component)” over the washer.

④ Combine the nuts by turning them counterclockwise by hand.

⑤ Press a hexagon wrench into the top of the grass eliminator and turn the blade to fix it.

⑥ Hold the hexagon wrench down and use the “플러그 복스(Component)” to secure the nut completely.

⑦ After completing prior processes, turn on the grass eliminator and perform the simulation.

⑧ Check with the instructor, then turn off the power and perform the disassemble operation.

Job Category	Forestry	Subject	Using a grass eliminator

Ⅲ Equipment & Materials

Equipment & Materials		Spec.	Unit	QTY	Remakrs
	Grass Eliminator	· Backpack-type Grass eliminatoInclude blade, flange, washer	SET	1	For 1 person
	Plug Wrench	· 17mm17 mm for lawn mower	PCS	1	For 1 person
	Wrench	· 4mm L 4mm L wrench	PCS	1	For 1 person
	Safety Gloves	· Standard	PCS	1	For 1 person

Time Limit

2M 30S

Measure and Cut

Watch the video


Job Category	Manufacting / Servce I	Subject	Measure and Cut

I Requirements

– Measure weight and length of the given substances, and cut the given material to the desired length.

II Diagram & Requirements

1) Diagram

Meausre Weight	Measure Length	Cutting
		

2) Requirements

⓪ (Pre) After confirming the level of the scale, adjust the zero adjustment screw to align the scale reading to 0.


① Measure the weight of a given item with a scale and record it on paper.

② Measure the length of width, length, inner diameter, outer diameter of the given item and recored it on paper.

③ Cut the wire using a ruler to the length indicated by instructor.

Job Category	Forestry	Subject	Measure and Cut

Ⅲ Equipment & Materials

Equipment & Materials		Spec.	Unit	QTY	Remakrs
	Scale	· Unit for 100g / 30kg	PCS	1	For 1 person
	Items	· Weight Measurement Goods (Box) 5–10 kg · Have a number of items of various weights	PCS	1	Select by the supervisor
	Nipper	· Regular Nipper	PCS	1	For 1 person
	Wires, Ruler	· Minimum length 15cm (or more)	PCS	3/1	(Wire) 3 pieces per person, (Ruler) 1 piece per person
	Component	· Items for measuring legnth	PCS	1	Available in a variety of sizes
	Vernier Calipers	· Digital Vernier Calipers	PCS	1	1 piece per person (If not locally available, replace with a ruler)

Time Limit

2min

Rope Arrangement And Knots

Watch the video


Job Category	Forestry	Subject	Rope arrangement and knots

I Requirements

– Tie and organize the rope according to the Coiling knot method.

II Diagram & Requirements

1) Diagram



Job Category	Forestry	Subject	Rope arrangement and knots

2) Requirements

①-⑧ (Rope arrangement) Hold the rope in one hand, fold it into an oval shape with the other hand, and organize it until itleaves a tail of about 70~80cm. Be careful not to twist the rope.

⑨-⑩ (Hank – rope bundle) Start wrapping the remaining 70~80cm of tail around the hank. Start at one end of the hankand wrap the ail evenly.

⑪-⑯ (Hank Coiling) Keep winding the tail part, and keep winding it repeatedely until there are about 20~25cm left ofthe remaining rope.

⑰ (Make a ring) Make a small ring with the remaining 20~25cm of rope tail, and insert this ring into the hole in the hank.

⑱ After inserting the ring into the hank, spread the ring part wide and wrap it around the hank

Finish the coiling work by pulling the tail rope part.

❖ After confirmation by the instructor, untie the knot and restore the rope to its original state.

Ⅲ Equipment & Materials

Equipment & Materials		Spec.	Unit	QTY	Remakrs
	Rope	• Ø10, PP, ZØ10, PP, Z twisted, 10m long	PCS	1	For 1 person

Time Limit

7min

Pipe Volting

Watch the video


Job Category	Forestry	Subject	Pipe Volting

Ⅰ Requirements

– Use the tool to join the piping flanges.

Ⅱ Diagram & Requirements

1) Diagram

Assemble Sequence	Example
	
Result	**Result (Side)**
	

Job Category	Forestry	Subject	Pipe Volting

2) Requirements

① Assemble the flange using the provided materials and tools, and obtain confirmation from the supervising officer.

<order of assembly>

1. Insert the gasket between the flanges and align it.
2. Lightly tighten the bolts, then check the offset between the two flanges.
3. Using a spanner, tighten the bolts and nuts in a diagonal sequence.
4. During the final tightening, confirm that there is no offset on the flange to complete the task.

② After the supervisor's confirmation, disassemble the assembled flange and gasket within the time limit according toinstructions.

Job Category	Forestry	Subject	Pipe Volting

Ⅲ Equipment & Materials

Equipment & Materials		Spec.	Unit	QTY	Remakrs
	Flange	· 5K 50A	PCS	2	For 1 person
	Gasket	· 5K 50A	PCS	1	For 1 person
	Hex Bolt	· M12, 45mm	PCS	4	For 1 person
	Hexagon Nut	· M12	PCS	4	For 1 person
	Washer	· M12	PCS	8	For 1 person
	Spanner	· 19mm	PCS	2	For 1 person
	Vernier Calipers	· Digital Vernier Calipers · Replace with a ruler if local supply is not available	PCS	1	For 1 person