

LEARJET 60XR S/N 60 333 YV3167

SERVICIOS AEREOS PLATINUM C.A. **OPERATOR:** AERONAUTIC SOLUTIONS JOANRIGER, **OPERATOR:** AERONAUTIC SOLUTIONS JOANRIGER, OWNER: S.A DE C.V. S.A DE C.V. **ADDRESS:** CALLE SANTA ANA EDIF. CENTRO **ADDRESS:** BOULEVARD MIGUEL ALEMAN # 433 INT. **ADDRESS:** CIRCUITO CUAUHTEMOC # 173 PENAFIEL APT 5B METEPEC EDO DE MEXICO 52176 CARACAS 1070 **TOLUCA ESTADO DE MEXICO 52176** PHONE: +58 424 161 5580 PHONE: PHONE: FAX: FAX: FAX: ANALYST: MAURICIO ALVAREZ +1-316-462-2410 (DIRECT) 800-787-9749 (EFAX-CARDS) PLEASE RECORD CHANGES TO ADDRESS, LAST **EMAIL:** MALVAREZ@AVTRAK.COM 1-866-581-2267 (OFFICE) 631-980-4222 (EFAX-CARDS) ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO WWW.CAMPSYSTEMS.COM CAMP. Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; **AIRCRAFT SERIAL/REGNO:** 60 333/YV3167 **MODEL: LEARJET 60XR MANUFACTURER: BOMBARDIER INCORPORATED** LAST ACTUALS **CURRENT ACTUAL DATES** A/C HRS 4301.5 A/C HRS as of 24-JUN-2021 as of CERTIFICATION DATE: 09-DEC-2007 AFL 2772 AFL as of 24-JUN-2021 as of 2796 APH APH as of 24-JUN-2021 as of 2023.1 ACH as of 24-JAN-2019 ACH as of **APU SERIAL/PART:** SP-E980299/4503135 MODEL: T-20G-10C3A (CIMMS) **MANUFACTURER: HAMILTON SUNDSTRAND CORPORATION** LAST ACTUALS **CURRENT ACTUAL INSTALLED ON 26-JAN-2016** 1727 APU HRS 2296 APU HRS as of 24-JUN-2021 APU HRS as of 3371 APUS 4762 APUS **APUS** as of 24-JUN-2021 as of MODEL: PW305/PW305A/PW305B (CIMMS) ENGINE NO. 1 SERIAL/PART: PCE-CA0525/31B4067-04 MANUFACTURER: PRATT & WHITNEY CANADA CORP. LAST ACTUALS **CURRENT ACTUAL INSTALLED ON 24-JUN-2011** ENG. HRS 2586.6 ENG. HRS 2844.73 A/C HRS 4043.5 ENG. HRS as of 24-JUN-2021 1224 ENC 2614 ENC as of 24-JUN-2021 ENC as of ENGINE NO. 2 SERIAL/PART: PCE-CA0526/31B4067-04 MODEL: PW305/PW305A/PW305B (CIMMS) MANUFACTURER: PRATT & WHITNEY CANADA CORP. **INSTALLED ON 12-DEC-2011** LAST ACTUALS **CURRENT ACTUAL**

4301.5 ENG. HRS

2772 ENC

as of 24-JUN-2021

as of 24-JUN-2021

3022.9 ENG. HRS

1488 ENC

0 A/C HRS

ENG. HRS

ENC

as of

as of



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

					ALKONAOTIC SOLOTIONS			Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION	UNIT	INTERV	'AL	ADJ WARR EX	P COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENAM	NCE CHECKS						
05-10-01-A1	PHASE A1-300 HOUR							
	PKG 1	MOS	12	+14d/-14d	-7	12-MAR-2021	05 MAD 0000	40 MAD 0000
	FRG I	HRS/MSC		+25/-25	-1	4286.9	05-MAR-2022 4586.9	19-MAR-2022 4611.9
	REF: AMM 5-10-01	AFL				2754		
05-10-02-A2	PHASE A2-300 HOUR							
	PKG 2	MOS	12	+14d/-14d	-7	12-MAR-2021	05-MAR-2022	19-MAR-2022
		HRS/MSC		+25/-25	·	4286.9	4586.9	4611.9
	REF : AMM 5-10-02	AFL				2754		
05-10-03-A3	PHASE A3-300 HOUR							
	PKG 3	MOS	12	+14d/-14d	-7	12-MAR-2021	05-MAR-2022	19-MAR-2022
		HRS/MSC		+25/-25	·	4286.9	4586.9	4611.9
	REF: AMM 5-10-03	AFL				2754		
05-10-04-A4	PHASE A4-300 HOUR							
	DICO 4	MOG	40	. 4 4 - 1 / 4 4 - 1	7	40 MAD 0004		40.445.0000
	PKG 4	MOS HRS/MSC	12 300	+14d/-14d +25/-25	-7	12-MAR-2021 4286.9	05-MAR-2022 4586.9	19-MAR-2022 4611.9
	REF: AMM 5-10-04	AFL				2754		
05-10-05-A5	PHASE A5-300 HOUR							
	PKG 5	MOS HRS/MSC	12 300	+14d/-14d +25/-25	-7	12-MAR-2021 4286.9	05-MAR-2022 4586.9	19-MAR-2022 4611.9
	REF: AMM 5-10-05	AFL				2754		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTER	-	ADJ WARR EXP			Report Date: 10-SEP-202 MAX LIMIT
IASK NO	TASK DESCRIPTION	UNII	INTER	/AL	ADJ WARK EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
05-10-06-A6	PHASE A6-300 HOUR							
	PKG 6	MOS	12	+14d/-14d	-7	12-MAR-2021	05-MAR-2022	
	REF : AMM 5-10-06	HRS/MSC AFL	300	+25/-25		4286.9 2754	4586.9	4611.9
05-10-07-B1	PHASE B1-600 HOUR							
	PKG 7	MOS	24	+14d/-14d	-39	06-MAR-2020	26-JAN-2022	
	REF : AMM 5-10-07	HRS/MSC AFL	600	+25/-25		4262.1 2723	4862.1	4887.1
05-10-08-B2	PHASE B2-600 HOUR							
	PKG 8	MOS HRS/MSC	24	+14d/-14d +25/-25	-39	06-MAR-2020 4262.1	26-JAN-2022 4862.1	09-FEB-2022 4887.1
	REF : AMM 5-10-08	AFL	000	+201-20		2723	4002.1	4007.1
05-10-09-B3	PHASE B3-600 HOUR							
	PKG 9	MOS	24	+14d/-14d	-39	06-MAR-2020	26-JAN-2022	
	REF : AMM 5-10-09	HRS/MSC AFL	600	+25/-25		4262.1 2723	4862.1	4887.1
05-10-10-B4	PHASE B4-600 HOUR							
	PKG 10	MOS	24	+14d/-14d	-39	06-MAR-2020	26-JAN-2022	
	REF : AMM 5-10-10	HRS/MSC AFL	OUU	+25/-25		4262.1 2723	4862.1	4887.1



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				_	ERONAUTIC SOLUTIONS			Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION	UNIT	INTERV	/AL	ADJ WARR EXF	P COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-11-B5	PHASE B5-600 HOUR							
	PKG 11	MOS	24	+14d/-14d	-39	06-MAR-2020	26-JAN-2022	09-FEB-2022
	REF : AMM 5-10-11	HRS/MSC AFL	600	+25/-25		4262.1 2723	4862.1	4887.1
05-10-12-B6	PHASE B6-600 HOUR							
	PKG 12	MOS	24	+14d/-14d	-39	06-MAR-2020	26-JAN-2022	09-FEB-2022
	REF : AMM 5-10-12	HRS/MSC AFL	600	+25/-25		4262.1 2723	4862.1	4887.1
05-10-13-C1	PHASE C1-1200 HOUR							
	PKG 13	MOS	48	+14d/-14d	-85	06-MAR-2020	12-DEC-2023	26-DEC-2023
	REF: AMM 5-10-13	HRS/MSC AFL	1200	+25/-25		4262.1 2723	5462.1	5487.1
05-10-14-C2	PHASE C2-1200 HOUR							
	PKG 14	MOS	48	+14d/-14d	-85	06-MAR-2020	12-DEC-2023	26-DEC-2023
	REF: AMM 5-10-14	HRS/MSC AFL	1200	+25/-25		4262.1 2723	5462.1	5487.1
05-10-15-C3	PHASE C3-1200 HOUR							
	PKG 15	MOS HRS/MSC	48 1200	+14d/-14d +25/-25	-85	06-MAR-2020 4262.1	12-DEC-2023 5462.1	26-DEC-2023 5487.1
	REF : AMM 5-10-15	AFL	1200	· 20/-20		2723	5-102.1	3707.1



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTER\	/AI	ADJ WARR EXP	COMPLIANCE	NEXT DUE	Report Date: 10-SEP-202 MAX LIMIT
		ONII			ABO WARKELAF	- COMITEIANCE	(ENG/APU) A/C	
05-10-16-C4	PHASE C4-1200 HOUR							
	PKG 16	MOS	48	+14d/-14d	-85	06-MAR-2020	12-DEC-2023	26-DEC-2023
	REF : AMM 5-10-16	HRS/MSC AFL	1200	+25/-25		4262.1 2723	5462.1	5487.1
05-10-17-C5	PHASE C5-1200 HOUR							
	PKG 17	MOS	48	+14d/-14d	-85	06-MAR-2020	12-DEC-2023	26-DEC-2023
	REF : AMM 5-10-17	HRS/MSC AFL	1200	+25/-25		4262.1 2723	5462.1	5487.1
05-10-18-C6	PHASE C6-1200 HOUR							
	PKG 18	MOS HRS/MSC	48	+14d/-14d +25/-25	-85	06-MAR-2020 4262.1	12-DEC-2023 5462.1	26-DEC-2023 5487.1
	REF: AMM 5-10-18	AFL	1200	1231-23		2723	3402.1	3407.1
05-10-19-D1	PHASE D1-2400 HOUR							
	PKG 19	MOS	96	+14d/-14d	-7	31-AUG-2018	24-AUG-2026	
	REF : AMM 5-10-19	HRS/MSC AFL	2400	+25/-25		4067 2472	6467	6492
05-10-20-D2	PHASE D2-2400 HOUR							
	PKG 20	MOS	96	+14d/-14d	-7	31-AUG-2018	24-AUG-2026	
	REF : AMM 5-10-20	HRS/MSC AFL	∠400	+25/-25		4067 2472	6467	6492



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

					ERONAOTIC SOLOTIONS			Report Date: 10-SEP-202
TASK NO	TASK DESCRIPTION	UNIT	INTERV	AL	ADJ WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-21-D3	PHASE D3-2400 HOUR							
	PKG 21	MOS HRS/MSC	96 2400	+14d/-14d +25/-25	-7	31-AUG-2018 4067	24-AUG-2026 6467	
	REF: AMM 5-10-21	AFL	2100	120/20		2472	3.10.1	0.02
05-10-22-D4	PHASE D4-2400 HOUR							
	PKG 22	MOS HRS/MSC	96 2400	+14d/-14d +25/-25	-7	31-AUG-2018 4067	24-AUG-2026 6467	
	REF : AMM 5-10-22	AFL				2472		
05-10-23-D5	PHASE D5-2400 HOUR							
	PKG 23	MOS HRS/MSC	96 2400	+14d/-14d +25/-25	-7	31-AUG-2018 4067	24-AUG-2026 6467	
	REF: AMM 5-10-23	AFL				2472		
05-10-24-D6	PHASE D6 2400 HOUR							
	PKG 24	MOS HRS/MSC	96 2400	+14d/-14d +25/-25	-7	31-AUG-2018 4067	24-AUG-2026 6467	
	REF: AMM 5-10-24	AFL				2472		
05-10-25-3000 LDG	3000 LANDING							
	PKG 25	MOS HRS/MSC				12-MAR-2021 4286.9		
	REF : AMM 5-10-25	AFL	3000	+25/-25		2754	5754	5779



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				-	AERONAUTIC SOLUTIONS	•		Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION	UNIT	INTERV	AL	ADJ WARR EX	XP COMPLIANCE	E NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-10-26-6000 LDG	MAJOR LANDING GEAR							
	PKG 26	MOS				09-DEC-2007		
	REF : AMM 5-10-26	HRS/MSC AFL	6000	+25/-25		0 0	6000	6025
05-10-27-12 YR	12 YEAR AIRFRAME							
	PKG 27	MOS HRS/MSC	144	+14d/-14d	-88	06-MAR-2020 4262.1	09-DEC-2031	23-DEC-2031
	REF : AMM 05-10-27	AFL	6000	+25/-25		2723	8723	8748
05-10-28-12000 HR	12000 HOUR AIRFRAME							
	PKG 28	MOS				09-DEC-2007		
	REF: AMM 5-10-28	HRS/MSC AFL	12000	+25/-25		0 0	12000	12025
	: PW305/PW305A/PW305B (CIM		PCE-CA	0525 Part # 3 [,]	B4067-04			
052000	NO. 1 ENGINE - MINOR INSPE	CTION ITEMS						
	PKG 0	MOS HRS/MSC	24 600	+14d/-14d +25/-25		06-MAR-2020 4004.1	06-MAR-2022 (4604.1) 4862.1	20-MAR-2022 4629.1
	REF: GENERIC NO REF	ENC	000	+ ZJI-ZJ		2565	(4004.1) 4002.1	4025.1
ENGINE NO. 2 Model:	PW305/PW305A/PW305B (CIM NO. 2 ENGINE - MINOR INSPE		PCE-CA	0526 Part # 31	B4067-04			
002000			24	+114/144	50	06 MAD 2020	40 1411 0000	07 IAN 0000
	PKG 0	MOS HRS/MSC	24 600	+14d/-14d +25/-25	-52	06-MAR-2020 4262.1	13-JAN-2022 (4862.1) 4862.1	27-JAN-2022 4887.1
	REF: GENERIC NO REF	ENC				2723		
HAPTER 70	STANDARD PRACTICES	- ENGINES						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021

								Report Date: 10.	3EP-2U21
TASK NO	TASK DESCRIPTION	UNIT INTERV	'AL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
700010	LEFT ENGINE INSPECTION-A	RFRAME ITEMS							
	PKG 29	MOS HRS/MSC 3600	+50			24-JUN-2011 2844.73	6444.73	6494.73	
	REF: GENERIC NO REF	AFL				1382			
70000	DIQUIT ENGINE INODESTION	NIDEDAME ITEMO							
700020	RIGHT ENGINE INSPECTION-	AIRFRAME ITEMS							
	PKG 30	MOS HRS/MSC 3600	+50			12-DEC-2011 3011.9	6611.9	6661.9	
	REF: GENERIC NO REF	AFL				1487			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE	NEYT DUE	oort Date: 10-SI MAX	EP-202
TASK NU	PART/SERIAL	— UNII	TRIERVAL	TIME SINCE	— ADJ	EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT	
APTER 00	INFORMATION									
Cl60-161006	REVIEW LEARJET 60 AMM F	REVISION A15								
REQUIREMENT CHANGE FORMS	REF: RCF Cl60	MOS HRS/MSC AFL	-				(EBT)			
GINE NO. 1 Model: PW	/305/PW305A/PW305B (CIM	MMS) Serial#	PCE-CA0525	Part # 31B4067-04						
EC24-160516	NO. 1 ENGINE - REVIEW PW	/305/PW305A/PW3	05B (CIMMS) EMN	M REV 66.0						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC ENC	-				(EBT)			
EC24-170116	NO. 1 ENGINE - REVIEW PW	/ 305/305A/305B MI	M REV 67.2							
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC ENC	-							
EC24-180214	NO. 1 ENGINE - REVIEW PW	/305/PW305A/PW3	05B EMM REV 69	.1						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC ENC	-				(EBT)			
GINE NO. 2 Model: PW	/305/PW305A/PW305B (CIM	MMS) Serial#	PCE-CA0526	Part # 31B4067-04		-				
EC24-160516	NO. 2 ENGINE - REVIEW PW	/305/PW305A/PW3	05B (CIMMS) EMN	M REV 66.0						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC ENC	-				(EBT)			
EC24-170116	NO. 2 ENGINE - REVIEW PW	/ 305/305A/305B MI	M REV 67.2							
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF:	HRS/MSC ENC	-							



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		port Date: 10-SEP-2 MAX LIMIT
EC24-180214	NO. 2 ENGINE - REVIEW PW	305/PW305A/PW3	305B EMM REV 69.1						
REQUIREMENT CHANGE FORMS	REF: RCF EC24	MOS HRS/MSC ENC	-				(EBT)		
IAPTER 05	TIME LIMITS/MAINTENA	NCE CHECKS							
05-50-05 (s)	PERFORM NO. 2 ENGINE UN	SCHEDULED EN	GINE CHANGE / RE	MOVAL INSPECTIONS (REF	ER TO 5-50-00)		PKG		
	PKG 29,30	MOS HRS/MSC	Δ/R				09-DEC-2007 0		
UNSCHEDULED MAINTENANCE CHECK	REF : AMM 5-50-00	AFL	,				0		
05-50-17	PERFORM FOREIGN OBJEC		ECTION (REFER TO	5-50-00)					
UNSCHEDULED MAINTENANCE CHECK	REF : AMM 5-50-00	MOS HRS/MSC AFL	A/R						
05-PATS-490005	VISUALLY INSPECT ALL MO	UNT PARTS AND	FUSELAGE ATTACH	HMENT POINTS FOR CRACK	KS OR DAMAGE				
		MOS					01-JUN-2011		
	REF: See Workcard	HRS/MSC AFL	3000				2785.83 1342	5785.83	
05-PATS-490006	PERFORM EXHAUST & INLE	T DOUBLER FRA	MES & STRINGERS						
	REF: See Workcard	MOS HRS/MSC AFL	10000				09-DEC-2007 0 0	10000	
PU Model : T-20G-10C3A	A (CIMMS) Serial # SP-E98	0299 Part	# 4503135						
05-PATS-490001	APU - INSP APU PER MANUF	FACTURERS INST	TRUCTIONS						
	REF: SMM 49-11-03	MOS HRS/MSC APUS	200				06-MAR-2020 2236 4640	2436	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 05-PATS-490002 APU - VISUAL INSPECTION APU SUPPORT STRUCTURE MOS 12 12-MAR-2021 12-MAR-2022 HRS/MSC 2268 **APUS** 4714 **REF:** SMM 49-11-03 05-PATS-490004 APU - DETAILED INSPECTION APU SUPPORT STRUCTURE MOS 18-AUG-2002 HRS/MSC 3000 501 3501 **APUS** 1072 **REF:** SMM 49-11-03 05-PATS-490007 APU - DRAIN EPA SUMP MOS 13-JAN-1999 HRS/MSC O/C 0 REF: **APUS** 0 APU - PERFORM OIL LEVEL CHECK 05-T20G-490001 MOS 12-MAR-2021 12-APR-2021 HRS/MSC 2268 **REF:** MM 49-20-00 **APUS** 4714 05-T20G-490002 APU - CHECK EXTERNAL FUEL AND OIL LEAKAGE, AIR INLET AND EXHAUST DUCTS FOR OBSTRUCTION AND ATTACHING BOLTS AND SCREWS FOR ATTACHMENT AND SECURITY MOS 30-JUL-2019 HRS/MSC 500 2203 2703 **REF:** MM 49-20-00 **APUS** 4561 05-T20G-HS-490003 APU - PERFORM APU OIL & FILTER CHANGE MOS 24 30-JUL-2019 30-JUL-2021 HRS/MSC 500 2203 2703 REF: See Workcard **APUS** 4561 05-T20G-HS-490004 APU - VISUAL INSPECTION ENGINE HARNESS MOS 30-JUL-2019 HRS/MSC 500 2203 2703 **APUS** 4561 REF: MM 49-20-00



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		oort Date: 10-SEP-20 MAX
ASK NO	PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	EXP		(ENG/APU) A/C	LIMIT
5-T20G-HS-490005	APU - INSPECTION OF IGNIT	OR PLUG							
	160544-1	MOS					30-JUL-2019		
	NSN	HRS/MSC	500				2203	2703	
	REF: MM 49-20-00	APUS					4561		
05-T20G-HS-490006	APU - INSPECT COMBUSTOR	R FUEL DRAIN L	INE						
		MOS					30-JUL-2019		
	DEE 144 40 00 00	HRS/MSC	500				2203	2703	
	REF : MM 49-20-00	APUS					4561		
05-T20G-HS-490007	APU - INSPECT OIL OVERFIL	L TUBE ASSEM	BLY FOR CLEANLINI	ESS AND OBSTRUCTIONS					
		MOS					30-JUL-2019		
	DEE 144 40 00 00	HRS/MSC	500				2203	2703	
	REF : MM 49-20-00	APUS					4561		
05-T20G-HS-490008	APU - VISUALLY CHECK FUE	L ATOMIZER CU	JP						
		MOS					20-SEP-2004		
		HRS/MSC	O/C				783		
	REF:	APUS					1461		
05-T20G-HS-490009	APU - INSPECTION COMBUS	TOR							
		MOS					12-AUG-2002		
		HRS/MSC	O/C				501		
	REF:	APUS					1072		
05-T20G-HS-490010	APU - INSPECT APU HOUSIN	G, COVERS AN	D BRACKETS						
		MOS					30-JUL-2019		
	DEE 144 40 00 00	HRS/MSC	500				2203	2703	
	REF: MM 49-20-00	APUS					4561		
05-T20G-HS-490011	APU - REPLACE FUEL INLET	FILTER							
		MOS	24				30-JUL-2019	30-JUL-2021	
		HRS/MSC					2203	2703	
	REF: MM 49-20-00	APUS					4561		

?-Insufficient Information +-Task exists in Inspection Manual



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 WARR TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT ENGINE NO. 1 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0525 Part # 31B4067-04 055012 NO. 1 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00) MOS 08-JUL-2007 HRS/MSC A/R 0 UNSCHEDULED **REF:** See Workcard **ENC** MAINTENANCE CHECK ENGINE NO. 2 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0526 Part # 31B4067-04 055012 NO. 2 ENGINE - PERFORM STARTER GENERATOR FAIL INDICATION INSPECTION (REFER TO 05-50-00) MOS 21-JUL-2007 HRS/MSC A/R 0 0 UNSCHEDULED **REF:** See Workcard **ENC** MAINTENANCE CHECK CHAPTER 08 **LEVELING AND WEIGHING** 082000 WEIGHT AND BALANCE 36 MOS 06-MAR-2020 06-MAR-2023 HRS/MSC 4262.1 **REF:** AMM 08-20-00 **AFL** 2723 CHAPTER 11 **PLACARDS AND MARKINGS** 113000 GENERAL VISUAL INSPECTION OF THE CABIN PLACARDS - INTERNAL MOS 06-MAR-2020 HRS/MSC 300 4262.1 4562.1 SMM REF: AFL 2723 CHAPTER 12 **SERVICING** 121005 PERFORM NOSE AND MAIN TIRE PRESSURE CHECKS MOS 25-JUL-2013 HRS/MSC A/R 3238.27 **REF:** AMM 12-10-05 AFL 1618 CHAPTER 21 **AIR CONDITIONING** 05-10-29-U2130007 PERFORM CABIN LEAK RATE CHECK MOS 01-AUG-2014 HRS/MSC 1200 +25/-25 3366.65 4566.65 4591.65 **REF:** AMM 21-30-00 **AFL** 1685

?-Insufficient Information +-Task exists in Inspection Manual (ENG/APU) = Engine/APU Units

(s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TACK NO				IC SOLUTIONS JOANS	Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
212001	COCKPIT AIR CHECK VALVE					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-20-01	AFL	N:0		0	
212003	LEFT CABIN AIR CHECK VAL	VE				
	60160-11	MOS	N:0		09-DEC-2007	
	3BC15	HRS/MSC O/C	N:0		0	
	REF : AMM 21-20-02	AFL	N:0		0	
212004	RIGHT CABIN AIR CHECK VA	LVE				
	60160-11	MOS	N:0		09-DEC-2007	
	6862AC	HRS/MSC O/C	N:0		09-DEC-2007	
	REF : AMM 21-20-02	AFL	N:0		0	
212005	LEFT CABIN OVERHEAD DIFF	FUSER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-20-03	AFL	N:0		0	
212006	RIGHT CABIN OVERHEAD DII	FFUSER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-20-03	AFL	N:0		0	
212007	AFT EVAPORATOR BLOWER	ASSEMBLY				
	66-0261-2	MOS			25-OCT-2013	
	6602612-015	HRS/MSC O/C			3308.7	
	REF : AMM 21-51-10	AFL			1660	
212007A	INSPECT AFT EVAPORATOR	BLOWER ASSEMBLY BRUSHES				
	66-0261-2	MOS			25-OCT-2013	
	6602612-015	HRS/MSC O/C			3308.7	
	REF: GENERIC NO REF	AFL			1660	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

		US AEREUS PLATINUM C.A.					Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ I	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212008	FWD EVAPORATOR BLOWER	R ASSEMBLY						
	66-0251-4SB	MOS	N:0			09-DEC-2007		
	K21417	HRS/MSC O/C	N:0			0		
	REF : AMM 21-51-08	AFL	N:0			0		
212101	CABIN EVAPORATOR BLOWI	ER						
	66-0261-2	MOS	R:0			26-OCT-2013		
	6602612-054	HRS/MSC O/C	R:0			3308.7		
	REF : AMM 21-21-01	AFL	R:0			1660		
212104	COCKPIT EVAPORATOR BLC	OWER						
-	66-0251-4	MOS	R:0			22-FEB-2018		
	K10368	HRS/MSC O/C	R:0			3974.8		
	REF : AMM 21-21-04	AFL	R:0			2358		
212105	COCKPIT BLOWER CONTRO	DL BOX ASSEMBLY						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 21-21-05	AFL	N:0			0		
212155	LEFT BLEED AIR MUFFLER A	ASSEMBLY						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF: GENERIC NO REF	AFL	N:0			0		
212156	RIGHT BLEED AIR MUFFLER	ASSEMBLY						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF: GENERIC NO REF	AFL	N:0			0		
212201	LEFT WINDSHIELD DEFOG/E	EQUIPMENT COOLING FAN						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 21-22-01	AFL	N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE NEXT DUE	port Date: 10-SEP-202 MAX
	PART/SERIAL			THIL SINGE		EXP	(ENG/APU) A/C	LIMIT
212202	RIGHT WINDSHIELD DEFOG/	EQUIPMENT CO	OLING FAN					
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-22-01	AFL		N:0			0	
212205	AVIONICS COOLING FAN							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-22-02	AFL		N:0			0	
213001	PRIMARY OUTFLOW VALVE							
	103780-2	MOS		N:0			26-JAN-2016	
	76-B0105	MOS HRS/MSC	O/C	N:0 N:0			26-JAN-2016 3583.3	
	REF : AMM 21-30-01	AFL	0.0	N:0			1916	
213002	SECONDARY OUTFLOW VAL	VE						
	103780-2	MOS		N:0			09-DEC-2007	
	126B0345	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-30-02	AFL		N:0			0	
213003	CABIN AIR PRESSURE SELE	CTOR						
	2119828-2	MOS		N:0			09-DEC-2007	
	67-B0382	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-30-03	AFL		N:0			0	
213004	CABIN PRESSURE CONTROL	LER						
	2119830-4 / 6600812-014	MOS					13-FEB-2008	
	47-F0117	HRS/MSC	O/C	R:0			205.35	
	REF : AMM 21-30-04	AFL		R:0			84	
213005	MANUAL PRESSURE CONTR	OLLER						
	4222152-1001	MOS		N:0			09-DEC-2007	
	1311D	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-30-05	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT II	NTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-20 MAX LIMIT
213006	AIR FILTER					_	(2.13.7.1.3)	LIMIT
	147240-1	MOS		N:0			24-AUG-2010	
	NONE REF: AMM 21-30-06	HRS/MSC C AFL	D/C	N:0 N:0			2317.85 1066	
213008	PRESSURIZATION MODE SW	VITCH						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN REF: AMM 21-30-08	HRS/MSC C AFL	5/C	N:0 N:0			0	
213009	EMERGENCY DEPRESSURIZ	ZATION SWITCH						
213003	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC C	D/C	N:0			0	
	REF: AMM 21-30-09	AFL		N:0			0	
213010	CABIN PRESSURE INDICATO	DR						
	10403N04C00	MOS		N:0			09-DEC-2007	
	0803A REF : AMM 21-30-10	HRS/MSC C AFL	D/C	N:0 N:0			0 0	
213011	VACUUM REGULATOR							
	131402-2 1484D	MOS HRS/MSC C	O/C	N:0 N:0			09-DEC-2007	
	REF: AMM 21-30-11	AFL	<i>5</i> /C	N:0 N:0			0	
213012	VACUUM PUMP							
	131410-3	MOS		N:0			09-DEC-2007	
	56-1672	HRS/MSC C	D/C	N:0			0	
	REF: AMM 21-30-12	AFL		N:0			0	
213013	VACUUM CHECK VALVE							
	130158-1	MOS		N:0			09-DEC-2007	
	126-4407 REF : AMM 21-30-13	HRS/MSC C AFL	D/C	N:0 N:0			0	
	11217	=					-	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR	COMPLIANCE NEXT DUE	port Date: 10-SEP-202 MAX
	PART/SERIAL			EXP	(ENG/APU) A/C	LIMIT
213101	LEFT EMERGENCY PRESSU	JRIZATION VALVE				
	61700-1	MOS	N:0		09-DEC-2007	
	1090	HRS/MSC O/C	N:0		0	
	REF : AMM 21-31-01	AFL	N:0		U	
213102	RIGHT EMERGENCY PRESS	SURIZATION VALVE				
	61700-1	MOS	N:0		09-DEC-2007	
	1087	HRS/MSC O/C	N:0		0	
	REF : AMM 21-31-01	AFL	N:0		0	
213103	LEFT EMERGENCY PRESSU	IRIZATION ANEROID SWITCH				
	2E37C-30	MOS	N:0		09-DEC-2007	
	824	HRS/MSC O/C	N:0		0	
	REF : AMM 21-31-02	AFL	N:0		0	
213104	RIGHT EMERGENCY PRESS	SURIZATION ANEROID SWITCH				
	2E37C-30	MOS	N:0		09-DEC-2007	
	867	HRS/MSC O/C	N:0		0	
	REF: AMM 21-31-02	AFL	N:0		0	
213105	LEFT CONDITIONED AIR CH	ECK VALVE				
	60160-2	MOS	N:0		09-DEC-2007	
	7424AC	HRS/MSC O/C	N:0		0	
	REF: AMM 21-31-03	AFL	N:0		0	
213106	RIGHT CONDITIONED AIR C	HECK VALVE				
	60160-2	MOS	N:0		09-DEC-2007	
	7419AC	HRS/MSC O/C	N:0		0	
	REF : AMM 21-31-03	AFL	N:0		0	
213107	POSITIVE VENTILATION CHI	ECK VALVE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-31-04	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	TERVAL TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-20 MAX LIMIT
214001	FLOW CONTROL VALVE					
	320335-3	MOS	O:0		25-MAR-2010	
	397 REF : AMM 21-40-01	HRS/MSC O/O AFL	O:0 O:0		2031.7 932	
	REF. AIVIIVI 21-40-01	AFL	0.0		932	
214002	HEAT EXCHANGER					
	6608060-009	MOS	N:0		09-DEC-2007	
	A212	HRS/MSC O/O			0	
	REF: AMM 21-40-02	AFL	N:0		0	
214101	COCKPIT HEATER					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/O			0	
	REF : AMM 21-41-01	AFL	N:0		0	
214102	COCKPIT DIVERTER DOOR S	SOLENOID				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/O			0	
	REF: AMM 21-41-02	AFL	N:0		0	
214103	COCKPIT DIVERTER DOOR F	RESISTOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/O			0	
	REF: AMM 21-41-03	AFL	N:0		0	
214104	COCKPIT DIVERTER DOOR T	THERMOSTAT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/O			0	
	REF : AMM 21-41-04	AFL	N:0		0	
214201	LEFT AUXILIARY CABIN HEA	TER				
	7026-3	MOS	N:0		09-DEC-2007	
	0317	HRS/MSC O/O			0	
	REF : AMM 21-42-01	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MA (ENG/APU) A/C LIN	AX MIT
214202	RIGHT AUXILIARY CABIN HE	EATER				
	7026-4	MOS	N:0		09-DEC-2007	
	0315	HRS/MSC O/C	N:0		0	
	REF: AMM 21-42-01	AFL	N:0		0	
214203	AUXILIARY HEAT OVERTEM	PERATURE MONITOR BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-42-02	AFL	N:0		0	
214301	LEFT OUTBOARD ELECTRIC	C FOOT WARMER ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-43-00	AFL	N:0		0	
214302	LEFT INBOARD ELECTRIC F	OOT WARMER ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-43-00	AFL	N:0		0	
214303	RIGHT INBOARD ELECTRIC	FOOT WARMER ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-43-00	AFL	N:0		0	
214304	RIGHT OUTBOARD ELECTR	IC FOOT WARMER ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-43-00	AFL	N:0		0	
215001	AIR CONDITIONING COMPR	ESSOR				
	JBS222-1	MOS	O:0		24-JAN-2019	
	SA4146	HRS/MSC O/C	O:0		4067	
	REF: See Workcard	AFL	O:0		2472	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	eport Date: 10-SEP-20 MAX LIMIT
215003	CONDENSER							
	7608061-1	MOS		N:0			09-DEC-2007	
	984	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
215004	RECEIVER/DRYER							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
215005	FREON PRESSURE SWITCH							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
215006	COCKPIT EVAPORATOR							
	6009002V2-002	MOS		N:0			09-DEC-2007	
	K26515	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
215007	FREON COMPRESSOR DRIV	E (R134) MOTOF	₹					
	ES61134-3	MOS					05-APR-2018	
	221	HRS/MSC					3981.3	
OVERHAUL	REF: AMM 21-51-02	AFL ACH	2000 +25	-25			2361 ?	?
0450074	NODEST/DEDLAGE EDESNA		DIVE (D404) 140	TOD DD1101150 OF 40 00 1/0	450000			
215007A	INSPECT/REPLACE FREON (IKIVE (K134) MO	I OK BRUSHES - 05-10-29-K2	100036			
	ES61134-3 221	MOS HRS/MSC					24-JAN-2019 4067	
	REF : AMM 21-51-02	AFL					2472	
		ACH	1200 +25	-25				M 2948
215008	COCKPIT EVAPORATOR PRE	SSURE REGULA	ATOR VALVE					
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-50-08	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE	NEXT DUE	oort Date: 10-SEP-2 MAX
	PART/SERIAL					EXP		(ENG/APU) A/C	LIMIT
215009	CABIN EVAPORATOR								
	6009002V2-001	MOS		N:0			09-DEC-2007		
	K20995 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
	REF. See Workdard	AFL		N.U			Ü		
215010	CABIN EXPANSION VALVE								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
215012	FREON MOTOR CONTROL B	OX							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			09-DEC-2007		
	REF: See Workcard	AFL		N:0			0		
215013	K61 FREON MOTOR CONTAC	CTOR							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
215014	K62 FREON MOTOR CONTAC	CTOR							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
215015	K63 FREON MOTOR CONTAC	CTOR							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
215016	FREON MOTOR DIFFERENTI	AL CURRENT SE	ENSOR						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICIO	JJ ALKLUJ P	LATINOPI C.A. (operator. AEKONAOTIC	. 30LU 10N.	3 JUANK	IGER, S.A DE C.V.	Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUI (ENG/APU) A/	MAX
215017	COMPRESSOR MOTOR HOU	IRMETER						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
215031	ABSOLUTE PRESSURE SWIT	ГСН						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
215049	COCKPIT EXPANSION VALVE	 E						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
215101	FREON COMPRESSOR DRIV	E (R-12) MOTOR						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
N/A EQUIPMENT NOT INSTALLED	REF: AMM 21-50-02	AFL		N:0			0	
215101A	PERFORM FREON COMPRES	SSOR DRIVE (R-	12) MOTOR BRUSH	WEAR INSPECTION - 05-10-2	9-K2150012			
	PN	MOS					09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C				0	
N/A EQUIPMENT NOT INSTALLED	REF : AMM 21-50-02	AFL					0	
215120	CONDENSER FAN							
	B.1.	MOS		N:0			09-DEC-2007	
	PN							
	PN SN-UNKNOWN REF : AMM 21-50-02	HRS/MSC AFL	O/C	N:0 N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TACK NO.		OS AEREOS PLATINUM C.A.			Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
216001	REMOTE CABIN TEMPERAT	URE SETTING BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-60-01	AFL	N:0		0	
216002	CREW TEMPERATURE SELE	ECTOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-60-02	AFL	N:0		0	
216003	CABIN TEMPERATURE SELE	-CTOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0 N:0		09-DEC-2007 0	
	REF : AMM 21-60-02	AFL	N:0		0	
216004	TEMPERATURE CONTROL II	NDICATOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-60-03	AFL	N:0		0	
216005	COCKPIT TEMPERATURE CO	ONTROLLER				
	625734-2	MOS	N:0		09-DEC-2007	
	625734-01159	HRS/MSC O/C	N:0		0	
	REF : AMM 21-60-04	AFL	N:0		0	
216006	CABIN TEMPERATURE CON	TROLLER				
	625734-2	MOS	N:0		09-DEC-2007	
	625734-01158	HRS/MSC O/C	N:0		0	
	REF : AMM 21-60-04	AFL	N:0		0	
216007	COCKPIT TEMPERATURE SI	ENSOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-60-05	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

ASK NO	TASK DESCRIPTION	UNIT INTERVAL						
	PART/SERIAL	ONII INTERVAL	TIME SINCE	ADJ W E	/ARR (XP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216008	CABIN TEMPERATURE SENS	SOR						
	625704-1	MOS	N:0		(09-DEC-2007		
	0570-7180	HRS/MSC O/C	N:0)		
	REF : AMM 21-60-05	AFL	N:0		()		
216009	COCKPIT TEMPERATURE SE	NSOR BLOWER						
	660231-1	MOS			(04-MAR-2010		
	N/A	HRS/MSC O/C				1997.87		
	REF : AMM 21-60-05	AFL			ę	916		
216010	CABIN TEMPERATURE SENS	SOR BLOWER						
	6600231-1	MOS			2	28-MAY-2009		
	SN-UNKNOWN	HRS/MSC O/C				1407.23		
	REF : AMM 21-60-05	AFL			6	311		
216011	COCKPIT SKIN TEMPERATUR	RE SENSOR						
	PN	MOS	N:0		(09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0)		
	REF : AMM 21-60-06	AFL	N:0		()		
216012	CABIN SKIN TEMPERATURE	SENSOR						
	625704-1	MOS	N:0		(09-DEC-2007		
	0570-7182	HRS/MSC O/C	N:0		(
	REF : AMM 21-60-06	AFL	N:0		()		
216013	COCKPIT TEMPERATURE CO	ONTROL VALVE						
	3291290-2	MOS	N:0		(09-DEC-2007		
	677	HRS/MSC O/C	N:0		(
	REF : AMM 21-60-07	AFL	N:0		()		
216014	CABIN TEMPERATURE CONT	TROL VALVE						
	3291290-1	MOS	N:0		(09-DEC-2007		
	681	HRS/MSC O/C	N:0)		
	REF: AMM 21-60-07	AFL	N:0		()		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				-			RIGER, S.A DE C.V. Re	eport Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP		MAX LIMIT
216015	COCKPIT TEMPERATURE CO	ONTROL VALVE 1	TORQUE MOTOR					
	124904-1-1	MOS		N:0			09-DEC-2007	
	6768	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-60-08	AFL		N:0			0	
216016	CABIN TEMPERATURE CON	TROL VALVE TOF	RQUE MOTOR					
	124904-1-1	MOS		N:0			09-DEC-2007	
	6773	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-60-08	AFL		N:0			0	
216017	SERVO AIR PRESSURE REG	GULATOR						
	60810-1	MOS		N:0			09-DEC-2007	
	1196	HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0	
	REF : AMM 21-60-09	AFL		N:0			0	
216018	COCKPIT AIR DISTRIBUTION	I CHECK VALVE						
	3202078-1	MOS		N:0			09-DEC-2007	
	1334	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-60-10	AFL		N:0			0	
216019	CABIN AIR DISTRIBUTION C	HECK VALVE						
	3202188-1	MOS		N:0			09-DEC-2007	
	737	HRS/MSC	O/C	N:0			0	
	REF : AMM 21-60-10	AFL		N:0			0	
216020	COCKPIT DUCT TEMPERATU	JRE SENSOR						
	627962-2	MOS		N:0			09-DEC-2007	
	627962-20712	HRS/MSC	O/C	N:0			0	
	REF: AMM 21-60-11	AFL		N:0			0	
216021	CABIN DUCT TEMPERATURE	E SENSOR						
	627962-2	MOS		N:0			09-DEC-2007	
	627962-20596	HRS/MSC	O/C	N:0			0	
				N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP		-SEP-202
216022	COCKPIT DUCT OVERHEAT	THERMOSTAT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-60-12	AFL	N:0		0	
216023	CABIN DUCT OVERHEAT TH	ERMOSTAT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-60-12	AFL	N:0		0	
216024	CLIMATE CONTROL BOX					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-60-13	AFL	N:0		0	
216025	PILOT ELECTRICAL EQUIPM	ENT BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 21-60-14	AFL	N:0		0	
216050	MEMBRANE, CABIN TEMPER	RATURE SWITCH				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
216101	CABIN TEMPERATURE INDIC	CATOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 21-61-01	AFL	N:0		0	
216102	CABIN TEMPERATURE INDIC	CATOR SENSOR				
	RTD-1-F3142-48-T	MOS			28-MAY-2009	
	SN-UNKNOWN	HRS/MSC O/C			1407.23	
	REF: AMM 21-61-02	AFL			611	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 218105 LEFT TRANSITION DUCT ASSEMBLY PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 21-51-10 0 AFL N:0 218106 RIGHT TRANSITION DUCT ASSEMBLY PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 AFL N:0 0 **REF:** AMM 21-51-10 CHAPTER 22 **AUTO FLIGHT** 221001 **AUTOPILOT CONTROLLER** 501-1679-03 MOS N:0 09-DEC-2007 HRS/MSC O/C N:0 0 80009 **REF:** AMM 22-10-01 N:0 0 AFL 221002 **AUTOPILOT ELECTRICAL BOX** PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 REF: AMM 22-10-02 AFL N:0 0 221003 PITCH SERVO ACTUATOR 622-5027-102 MOS N:0 09-DEC-2007 2HJRC HRS/MSC O/C N:0 0 0 **REF:** AMM 22-10-03 AFL N:0 221004 PITCH SERVO MOUNT 622-5029-101 MOS N:0 09-DEC-2007 2LK4X HRS/MSC O/C N:0 0 **REF:** AMM 22-10-04 AFL N:0 0 221005 AUTOPITCH TRIM AMPLIFIER BOX ASSEMBLY 5418419-009 MOS 27-MAR-2011 A00861372-01 HRS/MSC O/C 2677.77 **REF:** AMM 22-10-05 AFL 1279



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR		port Date: 10-SEP-20 MAX
AON NO	PART/SERIAL	- ONIT	INTERVAL	TIME SINGE		EXP	(ENG/APU) A/C	LIMIT
21006	ROLL SERVO ACTUATOR							
	622-5027-102	MOS		N:0			09-DEC-2007	
	2HHXB	HRS/MSC	O/C	N:0			0	
	REF : AMM 22-10-06	AFL		N:0			0	
221007	ROLL DISCONNECT RELAY B	OX						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 22-10-07	AFL		N:0			0	
221008	YAW DISCONNECT RELAY BO	OX						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0	
	REF : AMM 22-10-08	AFL	- · -	N:0			0	
221009	YAW SERVO ACTUATOR							
	622-5027-102	MOS HRS/MSC	0/0	N:0			09-DEC-2007	
	2HJFH REF : AMM 22-10-09	AFL	0/0	N:0 N:0			0 0	
	1121 17111111 22 10 00	7						
221010	YAW SERVO MOUNT							
	622-5029-101	MOS		N:0			09-DEC-2007	
	2LK2Y	HRS/MSC	O/C	N:0			0	
	REF : AMM 22-10-10	AFL		N:0			0	
221011	ROLL SERVO MOUNT							
	6080014-2	MOS		N:0			09-DEC-2007	
	2K77Y	HRS/MSC	O/C	N:0			0	
	REF : AMM 22-10-11	AFL		N:0			0	
221012	REMOTE TUNING RELAY BOX	×						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: AMM 22-10-12	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				Operator: AERONAUT			Re	port Date: 10-SEP-202		
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE		VARR XP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT		
221013	NO. 1 FLIGHT GUIDANCE COMPUTER									
	822-1108-041	MOS		O:0			09-MAY-2011			
	2HRBN REF : AMM 22-10-14	HRS/MSC AFL	O/C	O:0 O:0			2764.07 1332			
	REF. AIVIIVI 22-10-14	AFL		0.0			1332			
221014	NO. 2 FLIGHT GUIDANCE CO	MPUTER								
	822-1108-041	MOS		O:0			01-JUN-2011			
	33DHV	HRS/MSC	O/C	O:0			2785.83			
	REF : AMM 22-10-14	AFL		O:0			1342			
222001	MACH TRIM COMPUTER									
	501-1132-04	MOS		N:0			09-DEC-2007			
	80055	HRS/MSC	O/C	N:0			0			
	REF : AMM 22-20-01	AFL		N:0			0			
222002	MACH TRIM ADAPTER									
	902-1-2	MOS		N:0			09-DEC-2007			
	207210095	HRS/MSC	O/C	N:0			0			
	REF : AMM 22-20-02	AFL		N:0			0			
222003	MACH TRIM POSITION (FOLL	_OW UP) SENSO	R							
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF : AMM 22-20-03	AFL		N:0			0			
225001	YAW FORCE INTERFACE BOX									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 22-50-01	AFL		N:0			0			
225002	PILOT FORCE SENSOR									
	3454-101-650	MOS		N:0			09-DEC-2007			
	1165996	HRS/MSC	O/C	N:0			0			
	REF : AMM 22-50-02	AFL		N:0			0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	S AEREOS P	LATINUM C.A. (Operator: AERONAUTI	C SOLUTIO	NS JOANR	IGER, S.A DE C.	V.	oort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
225003	COPILOT FORCE SENSOR								
	3454-101-650 2659 REF : AMM 22-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
CHAPTER 23	COMMUNICATIONS								
23-15-00-M100471ICT-1	FUNCTIONAL TEST OF IRIDIU M100471ICT)	M SATELLITE C	OMMUNICATIONS	PHONE SYSTEM (STC ST01-	422WI-D, IFCA				
		MOS HRS/MSC	24				06-MAR-2020 4262.1	06-MAR-2022 4862.1	
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF:	AFL	000				2723	4002.1	
23-15-00-M100471ICT-2	GENERAL VISUAL INSPECTIO CHECK FOR SECURITY OF AT					RDWARE.			
		MOS	48				31-AUG-2018	31-AUG-2022	
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF:	HRS/MSC AFL	1200				4067 2472	5267	
23-15-00-M100471ICT-3	GENERAL VISUAL INSPECTIO CHECK FOR SECURITY OF AT					ARDWARE.			
		MOS	48				31-AUG-2018	31-AUG-2022	
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF:	HRS/MSC AFL	1200				4067 2472	5267	
23-15-00-M100471ICT-4	GENERAL VISUAL INSPECTIO HARDWARE. CHECK FOR SEC								
		MOS	48				31-AUG-2018	31-AUG-2022	
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF:	HRS/MSC AFL	1200				4067 2472	5267	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE WARR **COMPLIANCE NEXT DUE** INTERVAL ADJ MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 23-15-00-M100471ICT-5 GENERAL VISUAL INSPECTION OF THE IRIDIUM SATCOM ANTENNA AND RETAINING HARDWARE. CHECK FOR SECURITY OF ATTACHMENT AND OTHER DEFECTS (STC ST01422WI-D, IFCA M100471ICT) MOS 48 31-AUG-2018 31-AUG-2022 HRS/MSC 1200 4067 5267 STC-SUPPLEMENTAL TYPE REF: AFL 2472 CERTIFICATE 23-15-00-M100471ICT-6 GENERAL VISUAL INSPECTION OF THE IRIDIUM SATCOM SYSTEM CONNECTORS AND THE WIRING. CHECK FOR CHAFFING, DAMAGE, SECURITY OF ATTACHMENT, AND OTHER DEFECTS (STC ST01422WI-D, IFCA M100471ICT) MOS 48 31-AUG-2022 31-AUG-2018 HRS/MSC 1200 4067 5267 STC-SUPPLEMENTAL TYPE REF: AFL 2472 CERTIFICATE DETAILED INSPECTION OF THE ENTIRE AREA AROUND THE IRIDIUM ANTENNA SKIN CUTOUT AND THE DOUBLER 23-15-00-M100471ICT-AWL LOCATED ON THE AIRCRAFT CENTERLINE AT FS326 (STC ST01422WI-D, IFCA M100471ICT) MOS 09-DEC-2007 HRS/MSC STC-SUPPLEMENTAL TYPE REF: **AFL** 6000 0 6000 CERTIFICATE 231101 NO. 1 VHF TRANSCEIVER 822-1115-001 MOS R:0 18-JUN-2009 1RLP HRS/MSC O/C R:0 1442.57 **REF:** AMM 23-11-01 AFL R:0 628 231102 NO. 2 VHF TRANSCEIVER 822-1115-001 MOS 30-NOV-2010 2D27V HRS/MSC O/C 2484.57 REF: AMM 23-11-01 AFL 1162 231103 NO. 1 VHF ANTENNA VF10-347 MOS N:0 09-DEC-2007 5423 HRS/MSC O/C N:0 0 **REF:** AMM 23-11-02 **AFL** N:0 0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-202 MAX LIMIT		
231104	NO. 2 VHF ANTENNA								
	VF10-347	MOS		N:0		09-DEC-2007			
	5140	HRS/MSC	O/C	N:0		0			
	REF: AMM 23-11-02	AFL		N:0		0			
231121	AERO M SATCOM ANTENNA								
	PN	MOS		N:0		09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF: GENERIC NO REF	AFL		N:0		0			
231123	SATCOM PHONE								
	PN	MOS		N:0		09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF: GENERIC NO REF	AFL		N:0		0			
231180	NO. 1 HF AUDIO AMPLIFIER								
	PN	MOS		N:0		09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF: GENERIC NO REF	AFL		N:0		0			
231181	NO. 2 HF AUDIO AMPLIFIER								
	PN	MOS		N:0		09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF: GENERIC NO REF	AFL		N:0		0			
231192	HF ANTENNA LEADTHRU INSULATOR								
	PN	MOS		N:0		09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF : AMM 23-12-03	AFL		N:0		0			
231201	NO. 1 HF RECEIVER/EXCITE	R							
	064-01073-0101	MOS		N:0		09-DEC-2007			
	2522	HRS/MSC	O/C	N:0		0			
	REF: AMM 23-12-01	AFL		N:0		0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	JO ALKLOO I	LATINOTI CIAI					Re	port Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
231202	NO. 2 HF RECEIVER/EXCITE	R							
	064-01073-0101	MOS		N:0			09-DEC-2007		
	2480	HRS/MSC	O/C	N:0			0		
	REF : AMM 23-12-01	AFL		N:0			0		
231203	PRIMARY POWER AMPLIFIEI	R/ANTENNA COL	JPLER						
	064-01074-0101	MOS		N:0			09-DEC-2007		
	2050	HRS/MSC	O/C	N:0			0		
	REF : AMM 23-12-02	AFL		N:0			0		
231203A	PERFORM PRIMARY POWEF INPUT AND MEASUREMENT				(AC 1052 PRESS	SURE			
	064-01074-0101	MOS	12 +14d/-		-6		12-MAR-2021	06-MAR-2022	20-MAR-2022
	2050	HRS/MSC					4286.9		
SMM	REF : AMM 23-12-08	AFL					2754		
231204	STANDBY POWER AMPLIFIE	R/ANTENNA COU	JPLER						
	064-01074-0101	MOS		N:0			09-DEC-2007		
	1863	HRS/MSC	O/C	N:0			0		
	REF : AMM 23-12-02	AFL		N:0			0		
231204A	PERFORM STANDBY POWER	R AMPLIFIER/AN ⁻ CHECK VALVE (TENNA COUPLER OF THE KHF 1050 S	PRESSURE CHECK OF THE I	KAC 1052 PRESS	SURE			
	064-01074-0101	MOS	12 +14d/-	14d			12-MAR-2021	12-MAR-2022	26-MAR-2022
	1863	HRS/MSC					4286.9		
SMM	REF : AMM 23-12-08	AFL					2754		
231205	HF ANTENNA								
-	5489123-2	MOS		N:0			16-JUL-2017		
		1100/1400	0/0	NI-O			3849.9		
	N/A REF: AMM 23-12-03	HRS/MSC AFL	0/0	N:0 N:0			2207		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-2 MAX LIMIT
231207	NO. 1 HF CONTROL UNIT								
	PN SN-UNKNOWN REF : AMM 23-12-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
231208	NO. 2 HF CONTROL UNIT								
	G7511-01 1194 REF : AMM 23-12-04	MOS HRS/MSC AFL	O/C				11-AUG-2015 3533.1 1882		
231209	HF AUDIO ADAPTER								
20.1200	PN SN-UNKNOWN REF : AMM 23-12-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
231210	HF COMMUNICATION FUSE E	OX ASSEMBLY							
	PN SN-UNKNOWN REF : AMM 23-12-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
231211	(CBR8) HF REMOTE CIRCUIT	BREAKER							
	PN SN-UNKNOWN REF : AMM 23-12-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
231212	UPPER HF POWER AMPLIFIE	R							
	064-01072-0101 2501 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
231213	LOWER HF POWER AMPLIFIE	:R							
	064-01072-0101 2507 REF : AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	port Date: 10-SEP-202 MAX LIMIT	
231271	HF GROUND ASSEMBLY							
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN REF : GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0		0 0		
	REF. GENERIC NO REF	AFL		IN.U		U		
231301	FLITEFONE TRANSCEIVER							
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF : AMM 23-13-01	AFL		N:0		0		
231302	FLITEFONE ANTENNA							
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF: AMM 23-13-02	AFL		N:0		0		
231303	COCKPIT FLITEFONE BASE - CONTROL UNIT							
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF: AMM 23-13-03	AFL		N:0		0		
231304	CABIN FLITEFONE BASE - CO	ONTROL UNIT						
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF : AMM 23-13-03	AFL		N:0		0		
231305	COCKPIT ASSEMBLY PHONE	<u> </u>						
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF: GENERIC NO REF	AFL		N:0		0		
231306	CABIN ASSEMBLY PHONE							
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF: GENERIC NO REF	AFL		N:0		0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

		DS AEREOS PLATINUM C.A.	Operator: AERONAUTI	C SOLUTIONS JOANI		Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX
231307	COCKPIT FLIGHT PHONE (T)	T-3000) HANDSET				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
231308	CABIN FLIGHT PHONE (TT-30	000) HANDSET				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
231310	AIRBORNE RADIO TELECOM	MUNICATIONS TRAY				
- 1- 1-	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
231312	CABIN DISTRIBUTION BUS R	EPEATER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
231313	LEFT CABIN DISTRIBUTION,	FLITEFONE REPEATER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
231314	RIGHT CABIN DISTRIBUTION	, FLITEFONE REPEATER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
231315	CALL ALERTER, FLITEFONE	SWITCH				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ WARR	COMPLIANCE NEXT DUE	ort Date: 10-SEP-20 MAX
	PART/SERIAL				EXP	(ENG/APU) A/C	LIMIT
31316	ASSEMBLY, ARTU TRAY						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231317	MAGNASTAR (C-2000/C-750 1	ΓMU) ARTU					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231318	MAGNASTAR ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231319	MAGNASTAR ANALOG INTER	RFACE UNIT					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231320	AIRSAT 1 TRANSCEIVER						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231321	AIRSAT 1 HANDSET						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231335	CELLULAR PHONE						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF		-	N:0		0	
	REF: GENERIC NO REF	AFL		IN.U		U	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-202 MAX LIMIT
231340	CELL PHONE ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231351	SATELLITE DATA (SDU) UNIT	T					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
231401	SELCAL CONTROL PANEL						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 23-14-01	AFL		N:0		0	
231402	SELCAL DECODER						
	2800-0012-105	MOS		N:0		09-DEC-2007	
	7255042	HRS/MSC	O/C	N:0		0	
	REF : AMM 23-14-02	AFL		N:0		0	
231403	SELCAL SONALERT						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 23-14-03	AFL		N:0		0	
231501	PASSENGER BRIEFER CONT	FROL PANEL					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 23-15-01	AFL		N:0		0	
231502	PASSENGER BRIEFER COMF	PUTER					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: AMM 23-15-02	AFL		N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PLATINUM C.A.	Operator: AEKUNAUII	IC SOLUTIONS JOANKI	GER, S.A DE C.V. Rep	ort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
232001	IRIDIUM SATCOM TRANSCE	IVER				
	500617-2	MOS	N:0		09-DEC-2007	
	5652	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232005	IRIDIUM SATCOM ANTENNA					
	500644-1	MOS	N:0		09-DEC-2007	
	4091090	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232010	COCKPIT IRIDIUM SATCOM I	PHONE ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232015	CABIN IRIDIUM SATCOM PHO	ONE ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232020	COCKPIT IRIDIUM SATCOM I	HANDSET				
	9L8810A-B	MOS	N:0		09-DEC-2007	
	2704005	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232025	CABIN IRIDIUM SATCOM HAI	NDSET				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232030	IRIDIUM SATCOM PHONE CF	RADLE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR	COMPLIANCE NEXT DUE MAX	10-SEP-202
	PART/SERIAL	24815		EXP	(ENG/APU) A/C LIMIT	
32035	IRIDIUM SATCOM PHONE CF					
	PN	MOS	N:0 N:0		09-DEC-2007 0	
	SN-UNKNOWN REF : GENERIC NO REF	HRS/MSC O/C AFL	N:0 N:0		0	
		,			•	
232040	IRIDIUM SATCOM CORDLES	S BASE UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232045	IRIDIUM SATCOM CORDLES	S BASE UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232055	UNILINK (UL-601) PROCESSO	DR .				
	MSM2905-02-1	MOS			06-OCT-2009	
	060900275	HRS/MSC O/C			1736.45	
	REF: GENERIC NO REF	AFL			787	
232105	VHF DATA LINK TRANSCEIVI	ER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 23-11-01	AFL	N:0		0	
232110	COMMUNICATION MANAGEM	MENT (CMU) UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
232111	CMU EXTERNAL COMPENSA	ATION UNIT (ECU-3000)				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TA 01/ N 0		OS AEREOS PLATINUM C.A.			Rej	oort Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR C EXP	OMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
232120	SATPHONE ANTENNA					
	PN	MOS	N:0	09	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF: GENERIC NO REF	AFL	N:0	0		
233001	LEFT FORWARD CABIN STE	REO SPEAKER				
	PN	MOS	N:0	09	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF : AMM 23-30-01	AFL	N:0	0		
233002	RIGHT FORWARD CABIN ST	EREO SPEAKER				
	PN	MOS	N:0	nc	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0 N:0	08	J-DLO-2001	
	REF : AMM 23-30-01	AFL	N:0	0		
233003	LEFT AFT CABIN STEREO SF	PEAKER				
	PN	MOS	N:0	09	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF : AMM 23-30-01	AFL	N:0	0		
233004	RIGHT AFT CABIN STEREO S	SPEAKER				
	PN	MOS	N:0	09	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF: AMM 23-30-01	AFL	N:0	0		
233005	PASSENGER SPEAKER AMP	PLIFIER				
	PA-7501-01-1	MOS	N:0	09	9-DEC-2007	
	040700620	HRS/MSC O/C	N:0	0		
	REF: AMM 23-30-02	AFL	N:0	0		
233007	DVD PLAYER					
	PN	MOS	N:0	nc	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF: GENERIC NO REF	AFL	N:0	0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	AD.J	WARR	COMPLIANCE	NEXT DUE	oort Date: 10-SEP-20 MAX
	PART/SERIAL					EXP		(ENG/APU) A/C	LIMIT
233023	FORWARD WOOFER, CABIN	SPEAKER							
	EN-W-60-4	MOS		N:0			09-DEC-2007		
	070700190	HRS/MSC	O/C	N:0			0		
	REF : AMM 23-30-01	AFL		N:0			0		
233024	AFT WOOFER, CABIN SPEAK	ŒR							
	EN-W-60-4	MOS		N:0			09-DEC-2007		
	070700191	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-30-01	AFL		N:0			0		
233026	VIDEO CASSETTE PLAYER								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
233030	CONFIGURATION MODULE								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
233040	INFRARED REMOTE CONTRO	DL							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
233051	CD CHANGER								
	MCD-102-RU-3	MOS					18-DEC-2007		
	120700349	HRS/MSC	O/C	N:0			11		
	REF: GENERIC NO REF	AFL		N:0			7		
233052	CONTROL HEAD CD CHANGE	ΞR							
	MCD-102-CH-1	MOS					16-DEC-2007		
	110700296	HRS/MSC	O/C				11		
	REF : GENERIC NO REF	AFL					7		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

FACK NO	TACK DECORRESON	LINUT	INTERVAL	TIME OWNER	40.	VA/A-D-D		port Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
33075	CABIN DISPLAY							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
233084	FORWARD 15.1 LCD COLOR	DISPLAY						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
233085	FORWARD VIDEO MONITOR							
	PN PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0	
	REF: GENERIC NO REF	AFL	5/0	N:0			0	
233086	AFT VIDEO MONITOR-							
	LCD-9151-201-1	MOS		R:0			31-AUG-2018	
	020800163	HRS/MSC	O/C	R:0			4067	
	REF: GENERIC NO REF	AFL		R:0			2472	
233087	FORWARD 10.4 LCD COLOR	DISPLAY						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
233088	AFT 15.1 LCD COLOR DISPLA	ΑΥ						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0	
	REF: GENERIC NO REF	AFL	5.0	N:0			0	
233101	STEREO ANTENNA							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN REF: AMM 23-31-01	HRS/MSC	O/C	N:0			0	
		AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-202 MAX LIMIT
233102	STEREO					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0 0	
	REF: AMM 23-31-02	AFL	N:0		U	
233103	STEREO BATTERY					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 23-31-03	AFL	N:0		0	
233104	STEREO VOLTAGE REGULA	TOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 23-31-04	AFL	N:0		0	
233105	AUDIO DISTRIBUTION MODU	JLE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 23-31-05	AFL	N:0		0	
233106	LEFT DIGITAL SELECTOR M	ODULE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 23-31-06	AFL	N:0		0	
233107	RIGHT DIGITAL SELECTOR I	MODULE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 23-31-06	AFL	N:0		0	
234101	INTERPHONE AUDIO AMPLII	FIER				
	MODEL204	MOS	N:0		09-DEC-2007	
	2895	HRS/MSC O/C	N:0		0	
	REF : AMM 23-41-01	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK DESCRIPTION PART/SERIAL PILOT AUDIO CONTROL PANE 802-009 2093 REF: AMM 23-50-01 COPILOT AUDIO CONTROL PANE 802-009 824 REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487 REF: AMM 23-50-02	MOS HRS/MSC AFL		N:0 N:0 N:0	ADJ	WARR EXP	09-DEC-2007 0 0 30-NOV-2010 2484.57 1162	MAX LIMIT
802-009 2093 REF: AMM 23-50-01 COPILOT AUDIO CONTROL PA 802-009 824 REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	MOS HRS/MSC AFL ANEL MOS HRS/MSC AFL		N:0			30-NOV-2010 2484.57	
2093 REF: AMM 23-50-01 COPILOT AUDIO CONTROL PA 802-009 824 REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	ANEL MOS HRS/MSC AFL		N:0			30-NOV-2010 2484.57	
REF: AMM 23-50-01 COPILOT AUDIO CONTROL PA 802-009 824 REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	AFL ANEL MOS HRS/MSC AFL					30-NOV-2010 2484.57	
COPILOT AUDIO CONTROL PA 802-009 824 REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	ANEL MOS HRS/MSC AFL	O/C	N:0			30-NOV-2010 2484.57	
802-009 824 REF : AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	MOS HRS/MSC AFL	O/C				2484.57	
824 REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	HRS/MSC AFL	O/C				2484.57	
REF: AMM 23-50-01 LEFT AUDIO AMPLIFIER 700-002 2487	AFL	O/C					
LEFT AUDIO AMPLIFIER 700-002 2487						1162	
700-002 2487	MOS						
700-002 2487	MOS						
2487			N:0			09-DEC-2007	
REF: AMM 23-50-02	HRS/MSC	O/C	N:0			0	
	AFL		N:0			0	
RIGHT AUDIO AMPLIFIER							
700-002	MOS		N:0			09-DEC-2007	
		O/C					
REF: AIVIIVI 25-50-02	AFL		N.U			U	
WEATHER WORX XM RADIO (CONTROLLER						
PN	MOS		N:0			09-DEC-2007	
SN-UNKNOWN		O/C	N:0			0	
REF: GENERIC NO REF	AFL		N:0			0	
WEATHER WORX XM DATA P	ORT						
PN	MOS		N:0			09-DEC-2007	
SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
REF: GENERIC NO REF	AFL		N:0			0	
COCKPIT VOICE (CVR) RECO	RDER						
			N:0			09-DEC-2007	
1957		O/C	N:0			0	
REF : AMM 23-70-01	AFL		N:0			0	
	700-002 2829 REF: AMM 23-50-02 WEATHER WORX XM RADIO OF PN SN-UNKNOWN REF: GENERIC NO REF WEATHER WORX XM DATA POR SN-UNKNOWN REF: GENERIC NO REF COCKPIT VOICE (CVR) RECO 1603-02-12 1957	700-002 MOS 2829 HRS/MSC REF: AMM 23-50-02 AFL WEATHER WORX XM RADIO CONTROLLER PN MOS SN-UNKNOWN HRS/MSC REF: GENERIC NO REF AFL WEATHER WORX XM DATA PORT PN MOS SN-UNKNOWN HRS/MSC REF: GENERIC NO REF AFL COCKPIT VOICE (CVR) RECORDER 1603-02-12 MOS 1957 HRS/MSC	700-002 MOS 2829 HRS/MSC O/C REF: AMM 23-50-02 AFL WEATHER WORX XM RADIO CONTROLLER PN MOS SN-UNKNOWN HRS/MSC O/C REF: GENERIC NO REF AFL WEATHER WORX XM DATA PORT PN MOS SN-UNKNOWN HRS/MSC O/C REF: GENERIC NO REF AFL COCKPIT VOICE (CVR) RECORDER 1603-02-12 MOS 1957 HRS/MSC O/C	700-002 MOS N:0 2829 HRS/MSC O/C N:0 REF: AMM 23-50-02 AFL N:0 WEATHER WORX XM RADIO CONTROLLER PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: GENERIC NO REF AFL N:0 WEATHER WORX XM DATA PORT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: GENERIC NO REF AFL N:0 COCKPIT VOICE (CVR) RECORDER 1603-02-12 MOS N:0 1957 HRS/MSC O/C N:0	700-002 MOS N:0 2829 HRS/MSC O/C N:0 REF: AMM 23-50-02 AFL N:0 WEATHER WORX XM RADIO CONTROLLER PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: GENERIC NO REF AFL N:0 WEATHER WORX XM DATA PORT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: GENERIC NO REF AFL N:0 COCKPIT VOICE (CVR) RECORDER 1603-02-12 MOS N:0 1957 HRS/MSC O/C N:0	700-002 MOS N:0 2829 HRS/MSC O/C N:0 REF: AMM 23-50-02 AFL N:0 WEATHER WORX XM RADIO CONTROLLER PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: GENERIC NO REF AFL N:0 WEATHER WORX XM DATA PORT PN MOS N:0 REF: GENERIC NO REF AFL N:0 COCKPIT VOICE (CVR) RECORDER 1603-02-12 MOS N:0 1957 HRS/MSC O/C N:0 100 N:0 110 N:	700-002 MOS N:0 09-DEC-2007 2829 HRS/MSC O/C N:0 0 REF: AMM 23-50-02 AFL N:0 0 WEATHER WORX XM RADIO CONTROLLER PN MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 REF: GENERIC NO REF AFL N:0 0 WEATHER WORX XM DATA PORT PN MOS N:0 09-DEC-2007 N:0 0 REF: GENERIC NO REF AFL N:0 0 COCKPIT VOICE (CVR) RECORDER 1603-02-12 MOS N:0 09-DEC-2007 1957 HRS/MSC O/C N:0 0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	HINUT	INTERVAL	TIME SINCE	ADL	WARD.	COMPLIANCE		port Date: 10-SEP-20
ASK NU	PART/SERIAL	UNIT	INTERVAL	TIME SINCE		WARR EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
237002	CVR REMOTE MICROPHONE	AMPLIFIER							
	1635-02	MOS		N:0			09-DEC-2007		
	194	HRS/MSC	O/C	N:0			0		
	REF : AMM 23-70-03	AFL		N:0			0		
37003	CVR REMOTE AREA MICROF	PHONE							
	16301-01	MOS		N:0			09-DEC-2007		
	2385	HRS/MSC	O/C	N:0			0		
	REF : AMM 23-70-04	AFL		N:0			0		
237004	CVR INERTIA SWITCH								
	3L0-453/8	MOS		N:0			09-DEC-2007		
	81656	HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0		
	REF: AMM 23-70-05	AFL	0/0	N:0			0		
							_		
237021	CVR UNDERWATER LOCATO	R (ULB) BEACC	N						
	DK120	MOS		N:0			09-DEC-2007		
	SC18759	HRS/MSC	O/C	N:0			0		
	REF : AMM 25-63-00	AFL		N:0			0		
237021A	CLEAN/FUNCTIONAL TEST C	VR UNDERWAT	ER LOCATOR (ULB)	BEACON SWITCH, BEACON	N AND BATTERY				
	DK120	MOS	24 +14d/-1	4d	-39		06-MAR-2020	26-JAN-2022	09-FEB-2022
	SC18759	HRS/MSC					4262.1		
	REF : AMM 25-63-00	AFL					2723		
237021B	REPLACE CVR UNDERWATE	R LOCATOR (UI	_B) BEACON BATTEI	RY - 05-11-00-F2566000					
	DK120	MOS					16-JUL-2017	30-APR-2023 M	
	SC18759	HRS/MSC	DUE				3849.9	50 N 2020 N	
	REF : AMM 25-63-00	AFL					2207		
237032	AUDIO/VIDEO AMPLIFIER								
	AV-4589-01-1	MOS					25-JUL-2016		
-07002		IVIOS							
107002		HRS/MSC	O/C				3709 5		
201002	110500491 REF : AMM 23-41-01	HRS/MSC AFL	O/C				3709.5 2046		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAI	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	port Date: 10-SEP-20 MAX LIMIT
238001	NO. 1 RADIO TUNING (RTU) U	JNIT			· · · · · · · · · · · · · · · · · · ·	
	822-0730-438	MOS	N:0		09-DEC-2007	
	2CNFF REF : AMM 23-80-01	HRS/MSC O/C AFL	N:0 N:0		0 0	
	REF. AIVIIVI 25-00-0 I	ALL	14.0		U	
238002	NO. 2 RADIO TUNING (RTU) l	JNIT				
	822-0730-438	MOS	0:2		13-JAN-2011	
	2CNFF	HRS/MSC O/C	O:0		2572.78	
	REF : AMM 23-80-01	AFL	O:0		1219	
239007	NO. 1 SWITCHING MODULE					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
239008	NO. 2 SWITCHING MODULE					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
239009	NO. 3 SWITCHING MODULE					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
239015	ORDINANCE SIGN SWITCH					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
239016	AUDIO AMPLIFIER					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 23-41-01	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 05-10-29-B2432010 INSPECT MAIN AIRCRAFT BATTERY INSTALLATION MOS 6 +14d/-14d -6 12-MAR-2021 06-SEP-2021 20-SEP-2021 HRS/MSC 4286.9 2754 **REF: GENERIC NO REF** AFL 05-10-29-H2431017 PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION MOS 06-MAR-2020 HRS/MSC 300 +25/-25 4262.1 4562.1 4587.1 **AFL** 2723 **REF:** AMM 24-31-01 GENERAL VISUAL INSPECTION OF THE CABIN INVERTER SYSTEM COMPONENTS (STC ST01422WI-D, IFCA 24-25-00-600-STC M100471ICT) MOS HRS/MSC 4800 0 4800 STC-SUPPLEMENTAL TYPE REF: AFL CERTIFICATE 242001 LEFT PRIMARY AC POWER INVERTER 19-NOV-2014 501-1666-01 MOS N:83 80105 HRS/MSC O/C N:3390 3390 1711 REF: AMM 24-20-01 AFL N:1711 242002 RIGHT SECONDARY AC POWER INVERTER 501-1666-01 MOS 0:0 19-NOV-2014 0:0 3390 1101 HRS/MSC O/C REF: AMM 24-20-01 **AFL** 0:0 1711 242003 POWER MONITOR INDICATOR PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 24-20-03 AFL N:0 0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTER	RVAL TIME SINCE	ADJ WARR C EXP	OMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-202 MAX LIMIT
242005	ISOLATION PARALLELING BO	OX				
	PN	MOS	N:0	09	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF: GENERIC NO REF	AFL	N:0	0		
242009	NO. 1 GROUND FAULT TRAN	ISFORMER				
	CTSG700	MOS	N:0	09	9-DEC-2007	
	4460	HRS/MSC O/C	N:0	0		
	REF: GENERIC NO REF	AFL	N:0	0		
242010	NO. 2 GROUND FAULT TRAN	ISFORMER				
	CTSG700	MOS	N:0	09	9-DEC-2007	
	4479	HRS/MSC O/C	N:0	0		
	REF: GENERIC NO REF	AFL	N:0	0		
242016	GENERATOR CONTROL PAN	IEL				
	PN	MOS	N:0	09	9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF : AMM 24-30-02	AFL	N:0	0		
242031	DC AMMETER SENSOR					
	PN	MOS	N:0		9-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0	0		
	REF : AMM 24-30-05	AFL	N:0	0		
242032	NO. 1 DC CURRENT SENSOF	₹				
	952-500-C	MOS	N:0		9-DEC-2007	
	3149	HRS/MSC O/C	N:0	0		
	REF : AMM 24-30-05	AFL	N:0	0		
242033	NO. 2 DC CURRENT SENSOF	₹				
	268-1	MOS	N:0		9-DEC-2007	
	206450150	HRS/MSC O/C	N:0	0		
	REF : AMM 24-30-05	AFL	N:0	0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP		IEXT DUE MA NG/APU) A/C LIM	XX IIT
242081	1200 VA, 115 VAC, 60 HZ INV	ERTER					
	SS120(C)	MOS	N:0		09-DEC-2007		
	122 REF : AMM 24-20-01	HRS/MSC O/C AFL	N:0 N:0		0 0		
	REF. AIVIIVI 24-20-01	AFL	N.U		U		
42505	GROUND FAULT INTERRUPT	ER					
	106072-1	MOS	N:0		09-DEC-2007		
	15100607	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
42507	60HZ POWER SYSTEM ANER	ROID SWITCH					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
243001	NO. 1 STARTER/GENERATO	₹					
	400SG138Q	MOS	O:0		06-MAR-2020		
	2606XL	HRS/MSC O/C	O:104.8		4262.1		
	REF: AMM 24-30-01	AFL	O:0		2723		
243001A	OVERHAUL NO. 1 STARTER/	GENERATOR - (Y2431025)					
	400SG138Q	MOS			06-MAR-2020		
OVERHALII	2606XL		/-25 I:104.8		4262.1	5157.3 5182.3	3
OVERHAUL	REF: GENERIC NO REF	AFL			2723		
243002	NO. 2 STARTER/GENERATO	र					
	400SG138Q-1	MOS	O:0		11-AUG-2015		
OVERHALII	2045XL	HRS/MSC 1000	O:0		3533.1	4533.1	
OVERHAUL	REF: AMM 24-30-01	AFL	O:0		1882		
243002A	OVERHAUL NO. 2 STARTER/	GENERATOR - (Y2431025)					
	400SG138Q-1	MOS			11-AUG-2015		
	2045XL	HRS/MSC 1000			3533.1	4533.1	
	REF: GENERIC NO REF	AFL			1882		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE		ort Date: 10-SEP-20 MAX LIMIT
243003	APU STARTER/GENERATOR							
	400SG159Q S00033 REF: See Workcard	MOS HRS/MSC AFL APH	O/C	O:0 O:0 O:0 O:0		07-OCT-2017 3901.9 2257 1958		
243003A	OVERHAUL/REPLACE APU S	TARTER/GENER	ATOR BRUSHES					
	400SG159Q S00033 REF : GENERIC NO REF	MOS HRS/MSC AFL APH	1000			07-OCT-2017 3901.9 2257 1958	2958	
243005	LEFT (GCU) GENERATOR CO	ONTROL UNIT						
	GCSG505-16B 1739B REF : AMM 24-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		09-DEC-2007 0 0		
243006	RIGHT (GCU) GENERATOR C	CONTROL UNIT						
	GCSG505-16B 1786B REF : AMM 24-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		09-DEC-2007 0 0		
243007	A11 GENERATOR CURRENT	TRANSFORMER						
	CTSG700 4976 REF : AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		09-DEC-2007 0 0		
243008	2A11 GENERATOR CURREN	T TRANSFORME	₹					
	CTSG700 4974 REF : AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		09-DEC-2007 0 0		
243009	A12 GENERATOR CURRENT	TRANSFORMER						
	CTSG700 4968 REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		09-DEC-2007 0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR COMPLIANCE NEXT DUE MAX PART/SERIAL (ENG/APU) A/C LIMIT 243010 2A12 GENERATOR CURRENT TRANSFORMER CTSG700 MOS N:0 09-DEC-2007 4971 HRS/MSC O/C N:0 0 REF: AMM 24-30-04 AFL N:0 0

43011	LEFT DC AMMETER CURR	RENT SENSOR			
	256-1	MOS	N:0	09-DEC-2007	
	207200240	HRS/MSC O/C	N:0	0	
	REF: AMM 24-30-05	AFL	N:0	0	
243012	RIGHT DC AMMETER CUR	RENT SENSOR			
	256-1	MOS	N:0	09-DEC-2007	
	207210004	HRS/MSC O/C	N:0	0	
	REF: AMM 24-30-05	AFL	N:0	0	
243049	UPPER / RIGHT / NO. 2 LE/	AD-ACID (CAPTIVE) BATTERY			
	RG380E/60L	MOS 48	N:0	06-MAR-2020	06-MAR-2024
	41080484	HRS/MSC	N:0	4262.1	
SERVICE LIFE LIMIT	REF : AMM 24-31-01	AFL	N:0	2723	
243049B	CAPACITY CHECK UPPER	/ RIGHT / NO. 2 LEAD-ACID (CAF	PTIVE) BATTERY 05-10-29-G1222002		
243049B	CAPACITY CHECK UPPER RG380E/60L	MOS 6	PTIVE) BATTERY 05-10-29-G1222002	12-MAR-2021	12-SEP-2021
243049B	RG380E/60L 41080484	MOS 6 HRS/MSC	PTIVE) BATTERY 05-10-29-G1222002	4286.9	12-SEP-2021
243049B	RG380E/60L	MOS 6	PTIVE) BATTERY 05-10-29-G1222002		12-SEP-2021
	RG380E/60L 41080484 REF : AMM 12-22-00	MOS 6 HRS/MSC	PTIVE) BATTERY 05-10-29-G1222002	4286.9	12-SEP-2021
	RG380E/60L 41080484 REF : AMM 12-22-00	MOS 6 HRS/MSC AFL	PTIVE) BATTERY 05-10-29-G1222002 N:0	4286.9	12-SEP-2021 06-MAR-2024
	RG380E/60L 41080484 REF: AMM 12-22-00 LOWER / LEFT / NO. 1 LEA	MOS 6 HRS/MSC AFL D-ACID (CAPTIVE) BATTERY		4286.9 2754	
243050	RG380E/60L 41080484 REF: AMM 12-22-00 LOWER / LEFT / NO. 1 LEA RG380E/60L	MOS 6 HRS/MSC AFL D-ACID (CAPTIVE) BATTERY MOS 48	N:0	4286.9 2754 06-MAR-2020	
243050 SERVICE LIFE LIMIT	RG380E/60L 41080484 REF: AMM 12-22-00 LOWER / LEFT / NO. 1 LEA RG380E/60L 41080483 REF: AMM 24-31-01	MOS 6 HRS/MSC AFL D-ACID (CAPTIVE) BATTERY MOS 48 HRS/MSC AFL	N:0 N:0	4286.9 2754 06-MAR-2020 4262.1	
243049B 243050 SERVICE LIFE LIMIT 243050B	RG380E/60L 41080484 REF: AMM 12-22-00 LOWER / LEFT / NO. 1 LEA RG380E/60L 41080483 REF: AMM 24-31-01	MOS 6 HRS/MSC AFL D-ACID (CAPTIVE) BATTERY MOS 48 HRS/MSC AFL	N:0 N:0 N:0	4286.9 2754 06-MAR-2020 4262.1	
243050 SERVICE LIFE LIMIT	RG380E/60L 41080484 REF: AMM 12-22-00 LOWER / LEFT / NO. 1 LEA RG380E/60L 41080483 REF: AMM 24-31-01	MOS 6 HRS/MSC AFL D-ACID (CAPTIVE) BATTERY MOS 48 HRS/MSC AFL R / LEFT / NO. 1 LEAD-ACID (CAPT	N:0 N:0 N:0	4286.9 2754 06-MAR-2020 4262.1 2723	06-MAR-2024



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO			•			· , ·	Report Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/O	MAX
243051	NO. 1 MAIN - SEALED RECUI	MBANT BATTERY						
N/A EQUIPMENT NOT INSTALLED	PN SN-UNKNOWN REF: AMM 24-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0	
243051A	SERVICE NO. 1 MAIN - SEAL	ED RECUMBANT E	BATTERY - 05-10-	.29-G1222001				
	PN	MOS					09-DEC-2007	
N/A EQUIPMENT NOT INSTALLED	SN-UNKNOWN REF: AMM 12-22-00	HRS/MSC AFL	N/A				0	
243052	NO. 2 MAIN - SEALED RECUI	MBANT BATTERY						
	PN	MOS		N:0			09-DEC-2007	
N/A EQUIPMENT NOT INSTALLED	SN-UNKNOWN REF: AMM 24-31-01	HRS/MSC AFL	O/C	N:0 N:0			0	
243052A	SERVICE NO. 2 MAIN - SEAL	ED RECUMBANT E	BATTERY 05-10-29	9-G1222001				
	PN	MOS					09-DEC-2007	
N/A EQUIPMENT NOT INSTALLED	SN-UNKNOWN REF: AMM 12-22-00	HRS/MSC AFL	N/A				0	
243055	EMERGENCY POWER (24VD	C TO 5VDC) CONV	/ERTER					
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0	
243062	NO. 1 EMERGENCY POWER	BATTERY						
	100-2410-06	MOS		O:0			12-MAR-2021	
	0706849	HRS/MSC	O/C	O:0			4286.9	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 243063 NO. 2 EMERGENCY POWER BATTERY 501-1712-02 MOS R:0 26-JAN-2016 80452 HRS/MSC O/C R:0 3583.3 1916 **REF:** AMM 24-32-01 AFL R:0 243063A PERFORM OPERATIONAL CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. F1223010 MOS 501-1712-02 6 +14d/-14d -7 12-MAR-2021 05-SEP-2021 19-SEP-2021 80452 HRS/MSC 4286.9 2754 **REF:** AMM 24-32-01 AFL 243063B PERFORM DISCHARGE CHECK OF PS-835 OR PS-855 NO. 2 LEAD-ACID EMERGENCY POWER SUPPLY BATTERY. D1223015 501-1712-02 +14d/-14d MOS 12 -7 12-MAR-2021 05-MAR-2022 19-MAR-2022 80452 HRS/MSC 4286.9 REF: See Workcard AFL 2754 243103 BATTERY TEMPERATURE INDICATOR PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 24-31-03 AFL N:0 0 243200 PERFORM NO. 1 EMERGENCY POWER BATTERY OPERATIONAL CHECK (XL2410) (IRN Y2431061) MOS 100-2410-06 12 +14d/-14d 12-MAR-2021 12-MAR-2022 26-MAR-2022 0706849 HRS/MSC 4286.9 AFL 2754 **REF:** AMM 24-32-01 PERFORM A FUNCTIONAL TEST OF THE EMERGENCY BUS SYSTEMS. (REF. STC ST01424WI-D, IFCA 243200A M100487ICT-SM-1) MOS 24 12-MAR-2021 12-MAR-2023 HRS/MSC 600 4886.9 4286.9 STC-SUPPLEMENTAL TYPE REF: AFL 2754 CERTIFICATE



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				operator: AERONAOT				Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243200B	PERFORM A GENERAL VISUA (SECRUAPLANE ISIS) MOUNT OTHER DEFECTS								
		MOS	48				12-MAR-2021	12-MAR-2025	
		HRS/MSC	1200				4286.9	5486.9	
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF:	AFL					2754		
243301	NO. 1 EMERGENCY EXIT LIG	HTING BATTER	Y PACK						
	M6088352-025	MOS					02-DEC-2010		
	A00971934-01 REF : GENERIC NO REF	HRS/MSC AFL	O/C				2493.13 1170		
	REF: GENERIC NO REF	AFL					1170		
243301A	CHARGE NO. 1 EMERGENCY	EXIT LIGHTING	BATTERY PACK	05-10-29-C1223030					
	M6088352-025	MOS	12 +14d	/-14d	-6		12-MAR-2021	06-MAR-2022	20-MAR-2022
	A00971934-01 REF : AMM 12-23-02	HRS/MSC AFL					4286.9 2754		
	NET : AWW 12-25-02	ALL					2104		
243302	NO. 2 EMERGENCY EXIT LIG	HTING BATTER	Y PACK						
	M6088352-025	MOS					02-DEC-2010		
	A00887701-01 REF : GENERIC NO REF	HRS/MSC AFL	O/C				2493.13 1170		
	REF. GENERIO NO REI	ALL					1170		
243302A	CHARGE NO. 2 EMERGENCY	EXIT LIGHTING	BATTERY PACK	05-10-29-C1223030					
	M6088352-025	MOS	12 +14d	/-14d	-6		12-MAR-2021	06-MAR-2022	20-MAR-2022
	A00887701-01 REF : AMM 12-23-02	HRS/MSC AFL					4286.9 2754		
	12-1. / AVIIVI 12-20-02	7 U. L.					2107		
244002	GROUND POWER MONITOR-								
	PN	MOS	0.10	N:0			09-DEC-2007		
	SN-UNKNOWN REF: AMM 24-40-02	HRS/MSC AFL	O/C	N:0 N:0			0 0		
	NET. AIVIIVI 24-4U-UZ	AFL		IN.U			U		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 245001 PILOT CIRCUIT BREAKER PANEL PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 24-50-01 0 AFL N:0 245002 COPILOT CIRCUIT BREAKER PANEL MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 24-50-01 **AFL** N:0 0 LEFT OVERLOAD (CBR2) SENSOR 245003 PΝ N:0 MOS 09-DEC-2007 HRS/MSC O/C N:0 SN-UNKNOWN 0 **REF:** AMM 24-50-03 AFL N:0 0 245004 RIGHT OVERLOAD (CBR2) SENSOR PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 24-50-03 AFL N:0 0 AA2432003 (s) PERFORM OPERATIONAL CHECK OF AC POWER SYSTEM PKG PKG 19 MOS 96 +14d/-14d 31-AUG-2018 HRS/MSC 2400 +25/-25 4067 **AFL** 2472 **REF:** AMM 24-20-00 CHAPTER 25 **EQUIPMENT/FURNISHINGS** 25-30-00-603 GENERAL VISUAL INSPECTION OF THE HOT LIQUID CONTAINER MOS HRS/MSC 4800 0 4800 SMM REF: AFL 250000 STEREO/PAGE AMPLIFIER PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 REF: GENERIC NO REF **AFL** N:0 0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

									ort Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
250001	GENERAL VISUAL INSPECTI WINDOW PANELS, BULKHE				INETS, HEADL	INER,			
		MOS					06-MAR-2020		
		HRS/MSC	300				4262.1	4562.1	
SMM	REF:	AFL					2723		
250002	INSPECT INTERIOR CABINE IN THE STOWED POSITION,	T DRAWER AND AND PROPER O	DOOR LATCHES FO	OR WEAR, CONDITION, SEC	URITY OF ATTA	ACHMENT			
		MOS	36				06-MAR-2020	06-MAR-2023	
		HRS/MSC					4262.1		
SMM	REF:	AFL					2723		
250003	INSPECT SIDELEDGE COMP STOWED POSITION, AND PR			EAR, CONDITION, SECURITY	OF ATTACHM	ENT IN THE			
		MOS					30-JUL-2019		
		HRS/MSC	400				4218.5	4618.5	
SMM	REF:	AFL					2672		
250004	INSPECT THE GALLEY, POT	TY, AND LAVATO	ORY FOR SPILLAGE	<u> </u>					
		MOS					22-FEB-2018		
		HRS/MSC	600				3974.8	4574.8	
БММ	REF:	AFL					2358		
250005	CHECK THE OPERATION, LA	ATCHING AND SE	EALING OF THE WA	STE CONTAINER COMPART	MENTS				
		MOS					22-FEB-2018		
		HRS/MSC	600				3974.8	4574.8	
SMM	REF:	AFL					2358		
250006	CHECK THE OPERATION OF	THE AFT PARTI	TION DOOR HOLD-	-OPEN LATCH					
		MOS					12-MAR-2021		
		HRS/MSC	300				4286.9	4586.9	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	TERVAL TIME SIN	CE ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	port Date: 10-SEP-202 MAX LIMIT
250009	CABIN HOT LIQUID CONTAIN	IER				ENGIAPU) AIC	EIIVIII
	AR9061-3 0307 REF :	MOS HRS/MSC O/O AFL	N:0 N:0 N:0			19-APR-2009 1310.35 564	
251001	PILOT CREW SEAT						
	6603000-001 49748 REF: AMM 25-10-01	MOS HRS/MSC O/O AFL				24-AUG-2010 2317.85 1066	
251002	COPILOT CREW SEAT						
	6603000-002 48323 REF : AMM 25-10-01	MOS HRS/MSC O/O AFL				24-AUG-2010 2317.85 1066	
251005	PILOT LIGHTED CHART HOL	DER					
	10-62-01 5354 REF : AMM 25-10-05	MOS HRS/MSC O/O AFL	N:0 N:0 N:0			09-DEC-2007 0 0	
251006	COPILOT LIGHTED CHART H	OLDER					
	10-62-01 5335 REF : AMM 25-10-05	MOS HRS/MSC O/O AFL	N:0 N:0 N:0			09-DEC-2007 0 0	
252001	LEFT FORWARD PASSENGE	R SEAT					
	6625206011-004A 50913 REF: AMM 25-20-05	MOS HRS/MSC O/O AFL				24-AUG-2010 2317.85 1066	
252002	RIGHT FORWARD PASSENG	ER SEAT					
	6625206011-003A 50911 REF: AMM 25-20-05	MOS HRS/MSC O/O AFL				24-AUG-2010 2317.85 1066	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				Operator: AERONAUTI			Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
252003	LEFT MID PASSENGER SEAT							
	6625206011-001A 50914 REF : AMM 25-20-05	MOS HRS/MSC AFL	O/C				24-AUG-2010 2317.85 1066	
252004	RIGHT MID PASSENGER SEAT							
	6625206011-002A 50915 REF : AMM 25-20-05	MOS HRS/MSC AFL	O/C				24-AUG-2010 2317.85 1066	
252005	LEFT AFT PASSENGER SEAT							
	3A394-0010-102-1 50914 REF : AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0	
252006	RIGHT AFT PASSENGER SEAT							
	6625206011-003A 50912 REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C				24-AUG-2010 2317.85 1066	
252007	RIGHT PASSENGER DIVAN							
	PN SN-UNKNOWN REF : AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0	
252025	RIGHT LOWER DIFFUSER							
	PN SN-UNKNOWN REF: AMM 25-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0	
252027	LEFT LOWER DIFFUSER							
	PN SN-UNKNOWN REF : AMM 25-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO							port Date: 10-SEP-20
	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WA EXI		E NEXT DUE (ENG/APU) A/C	MAX LIMIT
52100	GENERAL VISUAL INSPECTION	ON OF THE PASSENGER SEAT I	RESTRAINTS				
		MOS			06-MAR-2020		
		HRS/MSC 300			4262.1	4562.1	
SMM	REF:	AFL			2723		
253000	GENERAL VISUAL INSPECTION	ON OF THE GALLEY					
		MOS			22-FEB-2018		
		HRS/MSC 600			3974.8	4574.8	
SMM	REF:	AFL			2358		
253001	GENERAL VISUAL INSPECTION	ON OF THE WARMING OVEN					
		MOS			09-DEC-2007		
		HRS/MSC 4800			0	4800	
SMM	REF:	AFL					
253007	LEFT FORWARD COLD CATH	IODE LAMP INVERTER					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
253009	LEFT FORWARD COLD CATH	IODE LAMP INVERTER					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
253010	RIGHT FORWARD COLD CAT	HODE LAMP INVERTER					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
253012	RIGHT FORWARD COLD CAT	HODE LAMP INVERTER					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		09-52007		
	REF: GENERIC NO REF	AFL	N:0		0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				Operator: AERONAUTI			Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
253021	NO. 1 TOUCH-SCREEN CONT	TROLLER						
	PCI-102-01-1	MOS					23-JUN-2013	
CUSTOMER CODE	031100391 REF :	HRS/MSC AFL	O/C				3222.6 1610	
COSTOMER CODE	REF:	AFL					1610	
253022	NO. 2 TOUCH-SCREEN CON	TROLLER						
	PCI-102-01-1	MOS		R:0			25-OCT-2013	
	010800489	HRS/MSC	O/C	R:0			3308.7	
CUSTOMER CODE	REF:	AFL		R:0			1660	
253023	NO. 3 TOUCH-SCREEN CON	TROLLER						
	CPC-202-02-1	MOS					12-DEC-2011	
	020701083	HRS/MSC	O/C				3011.9	
CUSTOMER CODE	REF:	AFL					1487	
253024	NO. 4 TOUCH-SCREEN CON	TROLLER						
	CPC-202-02-1	MOS					01-JUN-2011	
	020800898	HRS/MSC	O/C				2785.83	
CUSTOMER CODE	REF:	AFL					1342	
253052	VOLTAGE REGULATOR							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
253068	WARMER-LIQUID							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
253069	WARMER-LIQUID							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 253090 AM/FM/CASSETTE STEREO PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 REF: GENERIC NO REF 0 **AFL** N:0 GENERAL VISUAL INSPECTION OF THE LAVATORY 254000 MOS 22-FEB-2018 HRS/MSC 600 3974.8 4574.8 SMM REF: **AFL** 2358 255050 MICROWAVE OVEN MOS 4001338-02-L 11-DEC-2009 HRS/MSC O/C N:0 08-10-44722 1860.48 REF: GENERIC NO REF AFL N:0 835 255050B CHECK MICROWAVE OVEN MICROWAVE OVEN AND BAROMETRIC SWITCH 4001338-02-L MOS 31-AUG-2018 HRS/MSC 600 4067 4667 08-10-44722 SMM REF: AFL 2472 255050C GENERAL VISUAL INSPECTION MICROWAVE OVEN 4001338-02-L MOS 1:0 11-DEC-2009 08-10-44722 HRS/MSC 4800 1860.48 6660.48 SMM REF: AFL 1:0 835 255050D INSPECT MICROWAVE OVEN MICROWAVE OVEN DOOR GASKET 4001338-02-L MOS 26-JAN-2018 08-10-44722 HRS/MSC N/A SMM REF: **AFL**

255050E INSPECT MICROWAVE OVEN MICROWAVE OVER WAVEGUIDE MOISTURE COVER

4001338-02-L MOS 12 08-10-44722 HRS/MSC **REF**: AFL 12-MAR-2021 4286.9 2754 12-MAR-2022

SMM



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	ME SINCE ADJ WARI EXP	Report Date: 10-SEP-202 R COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT
		(LNG/AFO) AC LIIVIII
MITTER		
S S/MSC O/C		15-OCT-2015 3577.8
		1913
MERGENCY LOCATOR TRANSMITTE	ER .	
S 12 +14d/-14d		12-MAR-2021 12-MAR-2022 26-MAR-2022
B/MSC -		4286.9 2754
00		
S NAMES BLIE		25-JUL-2016 01-SEP-2021 M
S/MSC DUE		3709.5 2046
RGENCY LOCATOR TRANSMITTER		
S R/MSC N/A		15-OCT-2015 3577.8
-		1913
		09-DEC-2007
		0
		09-DEC-2007
		0 0
		24-AUG-2010
		2317.85 1066
1 9 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	JERGENCY LOCATOR TRANSMITTE S 12 +14d/-14d B/MSC DO S B/MSC DUE RGENCY LOCATOR TRANSMITTER S B/MSC N/A S B/MSC O/C N:0 S B/MSC O/C N:0 N:0 S B/MSC O/C	BERGENCY LOCATOR TRANSMITTER S 12 +14d/-14d SMSC D00 S SMSC DUE RGENCY LOCATOR TRANSMITTER S SMSC N/A N:0 N:0 N:0 N:0 N:0 N:0 N:0 N:0 N:0 N:



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				perator: AERONAUTI			·	Rej	oort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56061A	INSPECT NO. 1 LIFE VEST P	ER MANUFACTUF	RER'S INSTRUCTION	NS					
	D21343-153 L976830 REF: See Workcard	MOS HRS/MSC AFL	60	l:2			16-JUL-2017 3849.9 2207	16-MAY-2022	
256062	NO. 2 LIFE VEST								
	D21343-153 L976847 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-AUG-2010 2317.85 1066		
256062A	INSPECT NO. 2 LIFE VEST PI	ER MANUFACTUF	RER'S INSTRUCTIO	NS					
	D21343-153 L976847 REF: See Workcard	MOS HRS/MSC AFL	60	l:2			16-JUL-2017 3849.9 2207	16-MAY-2022	
256063	NO. 3 LIFE VEST								
	D21343-153 L976833 REF : GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-AUG-2010 2317.85 1066		
256063A	INSPECT NO. 3 LIFE VEST P	ER MANUFACTUF	RER'S INSTRUCTIO	NS					
	D21343-153 L976833 REF: See Workcard	MOS HRS/MSC AFL	60	1:2			16-JUL-2017 3849.9 2207	16-MAY-2022	
256064	NO. 4 LIFE VEST								
	D21343-153 L976834 REF : GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:32 N:2317.85 N:1066			24-AUG-2010 2317.85 1066		
256064A	INSPECT NO. 4 LIFE VEST PI	ER MANUFACTUF	RER'S INSTRUCTION	NS					
	D21343-153 L976834 REF : See Workcard	MOS HRS/MSC AFL	60	l:2			16-JUL-2017 3849.9 2207	16-MAY-2022	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 256065 NO. 5 LIFE VEST D21343-153 MOS 24-AUG-2010 L976831 HRS/MSC O/C 2317.87 REF: GENERIC NO REF 1066 AFL 256065A INSPECT NO. 5 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 1:2 D21343-153 MOS 60 16-JUL-2017 16-MAY-2022 L976831 HRS/MSC 3849.9 REF: See Workcard **AFL** 2207 256066 NO. 6 LIFE VEST MOS 24-AUG-2010 D21343-153 HRS/MSC O/C L976832 2317.85 REF: GENERIC NO REF AFL 1066 256066A INSPECT NO. 6 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS D21343-153 MOS 60 1:2 16-JUL-2017 16-MAY-2022 L976832 HRS/MSC 3849.9 **REF:** See Workcard AFL 2207 256067 NO. 7 LIFE VEST PΝ MOS N:133 24-JAN-2019 SN-UNKNOWN HRS/MSC O/C N:4067 4067 N:2472 2472 **REF: GENERIC NO REF AFL** INSPECT NO. 7 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS 256067A PΝ 60 MOS 24-JAN-2019 31-JAN-2022 M SN-UNKNOWN HRS/MSC 4067 REF: See Workcard AFL 2472

256068	NO. 8 LIFE VEST			
	D21343-153	MOS	N:32	24-AUG-2010
	L976846	HRS/MSC O/C	N:2317.85	2317.85
	REF : GENERIC NO REF	AFL	N:1066	1066



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 256068A INSPECT NO. 8 LIFE VEST PER MANUFACTURER'S INSTRUCTIONS D21343-153 MOS 60 1:2 16-JUL-2017 16-MAY-2022 L976846 HRS/MSC 3849.9 2207 **REF:** See Workcard AFL 256071 PILOT LIFE VEST D21343-153 MOS N:32 24-AUG-2010 L976826 HRS/MSC O/C N:2317.85 2317.85 REF: GENERIC NO REF N:1066 1066 **AFL** 256071A INSPECT PILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS D21343-153 MOS 60 1:2 16-JUL-2017 16-MAY-2022 L976826 HRS/MSC 3849.9 REF: See Workcard AFL 2207 256072 COPILOT LIFE VEST D21343-153 MOS N:32 24-AUG-2010 L976829 HRS/MSC O/C N:2317.85 2317.85 **REF: GENERIC NO REF** AFL N:1066 1066 256072A INSPECT COPILOT LIFE VEST PER MANUFACTURER'S INSTRUCTIONS D21343-153 MOS 60 1:2 16-JUL-2017 16-MAY-2022 L976829 HRS/MSC 3849.9 **AFL** 2207 **REF:** AMM 25-61-00 256076 FIRST AID KIT FL220-FAK-FAA MOS 12-MAR-2021 30-SEP-2021 M 1115-0355 HRS/MSC DUE 4286.9 REF: GENERIC NO REF **AFL** 2754 Expiry Date: 30-SEP-2021 256076A CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES FL220-FAK-FAA MOS 12 12-MAR-2021 12-MAR-2022 1115-0355 HRS/MSC 4286.9 REF: GENERIC NO REF AFL 2754



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				perator: AERONAUTI				Rej	oort Date: 10-SEP-20	
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
56116	ELT REMOTE SWITCH PANEI	L								
	SP-60XR-006 030800580 REF : GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-SEP-2008 857.75 361			
256117	GALLEY SWITCH PANEL									
	SP-60XR-007 060900309 REF :	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-JAN-2016 3583.3 1916			
256202	ELT ANTENNA									
	110-337	MOS		N:0			09-DEC-2007			
	146696	HRS/MSC	O/C	N:0			0			
	REF: AMM 25-62-02	AFL		N:0			0			
256410	(ELT) EMERGENCY LOCATO	R TRANSMITTER	RBATTERY							
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0			
257101	NOSE AVIONICS EXHAUST BLOWER									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN REF: AMM 25-71-01	HRS/MSC AFL	O/C	N:0 N:0			0			
258010	AIRSHOW DIGITAL INTERFAC	CE UNIT								
	925000-100	MOS		N:0			09-DEC-2007			
	D01001508	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
258011	COCKPIT CONTROL - AIRSHO	OW UNIT								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
258012	AIRSHOW FLIGHT DECK COM	NTROLLER								
	922000-2	MOS		N:0			09-DEC-2007			
	H01001072	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

				operator: ALKONAOTI				Rep	ort Date: 10-SEP-2	
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT	
258014	FORWARD AIRSHOW COLO	R MONITOR-								
	LCD-8151-201-1 120600196 REF : GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-MAR-2010 1997.87 916			
258015	AFT AIRSHOW COLOR MON	ITOR-								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN REF : GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0			
258016	FORWARD 10.4 LCD COLOR	, AIRSHOW 400	DISPLAY							
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0			
258020	AIRSHOW 400 VIDEO SWITC	H PANEL								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
HAPTER 26	FIRE PROTECTION									
261001	NO. 1 FIRE DETECTION CON	ITROL UNIT								
	377-02833	MOS		N:0			09-DEC-2007			
	0709-240	HRS/MSC	O/C	N:0			0			
	REF : AMM 26-11-02	AFL		N:0			0			
261002	NO. 2 FIRE DETECTION CON	ITROL UNIT								
	377-02833	MOS		N:0			09-DEC-2007			
	0709-247	HRS/MSC	O/C	N:0			0			
	REF : AMM 26-11-02	AFL		N:0			0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

ASK NO	TASK DESCRIPTION	UNIT IN	TERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		port Date: 10-SEP-20	
ASK NO-	PART/SERIAL	— UNIT IN	TERVAL	TIME SINCE	— ADJ	EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT	
261006	TAILCONE BLEED AIR OVER	HEAT (E267) CONTR	OL BOX							
	35009-20	MOS					19-APR-2018			
	D3608	HRS/MSC O/0	0				3981.3			
	REF: AMM 26-13-02	AFL					2361			
261007	TAILCONE BLEED AIR OVER	HEAT (E268) CONTR	OL BOX							
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC O/0	3	N:0			0			
	REF : AMM 26-13-02	AFL		N:0			0			
261051	NO. 1 TEE DOUBLE CHECK V	/ALVE								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC O/O	0	N:0			09-DEC-2007			
	REF: AMM 26-21-05	AFL		N:0			0			
261052	NO. 2 TEE DOUBLE CHECK V	/ALVE								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC O/	3	N:0			09-DEC-2007 0			
	REF : AMM 26-21-05	AFL		N:0			0			
261207	BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC O/0	0	N:0			0			
	REF : AMM 26-12-01	AFL		N:0			0			
262013	FORWARD FIRE EXTINGUISH	HER BOTTLE								
	32700004-1	MOS		N:72			12-FEB-2014			
	27428C1	HRS/MSC O/0	0							
	REF : AMM 26-21-03	AFL					1670			
262013A	CHECK FORWARD FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY (REF TO 05-10-00)									
	32700004-1	MOS 6	+14d/-14	d	-6		12-MAR-2021	06-SEP-2021	20-SEP-2021	
	27428C1	HRS/MSC	1 170/-14	~	-0		4286.9	00-0LI -202 I	20 OL: 2021	
	REF : AMM 26-21-00	AFL					2754			
262013C	HYDROSTATIC TEST FORWA	ARD FIRE EXTINGUIS	SHER BOTTLE							
	32700004-1	MOS 60		d			01-AUG-2018	01-AUG-2023	15-AUG-2023	
	32700004-1 27428C1	HRS/MSC	+ 14u/-14	u			01-A0G-2010	U1-AUG-2023	10-AUG-2023	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 WARR TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX INTERVAL PART/SERIAL **EXP** (ENG/APU) A/C LIMIT AFT FIRE EXTINGUISHER BOTTLE 262014 MOS N:73 03-JAN-2014 32700004-1 25879C1 HRS/MSC O/C **REF:** AMM 26-21-03 **AFL** 262014A CHECK AFT FIRE EXTINGUISHER BOTTLE PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY, (REF TO 05-10-00) -6 32700004-1 MOS 6 +14d/-14d 12-MAR-2021 06-SEP-2021 20-SEP-2021 HRS/MSC 25879C1 4286.9 2754 **REF:** AMM 26-21-00 AFL 262014C HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE 32700004-1 MOS 60 +14d/-14d 01-MAY-2017 01-MAY-2022 15-MAY-2022 HRS/MSC 25879C1 REF: GENERIC NO REF **AFL** 262036 FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 MOS 72 N:0 22-FEB-2018 +14d/-14d 22-FEB-2024 07-MAR-2024 09035 HRS/MSC N:0 3974.8 N:0 SERVICE LIFE LIMIT **REF:** AMM 26-21-04 **AFL** 2358 262036A REPLACE FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 MOS 108 +14d/-14d 01-FEB-2018 01-FEB-2027 15-FEB-2027 HRS/MSC 09035 LIFE LIMIT AFL **REF:** AMM 26-21-04 AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB 262037 M30903823 MOS 72 +14d/-14d N:0 12-MAR-2021 12-MAR-2027 26-MAR-2027 HRS/MSC 10099 N:0 4286.9 2754 SERVICE LIFE LIMIT **REF:** AMM 26-21-04 AFL N:0 262037A REPLACE AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB M30903823 MOS 108 +14d/-14d 01-NOV-2019 01-NOV-2028 15-NOV-2028 10099 HRS/MSC LIFE LIMIT AFL **REF:** AMM 26-21-04 262038 FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB M30903823 MOS 72 +14d/-14d N:0 22-FEB-2018 22-FEB-2024 07-MAR-2024 HRS/MSC 09022 N:0 3974.8 SERVICE LIFE LIMIT **REF:** AMM 26-21-04 AFL N:0 2358



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT	INTER	VAL	TIME SINCE	ADJ	WARR	COMPLIANCE		eport Date: 10-SEP-20 MAX
ASK NO	PART/SERIAL	— UNII	TINTER	VAL	TIME SINCE	— ADJ	EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
62038A	REPLACE FORWARD ENGIN	E FIRE EXTINGL	JISHER AF	T SQUIB						
	M30903823	MOS	108	+14d/-14d				01-FEB-2018	01-FEB-2027	15-FEB-2027
IEE IMIT	09022	HRS/MSC								
IFE LIMIT	REF : AMM 26-21-04	AFL								
62039	AFT ENGINE FIRE EXTINGUI	SHER AFT SQUI	В							
	M30903823	MOS	72	+14d/-14d	N:0			12-MAR-2021	12-MAR-2027	26-MAR-2027
	10117	HRS/MSC			N:0			4286.9		
SERVICE LIFE LIMIT	REF : AMM 26-21-04	AFL			N:0			2754		
262039A	REPLACE AFT ENGINE FIRE	EXTINGUISHER	AFT SQU	IIB						
	M30903823	MOS	108	+14d/-14d				01-NOV-2019	01-NOV-2028	15-NOV-2028
	10117	HRS/MSC								
LIFE LIMIT	REF : AMM 26-21-04	AFL								
262041	PILOT PORTABLE FIRE EXTI	NGUISHER								
	A344	MOS			N:95			06-MAR-2020		
	Y-197694	HRS/MSC	O/C					4262.1		
	REF: GENERIC NO REF	AFL						2723		
262041B	HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030									
	A344	MOS	144	+14d/-14d		-98		06-MAR-2020	06-JAN-2024	20-JAN-2024
	Y-197694	HRS/MSC								
	REF: GENERIC NO REF	AFL								
262041C	RESTORATION PILOT PORTABLE FIRE EXTINGUISHER									
	A344	MOS	72					06-MAR-2020	06-MAR-2026	
	Y-197694	HRS/MSC						4262.1		
	REF:	AFL						2723		
62042	COPILOT PORTABLE FIRE E	XTINGUISHER								
	A344	MOS			N:95			06-MAR-2020		
	Y-197688	HRS/MSC	O/C					4262.1		
	REF: GENERIC NO REF	AFL						2723		
62042B	HYDROSTATIC TEST COPILO	OT PORTABLE F	IRE EXTIN	IGUISHER 05-	10-29-R2620030					
	A344	MOS	144	+14d/-14d		-98		06-MAR-2020	06-JAN-2024	20-JAN-2024
	Y-197688	HRS/MSC								
	REF: GENERIC NO REF	AFL								



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INT	ERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		eport Date: 10-SEP-2 MAX LIMIT
62042C	RESTORATION COPILOT PO	RTABLE FIRE EXTING	UISHER						
	A344 Y-197688 REF :	MOS 72 HRS/MSC AFL					06-MAR-2020 4262.1 2723	06-MAR-2026	
262045	NO. 1 ENGINE FIRE - PULL S	WITCH							
	865201-3 761 REF: AMM 26-21-01	MOS HRS/MSC O/C AFL		N:0 N:0 N:0			09-DEC-2007 0 0		
262046	NO. 2 ENGINE FIRE - PULL S	WITCH							
	865201-3 742 REF: AMM 26-21-01	MOS HRS/MSC O/C AFL		N:0 N:0 N:0			09-DEC-2007 0 0		
262050	APU FIRE EXTINGUISHER								
	50-1200 09-1017 REF: See Workcard	MOS HRS/MSC O/C AFL		N:52 N:1018.1 N:642			26-FEB-2015 3430.9 1765		
262050C	INSPECT APU FIRE EXTINGL	JISHER WEIGHT CHEC	CK AND REPLA	CE AS NECESSARY					
	50-1200 09-1017 REF: See Workcard	MOS 12 HRS/MSC AFL					12-MAR-2021	12-MAR-2022	
262050D	CONTINUITY CHECK APU FIF	RE EXTINGUISHER PF	RESSURE SWIT	CH IAW SAFECRAFT CMM	26-20-02				
	50-1200 09-1017 REF: See Workcard	MOS 12 HRS/MSC AFL					12-MAR-2021 4286.9 2754	12-MAR-2022	
262051	CABIN PORTABLE FIRE EXTI	NGUISHER							
	C352TS Y-96260 REF: GENERIC NO REF	MOS HRS/MSC O/C AFL					06-MAR-2020 4262.1 2723		
262051B	HYDROSTATIC TEST CABIN	PORTABLE FIRE EXTI	NGUISHER 05-	10-29-R2620030					
	C352TS Y-96260 REF : GENERIC NO REF	MOS 144 HRS/MSC AFL	+14d/-14	4d	-110		06-MAR-2020	06-JAN-2023	20-JAN-2023



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		MAX
	PART/SERIAL					EXP		(ENG/APU) A/C	LIMIT
262051C	RESTORATION CABIN PORT	ABLE FIRE EXT	INGUISHER						
	C352TS	MOS	72				06-MAR-2020	06-MAR-2026	
	Y-96260	HRS/MSC					4262.1		
	REF:	AFL					2723		
262057	APU FIRE BOTTLE SQUIB								
	M3090000M	MOS	60	N:15			30-JUL-2019	30-APR-2023	
	08803	HRS/MSC		N:0					
LIFE LIMIT	REF: See Workcard	AFL		N:0					
T2620045 (s)	MANUFACTURE. CHECK OP	LE HAND HELD ERATING PRES	FIRE EXTINGUIS SURE AND WEIG	HER (IF EQUIPPED) FOR COND HT PER MAINTENANCE INSTR	OITION AND DA JCTIONS ON F	TE OF IRE	PKG		
	EXTINGUISHER BOTTLE	MOS	10 .4	14/144			42 MAD 2024		
	PKG 1	MOS HRS/MSC		4d/-14d 5/-25			12-MAR-2021 4286.9		
	REF: GENERIC NO REF	AFL	120	5, 20			2754		
U2610020A (s)	INSPECT NO. 1 ENGINE TAIL	CONE FIRE DE	TECTION ELEME	NT			PKG		
(-/	PKG 29	MOS					12-DEC-2011		
	11025	HRS/MSC	3600 +50)			3011.9		
	REF: GENERIC NO REF	AFL					1487		
U2610020B (s)	INSPECT NO. 2 ENGINE TAIL	CONE FIRE DE	TECTION ELEME	:NT			PKG		
	PKG 30	MOS					12-DEC-2011		
		HRS/MSC	3600 +50)			3011.9		
	REF: GENERIC NO REF	AFL					1487		
IAPTER 27	FLIGHT CONTROLS								
05-10-29-H2750044L	PERFORM DETAILED INSPE	CTION OF THE I	EFT FLAP CAM	FOLLOWER BEARING					
		MOS					26-FEB-2015		
		HRS/MSC	1200 +25	5/-25			3430.9	4630.9	4655.9
	REF: AMM 5-10-00	AFL					1765		
05-10-29-H2750044R	PERFORM DETAILED INSPE	CTION OF THE F	RIGHT FLAP CAN	/I FOLLOWER BEARING					
		MOS					26-FEB-2015		
		HRS/MSC	1200 +25	5/-25			3430.9	4630.9	4655.9
	REF : AMM 5-10-00	AFL					1765		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS	PLATINUM C.A. C	Operator: AERONAUT	C SOLUTIO	NS JOANR	IGER, S.A DE C	.V. Ror	ort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
05-11-00-E2710010L	REPLACE LEFT * AILERON D	RIVE YOKE BO	OLT (NAS1104-38D) (A	·WL*)					
		MOS					26-JAN-2016		
LIFE LIMIT	REF : AMM 27-10-02	HRS/MS(AFL	C 3600				3583.3 1916	7183.3	
LIFE LIMIT	REF. AIVIIVI 27-10-02	AFL					1910		
05-11-00-E2710010R	REPLACE RIGHT * AILERON	DRIVE YOKE E	BOLT (NAS1104-38D) ((AWL*)					
		MOS					26-JAN-2016		
LICCLIMIT	DEE: AMM 07 40 00	HRS/MS	C 3600				3583.3	7183.3	
LIFE LIMIT	REF: AMM 27-10-02	AFL					1916		
05-11-00-E2710013L	* REPLACE LEFT AILERON C	ENTER HINGE	BOLT (AN4H13A) (AV	VL*)					
		MOS					26-JAN-2016		
		HRS/MS	C 3600				3583.3	7183.3	
LIFE LIMIT	REF: AMM 27-10-02	AFL					1916		
05-11-00-E2710013R	* REPLACE RIGHT AILERON	CENTER HING	E BOLT (AN4H13A) (A	AWL*)					
		MOS					26-JAN-2016		
		HRS/MS	C 3600				3583.3	7183.3	
LIFE LIMIT	REF: AMM 27-10-02	AFL					1916		
05-11-00-E2710020L	REPLACE LEFT * AILERON C	CLEVIS BOLT (N	NAS464P4) (AWL*)						
		MOS	, , ,				09-DEC-2007		
			C 20000				0	20000	
LIFE LIMIT	REF : AMM 27-10-02	AFL					0		
05-11-00-E2710020R	REPLACE RIGHT * AILERON	CLEVIS BOLT	(NAS464P4) (AWL*)						
		MOS	(/ (/				09-DEC-2007		
			C 20000				0	20000	
LIFE LIMIT	REF : AMM 27-10-02	AFL					0		
05-11-00-E2710022L	* REPLACE LEFT AILERON S	SECTOR (54251	05) (AWL*)						
		MOS	, , ,				09-DEC-2007		
			C 20000				09-02007	20000	
LIFE LIMIT	REF: AMM 27-10-10	AFL					0		
05-11-00-E2710022R	* REPLACE RIGHT AILERON	SECTOR (5425	5105) (AWL*)						
		MOS	, , ,				09-DEC-2007		
			C 20000				09-02007	20000	
	REF: AMM 27-10-10	AFL					0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PL	ATINUM C.A.	Operator: AERONAUT	IC SOLUTIONS JUANI	RIGER, S.A DE C.V	r. Rer	ort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE		MAX LIMIT
05-11-00-E2710024L	* REPLACE LEFT AILERON C	CLEVIS (2324517)	(AWL*)					
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF: AMM 27-10-02	AFL				0		
05-11-00-E2710024R	* REPLACE RIGHT AILERON	CLEVIS (2324517)	(AWL*)					
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF: AMM 27-10-02	AFL				0		
05-11-00-E2710026L	REPLACE LEFT * AILERON Y	OKE ASSEMBLY ((2324511) (AWL*)					
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF: AMM 27-10-02	AFL				0		
05-11-00-E2710026R	REPLACE RIGHT * AILERON	YOKE ASSEMBLY	′ (2324511) (AWL*	·)				
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF: AMM 27-10-02	AFL				0		
05-11-00-E2710028L	REPLACE LEFT * AILERON B	EARING SUPPOR	T ASSEMBLY (542	25016) (AWL*)				
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF : AMM 27-10-02	AFL				0		
05-11-00-E2710028R	REPLACE RIGHT * AILERON	BEARING SUPPO	RT ASSEMBLY (54	425016) (AWL*)				
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF : AMM 27-10-02	AFL				0		
05-11-00-E2710031L	REPLACE LEFT * AILERON H	IINGE BRACKET A	SSEMBLY (23225	30) (AWL*)				
		MOS				09-DEC-2007		
		HRS/MSC	20000			0	20000	
LIFE LIMIT	REF: GENERIC NO REF	AFL				0		
05-11-00-E2710031R	REPLACE RIGHT * AILERON	HINGE BRACKET	ASSEMBLY (2322	530) (AWL*)				
		MOS	•			09-DEC-2007		
		HRS/MSC	20000			0	20000	
	REF: GENERIC NO REF	AFL						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

			operator: AERONAUTI		.13 JOANN		Rep	oort Date: 10-SEP-2021
TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
REPLACE * RUDDER HINGE	BOLTS (NAS6205	& NAS464P5) (AW	/L*)					
REF : AMM 27-20-01	MOS HRS/MSC AFL	20000				09-DEC-2007 0 0	20000	
REPLACE * RUDDER SECTO	R BEARING ASSE	EMBLY (5435052) (AWL*)					
REF: AMM 27-20-09	MOS HRS/MSC AFL	20000				12-DEC-2011 3011.9 1487	23011.9	
REPLACE * RUDDER HINGE	BRACKETS (5431	005 & 5431056) (A ¹	WL*)					
REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				09-DEC-2007 0 0	20000	
REPLACE LEFT * ELEVATOR	BELLCRANKS (2:	331511) (AWL*)						
REF : AMM 27-30-01	MOS HRS/MSC AFL	20000				09-DEC-2007 0 0	20000	
REPLACE RIGHT * ELEVATO	R BELLCRANKS ((2331511) (AWL*)						
	MOS					09-DEC-2007		
REF: AMM 27-30-01	HRS/MSC AFL	20000				0	20000	
REPLACE LEFT * ELEVATOR	UPPER PUSH-PL	JLL TUBES (543501	13) (AWL*)					
	MOS					09-DEC-2007		
REF: AMM 27-30-01	HRS/MSC AFL	20000				0 0	20000	
REPLACE RIGHT * ELEVATO	R UPPER PUSH-F	PULL TUBES (54350	013) (AWL*)					
	MOS					09-DEC-2007		
REF : AMM 27-30-01	HRS/MSC AFL	20000				0 0	20000	
REPLACE LEFT * ELEVATOR	HINGE BOLTS (A	N4H11A) (AWL*)						
	MOS					09-DEC-2007		
REF: GENERIC NO REF	HRS/MSC AFL	20000				0 0	20000	
	PART/SERIAL REPLACE * RUDDER HINGE REF: AMM 27-20-01 REPLACE * RUDDER SECTO REF: AMM 27-20-09 REPLACE * RUDDER HINGE REF: GENERIC NO REF REPLACE LEFT * ELEVATOR REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR	REPLACE * RUDDER HINGE BOLTS (NAS6205 MOS HRS/MSC REF: AMM 27-20-01 REPLACE * RUDDER SECTOR BEARING ASSE MOS HRS/MSC REF: AMM 27-20-09 REPLACE * RUDDER HINGE BRACKETS (5431) MOS HRS/MSC REF: GENERIC NO REF REPLACE LEFT * ELEVATOR BELLCRANKS (2: MOS HRS/MSC REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR BELLCRANKS (: MOS HRS/MSC REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PU MOS HRS/MSC REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PU MOS HRS/MSC REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PU MOS HRS/MSC REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PU MOS HRS/MSC REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PU MOS HRS/MSC REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PU MOS HRS/MSC REF: AMM 27-30-01	### PART/SERIAL REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AW MOS HRS/MSC 20000) REF: AMM 27-20-01 AFL REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AM MOS HRS/MSC 20000) REF: AMM 27-20-09 AFL REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AM MOS HRS/MSC 20000) REF: GENERIC NO REF AFL REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (543501 MOS HRS/MSC 20000) REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (543501 MOS HRS/MSC 20000) REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (543501 MOS HRS/MSC 20000) REF: AMM 27-30-01 AFL REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (543501 MOS HRS/MSC 20000) REF: AMM 27-30-01 AFL	PART/SERIAL REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-20-01 REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-20-09 REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*) MOS HRS/MSC 20000 REF: GENERIC NO REF AFL REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*) MOS HRS/MSC 20000	PART/SERIAL REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-20-01 REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-20-09 REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*) MOS HRS/MSC 20000 REF: GENERIC NO REF REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 200000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 200000 REF: AMM 27-30-01 REPLACE LEFT * ELEVATOR HINGE BOLTS (AN4H11A) (AWL*) MOS HRS/MSC 200000	REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P5) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-20-01 REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-20-09 REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*) MOS HRS/MSC 20000 REF: GENERIC NO REF AFL REPLACE LEFT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL REPLACE LEFT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HRS/MSC 20000 REF: AMM 27-30-01 AFL	REPLACE * RUDDER HINGE BOLTS (NAS6205 & NAS464P6) (AWL*) MOS HES/MSC 20000 REF: AMM 27-20-01 AFL MOS HES/MSC 20000 REF: AMM 27-20-01 AFL MOS HES/MSC 20000 REF: AMM 27-20-09 AFL REPLACE * RUDDER SECTOR BEARING ASSEMBLY (5435052) (AWL*) MOS HES/MSC 20000 REF: AMM 27-20-09 AFL REPLACE * RUDDER HINGE BRACKETS (5431005 & 5431056) (AWL*) MOS HES/MSC 20000 REF: GENERIC NO REF AFL MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR BELLCRANKS (2331511) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR UPPER PUSH-PULL TUBES (5435013) (AWL*) MOS HES/MSC 20000 REF: AMM 27-30-01 AFL REPLACE RIGHT * ELEVATOR HINGE BOLTS (ANMH11A) (AWL*) MOS NOS 09-DEC-2007 REF: AMM 27-30-01 AFL REPLACE LEFT * ELEVATOR HINGE BOLTS (ANMH11A) (AWL*)	TASK DESCRIPTION



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owller: SERVICIO	JS MEREUS PI		perator: AERONAUT	C 30LU I IU	IND JUANE		Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
05-11-00-E2730024R	REPLACE RIGHT * ELEVATO	R HINGE BOLTS	(AN4H11A) (AWL*)						
LIFE LIMIT	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				09-DEC-2007 0 0	20000	
05-11-00-E2740010	REPLACE * HORIZONTAL ST	ABILIZER HINGE	PIN (2331028) (AW	L*)					
LIFE LIMIT	REF : AMM 27-40-01	MOS HRS/MSC AFL	20000				09-DEC-2007 0 0	20000	
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE	ROLLER BUSHIN MOS HRS/MSC					26-FEB-2015 3430.9	4630.9	4655.9
	REF: AMM 27-50-01	AFL					1765		
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE		NGS (NAS76A4)				26 FFD 2015		
	REF : AMM 27-50-01	MOS HRS/MSC AFL	1200 +25/-25				26-FEB-2015 3430.9 1765	4630.9	4655.9
05-11-00-E2750035L	REPLACE LEFT * FLAP SECT	OR (2625031) (A	.WL*)						
		MOS HRS/MSC					09-DEC-2007 0		
	REF : AMM 27-50-01	AFL	6000				0	6000	
05-11-00-E2750035R	REPLACE RIGHT * FLAP SEC	TOR (2625031) ((AWL*)						
		MOS HRS/MSC					09-DEC-2007 0		
	REF : AMM 27-50-01	AFL	6000				0	6000	
05-11-00-E2760059L	REPLACE LEFT * SPOILER A	TTACH BOLTS, 5	/16 (NAS464-P5A14)) (AWL*)					
		MOS HRS/MSC	4500				09-DEC-2007 0	4500	
LIFE LIMIT	REF : AMM 27-60-01	AFL	4500				0	4500	
05-11-00-E2760059R	REPLACE RIGHT * SPOILER	ATTACH BOLTS,	5/16 (NAS464-P5A1	4) (AWL*)					
		MOS	4500				09-DEC-2007	4500	
LIFE LIMIT	REF: AMM 27-60-01	HRS/MSC AFL	4000				0	4500	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS	PLATINUM C.A. C	perator: AERONAUT	C SOLUTIO	NS JOANR	IGER, S.A DE C	.V. Ror	ort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
05-11-00-E2760061L	REPLACE LEFT * SPOILER A	CTUATOR ARM	И (2422511) (AWL*)						
		MOS					09-DEC-2007		
		HRS/MS0	C 4500				0	4500	
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
05-11-00-E2760061R	REPLACE RIGHT * SPOILER	ACTUATOR AF	RM (2422511) (AWL*)						
		MOS					09-DEC-2007		
		HRS/MS0	C 4500				0	4500	
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
05-11-00-E2760062L	REPLACE LEFT * SPOILER A	CTUATOR BOL	.T (NAS464P4) (AWL*))					
		MOS					09-DEC-2007		
		HRS/MS0	C 4500				0	4500	
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
05-11-00-E2760062R	REPLACE RIGHT * SPOILER	ACTUATOR BO	OLT (NAS464P4) (AWL	*)					
		MOS					09-DEC-2007		
		HRS/MS(C 4500				0	4500	
LIFE LIMIT	REF : AMM 27-60-04	AFL					0		
05-11-00-E2760063L	REPLACE LEFT * SPOILER C	ENTER PIVOT	BOLT (NAS464P5) (AV	NL*)					
		MOS					09-DEC-2007		
		HRS/MS(C 4500				0	4500	
LIFE LIMIT	REF : AMM 27-60-04	AFL					0		
05-11-00-E2760063R	REPLACE RIGHT * SPOILER	CENTER PIVO	T BOLT (NAS464P5) (A	AWL*)					
		MOS					09-DEC-2007		
		HRS/MS(C 4500				0	4500	
LIFE LIMIT	REF : AMM 27-60-04	AFL					0		
05-11-00-E2760064LI	REPLACE LEFT INBOARD * S	SPOILER HINGE	E BOLT (AN4-13) (AWI	_*)					
		MOS					09-DEC-2007		
		HRS/MS(C 4500				0	4500	
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
05-11-00-E2760064LO	REPLACE LEFT OUTBOARD	* SPOILER HIN	GE BOLT (AN4-13) (A	WL*)					
		MOS	. , ,				09-DEC-2007		
		HRS/MS(C 4500				09-2007	4500	
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		



05-11-00-G2750034R

Status Report

LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 05-11-00-E2760064RI REPLACE RIGHT INBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*) MOS 09-DEC-2007 HRS/MSC 4500 0 4500 **LIFE LIMIT** 0 **REF:** AMM 27-60-04 AFL 05-11-00-E2760064RO REPLACE RIGHT OUTBOARD * SPOILER HINGE BOLT (AN4-13) (AWL*) 09-DEC-2007 MOS HRS/MSC 4500 0 4500 LIFE LIMIT **REF:** AMM 27-60-04 **AFL** 0 05-11-00-F2710036 REPLACE * PRIMARY AILERON CONTROL CABLES (AWL*) MOS 24-AUG-2010 HRS/MSC 2400 2317.85 4717.85 LIFE LIMIT **REF:** AMM 27-10-07 AFL 1066 05-11-00-F2720029 REPLACE PRIMARY RUDDER CONTROL CABLES 24-AUG-2010 MOS HRS/MSC 2400 +25/-25 2317.85 4717.85 4742.85 **REF:** AMM 27-20-10 **AFL** 1066 REPLACE * PRIMARY ELEVATOR CONTROL SYSTEM CABLES (AWL*) 05-11-00-F2730030 MOS 24-AUG-2010 HRS/MSC 2400 2317.85 4717.85 **LIFE LIMIT** REF: AMM 27-30-05 AFL 1066 REPLACE * HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6) (AWL*) 05-11-00-G2740011 MOS 06-MAR-2020 06-MAR-2032 144 HRS/MSC 4262.1 **LIFE LIMIT** AFL 2723 **REF:** AMM 27-40-02 6000 8723 REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT 05-11-00-G2750034L MOS -88 06-MAR-2020 144 +14d/-14d 09-DEC-2031 23-DEC-2031 HRS/MSC 4262.1 **REF:** AMM 27-50-01 AFL 6000 +25/-25 2723 8723 8748

?-Insufficient Information	+-Task exists in Inspection Manual	(s)-Suppressed Requirement (EBT)-Estimated Base Time	*-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU l	Jnits	© CAMP SYSTEMS	

+14d/-14d

+25/-25

-88

06-MAR-2020

4262.1

2723

09-DEC-2031

8723

REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT

REF: AMM 27-50-01

MOS

AFL

HRS/MSC

144

6000

23-DEC-2031

8748



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 WARR TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT REPLACE LEFT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*) 05-11-00-L2750027LI MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT** 0 20000 **REF:** AMM 27-50-01 AFL 20000 05-11-00-L2750027LO REPLACE LEFT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*) 09-DEC-2007 MOS HRS/MSC 0 LIFE LIMIT **REF:** AMM 27-50-01 AFL 20000 0 20000 REPLACE RIGHT INBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*) 05-11-00-L2750027RI MOS 09-DEC-2007 HRS/MSC 0 LIFE LIMIT **REF:** AMM 27-50-01 AFL 20000 0 20000 05-11-00-L2750027RO REPLACE RIGHT OUTBOARD * FLAP TRACK ASSEMBLY (6022515) (AWL*) MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT** AFL 0 20000 **REF:** AMM 27-50-01 20000 REPLACE * INBOARD NOSE ROLLER TRACK (2322511) (AWL*) 05-11-00-L2750028 MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT REF:** AMM 27-50-01 AFL 20000 0 20000 REPLACE * OUTBOARD NOSE ROLLER TRACK (2322512) (AWL*) 05-11-00-L2750029 MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT** 20000 **REF:** AMM 27-50-01 AFL 20000 0 REPLACE LEFT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*) 05-11-00-L2750033L 09-DEC-2007 PΝ MOS SN-UNKNOWN HRS/MSC 0 **LIFE LIMIT REF:** AMM 27-50-01 AFL 10000 0 10000 REPLACE RIGHT LOWER * LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516) (AWL*) 05-11-00-L2750033R PNMOS 09-DEC-2007 SN-UNKNOWN HRS/MSC 0 **LIFE LIMIT** 0 **REF:** AMM 27-50-01 AFL 10000 10000



LIFE LIMIT

Status Report

LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 05-11-00-M2710021LI REPLACE LEFT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*) MOS 09-DEC-2007 HRS/MSC 20000 0 20000 **LIFE LIMIT** 0 **REF:** AMM 27-10-02 AFL 05-11-00-M2710021LO REPLACE LEFT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*) 09-DEC-2007 MOS HRS/MSC 20000 0 20000 LIFE LIMIT **REF:** AMM 27-10-02 **AFL** 0 REPLACE RIGHT INBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*) 05-11-00-M2710021RI MOS 09-DEC-2007 HRS/MSC 20000 0 20000 LIFE LIMIT **REF:** AMM 27-10-02 AFL 0 05-11-00-M2710021RO REPLACE RIGHT OUTBOARD * AILERON HINGE BOLTS (AN4H12A) (AWL*) MOS 09-DEC-2007 HRS/MSC 20000 0 20000 **LIFE LIMIT** AFL 0 **REF:** AMM 27-10-02 REPLACE * HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 05-11-00-M2730031 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY) (AWL*) MOS 09-DEC-2007 HRS/MSC 20000 0 20000 LIFE LIMIT **REF:** AMM 27-30-01 AFL 0 REPLACE LEFT INBOARD * FLAP SUPPORT FITTING (AWL*) 05-11-00-M2750049LI MOS 09-DEC-2007 HRS/MSC 0 LIFE LIMIT **REF:** AMM 27-50-01 AFL 20000 0 20000 05-11-00-M2750049LO REPLACE LEFT OUTBOARD * FLAP SUPPORT FITTING (AWL*) MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT** AFL 20000 0 20000 REF: AMM 27-50-01 REPLACE RIGHT INBOARD * FLAP SUPPORT FITTING (AWL*) 05-11-00-M2750049RI

?-Insufficient Information +-Task exists in Inspection Manual	(s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units	© CAMP SYSTEMS

HRS/MSC

20000

MOS

AFL

REF: AMM 27-50-01

20000

09-DEC-2007

0

0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	JS AEREOS I	PLATINUM C.A. (Operator: AERONAUTI	C SOLUTIO	NS JOANR	RIGER, S.A DE C.V.	Rei	oort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE N		MAX LIMIT
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD	* FLAP SUPPO	ORT FITTING (AWL*)						
		MOS					09-DEC-2007		
LIFE LIMIT	REF : AMM 27-50-01	HRS/MSC AFL	20000				0 0	20000	
LIFE LIMIT	REF. AIVIIVI 27-30-01	AFL	20000					20000	
05-11-00-N2750025	REPLACE * INBOARD FLAP T	RACK HINGE F	ITTING (ON FLAP) (P	/N 2625023) (AWL*)					
		MOS					09-DEC-2007		
NOT INOTAL LED	DEE: AMM 07 50 04	HRS/MSC	N/A				0		
NOT INSTALLED	REF: AMM 27-50-01	AFL					0		
05-11-00-N2750026	REPLACE * OUTBOARD FLAR	P TRACK HINGE	E FITTING (ON FLAP)	(P/N 2625024) (AWL*)					
		MOS					09-DEC-2007		
		HRS/MSC	N/A				0		
NOT INSTALLED	REF: AMM 27-50-01	AFL					0		
05-11-00-N2750031	REPLACE * INBOARD AND O	UTBOARD FLAF	P SUPPORT FITTING	(6022521-1 THRU-8) (AWL*)					
		MOS					09-DEC-2007		
		HRS/MSC	N/A				0		
N/A BY SERIAL NUMBER	REF : AMM 27-50-01	AFL					0		
05-11-00-N2750032	REPLACE * UPPER FLAP SE	CTOR BRACKE	T ASSEMBLY (602251	11-1, -2, -801, AND -802) (AW	′L*)				
		MOS					09-DEC-2007		
		HRS/MSC	O/C				0		
	REF : AMM 27-50-01	AFL					0		
05-11-00-N2750051	REPLACE * INBOARD FLAP H	IINGE FITTING	(P/N 6025022) (AWL*	·)					
		MOS	, , , , , , , , , , , , , , , , , , , ,	,			09-DEC-2007		
		HRS/MSC	;				0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0	20000	
05-11-00-N2750052	REPLACE * OUTBOARD FLAR	P HINGE FITTIN	G (P/N 6025021) (AW	/L*)					
3000		MOS	- , , (/ (/ /	,			09-DEC-2007		
		HRS/MSC	;				09-DEC-2007 0		
LIFE LIMIT	REF: AMM 27-50-01	AFL	20000				0	20000	
05-11-00-R2750050L	REPLACE LEFT UPPER * UPI	PER FLAP SECT	TOR BRACKET (AWL	*)					
	PN	MOS	(,			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	;				0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

	Owner: SERVICIO			perator: AERONAUTI	C 30LU I IUI	MIAOL CE	·	Rej	port Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5-11-00-R2750050R	REPLACE RIGHT UPPER * UI	PPER FLAP SECT	OR BRACKET (AW	′L*)					
	PN SN-UNKNOWN	MOS HRS/MSC					09-DEC-2007 0		
IFE LIMIT	REF : AMM 27-50-01	AFL	20000				0	20000	
05-11-00-R2760079L	REPLACE LEFT LEFT * SPOIL	LER ACTUATOR A	TTACH FITTING AI	ND BOLT (AWL*)					
		MOS					09-DEC-2007		
LIFE LIMIT	REF : AMM 27-60-04	HRS/MSC AFL	10000				0 0	10000	
LIFE LIMII I	REF. AIVIVI 27-00-04	AFL							
05-11-00-R2760079R	REPLACE RIGHT RIGHT * SP	OILER ACTUATOR	R ATTACH FITTING	S AND BOLT (AWL*)					
		MOS					09-DEC-2007		
		HRS/MSC	10000				0	10000	
LIFE LIMIT	REF: AMM 27-60-04	AFL					0		
27-51-06-082	LEFT INBOARD FLAP NOSE I	ROLLER SUPPOR	T ARM						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : AMM 27-50-01	AFL		N:0			0		
27-51-06-082	LEFT OUTBOARD FLAP NOS	E ROLLER SUPPO	ORT ARM						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : AMM 27-50-01	AFL		N:0			0		
27-51-06-082	RIGHT INBOARD FLAP NOSE	ROLLER SUPPO	RT ARM						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-01	AFL		N:0			0		
27-51-06-082	RIGHT OUTBOARD FLAP NO	SE ROLLER SUPP	ORT ARM						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-01	AFL		N:0			0		
27-51-06-085	LEFT FLAP LEADING EDGE F	RIB							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	US AEREOS PLA	I INUM C.A. C	perator: AERONAUTI	C SOLUTIONS	S JOANR	RIGER, S.A DE C.V.	Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	ITERVAL	TIME SINCE		WARR EXP		MAX
27-51-06-085	RIGHT FLAP LEADING EDGE	RIB						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-50-01	AFL		N:0			0	
270505	TRIM SWITCH PANEL ASSEM	MBLY						
	6027080002-005	MOS		N:0			12-DEC-2011	
	SN-UNKNOWN	HRS/MSC O	/C	N:0			3011.9	
	REF : AMM 27-00-01	AFL		N:0			1487	
271013	AILERON TRIM TAB ASSEME	BLY						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-10-04	AFL		N:0			0	
271015	LEFT AILERON BALANCE TA	AB ASSEMBLY						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-10-03	AFL		N:0			0	
271016	RIGHT AILERON BALANCE T	TAB ASSEMBLY						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-10-03	AFL		N:0			0	
271019	AILERON TRIM ACTUATOR							
	2R6203B	MOS		N:0			09-DEC-2007	
	B0188	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-10-11	AFL		N:0			0	
271025	PILOT CONTROL WHEEL							
	2415151-017	MOS		N:0			09-DEC-2007	
	2832	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-10-01	AFL		N:0			0	
271026	COPILOT CONTROL WHEEL							
	2415151-018	MOS		N:0			09-DEC-2007	
	2866	HRS/MSC O	/C	N:0			0	
	REF : AMM 27-10-01	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	S AEREOS PI	LATINUM C.A.	Operator: AERONAUTI	CSOLUTION	IS JOANK	IIGER, S.A DE C.V.	Ren	ort Date: 10-SEP-	-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT (ENG/AP	DUE	MAX LIMIT	
271027	PILOT CONTROL COLUMN									
	5415150-026	MOS		N:0			09-DEC-2007			
	A008593998	HRS/MSC	O/C	N:0			0			
	REF: AMM 27-30-06	AFL		N:0			0			
271028	COPILOT CONTROL COLUMN	N								
	5405011-1	MOS					24-AUG-2010			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			2317.85			
	REF : AMM 27-30-06	AFL		N:0			1066			
271031	AILERON TRIM TAB ACTUATO	OR POTENTIOME	ETER							
	P30LS0GJS102KAG222	MOS		N:0			30-JUL-2019			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			4218.5			
	REF: AMM 27-10-12	AFL		N:0			2672			
271126	AILERON TRIM POSITION INC	DICATOR								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF : AMM 27-10-05	AFL		N:0			0			
271131	LEFT AILERON POSITION SEI	NSOR								
	501-1123-03	MOS		N:0			09-DEC-2007			
	80549	HRS/MSC	O/C	N:0			0			
	REF : AMM 27-10-06	AFL		N:0			0			
271132	RIGHT AILERON POSITION SI	ENSOR								
	501-1123-03	MOS		N:0			22-SEP-2010			
	80648	HRS/MSC	O/C	N:0			2376.28			
	REF: AMM 27-10-06	AFL		N:0			1098			
271701	* LEFT AILERON ASSEMBLY	(AWL*)								
	2424000-313	MOS		N:0			09-DEC-2007			
	W792	HRS/MSC	20000	N:0				20000		
LIFE LIMIT	REF: AMM 27-10-02	AFL		N:0			0			
271702	* RIGHT AILERON ASSEMBLY	(AWL*)								
	2424000-314	MOS		N:0			09-DEC-2007			
	W761	HRS/MSC	20000	N:0				20000		
LIFE LIMIT	REF : AMM 27-10-02	AFL		N:0			0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT IN	ITERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		oort Date: 10-SEP-20 MAX
	PART/SERIAL					EXP		(ENG/APU) A/C	LIMIT
72001	* RUDDER ASSEMBLY (AWL	*)							
	5433000-020	MOS		N:74			12-FEB-2014		
	W560	HRS/MSC 20	0000	N:3333			3333	20000	
IFE LIMIT	REF : AMM 27-20-01	AFL					1670		
272005	AFT RUDDER SECTOR								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/	/C	N:0			0		
	REF : AMM 27-20-09	AFL		N:0			0		
272007	RUDDER TRIM TAB								
501		MOS		Nio			00 DEC 2007		
	PN SN-UNKNOWN	MOS HRS/MSC O/	/C	N:0 N:0			09-DEC-2007 0		
	REF: AMM 27-20-02	AFL AFL		N:0			0		
	TKET : / WINN ZI ZO OZ	70 2		14.0					
272013	RUDDER TRIM TAB ACTUATO	OR							
	2R6204B	MOS		N:0			09-DEC-2007		
	B0136	HRS/MSC O/	/C	N:0			0		
	REF: AMM 27-20-03	AFL		N:0			0		
272020	RUDDER TRIM TAB POTENTI	IOMETER							
	RV4SAYSD102A	MOS					01-JUN-2011		
	SN-UNKNOWN	HRS/MSC O/	/C				2785.83		
	REF : AMM 27-20-04	AFL					1342		
272026	RUDDER TRIM INDICATOR								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/	/C	N:0			09-DEC-2007 0		
	REF : AMM 27-20-06	AFL	· -	N:0			0		
272031	PILOT RUDDER PEDAL ACTU	JATOR							
	6600418-4	MOS		O:0			16-JUL-2017		
	132	HRS/MSC O/	/C	O:0			3849.9		
	REF : AMM 27-20-07	AFL	· -	O:0			2207		
272032	COPILOT RUDDER PEDAL AG	CTUATOR							
				Nio			00 DEC 2007		
	EM423-4 847	MOS HRS/MSC O/	IC	N:0 N:0			09-DEC-2007 0		
	REF: AMM 27-20-07	AFL AFL		N:0			0		
	TALL I AVAIN AT AU UT	/ U =		.1.0			•		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	port Date: 10-SEP-202 MAX LIMIT
273001	* LEFT ELEVATOR ASSEMBL	Y (AWL*)							
LIFE LIMIT	2434000-801 W657 REF : AMM 27-30-01	MOS HRS/MSC AFL APH ACH	20000	N:0 N:0 N:0			24-AUG-2010 2317.85 1066	22317.85	
273002	* RIGHT ELEVATOR ASSEME	BLY (AWL*)							
LIFE LIMIT	2434000-178 W774 REF: AMM 27-30-01	MOS HRS/MSC AFL APH ACH	20000	N:0 N:0 N:0			09-DEC-2007 0 0	20000	
2730036	ELEVATOR BELLCRANKS - P	PERFORM EDDY C	URRENT INSPECT	TION					
	REF: NDT 27-30-01	MOS HRS/MSC AFL	24 600				(EBT)	16-DEC-2021 4903.52	
273013	STALL WARNING COMPUTE	R							
	54301-3LMODA M3035 REF : AMM 27-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
273017	PILOT STICK SHAKER								
	20-7 1066A REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
273018	COPILOT STICK SHAKER								
	20-7 1064A REF : AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
273101	PILOT STALL WARNING TRA	NSDUCER							
	25147A-12 GST06155 REF : AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

FACIC NO	TACK DECORIDERA	LINIT -INTERVAL	TIME OWE	4D1 W4BB	Report Date:	10-3LP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
73102	COPILOT STALL WARNING T	RANSDUCER				
	25147A-12	MOS	R:0		17-JUL-2010	
	GST02592	HRS/MSC O/C	R:0		2267.35	
	REF : AMM 27-31-01	AFL	R:0		1041	
273105	PILOT ANGLE-OF-ATTACK (A	AOA) INDICATOR				
	N617-9025	MOS	N:0		09-DEC-2007	
	07018628	HRS/MSC O/C	N:0		0	
	REF : AMM 27-31-04	AFL	N:0		0	
273106	COPILOT ANGLE-OF-ATTAC	K (AOA) INDICATOR				
	N617-9025	MOS	N:0		09-DEC-2007	
	07018629	HRS/MSC O/C	N:0		0	
	REF : AMM 27-31-04	AFL	N:0		0	
273110	ANGLE-OF-ATTACK (AOA) V	ANE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 27-31-05	AFL	N:0		0	
274001	HORIZONTAL STABILIZER					
	2332000-60	MOS	N:0		09-DEC-2007	
	W442	HRS/MSC O/C	N:0		0	
	REF : AMM 27-40-01	AFL	N:0		0	
274002	(HSA) HEADING SPEED ALTI	TUDE CONTROL PANEL ASSY				
	6034080011-003	MOS			03-MAR-2008	
	A01060334-01	HRS/MSC O/C			238.65	
	REF:	AFL			107	
274003	HORIZONTAL STABILIZER A	CTUATOR CONTROLLER				
	6608444-2	MOS			19-JUN-2013	
	26A	HRS/MSC O/C			3217.3	
	REF : AMM 27-40-03	AFL			1608	
74010	TRIM-IN-MOTION DETECTOR	R				
	231-1-2	MOS	N:0		09-DEC-2007	
	206350156	HRS/MSC O/C	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	US AEREOS P	'LATINUM C.A. O	perator: AERONAUT	C SOLUTIONS	JUANRIG	EK, S.A DE C.V.	Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE		VARR C	COMPLIANCE N		MAX LIMIT
274013	HORIZONTAL STABILIZER AG	CTUATOR							
	5435005-028	MOS		O:0		2	4-JAN-2019		
	283	HRS/MSC	600 +25/-25	O:0		4	067	4667	4692
OVERHAUL	REF : AMM 27-40-02	AFL		O:0		2	2472		
274062	PITCH TRIM INDICATOR								
	PN	MOS		N:0		0	9-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	i		
	REF : AMM 27-40-04	AFL		N:0		0			
274070	STABILIZER POSITION SWIT	СН							
	CS402-3	MOS		N:0		0	9-DEC-2007		
	10911	HRS/MSC	O/C	N:0		0			
	REF : AMM 27-40-06	AFL		N:0		0			
274072	STABILIZER POSITION SENS	SOR							
	501-1123-03	MOS		N:0		0	9-DEC-2007		
	80577	HRS/MSC	O/C	N:0		0			
	REF: GENERIC NO REF	AFL		N:0		0			
275001	* LEFT FLAP ASSEMBLY (AV	VL*)							
	6025010-035	MOS		N:0		0	9-DEC-2007		
	W1554	HRS/MSC		N:0		0			
LIFE LIMIT	REF: AMM 27-50-01	AFL	10000	N:0		0		10000	
275002	* RIGHT FLAP ASSEMBLY (A	\WL*)							
	6025010-036	MOS		N:0		n	9-DEC-2007		
	W1550	HRS/MSC		N:0		0			
IFE LIMIT	REF : AMM 27-50-01	AFL	10000	N:0		0		10000	
275005	LEFT LOWER FLAP SECTOR	BRACKET							
	PN	MOS		N:0		0	9-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF:	AFL		N:0		0			
275005	LEFT UPPER FLAP SECTOR	BRACKET							
	PN	MOS		N:0		0	9-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0			
	REF:	AFL		N:0		0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTE	ERVAL TIM	E SINCE AD	J WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
75005	RIGHT LOWER FLAP SECTO	R BRACKET					
	PN	MOS	N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0			0	
	REF:	AFL	N:0			0	
275005	RIGHT UPPER FLAP SECTOR	R BRACKET					
	PN	MOS	N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0			0	
	REF:	AFL	N:0			0	
2750058	* LEFT FLAP LEADING EDGE	RIB - REPLACE (AWL*	·)				
	PN	MOS				09-DEC-2007	
	SN-UNKNOWN	HRS/MSC N/A				0	
NOT APPLICABLE	REF : AMM 27-50-01	AFL				0	
2750058	* LEFT INBOARD FLAP NOSE	ROLLER SUPPORT AF	RM - REPLACE (AWL*)				
	PN	MOS				09-DEC-2007	
	SN-UNKNOWN	HRS/MSC N/A				0	
	REF : AMM 27-50-01	AFL				0	
2750058	* LEFT OUTBOARD FLAP NO	SE ROLLER SUPPORT	ARM - REPLACE (AWL	*)			
	PN	MOS				09-DEC-2007	
	SN-UNKNOWN	HRS/MSC N/A				0	
	REF: AMM 27-50-01	AFL				0	
2750058	* RIGHT FLAP LEADING EDG	E RIB - REPLACE (AW	_*)				
	PN	MOS				09-DEC-2007	
	SN-UNKNOWN	HRS/MSC N/A				0	
NOT APPLICABLE	REF: AMM 27-50-01	AFL				0	
2750058	* RIGHT INBOARD FLAP NOS	SE ROLLER SUPPORT A	ARM - REPLACE (AWL*)			
	PN	MOS				09-DEC-2007	
	SN-UNKNOWN	HRS/MSC N/A				0	
	REF : AMM 27-50-01	AFL				0	
750058	* RIGHT OUTBOARD FLAP N	OSE ROLLER SUPPOR	T ARM - REPLACE (AW	L*)			
	PN	MOS				09-DEC-2007	
	SN-UNKNOWN	HRS/MSC N/A				0	
	REF : AMM 27-50-01	AFL				0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

					Report Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT
75010	FLAP & ENGINE SYNCHRON	IZER RELAY BOX ASSEMBLY			
	PN	MOS	N:0		09-DEC-2007
	SN-UNKNOWN	HRS/MSC O/C	N:0		0
	REF : AMM 27-50-06	AFL	N:0		0
75012	FLAP POSITION POTENTION	1ETER			
	RV4SAYSD102A	MOS			01-JUN-2011
	SN-UNKNOWN	HRS/MSC O/C			2785.83
	REF : AMM 27-50-09	AFL			1342
75019	LEFT LIMIT, INBOARD FLAP/	STABILIZER SWITCH			
	CS402-3	MOS	N:0		09-DEC-2007
	10843	HRS/MSC O/C	N:0		0
	REF : AMM 27-50-05	AFL	N:0		0
75020	RIGHT LIMIT, INBOARD FLAF	P/STABILIZER SWITCH			
	2625045-32	MOS	N:0		29-SEP-2010
	SN-UNKNOWN	HRS/MSC O/C	N:0		2384.8
	REF : AMM 27-50-05	AFL	N:0		1104
275021	LEFT POSITION, OUTBOARD) FLAP/STABILIZER SWITCH			
	CS402-3	MOS	N:0		09-DEC-2007
	10799	HRS/MSC O/C	N:0		0
	REF : AMM 27-50-04	AFL	N:0		0
75022	RIGHT POSITION, OUTBOAR	RD FLAP/STABILIZER SWITCH			
	CS402-3	MOS	N:0		09-DEC-2007
	10895	HRS/MSC O/C	N:0		0
	REF : AMM 27-50-04	AFL	N:0		0
75031	FLAP CONTROL (FLAP/SPOI	LER) VALVE			
	65770	MOS	N:0		09-DEC-2007
	1173A	HRS/MSC O/C	N:0		0
	REF : AMM 27-50-07	AFL	N:0		0
75036	FLAP RESTRICTOR VALVE				
	2R1047-0312	MOS	N:0		09-DEC-2007
	2285	HRS/MSC O/C	N:0		0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ARR COMPLIANCE NE		ort Date: 10-SEP-20 MAX LIMIT
275037	LEFT FLAP ACTUATOR				 (2)	on o, no	- Envil 1
	6600493-2	MOS		N:0	09-DEC-2007		
	0579	HRS/MSC	O/C	N:0	0		
	REF : AMM 27-50-08	AFL		N:0	0		
275038	RIGHT FLAP ACTUATOR						
	6600493-2	MOS		O:0	29-JAN-2009		
	0179	HRS/MSC	O/C	O:0	1151.95		
	REF : AMM 27-50-08	AFL			495		
275200	FLAP POSITION INDICATOR						
	RV4SAYSD102A	MOS		N:0	11-AUG-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0	3533.1		
	REF : AMM 27-50-10	AFL		N:0	1882		
275213	FLAP PRESSURE RELIEF VA	LVE					
	AN6245A4	MOS		N:0	09-DEC-2007		
	19142	HRS/MSC	O/C	N:0	0		
	REF : AMM 27-50-13	AFL		N:0	0		
275217	FLAP ACTUATION CHECK VA	LVE					
	PN	MOS		N:0	09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0	0		
	REF: AMM 27-50-12	AFL		N:0	0		
276001	* LEFT SPOILER ASSEMBLY	(AWL*)					
	2422510-131	MOS		N:0	09-DEC-2007		
	W1993	HRS/MSC	4500	N:0	0	4500	
LIFE LIMIT	REF : AMM 27-60-01	AFL		N:0	0		
276002	* RIGHT SPOILER ASSEMBL\	(AWL*)					
	2422510-130	MOS		N:0	09-DEC-2007		
	W1995	HRS/MSC	4500	N:0	0	4500	
LIFE LIMIT	REF : AMM 27-60-01	AFL		N:0	0		
276010	SPOILER COMPUTER						
	501-1133-11	MOS		R:0	29-SEP-2010		
	1470	HRS/MSC	O/C	R:0	2384.8		
	REF : AMM 27-60-02	AFL		R:0	1104		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

							ort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP		EXT DUE NG/APU) A/C	MAX LIMIT
76013	* LEFT SPOILER ACTUATOR	ASSEMBLY (AWL*)					
	2417015-5	MOS	N:0		09-DEC-2007		
	2456	HRS/MSC 10000	N:0		0	10000	
IFE LIMIT	REF : AMM 27-60-04	AFL	N:0		0		
276014	* RIGHT SPOILER ACTUATO	R ASSEMBLY (AWL*)					
	2417015-5	MOS	N:0		09-DEC-2007		
	2455	HRS/MSC 10000	N:0		0	10000	
LIFE LIMIT	REF : AMM 27-60-04	AFL	N:0		0		
276037	LEFT SPOILER POSITION SE	ENSOR					
	501-1123-03	MOS	N:0		09-DEC-2007		
	08551	HRS/MSC O/C	N:0		0		
	REF : AMM 27-60-07	AFL	N:0		0		
276038	RIGHT SPOILER POSITION S	SENSOR					
	501-1123-03	MOS	N:0		09-DEC-2007		
	80556	HRS/MSC O/C	N:0		0		
	REF : AMM 27-60-07	AFL	N:0		0		
276043	SPOILER POTENTIOMETER						
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 27-60-09	AFL	N:0		0		
276049	SPOILER POSITION INDICAT	OR					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF: AMM 27-60-10	AFL	N:0		0		
276128	SPOILER MANIFOLD VALVE						
	2627023-1	MOS	N:0		09-DEC-2007		
	1157	HRS/MSC O/C	N:0		0		
	REF : AMM 27-60-03	AFL	N:0		0		
276265	WHEEL SPEED DETECTION	вох					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 27-60-12	AFL	N:0		0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT CHECK CONTROL CABLES UNDER FLOORBOARDS FOR EVIDENCE OF CABLE FRAYING, STRAND BREAKAGE, AND PKG W2700062 (s) SECURITY. CHECK PULLEYS, GUARDS, AND SAFETIES FOR PROPER OPERATION. (REFER TO 5-10-00.) PKG 8 MOS 24 +14d/-14d 06-MAR-2020 HRS/MSC 600 +25/-25 4262.1 REF: GENERIC NO REF AFL 2723 CHAPTER 28 **FUEL** 05-10-29-L2812002L INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602 MOS 24 -39 06-MAR-2020 09-FEB-2022 +14d/-14d 26-JAN-2022 HRS/MSC 4262.1 REF: GENERIC NO REF **AFL** 2723 INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602 05-10-29-L2812002R MOS 24 -39 06-MAR-2020 +14d/-14d 26-JAN-2022 09-FEB-2022 HRS/MSC 4262.1 **REF: GENERIC NO REF** AFL 2723 05-10-29-L2812010L INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA MOS 24 +14d/-14d -39 06-MAR-2020 26-JAN-2022 09-FEB-2022 HRS/MSC 4262.1 REF: GENERIC NO REF **AFL** 2723 INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA 05-10-29-L2812010R MOS 24 +14d/-14d -39 06-MAR-2020 26-JAN-2022 09-FEB-2022 HRS/MSC 4262.1 **REF: GENERIC NO REF** AFL 2723 05-10-29-L2812020L INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION MOS 24 +14d/-14d -39 06-MAR-2020 26-JAN-2022 09-FEB-2022 HRS/MSC 4262.1 REF: GENERIC NO REF **AFL** 2723 05-10-29-L2812020R INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION MOS 24 +14d/-14d -39 06-MAR-2020 26-JAN-2022 09-FEB-2022 HRS/MSC 4262.1 2723 **REF: GENERIC NO REF** AFL



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Penort Date: 10-SED-2021

	Owner. SERVICE	OS ALICEOS FLATIN	OH C.A. Operator: ALKONAC	7110 3010 110113 30AI	TITOLIN, SIA DE C.T.	Report Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTER	RVAL TIME SINCE	ADJ WARR EXP	R COMPLIANCE NEXT I (ENG/APU	DUE MAX
5-10-29-T2820012	CLEAN AND LEAK CHECK LO	OW PRESSURE FUEL FIL	TERS			
		MOS			24-AUG-2010	
		HRS/MSC -			2317.85	
	REF: AMM 28-20-04	AFL			1066	
05-11-00-G2820003	REPLACE ALL FUEL HOSE A (PRESSURE)	SSEMBLIES (EXCLUDING	G ALL HOSES IN ENGINE NACELLE	AREA) IN AIRCRAFT		
		MOS			09-DEC-2007	
		HRS/MSC O/C			0	
TEFLON	REF: AMM 28-00-00	AFL			0	
280002	FUEL CONTROL SWITCH PA	NEL ASEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-00-02	AFL	N:0		0	
280003	LEFT WING DEFUEL VALVE					
	72DA0021	MOS	N:0		09-DEC-2007	
	0030	HRS/MSC O/C	N:0		0	
	REF : AMM 28-00-03	AFL	N:0		0	
280004	RIGHT WING DEFUEL VALVE	=				
	72DA0021	MOS	N:0		09-DEC-2007	
	0062	HRS/MSC O/C	N:0		09-DEC-2007	
	REF : AMM 28-00-03	AFL	N:0		0	
201007	LEFT CHECK, CROSSFLOW	\/A1 \/E				
281007			***		00 DE0 0007	
	7600004-1	MOS HRS/MSC O/C	N:0 N:0		09-DEC-2007	
	1003128 REF : AMM 28-14-05	AFL AFL	N:0 N:0		0	
281008	RIGHT CHECK, CROSSFLOV	V VALVE				
	7600004-1	MOS	N:0		09-DEC-2007	
	1003132	MOS HRS/MSC O/C	N:0 N:0		09-DEC-2007 0	
	REF : AMM 28-14-05	AFL	N:0		0	
281201	AFT FUSELAGE FUEL CELL					
		MOS	NI-O		00 DEC 2007	
	501847 105047	MOS HRS/MSC O/C	N:0 N:0		09-DEC-2007 0	
	REF: AMM 28-12-01	AFL	N:0		0	
					-	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021									
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERV	AL TIME SINCE	ADJ WARR EXP		AX					
281202	FORWARD FUSELAGE FUEL	CELL									
	501848	MOS	N:0		09-DEC-2007						
	105672	HRS/MSC O/C	N:0		0						
	REF : AMM 28-12-02	AFL	N:0		0						
281283	FUSELAGE DRAIN VALVE										
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF: GENERIC NO REF	AFL	N:0		0						
281301	LEFT WING FUEL VENT FLO	AT VALVE									
	35C15G	MOS	N:0		09-DEC-2007						
	4212	HRS/MSC O/C	N:0		0						
	REF: AMM 28-13-01	AFL	N:0		0						
281302	RIGHT WING FUEL VENT FL	OAT VALVE									
	35C15G	MOS	N:0		09-DEC-2007						
	4218	HRS/MSC O/C	N:0		0						
	REF : AMM 28-13-01	AFL	N:0		0						
281303	FUSELAGE FUEL VENT FLO	AT VALVE									
	35C15G	MOS	N:0		09-DEC-2007						
	4198	HRS/MSC O/C	N:0		0						
	REF: AMM 28-13-01	AFL	N:0		0						
281305	LEFT WING FLAME ARREST	OR									
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF: AMM 28-13-03	AFL	N:0		0						
281306	RIGHT WING FLAME ARRES	TOR									
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF: AMM 28-13-03	AFL	N:0		0						
281307	LEFT FUEL CELL PRESSURE	E RELIEF VALVE									
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF : AMM 28-13-07	AFL	N:0		0						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		ort Date: 10-SEP-20 MAX
	PART/SERIAL	JAN INTERVAL	- IMIL ON OL	EXP	(ENG/APU) A/C	LIMIT
31308	RIGHT FUEL CELL PRESSUF	RE RELIEF VALVE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-13-07	AFL	N:0		0	
81309	FUSELAGE FLAME ARRESTO	OR				
	9909018-101	MOS	N:0		09-DEC-2007	
	533	HRS/MSC O/C	N:0		0	
	REF: AMM 28-13-09	AFL	N:0		0	
81401	LEFT FUSELAGE CELL TRAN	NSFER PUMP				
	2380060-052	MOS	O:3		27-MAR-2011	
	C4532	HRS/MSC O/C	O:0		2677.77	
	REF : AMM 28-14-01	AFL	O:0		1279	
81402	RIGHT FUSELAGE CELL TRA	ANSFER PUMP				
	2380060-052	MOS	O:4		27-MAR-2011	
	C1597	HRS/MSC O/C	O:0		2677.77	
	REF : AMM 28-14-01	AFL	O:0		1279	
81403	LEFT INBOARD WING SCAVE	ENGE JET PUMP				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-02	AFL	N:0		0	
281404	RIGHT INBOARD WING SCA	VENGE JET PUMP				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-02	AFL	N:0		0	
81405	LEFT CENTER WING SCAVE	NGE JET PUMP				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-02	AFL	N:0		0	
81406	RIGHT CENTER WING SCAV	ENGE JET PUMP				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-02	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		ort Date: 10-SEP-20 MAX				
ASK NO	PART/SERIAL	ONII INTERVAL	TIME SINCE	EXP	(ENG/APU) A/C	MAX LIMIT				
31407	LEFT OUTBOARD WING SCAVENGE JET PUMP									
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-02	AFL	N:0		0					
81408	RIGHT OUTBOARD WING SC	CAVENGE JET PUMP								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-02	AFL	N:0		0					
81409	LEFT SCAVENGE PUMP									
	2380060-053	MOS	N:0		09-DEC-2007					
	C4264	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-03	AFL	N:0		0					
281410	RIGHT SCAVENGE PUMP									
	2380060-053	MOS	N:0		09-DEC-2007					
	C4273	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-03	AFL	N:0		0					
281411	LEFT FUEL TRANSFER VALV	/E								
	EM91-119	MOS	N:0		09-DEC-2007					
	07-0425617	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-04	AFL	N:0		0					
81412	RIGHT FUEL TRANSFER VAL	_VE								
	EM91-42	MOS	N:0		09-DEC-2007					
	06-1220185	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-04	AFL	N:0		0					
81413	CROSSFLOW VALVE									
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-05	AFL	N:0		0					
81414	FUSELAGE HIGH-LEVEL FLO	DAT SWITCH								
	L14F-110	MOS	N:0		09-DEC-2007					
	117	HRS/MSC O/C	N:0		0					
	REF : AMM 28-14-07	AFL	N:0		0					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

FACK NO	TACK DESCRIPTION	LINIT INTERVAL	TIME ONCE	AD I WARR		ort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
81415	LEFT FUEL TRANSFER PRES	SSURE INDICATING SWITCH				
	7600002-3	MOS	N:0		09-DEC-2007	
	1389	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-06	AFL	N:0		0	
281416	RIGHT FUEL TRANSFER PRE	ESSURE INDICATING SWITCH				
	7600002-3	MOS	N:0		09-DEC-2007	
	1397	HRS/MSC O/C	N:0		0	
	REF: AMM 28-14-06	AFL	N:0		0	
81417	LEFT WING HIGH-LEVEL FLO	DAT SWITCH				
	L15H-59	MOS	N:0		09-DEC-2007	
	253	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-08	AFL	N:0		0	
281418	RIGHT WING HIGH-LEVEL FL	LOAT SWITCH				
	L15H-59	MOS	N:0		09-DEC-2007	
	252	HRS/MSC O/C	N:0		0	
	REF : AMM 28-14-08	AFL	N:0		0	
281419	LEFT WING LOW-LEVEL FLO	DAT SWITCH				
	L15H59	MOS			07-MAR-2011	
	SN-UNKNOWN	HRS/MSC O/C			2634.63	
	REF: AMM 28-14-09	AFL			1247	
281420	RIGHT WING LOW-LEVEL FL	OAT SWITCH				
	L15H-59	MOS			20-JUN-2008	
	354	HRS/MSC O/C	N:0		564.8	
	REF : AMM 28-14-09	AFL	N:0		243	
281421	FUEL FILL AND TRANSFER E	вох				
	6018255-012	MOS	R:0		23-MAR-2011	
	822065	HRS/MSC O/C	R:0		2668.32	
	REF : AMM 28-14-10	AFL	R:0		1272	
282001	LEFT INBOARD JET PUMP					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 28-20-01	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

						DANRIGER, S.A DE C.V.	Report Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WA EXI	RR COMPLIANCE NEXT DI (ENG/APU)	
82002	RIGHT INBOARD JET PUMP						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-01	AFL		N:0		0	
282003	LEFT STANDBY PUMP						
	2380060-051	MOS		N:0		09-DEC-2007	
	C4252	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-02	AFL		N:0		0	
282004	RIGHT STANDBY PUMP						
	2380060-051	MOS		N:0		09-DEC-2007	
	C4270	HRS/MSC	O/C	N:0		0	
	REF: AMM 28-20-02	AFL		N:0		0	
282005	LEFT FUEL FILTER ASSEMBL	Υ					
	6600488-4	MOS		N:0		09-DEC-2007	
	1926	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-04	AFL		N:0		0	
282006	RIGHT FUEL FILTER ASSEMB	BLY					
	6600488-4	MOS		N:0		09-DEC-2007	
	1967	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-04	AFL		N:0		0	
282007	LEFT ENGINE FUEL SHUTOFF	F VALVE					
	EM91-119	MOS		N:0		09-DEC-2007	
	07-051874	HRS/MSC	O/C	N:0		0	
	REF: AMM 28-20-05	AFL		N:0		0	
282008	RIGHT ENGINE FUEL SHUTOI	FF VALVE					
	EM91-42	MOS		N:0		09-DEC-2007	
	06-0628133	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-05	AFL		N:0		0	
282009	LEFT WING AND FUSELAGE N	MOTIVE FLOW SH	HUTOFF VALVE				
	EM91-42	MOS		N:0		09-DEC-2007	
	07-0330163	HRS/MSC	O/C	N:0		0	
	REF: AMM 28-20-06	AFL		N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO							Report I	Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT (ENG/API	DUE MA	λX
282010	RIGHT WING AND FUSELAGE	MOTIVE FLOW	SHUTOFF VALVE						
	EM91-42	MOS		N:0			09-DEC-2007		
	07-0330162	HRS/MSC	O/C	N:0			0		
	REF : AMM 28-20-06	AFL		N:0			0		
282011	LEFT ENGINE RELIEF VALVE								
	7600005-1	MOS		N:0			09-DEC-2007		
	07-022616	HRS/MSC	O/C	N:0			0		
	REF : AMM 28-20-07	AFL		N:0			0		
282012	RIGHT ENGINE RELIEF VALVE								
-	7600005-1	MOS		N:0			09-DEC-2007		
	07-022617	HRS/MSC	O/C	N:0 N:0			09-DEC-2007		
	REF : AMM 28-20-07	AFL	0.0	N:0			0		
282013	FUEL CONTROL RELAY PANE	L							
	6018810-006	MOS		N:0			13-MAR-2009		
	MRP531268-01	HRS/MSC	O/C	N:0			1239.48		
	REF: AMM 28-20-08	AFL		N:0			534		
282015	LEFT WING PILOT VALVE								
	2780610-103	MOS		N:0			09-DEC-2007		
	2291	HRS/MSC	O/C	N:0			0		
	REF : AMM 28-20-09	AFL		N:0			0		
282016	RIGHT WING PILOT VALVE								
	2780610-103	MOS		N:0			09-DEC-2007		
	2283	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-09	AFL		N:0			0		
282017	LEFT WING REFUELING SHUT	OFF VALVE							
	2780614-104	MOS		N:0			09-DEC-2007		
	1465	HRS/MSC	O/C	N:0			0		
	REF: AMM 28-20-10	AFL		N:0			0		
282018	RIGHT WING REFUELING SHU	JTOFF VALVE							
	2780614-104	MOS		N:0			09-DEC-2007		
	1473	HRS/MSC	O/C	N:0			09-DEC-2007		
	REF : AMM 28-20-10	AFL	-	N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

							port Date: 10-SEP-202
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARI EXP	R COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
282019	FUSELAGE PILOT VALVE						
	2780610-103	MOS		N:0		09-DEC-2007	
	2255	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-11	AFL		N:0		0	
282020	FUSELAGE VENT VALVE						
	2780612-104	MOS		N:0		09-DEC-2007	
	906	HRS/MSC	O/C	N:0		0	
	REF: AMM 28-20-12	AFL		N:0		0	
282021	REFUELING CHECK VALVE						
	2780623-102	MOS		N:0		09-DEC-2007	
	737	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-13	AFL		N:0		0	
282022	FUSELAGE REFUELING SHUT	TOFF VALVE					
	2780624-103	MOS		N:0		09-DEC-2007	
	862	HRS/MSC	O/C	N:0		0	
	REF: AMM 28-20-14	AFL		N:0		0	
282023	FUEL SOLENOID VALVE						
	2780613-104	MOS		N:0		09-DEC-2007	
	0810	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-15	AFL		N:0		0	
282024	PRESSURE REFUELING ADAI	PTER					
	2780609-102	MOS		N:0		09-DEC-2007	
	853	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-16	AFL		N:0		0	
282025	LEFT PRECHECK VALVE						
	2780615-103	MOS		N:0		09-DEC-2007	
	1632	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-17	AFL		N:0		0	
282026	RIGHT PRECHECK VALVE						
	2780615-103	MOS		N:0		09-DEC-2007	
	1630	HRS/MSC	O/C	N:0		0	
	REF : AMM 28-20-17	AFL		N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		port Date: 10-SEP-2 MAX
AGIT NO	PART/SERIAL	ONII INTERVAL		AD3	EXP		(ENG/APU) A/C	LIMIT
82027	PRESSURE REFUELING COM	NTROL PANEL						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 28-20-18	AFL	N:0			0		
84001	LEFT INBOARD WING (MT5)	FUEL PROBE						
	FG250A55	MOS	O:0			25-JUL-2016		
	06081149	HRS/MSC O/C	O:0			3709.5		
	REF : AMM 28-40-01	AFL	O:0			2046		
84002	RIGHT INBOARD WING (MT6) FUEL PROBE						
	2326014-12	MOS	N:0			09-DEC-2007		
	2326014-12 06040708	HRS/MSC O/C	N:0 N:0			09-DEC-2007 0		
	REF: AMM 28-40-01	AFL	N:0 N:0			0		
	INCI : / WINN 20 40 01	711 L	14.0					
284003	LEFT OUTBOARD WING (MT	7) FUEL PROBE						
	2326014-9	MOS	N:0			09-DEC-2007		
	06112213	HRS/MSC O/C	N:0			0		
	REF : AMM 28-40-01	AFL	N:0			0		
84004	RIGHT OUTBOARD WING (M	T8) FUEL PROBE						
	2326014-9	MOS	N:0			09-DEC-2007		
	06092202	HRS/MSC O/C	N:0			0		
	REF : AMM 28-40-01	AFL	N:0			0		
284005	LEFT INBOARD WING EXTEN	NSION STA 189 (MT9) FUEL PROB	E					
	2826003-6	MOS	N:0			09-DEC-2007		
	07051519	HRS/MSC O/C	N:0			0		
	REF : AMM 28-40-01	AFL	N:0			0		
284006	RIGHT INBOARD WING EXTE	ENSION STA 189 (MT10) FUEL PRO	DBE					
	2826003-3	MOS	N:0			09-DEC-2007		
	07051521	HRS/MSC O/C	N:0			09-DEC-2007		
	REF : AMM 28-40-01	AFL	N:0			0		
84007	LEFT OUTBOARD WING FXT	ENSION STA 244 (MT11) FUEL PR	OBE					
						00 DEC 2007		
	2826003-3 07011476	MOS HRS/MSC O/C	N:0 N:0			09-DEC-2007 0		
	REF: AMM 28-40-01	AFL	N:0 N:0			0		
	INCL. AIVINI 20-40-01	AI L	IN.U			J		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	JS AEREUS PLATING	om C.A. Operator: AERONAUTI	C SOLUTIONS JUAN	RIGER, S.A DE C.V.	eport Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTER	VAL TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
284008	RIGHT OUTBOARD WING EX	TENSION STA 244 (MT12)	FUEL PROBE			
	2826003-3	MOS	N:0		09-DEC-2007	
	07011480	HRS/MSC O/C	N:0		0	
	REF: AMM 28-40-01	AFL	N:0		0	
284009	FUSELAGE (MT18) FUEL PRO	OBE				
	0118KTU01	MOS	N:0		09-DEC-2007	
	FP028798	HRS/MSC O/C	N:0		0	
	REF : AMM 28-40-01	AFL	N:0		0	
284011	LEFT ENGINE LOW FUEL PR	ESSURE SWITCH				
	7600002-2	MOS	N:0		09-DEC-2007	
	4406	HRS/MSC O/C	N:0		0	
	REF : AMM 28-40-02	AFL	N:0		0	
284012	RIGHT ENGINE LOW FUEL P	RESSURE SWITCH				
	7600002-2	MOS	N:0		09-DEC-2007	
	4415	HRS/MSC O/C	N:0		0	
	REF : AMM 28-40-02	AFL	N:0		0	
284013	FUEL QUANTITY INDICATOR					
	2323-01-1	MOS			19-SEP-2008	
	FM3372	HRS/MSC O/C			857.75	
	REF : AMM 28-40-03	AFL			361	
HAPTER 29	HYDRAULIC POWER					
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES IN THE ENGINE		G HOSES FOR THE LANDING GEAR AI	ND THE HOSE		
		MOS			09-DEC-2007	
		HRS/MSC O/C			0	
TEFLON	REF: GENERIC NO REF	AFL			0	
05-11-00-L2910020	REPLACE PRESSURE AND R	RETURN HYDRAULIC FILT	ER ELEMENTS			
		MOS			24-AUG-2010	
		HRS/MSC O/C			2317.85	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

			i C.A. Operator: AEKONAU	110 3010110113 30	ANKIGER, S.A DE C.V.	Report Date: 10-SEP-203
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERV	AL TIME SINCE	ADJ WA EXF	RR COMPLIANCE NE	
90002	HYDRAULIC PRESSURE REG	GULATOR				
	55950-2D 0463 REF: AMM 29-00-02	MOS HRS/MSC O/C AFL			01-JUN-2011 2785.83 1342	
290003	HYDRAULIC RESERVOIR					
	PN SN-UNKNOWN REF: AMM 29-00-03	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0	
290005	PRESSURE REGULATOR CH	ECK VALVE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN REF: AMM 29-00-05	HRS/MSC O/C AFL	N:0 N:0		0	
291001	LEFT ENGINE HYDRAULIC SI	UPPLY SHUTOFF VALVE				
	AV24B1119B	MOS	N:0		09-DEC-2007	
	07-0425612 REF: AMM 29-10-01	HRS/MSC O/C AFL	N:0 N:0		0	
291002	RIGHT ENGINE HYDRAULIC	SUPPLY SHUTOFF VALVE				
	AV24B1119B	MOS	N:0		09-DEC-2007	
	07-0425609 REF: AMM 29-10-01	HRS/MSC O/C AFL	N:0 N:0		0 0	
291003	LEFT ENGINE DRIVEN HYDR	AULIC PUMP				
	66137	MOS	R:0		05-NOV-2009	
	K0159AB REF : AMM 29-10-02	HRS/MSC O/C AFL	R:0 R:0		1788.18 815	
291004	RIGHT ENGINE DRIVEN HYD	RAULIC PUMP				
	6607066-1	MOS	N:0		09-DEC-2007	
	K0706AB REF : AMM 29-10-02	HRS/MSC O/C AFL	N:0 N:0		0	
291005	HYDRAULIC PRESSURE FILT	ER ASSEMBLY				
	M8815/2A-10	MOS	N:0		09-DEC-2007	
	0365	HRS/MSC O/C	N:0		0	
	REF : AMM 29-10-03	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PLATINUM C.A	Operator: AERONAUTI	IC SULUTIONS JUANI	Report Date: 10-SEP-2	2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP		
291006	HYDRAULIC RETURN FILTER	RASSEMBLY				
	M8815/1A-10	MOS	N:0		09-DEC-2007	
	0378	HRS/MSC O/C	N:0		0	
	REF : AMM 29-10-03	AFL	N:0		0	
291007	HYDRAULIC SYSTEM ACCUM	MULATOR				
	MS28700-3	MOS	N:0		09-DEC-2007	
	8424-19438	HRS/MSC O/C	N:0		0	
	REF : AMM 29-10-04	AFL	N:0		0	
291008	HYDRAULIC THRUST REVER	RSER ACCUMULATOR				
	MS28700-4	MOS	N:0		09-DEC-2007	
	8423-12305	HRS/MSC O/C	N:0		0	
	REF : AMM 29-10-04	AFL	N:0		0	
291010	HYDRAULIC GROUND SERV	ICE PANEL				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
291015	HYDRAULIC RELIEF VENT V	ALVE				
	2380103-1	MOS	N:0		09-DEC-2007	
	06-0829138	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
291020	HYDRAULIC RESERVOIR RE	LIEF VALVE				
	5120T-8TT-20	MOS	N:0		09-DEC-2007	
	07-0621398	HRS/MSC O/C	N:0		0	
	REF : AMM 29-00-08	AFL	N:0		0	
291220	THRUST REVERSER ISOLAT	TON VALVE				
	9555	MOS	N:0		09-DEC-2007	
	355	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-27	AFL	N:0		0	
291225	HYDRAULIC PRESSURE REL	LIEF VALVE				
	1280	MOS	N:0		09-DEC-2007	
	346	HRS/MSC O/C	N:0		0	
	REF: AMM 29-00-08	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE		ARR COMPLIANCE I	
	PART/SERIAL			EX		ENG/APU) A/C LIMIT
92001	AUXILIARY HYDRAULIC PUM	IP				
	MP500	MOS	N:0		09-DEC-2007	
	SN01914	HRS/MSC O/C	N:0		0	
	REF : AMM 29-20-01	AFL	N:0		0	
293001	HYDRAULIC PRESSURE MT	5 TRANSDUCER				
	820-665	MOS	N:0		09-DEC-2007	
	523	HRS/MSC O/C	N:0		0	
	REF : AMM 29-30-01	AFL	N:0		0	
93002	AUXILIARY HYDRAULIC PUN	IP PRESSURE SWITCH				
	730626	MOS	N:0		09-DEC-2007	
	H1489	HRS/MSC O/C	N:0		0	
	REF : AMM 29-30-02	AFL	N:0		0	
293003	HYDRAULIC PRESSURE IND	ICATOR				
	124058-3000	MOS	N:0		09-DEC-2007	
	42426	HRS/MSC O/C	N:0		0	
	REF : AMM 29-30-03	AFL	N:0		0	
293005	LEFT HYDRAULIC PUMP PRI	ESSURE SWITCH				
	730635	MOS	N:0		09-DEC-2007	
	C793	HRS/MSC O/C	N:0		0	
	REF : AMM 29-30-04	AFL	N:0		0	
293006	RIGHT HYDRAULIC PUMP PF	RESSURE SWITCH				
	730635	MOS	N:0		22-FEB-2018	
	E1201	HRS/MSC O/C	N:0		3974.8	
	REF: AMM 29-30-04	AFL	N:0		2358	
293010	HYDRAULIC SYSTEM PRESS	SURE GAUGE				
	S-218-2	MOS	N:0		09-DEC-2007	
	1565	HRS/MSC O/C	N:0		0	
	REF : AMM 29-30-05	AFL	N:0		0	
93015	THRUST REVERSER HYDRA	ULIC PRESSURE GAUGE				
	S-218-2	MOS	N:0		09-DEC-2007	
	1573	HRS/MSC O/C	N:0		03-520-2007	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021

							port Date: 10-SEP-2021			
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT			
CHAPTER 30	ICE AND RAIN PROTECT	TION								
300001	COPILOT ELECTRICAL EQUI	PMENT BOX								
	PN	MOS	N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/C	N:0			0				
	REF : AMM 30-00-01	AFL	N:0			0				
301001	WING ANTI-ICE SHUTOFF AN	ND PRESSURE REGULATING VALV	/E							
	15E51-4	MOS	N:0			09-DEC-2007				
	DUK0042A	HRS/MSC O/C	N:0			0				
	REF : AMM 30-10-01	AFL	N:0			0				
301002	WING RT10 ANTI-ICE TEMPE	RATURE SENSOR								
	0871HJ1	MOS	N:0			11-DEC-2009				
	0147	HRS/MSC O/C	N:0			1860.48				
	REF : AMM 30-10-02	AFL	N:0			835				
301003	WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR									
	PN	MOS	N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/C	N:0			0				
	REF : AMM 30-10-02	AFL	N:0			0				
301004	WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR									
	PN	MOS	N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/C	N:0			0				
	REF : AMM 30-10-02	AFL	N:0			0				
301005	WING OVERHEAT WARNING	THERMOSWITCH								
	PN	MOS	N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/C	N:0			0				
	REF : AMM 30-10-03	AFL	N:0			0				
301006	WING TEMPERATURE INDICA	ATOR								
	820-685	MOS	N:0			09-DEC-2007				
	673	HRS/MSC O/C	N:0			0				
	REF : AMM 30-10-04	AFL	N:0			0				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	LINIT - INTERVAL	TIME CINCE	AD I WARR	Report Date: 10	J-3EP-20
ASK NO	PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
01007	LEFT WING ANTI-ICE BYPAS	S VALVE				
	27441482-13	MOS	N:0		09-DEC-2007	
	7BC21	HRS/MSC O/C	N:0		0	
	REF : AMM 30-10-05	AFL	N:0		0	
01008	RIGHT WING ANTI-ICE BYPA	SS VALVE				
	27441482-13	MOS	N:0		09-DEC-2007	
	7BC22	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
01009	LEFT WING BLEED AIR OVE	RHEAT SWITCH				
	M2001-559	MOS	N:0		09-DEC-2007	
	000283	HRS/MSC O/C	N:0		0	
	REF : AMM 30-10-06	AFL	N:0		0	
01010	RIGHT WING BLEED AIR OVI	ERHEAT SWITCH				
	M2001-559	MOS	N:0		09-DEC-2007	
	000202	HRS/MSC O/C	N:0		0	
	REF: AMM 30-10-06	AFL	N:0		0	
301011	WING UNDERHEAT WARNIN	G SWITCH				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 30-10-07	AFL	N:0		0	
301014	WING ANTI-ICE VALVE					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
301015	LEFT WING ANTI-ICE CHECK	(VALVE				
	60160-10	MOS	N:0		09-DEC-2007	
	7636	HRS/MSC O/C	N:0		0	
	REF : AMM 30-10-08	AFL	N:0		0	
01016	RIGHT WING ANTI-ICE CHEC	CK VALVE				
	60160-10	MOS	N:0		09-DEC-2007	
	7568	HRS/MSC O/C	N:0		0	
	REF : AMM 30-10-08		N:0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICE	OS AEREOS PLATINUM C.A.	Operator. AERONAOTI	IC SOLUTIONS JUANI	Report Date: 10-SEP-202					
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP						
301101	HORIZONTAL STABILIZER A	NTI-ICE CONTROLLER								
	807-1-3 0018006 REF: AMM 30-11-01	MOS HRS/MSC O/C AFL			24-JUN-2008 568.4 246					
301103	LEFT HORIZONTAL STABILIZ	ZER HEAT BLANKET (BOOT)								
	4065-3481 18-66004 REF: AMM 30-11-02	MOS HRS/MSC O/C AFL	N:1 N:0 N:0		05-APR-2018 3981.3 2361					
301104	RIGHT HORIZONTAL STABIL	IZER HEAT BLANKET (BOOT)								
	4065-3481 18-66002 REF: AMM 30-11-02	MOS HRS/MSC O/C AFL	N:1 N:0 N:0		05-APR-2018 3981.3 2361					
301109	CBR9 REMOTE CIRCUIT BRI	EAKER								
	SM600BA40A1 99739 REF: AMM 30-11-03	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0					
301110	CBR10 REMOTE CIRCUIT BREAKER									
	SM600BA40A1 99743 REF: AMM 30-11-03	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0					
301111	CBR11 REMOTE CIRCUIT BF	REAKER								
	SM600BA40A1 99730 REF: AMM 30-11-03	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0					
302101	LEFT NACELLE ANTI-ICE SH	UTOFF VALVE								
	27441482-09 5BC22 REF: AMM 30-21-01	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0					
302102	RIGHT NACELLE ANTI-ICE S	HUTOFF VALVE								
	27441482-09 5BC18 REF: AMM 30-21-01	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	OWIIEI. SERVICIO	OS AEREOS PLATINUM C.A.	operator. ALKONAOTI	C SOLUTIONS JOAN	Report Date: 10-SEP	-202
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP		
02103	LEFT NACELLE ANTI-ICE PR	ESSURE SWITCH				
	7600020-1	MOS	N:0		09-DEC-2007	
	4896TW	HRS/MSC O/C	N:0		0	
	REF : AMM 30-21-02	AFL	N:0		0	
02104	RIGHT NACELLE ANTI-ICE P	RESSURE SWITCH				
	7600020-1	MOS	N:0		09-DEC-2007	
	4895TW	HRS/MSC O/C	N:0		0	
	REF : AMM 30-21-02	AFL	N:0		0	
03001	LEFT PITOT HEAT MONITOR	ļ-				
	76248-2	MOS	N:0		09-DEC-2007	
	3726	HRS/MSC O/C	N:0		0	
	REF : AMM 30-30-01	AFL	N:0		0	
03002	RIGHT PITOT HEAT MONITO	R-				
	76248-2	MOS	N:0		09-DEC-2007	
	3727	HRS/MSC O/C	N:0		0	
	REF : AMM 30-30-01	AFL	N:0		0	
303003	STANDBY PITOT HEAT MON	ITOR-				
	76248-2	MOS	N:0		09-DEC-2007	
	3728	HRS/MSC O/C	N:0		0	
	REF : AMM 30-30-01	AFL	N:0		0	
04001	WINDSHIELD ANTI-ICE SHUT	ΓOFF VALVE				
	6600201-1	MOS	O:0		11-AUG-2015	
	2540	HRS/MSC O/C	O:0		3533.1	
	REF : AMM 30-40-01	AFL	O:0		1882	
04002	WINDSHIELD ANTI-ICE MOD	ULATING VALVE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 30-40-02	AFL	N:0		0	
04003	WINDSHIELD ANTI-ICE RAM	AIR MODULATING VALVE				
	27441500	MOS	N:0		09-DEC-2007	
	3BC2	HRS/MSC O/C	N:0		0	
	REF : AMM 30-40-03	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owller: SERVICIO	OS AEREOS PLATINUM C.A.	Operator. ALKONAOTI	C SOLUTIONS JUANI	Report Date: 10-SEP-20					
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP						
304004	WINDSHIELD ANTI-ICE HEAT	Γ EXCHANGER								
	5F295-001	MOS	N:0		09-DEC-2007					
	1148	HRS/MSC O/C	N:0		0					
	REF : AMM 30-40-04	AFL	N:0		0					
304005	WINDSHIELD ANTI-ICE TEMP	PERATURE SENSOR								
	27431501-09	MOS	N:0		09-DEC-2007					
	12BB26	HRS/MSC O/C	N:0		0					
	REF : AMM 30-40-05	AFL	N:0		0					
04007	LEFT WINDSHIELD ANTI-ICE	LOW-LIMIT (S83) THERMOSWITCI	-1							
	27241287-12	MOS	N:0		09-DEC-2007					
	6BB10	HRS/MSC O/C	N:0		0					
	REF : AMM 30-40-07	AFL	N:0		0					
04008	RIGHT WINDSHIELD ANTI-IC	E LOW-LIMIT (S82) THERMOSWITC	СН							
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 30-40-07	AFL	N:0		0					
304009	LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH									
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 30-40-07	AFL	N:0		0					
304010	RIGHT WINDSHIELD ANTI-IC	E HIGH-LIMIT (S84) THERMOSWIT	СН							
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 30-40-07	AFL	N:0		0					
04101	ALCOHOL SUPPLY TANK AS	SEMBLY								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 30-41-01	AFL	N:0		0					
04102	ALCOHOL ANTI-ICE FLOAT S	SWITCH								
	L14F-74	MOS	N:0		14-SEP-2012					
	1056	HRS/MSC O/C	N:0		3040.6					
	REF: AMM 30-41-02	AFL	N:0		1503					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				operator: AEROHAOTI				Rep	ort Date: 10-SEP-202:		
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT		
304104	ALCOHOL PRESSURE RELIE	F VALVE									
	4P152-4	MOS		N:0			09-DEC-2007				
	906	HRS/MSC	O/C	N:0			0				
	REF: AMM 30-41-04	AFL		N:0			0				
304105	ANTI-ICE THREE-WAY SHUT	OFF VALVE									
	56360-1	MOS		N:0			09-DEC-2007				
	1790	HRS/MSC	O/C	N:0			0				
	REF : AMM 30-41-05	AFL		N:0			0				
304106	ALCOHOL ANTI-ICE SHUTOF	ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE									
	56410	MOS		N:0			09-DEC-2007				
	1778A	HRS/MSC	O/C	N:0			0				
	REF: AMM 30-41-06	AFL		N:0			0				
304203	WINDSHIELD DEFOG RELAY	BOX									
	6018505-002	MOS		R:0			30-JAN-2008				
	289065	HRS/MSC	O/C	R:0			173.1				
	REF : AMM 30-42-03	AFL		R:0			75				
308001	LEFT ICE DETECT LAMP										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0				
	REF: AMM 30-80-01	AFL		N:0			0				
308002	RIGHT ICE DETECT LAMP										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0				
	REF: AMM 30-80-01	AFL		N:0			0				
U3020001A (s)	INSPECT NO. 1 ENGINE NAC OTHER DEFORMATION	ELLE INLET BULK	HEAD, PLUMBING	G, AND SHUTOFF VALVE FOR	R SECURITY, C	RACKS, OR	PKG				
	PKG 29	MOS					12-DEC-2011				
		HRS/MSC	3600 +50				3011.9				
	REF : GENERIC NO REF	AFL					1487				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR COMPLIANCE NEXT DUE MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT U3020001B (s) INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR PKG OTHER DEFORMATION PKG 30 MOS 12-DEC-2011 HRS/MSC 3600 +50 3011.9 **REF:** GENERIC NO REF AFL 1487

HAPTER 31	INDICATING/RECORDII	NG SYSTEMS							
311006	TEST SWITCH PANEL ASS	EMBLY							
	6025180056-001	MOS	N:0	16-JUL-2009					
	N/A	HRS/MSC O/C	N:0	1515.62					
	REF : AMM 31-10-06	AFL	N:0	663					
311007	PILOT DISPLAY CONTROL	(DCP) PANEL							
	822-2117-202	MOS	N:0	09-DEC-2007					
	2KJOM	HRS/MSC O/C	N:0	0					
	REF : AMM 31-10-07	AFL	N:0	0					
311008	COPILOT DISPLAY CONTROL (DCP) PANEL								
3555	822-2117-202	MOS	N:0	24-JUN-2011					
	822-2117-202 462PX	MOS HRS/MSC O/C	N:0 N:0	24-JUN-2011 2844.73					
	REF: AMM 31-10-07	AFL	N:0	1382					
	11217,11111101	/ u _							
311009	LEFT CURSOR CONTROL (CCP) PANEL								
	822-1746-002	MOS	N:0	09-DEC-2007					
	227PK	HRS/MSC O/C	N:0	0					
	REF : AMM 31-10-09	AFL	N:0	0					
311010	RIGHT CURSOR CONTROL	_ (CCP) PANEL							
	822-1746-002	MOS	N:0	09-DEC-2007					
	2715R	HRS/MSC O/C	N:0	0					
	REF : AMM 31-10-09	AFL	N:0	0					
312001	PILOT CREW CLOCK								
	M877	MOS	N:0	09-DEC-2007					
	17887	HRS/MSC O/C	N:0	09-50-2007					
	REF: AMM 31-21-01	AFL	N:0	0					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

									ort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
12002	COPILOT CREW CLOCK								
	M877	MOS		N:0			12-MAR-2021		
	25463	HRS/MSC	O/C	N:0			4286.9		
	REF : AMM 31-21-01	AFL		N:0			2754		
12011	REPLACE PILOT DIGITAL CL	OCK BATTERY							
	PN	MOS	24	N:0			12-MAR-2021	12-MAR-2023	
	SN-UNKNOWN	HRS/MSC		N:0			4286.9		
	REF: See Workcard	AFL		N:0			2754		
312012	REPLACE COPILOT DIGITAL	CLOCK BATTER	Υ						
	PN	MOS	24	N:0			12-MAR-2021	12-MAR-2023	
	SN-UNKNOWN	HRS/MSC		N:0			4286.9		
	REF: See Workcard	AFL		N:0			2754		
313001	FLIGHT DATA (FDR) RECORI	DER							
	2100-2042-00	MOS		N:0			09-DEC-2007		
	000447423	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
313018	FDR INERTIA SWITCH								
	3L0-453/8	MOS		N:0			09-DEC-2007		
	82435	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
313103	MULTI-AXIAL ACCELEROME	TER							
	3001-01-111-2	MOS		N:0			09-DEC-2007		
	0907-11571	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
314002	IAPS CARD CAGE								
	822-2018-001	MOS		N:0			09-DEC-2007		
	2KCRT	HRS/MSC	O/C	N:0			0		
	REF : AMM 31-40-02	AFL		N:0			0		
314004	IAPS ENVIRONMENTAL (IEC)) CONTROLLER							
	822-1167-001	MOS		N:0			09-DEC-2007		
	2MTMD	HRS/MSC	O/C	N:0			0		
	REF : AMM 31-40-04	AFL		N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		ort Date: 10-SEP-20 MAX
	PART/SERIAL			EXP	(ENG/APU) A/C	LIMIT
14011	1A PWR-851A POWER SUPP	LY CARD				
	822-1137-001	MOS	N:0		09-DEC-2007	
	2MRNR	HRS/MSC O/C	N:0		0	
	REF: AMM 31-40-01	AFL	N:0		0	
314012	2A PWR-851A POWER SUPP	LY CARD				
	822-1137-001	MOS	N:0		09-DEC-2007	
	2MRPC	HRS/MSC O/C	N:0		0	
	REF : AMM 31-40-01	AFL	N:0		0	
14013	1B PWR-851A POWER SUPP	LY CARD				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 31-40-01	AFL	N:0		0	
14014	2B PWR-851A POWER SUPP	LY CARD				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 31-40-01	AFL	N:0		0	
314021	1A FLIGHT CONTROL CARD					
	822-1484-201	MOS	N:0		09-DEC-2007	
	2MTOC	HRS/MSC O/C	N:0		0	
	REF : AMM 31-40-01	AFL	N:0		0	
314022	2A FLIGHT CONTROL CARD					
	822-1484-201	MOS	N:0		09-DEC-2007	
	2MTOD	HRS/MSC O/C	N:0		0	
	REF: AMM 31-40-01	AFL	N:0		0	
314031	1B FLIGHT MANAGEMENT -	FMC 851C CARD				
	822-0891-027	MOS	O:0		24-JAN-2019	
	285PJ	HRS/MSC O/C	O:0		4067	
	REF: AMM 31-40-01	AFL	O:0		2472	
314032	2B FLIGHT MANAGEMENT -	FMC 851C CARD				
	822-0891-027	MOS	O:0		24-JAN-2019	
	48CGY	HRS/MSC O/C	O:0		4067	
	REF : AMM 31-40-01	AFL	O:0		2472	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021										
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP						
314033	1B FLIGHT MANAGEMENT - I	FMC 852C CARD								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 31-40-01	AFL	N:0		0					
314034	2B FLIGHT MANAGEMENT - I	FMC 852C CARD								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 31-40-01	AFL	N:0		0					
314041	1A INPUT/OUTPUT CONCEN	TRATOR CARD								
	822-1361-321	MOS	N:0		09-DEC-2007					
	2MWYT	HRS/MSC O/C	N:0		0					
	REF: See Workcard	AFL	N:0		0					
14042	2A INPUT/OUTPUT CONCEN	TRATOR CARD								
	822-1361-321	MOS	N:0		18-JUN-2009					
	3B81B	HRS/MSC O/C	N:0		1442.57					
	REF: See Workcard	AFL	N:0		628					
314043	1B INPUT/OUTPUT CONCENTRATOR CARD									
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF: See Workcard	AFL	N:0		0					
314044	2B INPUT/OUTPUT CONCEN	TRATOR CARD								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF: See Workcard	AFL	N:0		0					
314047	NO. 1 CONFIGURATION STR	APPING (CSU) UNIT								
	822-1363-002	MOS	N:0		09-DEC-2007					
	2MRWV	HRS/MSC O/C	N:0		0					
	REF : AMM 31-40-05	AFL	N:0		0					
314048	NO. 2 CONFIGURATION STR	APPING (CSU) UNIT								
	822-1363-002	MOS	N:0		09-DEC-2007					
	2MRWN	HRS/MSC O/C	N:0		0					
	REF: AMM 31-40-05	AFL	N:0		0					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

FACIC NO	TAOK DESCRIPTION	LINUT	INITEDVA	TIME OWNER	ABL	WARR	Report Date: 10-SEF	-202
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
14101	DATA ACQUISITION UNIT							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: AMM 31-41-01	AFL		N:0			0	
14110	MINI-FLIGHT DATA ACQUISIT	TION (MFDAU) UN	IT					
	2231230-20	MOS					12-DEC-2011	
	01732	HRS/MSC	O/C				3011.9	
	REF : AMM 31-41-01	AFL					1487	
15101	AURAL WARNING CONTROL	UNIT						
	883-1	MOS		N:0			09-DEC-2007	
	2269	HRS/MSC	O/C	N:0			0	
	REF : AMM 31-51-01	AFL		N:0			0	
315102	TONE GENERATOR							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 31-51-02	AFL		N:0			0	
315103	AURAL WARNING MIXER							
	1882-1	MOS		N:0			09-DEC-2007	
	826	HRS/MSC	O/C	N:0			0	
	REF : AMM 31-51-03	AFL		N:0			0	
315201	GLARESHIELD ANNUNCIATO	R PANEL						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 31-52-01	AFL		N:0			0	
15203	MASTER CAUTION/WARNING	G TRIGGER UNIT	ASSEMBLY					
	828-1-18	MOS		N:0			09-DEC-2007	
	207270097	HRS/MSC	O/C	N:0			0	
	REF : AMM 31-52-03	AFL		N:0			0	
16001	PILOT EFD-871 ELECTRONIC	FLIGHT DISPLAY	·					
	822-1084-020	MOS		N:0			09-DEC-2007	
	2K7YJ	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		port Date: 10-SEP-20 MAX
	PART/SERIAL	- INTERVAL		EXP	(ENG/APU) A/C	LIMIT
16002	COPILOT EFD-871 ELECTRON	NIC FLIGHT DISPLAY				
	822-1084-020	MOS	N:0		09-DEC-2007	
	2G88F	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
316003	MULTIFUNCTION DISPLAY					
	822-1753-020	MOS	O:0		26-JAN-2016	
	49T0M	HRS/MSC O/C	O:0		3583.3	
	REF : AMM 31-60-01	AFL	O:0		1916	
316004	MULTIFUNCTION DISPLAY					
	822-1753-020	MOS	O:0		26-JAN-2016	
	2K82P	HRS/MSC O/C	O:0		3583.3	
	REF : AMM 31-60-01	AFL	O:0		1916	
316005	PILOT EFIS CONTROL PANEL					
	822-1485-562	MOS	N:0		09-DEC-2007	
	273LW	HRS/MSC O/C	N:0		0	
	REF: AMM 31-60-02	AFL	N:0		0	
316006	COPILOT EFIS CONTROL PAI	NEL				
	822-1485-562	MOS	N:0		30-JAN-2008	
	2CNVM	HRS/MSC O/C	N:0		173.1	
	REF : AMM 31-60-02	AFL	N:0		75	
316011	NO. 1 DISPLAY IMT-871 TRAY					
	822-1140-101	MOS	N:0		09-DEC-2007	
	2KW3C	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
316012	NO. 2 DISPLAY IMT-871 TRAY					
	822-1140-101	MOS	N:0		09-DEC-2007	
	2KW3D	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
316013	NO. 3 DISPLAY IMT-871 TRAY					
	822-1140-101	MOS	N:0		09-DEC-2007	
	2CVNH	HRS/MSC O/C	N:0		0	
	REF : GENERIC NO REF	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	oort Date: 10-SEP-20 MAX LIMIT
316014	NO. 4 DISPLAY IMT-871 TRAY	,				(ENGIAPO) AIC	LIMIT
	822-1140-101	MOS		N:0		09-DEC-2007	
	2CKWX	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
316101	SENSOR DISPLAY UNIT						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 31-61-01	AFL		N:0		0	
316102	SENSOR DISPLAY DRIVER U	NIT					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 31-61-02	AFL		N:0		0	
316201	NO. 1 FILE SERVER (FSU) UN	IIT					
	822-1543-101	MOS		N:0		09-DEC-2007	
	2JOKC	HRS/MSC	O/C	N:0		0	
	REF : AMM 31-62-01	AFL		N:0		0	
316202	NO. 2 FILE SERVER (FSU) UN	IIT					
	822-1543-101	MOS				06-OCT-2008	
	2G3TW	HRS/MSC	O/C			915.43	
	REF : AMM 31-62-01	AFL				386	
316203	NO. 1 FILE SERVER EXTERN	AL COMPENSAT	ON UNIT (ECU-300	0)			
	822-1200-998	MOS		N:0		09-DEC-2007	
	2KKBP	HRS/MSC	O/C	N:0		0	
	REF : AMM 31-62-03	AFL		N:0		0	
316204	NO. 2 FILE SERVER EXTERN	AL COMPENSAT	ON UNIT (ECU-300	0)			
	822-1200-998	MOS		N:0		09-DEC-2007	
	2V1XM	HRS/MSC	O/C	N:0		0	
	REF : AMM 31-62-03	AFL		N:0		0	
316301	MAINTENANCE WARNING PA	NEL ASSEMBLY					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 31-63-01	AFL		N:0		0	



LIFE LIMIT

Status Report

LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 317021 FDR UNDERWATER LOCATOR (ULB) BEACON DK120 MOS 02-DEC-2009 SC16622 HRS/MSC O/C 1860.48 835 **REF:** AMM 25-63-00 AFL 317021A CLEAN/FUNCTIONAL TEST FDR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY -39 DK120 MOS 24 +14d/-14d 06-MAR-2020 26-JAN-2022 09-FEB-2022 SC16622 HRS/MSC 4262.1 **REF:** AMM 25-63-00 AFL 2723 REPLACE FDR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 317021B DK120 MOS 16-JUL-2017 30-APR-2023 M SC16622 HRS/MSC DUE 3849.9 **REF: GENERIC NO REF** AFL 2207 CHAPTER 32 **LANDING GEAR** 05-11-00-E3211066 REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4) MOS 09-DEC-2007 HRS/MSC 0 **REF:** AMM 32-32-01 AFL 6000 +25/-25 0 6000 6025 05-11-00-E3211084L REPLACE LEFT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*) MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT REF:** AMM 32-11-00 **AFL** 20000 0 20000 REPLACE RIGHT * MLG ACTUATOR ATTACH PIN (5441101) (AWL*) 05-11-00-E3211084R MOS 09-DEC-2007 HRS/MSC 0 **LIFE LIMIT REF:** AMM 32-11-00 **AFL** 20000 0 20000 05-11-00-E3211092L REPLACE LEFT * MLG UPPER BEARING (7600839) (AWL*) MOS 09-DEC-2007 HRS/MSC 0

6000

AFL

REF: AMM 32-11-00

6000

0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	US AEREUS F	LATINOM C.A.	Operator: AEKONAUI	IC SOLUTIO	NS JUANN	IGER, S.A DE C	v. Rei	ort Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
05-11-00-E3211092R	REPLACE RIGHT * MLG UPP	ER BEARING (76	600839) (AWL*)						
		MOS					09-DEC-2007		
LIFE LIMIT	REF: AMM 32-11-00	HRS/MSC AFL	6000				0 0	6000	
	TELL TANNO DE TELO	7 11 2							
05-11-00-E3211093L	REPLACE LEFT * MLG LOWE	ER BEARING (604	41105) (AWL*)						
		MOS					09-DEC-2007		
LIFE LIMIT	DEE: AMM 22 11 00	HRS/MSC AFL	6000				0 0	6000	
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0	6000	
05-11-00-E3211093R	REPLACE RIGHT * MLG LOW	/ER BEARING (6	041105) (AWL*)						
		MOS					09-DEC-2007		
		HRS/MSC					0		
LIFE LIMIT	REF: AMM 32-11-00	AFL	6000				0	6000	
05-11-00-G3210003	REPLACE HYDRAULIC HOSE DOOR ACTUATORS, AND TH				TUATORS, MAIN	I GEAR			
		MOS					09-DEC-2007		
		HRS/MSC	O/C				0		
TEFLON	REF: GENERIC NO REF	AFL					0		
05-11-00-G3233007	REPLACE EMERGENCY AIR GEAR EMERGENCY BLOWD				ALL EXTENSION	N, LANDING			
		MOS					09-DEC-2007		
		HRS/MSC	O/C				0		
TEFLON	REF: GENERIC NO REF	AFL					0		
05-11-00-G3243040	REPLACE HYDRAULIC BRAK	Œ HOSE ASSEM	IBLIES LOCATED ON	N THE STRUT AND IN WHEE	EL WELL AREA				
		MOS					09-DEC-2007		
		HRS/MSC	O/C				0		
TEFLON	REF: GENERIC NO REF	AFL					0		
05-11-00-U3211091L	REPLACE LEFT * MLG UPPE	R BEARING RET	ENTION PIN (60411	10-002 AND SUBSEQUENT)	(AWL*)				
		MOS					09-DEC-2007		
		HRS/MSC					0		
LIFE LIMIT	REF : AMM 32-11-00	AFL	6000				0	6000	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				operator: AERONAUTI		INS JUANE		Re	port Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
-11-00-U3211091R	REPLACE RIGHT * MLG UPP	ER BEARING RE	TENTION PIN (6041	110-002 AND SUBSEQUENT	(AWL*)				
		MOS					09-DEC-2007		
		HRS/MSC					0		
IFE LIMIT	REF: AMM 32-11-00	AFL	6000				0	6000	
321001	* LEFT MAIN LANDING GEAR	R STRUT ASSEME	BLY (AWL*)						
	6041000V3-001	MOS		N:0			09-DEC-2007		
	033	HRS/MSC		N:0			0		
IFE LIMIT	REF: AMM 32-11-00	AFL	16500	N:0			0	16500	
21002	* RIGHT MAIN LANDING GEA	IR STRUT ASSEN	MBLY (AWL*)						
	6041000V3-002	MOS	•	N:0			09-DEC-2007		
	034	HRS/MSC		N:0			0		
LIFE LIMIT	REF : AMM 32-11-00	AFL	16500	N:0			0	16500	
321003	* LEFT MAIN GEAR SHOCK S	STRUT UPPER TO	ORQUE ARM (AWL [*]	*)					
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321004	* RIGHT MAIN GEAR SHOCK	STRUT UPPER	TORQUE ARM (AW	L*)					
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF: AMM 32-11-01	AFL	6000	N:0			0	6000	
321005	* LEFT MAIN GEAR SHOCK S	STRUT LOWER TO	ORQUE ARM (AWL	*)					
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
AIRWORTHINESS	REF : AMM 32-11-01	AFL	6000	N:0			0	6000	
321006	* RIGHT MAIN GEAR SHOCK	STRUT LOWER	TORQUE ARM (AW	/L*)					
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
IRWORTHINESS	REF : AMM 32-11-01	AFL	6000	N:0			0	6000	
21501	LEFT HYDRAULIC, GEAR RE	TRACTION REST	FRICTOR						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0			09-DEC-2007		
	REF: AMM 32-31-04	AFL	J. J	N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				AD 1		Report Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVA	AL TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/G	
21502	RIGHT HYDRAULIC, GEAR R	ETRACTION RESTRICTOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 32-31-04	AFL	N:0		0	
321511	LEFT HYDRAULIC, GEAR EX	TENSION RESTRICTOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 32-31-04	AFL	N:0		0	
321512	RIGHT HYDRAULIC, GEAR E	XTENSION RESTRICTOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 32-31-04	AFL	N:0		0	
321515	LEFT HYDRAULIC RESTRICT	ror				
	1R3665-035	MOS	N:0		09-DEC-2007	
	D2244	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
321516	RIGHT HYDRAULIC RESTRIC	CTOR				
	1R3665-059	MOS	N:0		09-DEC-2007	
	D2245	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
322001	* NOSE GEAR STRUT ASSEM	ЛВLY (AWL*)				
	2342100-034	MOS	N:0		09-DEC-2007	
	220	HRS/MSC	N:0		0	
IFE LIMIT	REF : AMM 32-21-00	AFL 10000	N:0		0 10000	0
322002	NOSE LANDING GEAR & STE	EERING ASSEMBLY STRUT				
	2342003-101	MOS	N:0		09-DEC-2007	
	220	HRS/MSC	N:0		0	
IFE LIMIT	REF : AMM 32-21-00	AFL 10000	N:0		0 10000	0
323019	LEFT MAIN LANDING GEAR S	SQUAT SWITCH				
	426EN9-8	MOS			01-JUN-2011	
	SN-UNKNOWN	HRS/MSC O/C			2785.83	
	REF: AMM 32-30-03	AFL			1342	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owiler: SERVICIO			operator: AERONAUTI	C 30L0110	IND JUNIN		Re	oort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
3020	RIGHT MAIN LANDING GEAR	SQUAT SWITCH							
	426EN9-8 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C				01-JUN-2011 2785.83 1342		
323031	* LEFT MAIN LANDING GEAR	RACTUATOR (AWI	L*)						
	6600264-008	MOS		O:0			06-MAR-2020		
IEE I MAIT	1213A	HRS/MSC	20000	O:0			4262.1	2	0
LIFE LIMIT	REF : AMM 32-31-01	AFL	20000				2723	?	<i>'</i>
323032	* RIGHT MAIN LANDING GEA	R ACTUATOR (AV	VL*)						
	6600264-008	MOS		N:21 R:0			07-DEC-2012		
	1346	HRS/MSC		N:491 R:0			3077.6		
LIFE LIMIT	REF : AMM 32-31-01	AFL	20000	N:303 R:0			1527	21224	
323036	LEFT MAIN LANDING GEAR A	ACTUATOR ATTAC	CH PIN						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF:	AFL	20000	N:0			0	20000	
323037	RIGHT MAIN LANDING GEAR	R ACTUATOR ATTA	ACH PIN						
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC		N:0			0		
LIFE LIMIT	REF:	AFL	20000	N:0			0	20000	
323043	LEFT MAIN LANDING GEAR I	NBOARD GEAR DO	OOR ACTUATOR						
	95919-4	MOS		N:0			09-DEC-2007		
	0626	HRS/MSC	O/C	N:0			0		
	REF : AMM 32-31-03	AFL		N:0			0		
323044	RIGHT MAIN LANDING GEAR	R INBOARD GEAR [DOOR ACTUATOR						
	95919-4	MOS		N:0			09-DEC-2007		
	0625	HRS/MSC	O/C	N:0			0		
	REF : AMM 32-31-03	AFL		N:0			0		
323052	LANDING GEAR CONTROL P	ANEL ASSEMBLY							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : AMM 32-30-06	AFL		N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

	Owner: SERVICIO			perator: AERONAUTI	C 30L0 110	MIAOL CI		Re	port Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	TERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
3055	LEFT UPLOCK, MAIN LANDIN	IG GEAR INBOARD D	OOR ACTUATOR	₹					
	2417016-1	MOS		N:0			24-DEC-2012		
	6761	HRS/MSC O/0	C	N:0					
	REF: AMM 32-31-02	AFL		N:0					
23056	RIGHT UPLOCK, MAIN LANDI	NG GEAR INBOARD	DOOR ACTUATO)R					
	2417016-1	MOS					19-JUN-2013		
	6817	HRS/MSC O/0	C				3217.3		
	REF: AMM 32-31-02	AFL					1608		
23057	LEFT UPLOCK, MAIN LANDIN	IG GEAR INBOARD D	OOR FREEFALL	ACTUATOR					
	2417016-1	MOS		N:0			09-DEC-2007		
	6090	HRS/MSC O/0	С	N:0			0		
	REF : AMM 32-33-04	AFL		N:0			0		
323058	RIGHT UPLOCK, MAIN LANDI	NG GEAR INBOARD	DOOR FREEFAL	L ACTUATOR					
	2417016-1	MOS					19-JUN-2013		
	6783	HRS/MSC O/0	C				3217.3		
	REF : AMM 32-33-04	AFL					1608		
23073	* NOSE LANDING GEAR ACT	UATOR (AWL*)							
	2317100-017	MOS					19-SEP-2008		
	KI0157	HRS/MSC		N:1100			857.75		
IFE LIMIT	REF : AMM 32-32-01	AFL 100	000	N:595			361	9766	
23079	NOSE LANDING GEAR UPLO	CK ACTUATOR							
	2417016-1	MOS		N:0			09-DEC-2007		
	6088	HRS/MSC O/0	C	N:0			0		
	REF : AMM 32-32-02	AFL		N:0			0		
23080	UPLOCK, NOSE LANDING GE	EAR FREEFALL ACTU	JATOR						
	2417016-1	MOS		N:0			09-DEC-2007		
	6087	HRS/MSC O/0	С	N:0			0		
	REF : AMM 32-33-05	AFL		N:0			0		
23098	GEAR DOOR CONTROL VALV	/E							
23098				NO			09-DEC-2007		
323098	6600361-1	MOS		N:0			09-DEC-2001		
323098	6600361-1 1418	MOS HRS/MSC O/0	C	N:0 N:0			09-DEC-2007 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

EACK NO	TACK DESCRIPTION	LINUT	INTERVAL	TIME OWNER	AD I - WARR	COMPLIANCE NEVER	Report Date: 10-SEP-20			
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DU (ENG/APU)				
23099	SELECT, LANDING GEAR VA	LVE								
	48C48641	MOS		N:0		09-DEC-2007				
	0046T	HRS/MSC	O/C	N:0		0				
	REF: AMM 32-30-05	AFL		N:0		0				
23105	NOSE LANDING GEAR SHUT	TLE VALVE								
	2SV0614	MOS		N:0		09-DEC-2007				
	4638	HRS/MSC	O/C	N:0		0				
	REF: GENERIC NO REF	AFL		N:0		0				
323110	NOSE LANDING GEAR UPLA	TCH SHUTTLE V	'ALVE							
	2SV0413	MOS		N:0		09-DEC-2007				
	D18514	HRS/MSC	O/C	N:0		0				
	REF: GENERIC NO REF	AFL		N:0		0				
323205	LEFT MAIN LANDING GEAR I	EXTEND SHUTTI	LE VALVE							
	95930	MOS		N:0		09-DEC-2007				
	1255	HRS/MSC	O/C	N:0		0				
	REF : AMM 32-00-01	AFL		N:0		0				
323210	RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE									
	95930	MOS		N:0		09-DEC-2007				
	1254	HRS/MSC	O/C	N:0		0				
	REF: AMM 32-00-01	AFL		N:0		0				
323222	* LEFT MAIN LANDING GEAF	ACTUATOR AT	ΓACH PILLAR (AWL	*)						
	PN	MOS	•	N:0		09-DEC-2007				
	SN-UNKNOWN	HRS/MSC		N:0		0				
IFE LIMIT	REF : AMM 32-31-05	AFL	20000	N:0			000			
323223	* RIGHT MAIN LANDING GEA	R ACTUATOR A	TTACH PILLAR (AW	L*)						
	PN	MOS		N:0		09-DEC-2007				
	SN-UNKNOWN	HRS/MSC		N:0		0				
IFE LIMIT	REF: AMM 32-31-05	AFL	20000	N:0		0 200	000			
23305	LEFT MAIN LANDING GEAR I	DOOR SHUTTLE	VALVE							
	2SV0413	MOS		N:0		09-DEC-2007				
	D18519	HRS/MSC	O/C	N:0		0				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ '	WARR	COMPLIANCE		oort Date: 10-SEP-2 MAX	
ASK NO	PART/SERIAL	ONII INTERVAL	TIME SINCE		EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT	
3310	RIGHT MAIN LANDING GEAR	DOOR SHUTTLE VALVE							
	2SV0413	MOS	N:0			09-DEC-2007			
	D18504	HRS/MSC O/C	N:0			0			
	REF : AMM 32-00-01	AFL	N:0			0			
23315	LEFT MAIN LANDING GEAR [DOOR UPLATCH SHUTTLE VALVE							
	92465	MOS	N:0			09-DEC-2007			
	4636	HRS/MSC O/C	N:0			0			
	REF : AMM 32-00-01	AFL	N:0			0			
23320	RIGHT MAIN LANDING GEAR	DOOR UPLATCH SHUTTLE VALVI	E						
	92465	MOS	N:0			09-DEC-2007			
	4269	HRS/MSC O/C	N:0			0			
	REF : AMM 32-00-01	AFL	N:0			0			
323401	AFT EMERGENCY GEAR BLO	DWDOWN EXTENSION VALVE							
	53620-6	MOS	N:0			09-DEC-2007			
	2415	HRS/MSC O/C	N:0			0			
	REF: AMM 32-33-02	AFL	N:0			0			
23402	FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE								
	53620-6	MOS	N:0			09-DEC-2007			
	2424	HRS/MSC O/C	N:0			0			
	REF : AMM 32-33-03	AFL	N:0			0			
23405	LEFT CHECK, FREEFALL VAI	LVE							
	92465	MOS	N:0			09-DEC-2007			
	4591	HRS/MSC O/C	N:0			0			
	REF : AMM 32-33-01	AFL	N:0			0			
23406	RIGHT CHECK, FREEFALL V	ALVE							
	7600833-001	MOS	N:0			09-DEC-2007			
	0341	HRS/MSC O/C	N:0			0			
	REF : AMM 32-33-01	AFL	N:0			0			
23409	UPPER EMERGENCY GEAR	EXTENSION RESTRICTOR							
	6R7742S0135	MOS	N:0			09-DEC-2007			
	4792	HRS/MSC O/C	N:0			09-01-2007			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		oort Date: 10-SEP-20 MAX			
	PART/SERIAL			EXP	(ENG/APU) A/C	LIMIT			
23410	LOWER EMERGENCY GEAR	EXTENSION RESTRICTOR							
	6R7742S0135	MOS	N:0		09-DEC-2007				
	4794	HRS/MSC O/C	N:0		0				
	REF: GENERIC NO REF	AFL	N:0		0				
323430	NO. 1 EMERGENCY AIR BLO	WDOWN SHUTTLE VALVE							
	PN	MOS	N:0		09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/C	N:0		0				
	REF : AMM 32-00-01	AFL	N:0		0				
324001	NOSE TIRE								
	184F10-2	MOS	N:0		12-MAR-2021				
	03430618	HRS/MSC O/C	N:0		4286.9				
	REF : AMM 32-40-01	AFL	N:0		2754				
324007	ASSEMBLY, NOSE WHEEL								
	9544207-4	MOS	O:116 R:73		24-JAN-2019				
	AUG07-10465	HRS/MSC O/C	R:4067		4067				
	REF : AMM 32-40-01	AFL	R:2472		2472				
324013	NO. 1 MAIN LANDING GEAR TIRE								
	178K43-1	MOS	N:0		12-MAR-2021				
	02660513	HRS/MSC O/C	N:0		4286.9				
	REF : AMM 32-40-02	AFL	N:0		2754				
324014	NO. 2 MAIN LANDING GEAR	TIRE							
	178K43-1	MOS	N:0		12-MAR-2021				
	02670512	HRS/MSC O/C	N:0		4286.9				
	REF: AMM 32-40-02	AFL	N:0		2754				
324015	NO. 3 MAIN LANDING GEAR	TIRE							
	178K43-1	MOS	N:0		12-MAR-2021				
	02670523	HRS/MSC O/C	N:0		4286.9				
	REF: AMM 32-40-02	AFL	N:0		2754				
324016	NO. 4 MAIN LANDING GEAR	TIRE							
	178K43-1	MOS	N:0		12-MAR-2021				
	02680572	HRS/MSC O/C	N:0		4286.9				
	REF: AMM 32-40-02	AFL	N:0		2754				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	US AEREUS F	LATINUM C.A.	Operator: AERONAUTI	C SOLUTIO	NS JUANK	IGER, S.A DE C.V. Renor	t Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE	MAX LIMIT
324037	NO. 1 MAIN LANDING GEAR	WHEEL						
	6600330-20 JAN08-2749 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	R:16 R:122.2 R:105			26-FEB-2015 3430.9 1765	
324037A	NDT INSPECT NO. 1 MAIN LA	ANDING GEAR W	VHEEL					
	6600330-20 JAN08-2749 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C				12-MAR-2021 4286.9 2754	
324038	NO. 2 MAIN LANDING GEAR	WHEEL						
	6600330-20 JAN08-2741 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	R:16 R:122.2 R:105			26-FEB-2015 3430.9 1765	
324038A	NDT INSPECT NO. 2 MAIN LA	ANDING GEAR W	VHEEL					
	6600330-20 JAN08-2741 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C				12-MAR-2021 4286.9 2754	
324039	NO. 3 MAIN LANDING GEAR	WHEEL						
	6600330-20 SEP01-1774 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				22-FEB-2018 3974.8 2358	
324039A	NDT INSPECT NO. 3 MAIN LA	ANDING GEAR W	/HEEL					
	6600330-20 SEP01-1774 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C				12-MAR-2021 4286.9 2754	
324040	NO. 4 MAIN LANDING GEAR	WHEEL						
	6600330-20 SEP96-634 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				22-FEB-2018 3974.8 2358	
324040A	NDT INSPECT NO. 4 MAIN LA	ANDING GEAR W	VHEEL					
	6600330-20 SEP96-634 REF: NDT 32-40-01	MOS HRS/MSC AFL	O/C				12-MAR-2021 4286.9 2754	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		oort Date: 10-SEP-20 MAX
	PART/SERIAL			EXP	(ENG/APU) A/C	LIMIT
24048	NO. 1 ASSEMBLY, MAIN LAN	DING GEAR BRAKE				
	90002424-2	MOS	O:0		31-AUG-2018	
	MAY04-0265	HRS/MSC O/C	O:0		4067	
	REF : AMM 32-41-01	AFL	O:0		2472	
24049	NO. 2 ASSEMBLY, MAIN LAN	DING GEAR BRAKE				
	90002424-2	MOS	O:0		31-AUG-2018	
	DEC08-1058	HRS/MSC O/C	O:0		4067	
	REF: AMM 32-41-01	AFL	O:0		2472	
24050	NO. 3 ASSEMBLY, MAIN LAN	DING GEAR BRAKE				
	90002424-2	MOS	O:0		31-AUG-2018	
	DEC11-1524	HRS/MSC O/C	O:0		4067	
	REF: AMM 32-41-01	AFL	O:0		2472	
24051	NO. 4 ASSEMBLY, MAIN LAN	DING GEAR BRAKE				
	90002424-2	MOS	O:0		31-AUG-2018	
	MAR18-0164	HRS/MSC O/C	O:0		4067	
	REF : AMM 32-41-01	AFL	O:0		2472	
24061	NO. 1 POWER BRAKE, PILOT	TS VALVE				
	3321200-2	MOS	N:0		09-DEC-2007	
	2075	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
24062	NO. 2 POWER BRAKE, PILOT	TS VALVE				
	3321200-2	MOS	N:0		09-DEC-2007	
	2077	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
24063	NO. 1 POWER BRAKE, COPII	LOTS VALVE				
	3321200-2	MOS	N:0		09-DEC-2007	
	2072	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
24064	NO. 2 POWER BRAKE, COPII	LOTS VALVE				
	3321200-2	MOS	N:0		09-DEC-2007	
	2078	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PLATI	NUM C.A. Operator: AERONAU	IIC SOLUTIONS JOANK	RIGER, S.A DE C.V. Repor	t Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTI	ERVAL TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE	MAX LIMIT
324085	NO. 1 HYDRAULIC, BRAKE F	USE				
	2380114-1	MOS	N:0		09-DEC-2007	
	7281	HRS/MSC O/C	N:0		0	
	REF : AMM 32-41-03	AFL	N:0		0	
324086	NO. 2 HYDRAULIC, BRAKE F	USE				
	2380114-1	MOS	N:0		09-DEC-2007	
	7272	HRS/MSC O/C	N:0		0	
	REF : AMM 32-41-03	AFL	N:0		0	
324109	NO. 3 HYDRAULIC, BRAKE F	USE				
	2380114-1	MOS	N:0		09-DEC-2007	
	7275	HRS/MSC O/C	N:0		0	
	REF : AMM 32-41-03	AFL	N:0		0	
324110	NO. 4 HYDRAULIC, BRAKE F	USE				
	2380114-1	MOS	N:0		09-DEC-2007	
	7279	HRS/MSC O/C	N:0		0	
	REF: AMM 32-41-03	AFL	N:0		0	
324133	AFT PARKING BRAKE VALVE	Ē				
	6600392-003	MOS	N:0		09-DEC-2007	
	0231	HRS/MSC O/C	N:0		0	
	REF: AMM 32-41-04	AFL	N:0		0	
324134	FWD PARKING BRAKE VALV	E				
	6600392-003	MOS	N:0		09-DEC-2007	
	0249	HRS/MSC O/C	N:0		0	
	REF : AMM 32-41-04	AFL	N:0		0	
324145	NO. 1 WHEEL SPEED TRANS	BDUCER				
	40-911	MOS	N:0		09-DEC-2007	
	7685	HRS/MSC O/C	N:0		0	
	REF: AMM 32-42-02	AFL	N:0		0	
324146	NO. 2 WHEEL SPEED TRANS	BDUCER				
	40-911	MOS	N:0		09-DEC-2007	
	7679	HRS/MSC O/C	N:0		0	
	REF : AMM 32-42-02	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR	Report Date: 10-S	LP-20
tor no	PART/SERIAL	ONTI INTERVAL		EXP	(ENG/APU) A/C LIMIT	
4147	NO. 3 WHEEL SPEED TRANS					
	40-911	MOS	N:0		09-DEC-2007	
	7563	HRS/MSC O/C	N:0		0	
	REF : AMM 32-42-02	AFL	N:0		0	
24148	NO. 4 WHEEL SPEED TRANS	BDUCER				
	40-911	MOS	N:0		09-DEC-2007	
	7564	HRS/MSC O/C	N:0		0	
	REF : AMM 32-42-02	AFL	N:0		0	
24169	LEFT ANTI-SKID VALVE					
	39-309-4	MOS			26-JUL-2013	
	289	HRS/MSC O/C			3238.27	
	REF : AMM 32-42-01	AFL			1618	
324170	RIGHT ANTI-SKID VALVE					
	39-309-2	MOS	N:0		09-DEC-2007	
	2651A	HRS/MSC O/C	N:0		0	
	REF : AMM 32-42-01	AFL	N:0		0	
324175	ANTI-SKID CONTROL					
	42-379-1	MOS	N:0		09-DEC-2007	
	1910-B	HRS/MSC O/C	N:0		0	
	REF : AMM 32-42-03	AFL	N:0		0	
324413	PARK BRAKE ANNUNCIATOR	R BOX ASSEMBLY				
-	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 32-42-06	AFL	N:0		0	
24501	EMERGENCY BRAKE CONTR	ROL VALVE				
	63500-2	MOS	N:0		09-DEC-2007	
	544A	HRS/MSC O/C	N:0		0	
	REF : AMM 32-43-01	AFL	N:0		0	
24505	LEFT MAIN LANDING GEAR I	BRAKE SHUTTLE VALVE				
	2SV0413	MOS	N:0		09-DEC-2007	
	D18499	HRS/MSC O/C	N:0		0	
	REF : AMM 32-00-01	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR	Report Date: 10-S COMPLIANCE NEXT DUE MAX	
	PART/SERIAL	ONIT	TIME SINCE	EXP	(ENG/APU) A/C LIMIT	
4510	RIGHT MAIN LANDING GEAR	BRAKE SHUTTLE VALVE				
	2SV0413	MOS	N:0		09-DEC-2007	
	D18500	HRS/MSC O/C	N:0		0	
	REF : AMM 32-00-01	AFL	N:0		0	
24601	NO. 1 MAIN LANDING GEAR	BRAKE SHUTTLE VALVE				
	2SV0413	MOS	N:0		09-DEC-2007	
	D18517	HRS/MSC O/C	N:0		0	
	REF: AMM 32-00-01	AFL	N:0		0	
24602	NO. 2 MAIN LANDING GEAR	BRAKE SHUTTLE VALVE				
	2SV0413	MOS	N:0		09-DEC-2007	
	D18493	HRS/MSC O/C	N:0		0	
	REF : AMM 32-00-01	AFL	N:0		0	
324603	NO. 3 MAIN LANDING GEAR	BRAKE SHUTTLE VALVE				
	2SV0413	MOS	N:0		09-DEC-2007	
	D18501	HRS/MSC O/C	N:0		0	
	REF : AMM 32-00-01	AFL	N:0		0	
324604	NO. 4 MAIN LANDING GEAR	BRAKE SHUTTLE VALVE				
	2SV0413	MOS	N:0		09-DEC-2007	
	D18482	HRS/MSC O/C	N:0		0	
	REF : AMM 32-00-01	AFL	N:0		0	
25001	NOSE WHEEL STEERING AC	TUATOR				
	501-1711-02	MOS	R:0		16-JUL-2017	
	80024	HRS/MSC O/C	R:0		3849.9	
	REF : AMM 32-50-05	AFL	R:0		2207	
25005	NOSE WHEEL STEERING CO	MPUTER				
	6608468-011	MOS			25-JUL-2016	
	1195	HRS/MSC O/C			3709.5	
	REF : AMM 32-50-04	AFL			2046	
25015	LEFT RUDDER POSITION SE	NSOR				
	501-1123-03	MOS	N:0		09-DEC-2007	
	80449	HRS/MSC O/C	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

		OS ALKLOS I LATINOPI CIA	оролион наполи		Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
325016	RIGHT RUDDER POSITION S	ENSOR				
	501-1123-03 80486 REF: AMM 32-50-03	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0	
325019	NOSE WHEEL STEERING AC	TUATOR GEARBOX				
	3142020-3 358 REF: AMM 32-50-02	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0	
325020	NOSE WHEEL STEERING FO	DLLOW UP ASSEMBLY				
	60187101-003-601 031 REF: AMM 32-50-05	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0	
325024	RIGHT NOSE WHEEL STEER	ING FOLLOWUP				
	6608288-003 5706 REF: AMM 32-50-01	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		16-JUL-2017 3849.9 2207	
325025	LEFT NOSE WHEEL STEERIN	NG FOLLOWUP				
	6608288-003 5694 REF: AMM 32-50-01	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		16-JUL-2017 3849.9 2207	
325628	AFT EMERGENCY GEAR CO	NTROL VALVE				
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0	
326011	SQUAT SWITCH RELAY BOX					
	PN SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC O/C AFL	N:0 N:0 N:0		09-DEC-2007 0 0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 **COMPLIANCE NEXT DUE** TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT D3211060 (s) COMPLETELY DISASSEMBLE NOSE LANDING GEAR STRUT AND ACTUATOR. REMOVE AXLE AND PISTON FROM PKG HUB. CONDUCT VISUAL INSPECTION OF ALL COMPONENTS. DETERMINE EXTENT OF WEAR BY MAKING THE REQUIRED DIMENSIONAL CHECKS. (REFER TO 32-21-00 AND 32-32-01.) CONDUCT FLUORE PKG 26 MOS 16-JUL-2017 HRS/MSC 3849.9 REF: AMM 32-32-01 AFL 6000 +25/-25 2207 CHAPTER 33 **LIGHTS** 330000 OPERATIONAL TEST OF THE PASSENGER COMPARTMENT LIGHTING (SMM 33-00-00-601) MOS 06-MAR-2020 4562.1 HRS/MSC 300 4262.1 SMM REF: AFL 2723 331201 LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY 6900115-000 MOS N:0 25-MAY-2011 6464 HRS/MSC O/C N:0 2785.83 **REF:** AMM 33-12-02 AFL N:0 1342 331202 RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY 6900115-000 MOS N:0 09-DEC-2007 6566 HRS/MSC O/C N:0 0 **REF:** AMM 33-12-02 AFL N:0 0 331303 QUAD EL (ELECTROLUMINESCENT) POWER SUPPLY SDA16 MOS N:0 09-DEC-2007 483 HRS/MSC O/C N:0 0 **REF:** AMM 33-13-03 AFL N:0 0 331311 PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 REF: GENERIC NO REF **AFL** N:0 0 331312 COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0

AFL

REF: GENERIC NO REF

0

N:0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PLATINUM C.A.	Operator: AERONAU I	IC SOLUTIONS JOANE	RIGER, S.A DE C.V. Report Date: 10-SEP-	2021					
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP							
331313	PILOT AFT CIRCUIT BREAKER PANEL OVERLAY										
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF: GENERIC NO REF	AFL	N:0		0						
331314	COPILOT AFT CIRCUIT BREA	AKER PANEL OVERLAY									
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF: GENERIC NO REF	AFL	N:0		0						
331401	PILOT DIMMING CONTROL B	SOX									
	LT-48G	MOS	N:0		09-DEC-2007						
	2044	HRS/MSC O/C	N:0		0						
	REF: AMM 33-14-01	AFL	N:0		0						
331402	COPILOT DIMMING CONTRO	DL BOX									
	LT-48G	MOS	N:0		09-DEC-2007						
	2046	HRS/MSC O/C	N:0		0						
	REF : AMM 33-14-01	AFL	N:0		0						
331403	CENTER INSTRUMENT AND	PEDESTAL DIMMING CONTROL BO	ΟΧ								
	LT-48G	MOS	N:0		09-DEC-2007						
	2049	HRS/MSC O/C	N:0		0						
	REF : AMM 33-14-01	AFL	N:0		0						
331404	PEDESTAL DIMMING CONTR	ROL BOX									
	LT-48E	MOS	N:0		09-DEC-2007						
	6377	HRS/MSC O/C	N:0		0						
	REF: AMM 33-14-01	AFL	N:0		0						
331405	FUEL QUANTITY INDICATOR	DIMMING CONTROL BOX									
	LT-48E	MOS	N:0		09-DEC-2007						
	6379	HRS/MSC O/C	N:0		0						
	REF : AMM 33-14-01	AFL	N:0		0						
331406	CDU LAMP DIMMING CONTR	OL BOX									
	PN	MOS	N:0		09-DEC-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF : AMM 33-14-01	AFL	N:0		0						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	WARR	COMPLIANCE	NEXT DUE	oort Date: 10-SEP-2 MAX
	PART/SERIAL			EXP		(ENG/APU) A/C	LIMIT
331407	INSTRUMENT BACKLIGHTIN	G FUSE BOX					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 33-14-02	AFL	N:0		0		
331601	LEFT ACS DIMMER CONTRO	L BOX					
	LT-48G	MOS	N:0		09-DEC-2007		
	2045	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
31602	RIGHT ACS DIMMER CONTR	OL BOX					
	LT-48G	MOS	N:0		09-DEC-2007		
	2047	HRS/MSC O/C	N:0		0		
	REF: GENERIC NO REF	AFL	N:0		0		
331701	LEFT AFT LIGHT DIMMING (E	E215) CONTROL BOX					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF: AMM 33-17-01	AFL	N:0		0		
31801	LEFT FORWARD LIGHT DIMM	MING (AE9) CONTROL BOX					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 33-18-01	AFL	N:0		0		
331802	RIGHT LIGHT DIMMING (2AE	9) CONTROL BOX					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 33-18-01	AFL	N:0		0		
332001	OVERHEAD INDIRECT LIGHT	TING (PS2) INVERTER					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 33-20-08	AFL	N:0		0		
32002	OVERHEAD INDIRECT LIGHT	TING (2PS2) INVERTER					
	PN	MOS	N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0		0		
	REF : AMM 33-20-08	AFL	N:0		0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		oort Date: 10-SEP-2 MAX
ASIC NO	PART/SERIAL	ONII INTERVAL		ADJ	EXP	GOWIF LIANCE	(ENG/APU) A/C	LIMIT
32003	OVERHEAD INDIRECT LIGHT	TING (3PS2) INVERTER						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 33-20-08	AFL	N:0			0		
32004	OVERHEAD INDIRECT LIGHT	ΓING (4PS2) INVERTER						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 33-20-08	AFL	N:0			0		
32005	OVERHEAD INDIRECT LIGHT	TING (5PS2) INVERTER						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			09-020-2007		
	REF : AMM 33-20-08	AFL	N:0			0		
332006	OVERHEAD INDIRECT LIGHT	TING (6PS2) INVERTER						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 33-20-08	AFL	N:0			0		
32007	OVERHEAD INDIRECT LIGHT	TING (7PS2) INVERTER						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 33-20-08	AFL	N:0			0		
332009	INDIRECT LIGHTING CONTR	OL						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 33-20-09	AFL	N:0			0		
32010	ALTERNATE/MOMENTARY S	WITCHING MODULE						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 33-20-10	AFL	N:0			0		
32014	ZONE BACK LIGHTING CONT	FROL						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			09-020-2007		
	SIN-UINKINOVIN							



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK DESCRIPTION PART/SERIAL OPERATIONAL TEST OF THE	UNIT INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX
OPERATIONAL TEST OF THE						(ENG/APU) A/C	LIMIT
	ORDINANCE SIGNS				<u> </u>	<u> </u>	
	MOS				06-MAR-2020		
	HRS/MSC 300				4262.1	4562.1	
REF:	AFL				2723		
LEFT LANDING AND TAXI LIG	нт						
PN	MOS	N:0			09-DEC-2007		
SN-UNKNOWN	HRS/MSC O/C	N:0			0		
REF : AMM 33-41-01	AFL	N:0			0		
RIGHT LANDING AND TAXI LI	GHT						
		N·0			09-DEC-2007		
REF : AMM 33-41-01	AFL	N:0			0		
LEFT NAVIGATION LIGHT							
	MOS	N·0			09-DEC-2007		
					09-020-2007		
REF : AMM 33-42-01	AFL	N:0			0		
RIGHT NAVIGATION LIGHT							
PN	MOS	N:0			09-DEC-2007		
SN-UNKNOWN	HRS/MSC O/C				0		
REF : AMM 33-42-01	AFL	N:0			0		
TAIL NAVIGATION LIGHT							
PN	MOS	N:0			09-DEC-2007		
SN-UNKNOWN	HRS/MSC O/C	N:0			0		
REF : AMM 33-42-02	AFL	N:0			0		
UPPER STROBE/BEACON LIG	SHT						
		N:0			16-FEB-2011		
1557563	HRS/MSC O/C	N:0			2586.6		
REF : AMM 33-43-01	AFL	N:0			1224		
LOWER STROBE/BEACON LIG	GHT						
		P·∩			12-FER-2014		
					12-1 LD-2014		
REF : AMM 33-43-01	AFL	R:0			1670		
	PN SN-UNKNOWN REF: AMM 33-41-01 RIGHT LANDING AND TAXI LIP PN SN-UNKNOWN REF: AMM 33-41-01 LEFT NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01 RIGHT NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01 TAIL NAVIGATION LIGHT PN SN-UNKNOWN REF: AMM 33-42-01 UPPER STROBE/BEACON LIG GE16386-9-2 1557563 REF: AMM 33-43-01 LOWER STROBE/BEACON LIG GE16386-9-1 156	SN-UNKNOWN REF: AMM 33-41-01 RIGHT LANDING AND TAXI LIGHT PN MOS SN-UNKNOWN HRS/MSC O/C REF: AMM 33-41-01 LEFT NAVIGATION LIGHT PN MOS SN-UNKNOWN HRS/MSC O/C REF: AMM 33-42-01 RIGHT NAVIGATION LIGHT PN MOS SN-UNKNOWN HRS/MSC O/C REF: AMM 33-42-01 AFL TAIL NAVIGATION LIGHT PN MOS SN-UNKNOWN HRS/MSC O/C REF: AMM 33-42-01 TAIL NAVIGATION LIGHT PN MOS SN-UNKNOWN HRS/MSC O/C REF: AMM 33-42-02 UPPER STROBE/BEACON LIGHT GE16386-9-2 MOS 1557563 HRS/MSC O/C REF: AMM 33-43-01 LOWER STROBE/BEACON LIGHT GE16386-9-1 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS HRS/MSC O/C	PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-41-01 AFL N:0 RIGHT LANDING AND TAXI LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-41-01 AFL N:0 LEFT NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 RIGHT NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 TAIL NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 UPPER STROBE/BEACON LIGHT GE16386-9-2 MOS N:0 REF: AMM 33-43-01 AFL N:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS REF: AMM 33-43-01 AFL N:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS REF: AMM 33-43-01 AFL N:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS REF: AMM 33-43-01 AFL N:0	PN MOS N-0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-41-01 AFL N:0 RIGHT LANDING AND TAXI LIGHT PN MOS N-0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-41-01 AFL N:0 LEFT NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 RIGHT NAVIGATION LIGHT PN MOS N:0 REF: AMM 33-42-01 AFL N:0 RIGHT NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 TAIL NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-02 AFL N:0 UPPER STROBE/BEACON LIGHT GE:16386-9-2 MOS N:0 REF: AMM 33-43-01 AFL N:0 LOWER STROBE/BEACON LIGHT GE:16386-9-1 MOS R:0 REF: AMM 33-43-01 AFL N:0 LOWER STROBE/BEACON LIGHT GE:16386-9-1 MOS R:0 1566 HRS/MSC O/C R:0	PN MOS N-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-41-01 AFL N:0 RIGHT LANDING AND TAXI LIGHT PN MOS N-UNKNOWN HRS/MSC O/C N:0 SN-UNKNOWN HRS/MSC O/C N:0 LEFT NAVIGATION LIGHT PN MOS N-UNKNOWN HRS/MSC O/C N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 RIGHT NAVIGATION LIGHT PN MOS N-UNKNOWN HRS/MSC O/C N:0 RIGHT NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 TAIL NAVIGATION LIGHT PN MOS N:0 SN-UNKNOWN HRS/MSC O/C N:0 REF: AMM 33-42-01 AFL N:0 UPPER STROBE/BEACON LIGHT GE16386-9-2 MOS N:0 REF: AMM 33-43-01 AFL N:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS R:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS R:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS R:0 LOWER STROBE/BEACON LIGHT GE16386-9-1 MOS R:0	PN	PN



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-20										
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT		
34401	WING ICE INSPECTION LIGH	Т								
	GLJ140	MOS		N:0			09-DEC-2007			
	12462	HRS/MSC	O/C	N:0			0			
	REF: AMM 33-44-01	AFL		N:0			0			
334501	RECOGNITION LIGHT									
	Q4681	MOS		N:0			07-MAR-2011			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			2634.63			
	REF : AMM 33-45-01	AFL		N:0			1247			
34502	RECOGNITION LIGHT PULSE	CONTROL UNIT								
	2401S	MOS		N:0			09-DEC-2007			
	01225	HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0			
	REF: AMM 33-45-02	AFL	5/0	N:0			0			
	REF. / WIN 00 40 02	70 2		14.0						
335000	GENERAL VISUAL INSPECTION M1004711CT) (33-50-00-600 S	ON OF THE EME	RGENCY LIGHTING	SYSTEM COMPONENTS (S	TC ST01422WI-	-D, IFCA				
							00 DEC 2007			
		MOS HRS/MSC	4900				09-DEC-2007 0 4800			
ISPECT	REF:	AFL	4000				4800			
		711 2								
35001	EMERGENCY EXIT LIGHTING	S PANEL								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
35505	PILOT FLASHLIGHT									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			09-DEC-2007 0			
	REF: GENERIC NO REF	AFL	3,0	N:0			0			
35505A	REPLACE PILOT FLASHLIGH	T BATTERIES								
-		MOS					25 2016			
	PN SN-UNKNOWN	MOS HRS/MSC	N/Δ				25-JUL-2016 3709.5			
	REF: GENERIC NO REF	AFL	IN/A				2046			
	NEI . GENERIO NO REF	AI L					2010			
35506	COPILOT FLASHLIGHT									
35506	COPILOT FLASHLIGHT PN	MOS		N:0			09-DEC-2007			
35506		MOS HRS/MSC	O/C	N:0 N:0			09-DEC-2007 0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 335506A REPLACE COPILOT FLASHLIGHT BATTERIES PΝ MOS 25-JUL-2016 SN-UNKNOWN HRS/MSC A/R 3709.5 REF: GENERIC NO REF 2046 AFL CHAPTER 34 **NAVIGATION FUNCTIONAL TEST AIR DATA SYSTEM** 05-10-29-W3411025 MOS 24 +14d/-14d -47 12-MAR-2021 24-JAN-2023 07-FEB-2023 HRS/MSC 4286.9 2754 **REF:** AMM 34-17-00 AFL 05-10-30-RVSM-W3411015 PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (RVSM) (REFER TO 34-17-00) MOS 12 +14d/-14d 12-MAR-2021 12-MAR-2022 26-MAR-2022 HRS/MSC 4286.9 **AFL** 2754 **REF:** AMM 34-17-00 34-00-FAR-91.171 CHECK VOR FAR 91.171 MOS 31-AUG-2018 HRS/MSC O/C 4067 REF: See Workcard **AFL** 2472 34-00-FAR-91.217 PERFORM ALTITUDE DATA TRANSMISSION TEST MOS 09-DEC-2007 HRS/MSC A/R 0 **REF:** See Workcard **AFL** 0 RECERTIFY PITOT-STATIC SYSTEM 34-00-FAR-91.411 MOS 24 12-MAR-2021 12-MAR-2023 HRS/MSC 4286.9 REF: See Workcard **AFL** 2754 340010 (s) PERFORM FMS UPDATE DAYS 28 22-FEB-2018 HRS/MSC 3974.8 **CUSTOMER CODE** REF: 2358 AFL



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO								Re	port Date: 10-SEP-202
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTER\	/AL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
41020	LEFT PITOT/STATIC PROBE									
	856KR7	MOS			N:0			09-DEC-2007		
	230825	HRS/MSC	15000	+25/-25	N:0			0	15000	15025
IFE LIMIT	REF: AMM 34-11-02	AFL			N:0			0		
41020A	VERIFY LEFT PITOT/STATIC P	ROBE PITCH A	ND YAW A	LIGNMENT (RVSM) (REFER TO 34-1	I-02) 5-10-30-N34	11016			
	856KR7	MOS	24	+14d/-14d		-47		12-MAR-2021	24-JAN-2023	07-FEB-2023
	230825	HRS/MSC						4286.9		
	REF: AMM 34-11-02	AFL						2754		
41020B	DETAILED VISUAL INSPECTIO	N LEFT PITOT/	STATIC PI	ROBE (RVSI	И) (REFER TO 34-11-02) (5-10-30-N3411064	ŀ			
	856KR7	MOS	24	+14d/-14d				12-MAR-2021	12-MAR-2023	26-MAR-2023
	230825	HRS/MSC						4286.9		
	REF: AMM 34-11-02	AFL						2754		
341025	RIGHT PITOT/STATIC PROBE									
	856KR8	MOS			N:0			09-DEC-2007		
	232550	HRS/MSC	15000	+25/-25	N:0			0	15000	15025
IFE LIMIT	REF: AMM 34-11-02	AFL			N:0			0		
341025A	VERIFY RIGHT PITOT/STATIC	PROBE PITCH	AND YAW	ALIGNMENT	(RVSM) (REFER TO 34-	11-02) 5-10-30-N3	411016			
	856KR8	MOS	24	+14d/-14d		-47		12-MAR-2021	24-JAN-2023	07-FEB-2023
	232550	HRS/MSC						4286.9		
	REF: AMM 34-11-02	AFL						2754		
41025B	DETAILED VISUAL INSPECTIO	N RIGHT PITO	Γ/STATIC F	PROBE (RVS	M) (REFER TO 34-11-02)	5-10-30-N341106	4			
	856KR8	MOS	24	+14d/-14d				12-MAR-2021	12-MAR-2023	26-MAR-2023
	232550	HRS/MSC						4286.9		
	REF : AMM 34-11-02	AFL						2754		
41026	PITOT/STATIC PROBE									
	856KR8	MOS			N:0			09-DEC-2007		
	230504	HRS/MSC	O/C		N:0			0		
	REF : AMM 34-11-02	AFL			N:0			0		
41105	PILOT RIGHT STATIC SHUTOF	F VALVE								
	6600473-1	MOS			N:0			09-DEC-2007		
	0524T	HRS/MSC	O/C		N:0			0		
	REF: AMM 34-11-03	AFL			N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICE	00 /1211200 1 2/112	NUM C.A. Operator: AERONAU	TE SOLOTIONS SOAM	Rei	oort Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTI	ERVAL TIME SINCE	ADJ WARR EXP		MAX LIMIT
41106	COPILOT RIGHT STATIC SHU	JTOFF VALVE				
	6600473-1	MOS	N:0		09-DEC-2007	
	0356T	HRS/MSC O/C	N:0		0	
	REF : AMM 34-11-03	AFL	N:0		0	
341107	PILOT LEFT STATIC SHUTOR	F VALVE				
	6600473-2	MOS	N:0		09-DEC-2007	
	0293T	HRS/MSC O/C	N:0		0	
	REF: AMM 34-11-03	AFL	N:0		0	
41108	COPILOT LEFT STATIC SHU	TOFF VALVE				
	6600473-2	MOS	N:0		09-DEC-2007	
	0215T	HRS/MSC O/C	N:0 N:0		09-DEC-2007 0	
	REF: AMM 34-11-03	AFL	N:0		0	
341111	STANDBY ALTIMETER					
		1400	NO		00 DE0 0007	
	PN NOT INSTALLED	MOS HRS/MSC O/C	N:0		09-DEC-2007	
	REF: AMM 34-15-01	AFL AFL	N:0 N:0		0	
341111A	RECERTIFY STANDBY ALTIN	METER				
	PN	MOS			09-DEC-2007	
	NOT INSTALLED	HRS/MSC -			0	
N/A EQUIPMENT NOT NSTALLED	REF: See Workcard	AFL			0	
41133	NO. 1 LOWER (ADC) AIR DAT	ΓA COMPUTER				
	822-0389-629	MOS	R:0		12-FEB-2014	
	357LK	HRS/MSC O/C	R:0			
	REF : AMM 34-17-01	AFL	R:0		1670	
41133A	RECERTIFY NO. 1 LOWER (A	ADC) AIR DATA COMPU	TER PRIMARY AIR DATA SYSTEM			
	822-0389-629	MOS 24			12-MAR-2021 12-MAR-2023	
	357LK	HRS/MSC			mi u coli il-miruc-2020	
	REF: See Workcard	AFL				
		A COMPUTER				
41134	NO. 2 UPPER (ADC) AIR DAT	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
341134	` '		0.0		11-DEC-2009	
41134	NO. 2 UPPER (ADC) AIR DAT 822-0389-629 2FLGB	MOS HRS/MSC O/C	O:0 O:0		11-DEC-2009 1860.48	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

		OS AEREOS PLAT						Rep	ort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INT	ERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
41134A	RECERTIFY NO. 2 UPPER (A	.DC) AIR DATA COMPL	JTER PRIMARY	' AIR DATA SYSTEM					
	822-0389-629 2FLGB REF: See Workcard	MOS 24 HRS/MSC AFL					12-MAR-2021	12-MAR-2023	
341220	INTEGRATED / ELECTRONIC	STANDBY INDICATOR	R SYSTEM 3 IN	I 1 GAUGE					
	501-1860-0101 1316 REF: AMM 34-19-01	MOS HRS/MSC O/C AFL		N:0 N:0 N:0			09-DEC-2007 0 0		
341220A	RECERTIFY INTEGRATED / E	ELECTRONIC STANDB	Y INDICATOR :	SYSTEM 3 IN 1 GAUGE					
	501-1860-0101 1316 REF: AMM 34-19-01	MOS 24 HRS/MSC AFL					12-MAR-2021 4286.9 2754	12-MAR-2023	
341222	ESIS CONFIGURATION MOD	ULE							
	501-1870-66 1416 REF : GENERIC NO REF	MOS HRS/MSC O/C AFL		N:0 N:0 N:0			09-DEC-2007 0 0		
341225	STANDBY AIRSPEED INDICA	ATOR							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN REF: AMM 34-18-01	HRS/MSC O/C AFL		N:0 N:0			0 0		
341401	RADIO ALTIMETER TRANSC	EIVER							
	822-0615-205	MOS		O:0			18-JUN-2009		
	1YP7D REF : AMM 34-14-01	HRS/MSC O/C AFL		O:0 O:0			1442.57 628		
341402	RADIO ALTIMETER CONVER	RTER							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN REF: AMM 34-14-02	HRS/MSC O/C AFL		N:0 N:0			0 0		
341403	AFT RADIO ALTIMETER ANT	ENNA							
	622-0954-002	MOS		N:0			09-DEC-2007		
	4528 REF : AMM 34-14-03	HRS/MSC O/C AFL		N:0 N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTER\	AL TIME SINCE	ADJ WARR		ort Date: 10-SEP-20 MAX
ASK NO	PART/SERIAL	ONII INTER	THE SINCE	EXP	(ENG/APU) A/C	MAX LIMIT
11404	FORWARD RADIO ALTIMETE	R ANTENNA				
	622-0954-002	MOS	N:0		09-DEC-2007	
	4530	HRS/MSC O/C	N:0		0	
	REF : AMM 34-14-03	AFL	N:0		0	
41703	FORWARD SIGNAL INTERFA	CE ADAPTER				
	622-9732-003	MOS	N:0		09-DEC-2007	
	2FWJC	HRS/MSC O/C	N:0		0	
	REF : AMM 34-17-02	AFL	N:0		0	
41704	AFT SIGNAL INTERFACE AD.	APTER				
	622-9732-003	MOS	N:0		09-DEC-2007	
	2FWCX	HRS/MSC O/C	N:0		0	
	REF : AMM 34-17-02	AFL	N:0		0	
41705	PILOT AIR DATA REFERENC	E PANEL				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-17-03	AFL	N:0		0	
41706	COPILOT AIR DATA REFERE	NCE PANEL				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-17-03	AFL	N:0		0	
41707	TAT SENSOR PROBE					
	102AU1AG	MOS	N:0		09-DEC-2007	
	A71801	HRS/MSC O/C	N:0		0	
	REF: AMM 34-17-04	AFL	N:0		0	
41709	PRIMARY ADC SWITCHING U	JNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 34-17-06	AFL	N:0		0	
41710	SECONDARY ADC SWITCHIN	NG UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 34-17-06	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		: Date: 10-SEP-20 MAX
ASK NO	PART/SERIAL	ONIT INTERVAL	TIME SINCE	EXP		MAX IMIT
1801	STANDBY MACH/AIRSPEED	INDICATOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-18-01	AFL	N:0		0	
42001	MAGNETIC COMPASS MAGN	IETOMETER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
42025	AHRS COOLING FAN					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
342055	NO. 1 FLUX DETECTOR UNIT	-				
	622-5812-001	MOS	N:0		09-DEC-2007	
	36353	HRS/MSC O/C	N:0		0	
	REF : AMM 34-26-02	AFL	N:0		0	
342056	NO. 2 FLUX DETECTOR UNIT	-				
	622-5812-001	MOS	N:0		09-DEC-2007	
	36641	HRS/MSC O/C	N:0		0	
	REF : AMM 34-26-02	AFL	N:0		0	
42057	NO. 1 INTERNAL COMPENSA	TOR (ICU-85) UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-26-04	AFL	N:0		0	
42058	NO. 2 INTERNAL COMPENSA	TOR (ICU-85) UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-26-04	AFL	N:0		0	
42301	STANDBY GYRO					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
		AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				-		IS JOANR	Report Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	
42401	MAGNETIC COMPASS						
	C2350-L4-M23 3065BRU REF: AMM 34-24-01	MOS HRS/MSC AFL	O/C				11-JUN-2019
42410	NO. 1 ATTITUDE/HEADING (.	AHC-85E) COMP	UTER				
	822-1110-002 2KKCC REF : AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:33 N:2376.28 N:1098			22-SEP-2010 2376.28 1098
342411	NO. 2 ATTITUDE/HEADING (AHC-85E) COMP	UTER				
	822-1110-002 2KJKR REF : AMM 34-26-01	MOS HRS/MSC AFL	O/C	N:33 N:2376.28 N:1098			22-SEP-2010 2376.28 1098
342412	NO. 1 ATTITUDE/HEADING E	EXTERNAL COMP	ENSATION UNIT (E	ECU-3000)			
	822-1200-002 2NOCL REF: AMM 34-26-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0
42413	NO. 2 ATTITUDE/HEADING E	EXTERNAL COMP	ENSATION UNIT (E	ECU-3000)			
	822-1200-002	MOS		N:0			09-DEC-2007
	2KK2L REF : AMM 34-26-06	HRS/MSC AFL	O/C	N:0 N:0			0 0
42501	STANDBY ATTITUDE DIRECT	TIONAL (ADI) IND	ICATOR				
	PN	MOS		N:0			09-DEC-2007
	SN-UNKNOWN REF: AMM 34-25-01	HRS/MSC AFL	O/C	N:0 N:0			0 0
42605	AUXILIARY SWITCHING UNIT	Г					
	PN	MOS		N:0			09-DEC-2007
	SN-UNKNOWN REF: AMM 34-26-03	HRS/MSC AFL	O/C	N:0 N:0			0 0
43007	MARKER BEACON (37X-2) AI	NTENNA					
	522-0854-069	MOS		N:0			09-DEC-2007
	53753	HRS/MSC		N:0			0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TACK NO	TACK DECORIDERAN	LINITINTERVA	TIME ONCE	4D W4-DD		e: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVA	L TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
44007	RECEIVER, GPS-4000A #1 FV	VD				
	822-1377-001	MOS	O:2		07-MAR-2011	
	18NNH	HRS/MSC O/C	O:0		2634.63	
	REF : AMM 34-54-02	AFL	O:0		1247	
344008	RECEIVER, GPS-4000A #2 AF	Т				
	822-1377-001	MOS	N:0		09-DEC-2007	
	2LMNM	HRS/MSC O/C	N:0		0	
	REF : AMM 34-54-02	AFL	N:0		0	
44111	LOWER TCAS DIRECTIONAL	(TRE-920) ANTENNA				
	622-8973-001	MOS	N:0		09-DEC-2007	
	35378	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
344112	UPPER TCAS DIRECTIONAL	TRE-920) ANTENNA				
	622-8973-001	MOS	N:0		09-DEC-2007	
	34256	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
344142	TCAS (TTR-920) PROCESSOR	₹				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 34-43-01	AFL	N:0		0	
344143	TCAS (TTR-4000) PROCESSO	PR				
	822-1294-002	MOS			13-FEB-2008	
	148366	HRS/MSC O/C	R:0		205.35	
	REF : AMM 34-43-01	AFL	R:0		84	
44151	STORMSCOPE PROCESSOR					
	78-8060-6086-5	MOS	N:0		09-DEC-2007	
	80961	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
44153	STORMSCOPE DISPLAY					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : GENERIC NO REF	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	S AEREOS PI	ATINUM C.A.	Operator: AERONAUII	C SOLUTIONS JO	ANRIGER, S.A DE C.V. Report Da	te: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WAI EXP	RR COMPLIANCE NEXT DUE MAX	
344155	STORMSCOPE ANTENNA						
	78-8051-9200-8	MOS		N:0		09-DEC-2007	
	81753	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344171	NO. 1 VHF/NAV ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: AMM 34-51-02	AFL		N:0		0	
344176	NO. 2 VHF/NAV ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-51-02	AFL		N:0		0	
344201	EFIS RADAR (ERP) PANEL						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-61-07	AFL		N:0		0	
344205	WEATHER RADAR RECEIVER	R/TRANSMITTER/	ANTENNA				
	622-8440-004	MOS		O:0		25-OCT-2013	
	22HGX	HRS/MSC	O/C	O:0		3308.7	
	REF : AMM 34-42-01	AFL		O:0		1660	
344220	AV200 WSI ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344225	AV200 WSI SATELLITE RECEI	VER					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344226	WSI RECEIVER MOUNT TRAY	,					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

						NRIGER, S.A DE C.V. Report Date: 10	-SEP-202
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARI EXP	R COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
44513	TAWS COMPUTER						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344515	TAWS CONFIGURATION MOI	DULE					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344520	TERRAIN AWARENESS ISOL	ATION BOX					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344806	WEATHER RADAR INDICATO	DR .					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
344807	PILOT EFIS RADAR CONTRO	DL PANEL					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-61-07	AFL		N:0		0	
344808	COPILOT EFIS RADAR CONT	ROL PANEL					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-61-07	AFL		N:0		0	
345001	NO. 1 ADF (ADF-462) RECEIV	/ER					
	622-7382-101	MOS		N:0		09-DEC-2007	
	2K9PW	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-57-01	AFL		N:0		0	
345002	NO. 2 ADF (ADF-462) RECEIV	/ER					
	622-7382-101	MOS		N:0		09-DEC-2007	
	2K96N	HRS/MSC	O/C	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

	Owner: SERVICIOS	AEREUS PI	_	erator. AERONAOTI	C SOLUTIO	NS JUANK	ider, S.A DE C.	r. Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
45005	ENHANCED GROUND PROXIMI	TY WARNING S	SYSTEM COMPUTER						
	965-0976-040-226-226 25630 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C				15-MAY-2014		
345010	AUX GPWS/WINDSHEAR INDICA	ATOR							
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
345011	NO. 1 DME TRANSCEIVER								
	622-7309-101 1053 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C				22-FEB-2018 3974.8 2358		
345012	NO. 2 DME TRANSCEIVER								
	622-7309-101 2D4NC REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
345013	ADF, DUAL (ANT-462B) ANTENN	IA							
	622-7384-001 30JNW REF : AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0			29-JAN-2009 1151.95 495		
345021	NO. 1 VHF (VIR 432) RECEIVER								
	622-7194-201 2GBCN REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
345022	NO. 2 VHF (VIR 432) RECEIVER								
	622-7194-201 2GBCG REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
345031	NO. 1 NAVIGATION COMPUTER								
	PN SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	US AEREUS PI	LATINUM C.A.	Operator: AERONAUTI	C SOLUTIONS JO	ANRIGER, S.A DE C.V.	Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WA EXF	RR COMPLIANCE NEXT DUE	MAX
345032	NO. 2 NAVIGATION COMPUT	ER					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-61-06	AFL		N:0		0	
345043	LEFT NAVIGATION (BLADE)	ANTENNA					
	DMN4-45	MOS		N:0		09-DEC-2007	
	10892	HRS/MSC	O/C	N:0		0	
	REF: AMM 34-51-02	AFL		N:0		0	
345044	RIGHT NAVIGATION (BLADE)) ANTENNA					
	DMN4-45	MOS		N:0		09-DEC-2007	
	10893	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-51-02	AFL		N:0		0	
345045	NO. 1 VHF/NAV ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-51-02	AFL		N:0		0	
345046	NO. 2 VHF/NAV ANTENNA						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-51-02	AFL		N:0		0	
345048	ANTENNA, ATC LOWER SEC	(RVSM)					
	N813-9011 / CI100-2	MOS		N:0		09-DEC-2007	
	179387	HRS/MSC	O/C	N:0		0	
	REF:	AFL		N:0		0	
345049	ANTENNA, ATC UPPER SEC	(RVSM)					
	CI-100-2	MOS				12-DEC-2011	
	355922	HRS/MSC	O/C			3011.9	
	REF:	AFL				1487	
345079	PRIMARY ATC TRANSPONDI	ER					
	622-9210-008	MOS				12-FEB-2014	
	2LB8X	HRS/MSC	O/C				
	REF: AMM 34-56-01	AFL				1670	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

			C SOLUTIONS				oort Date: 10-SEP-20
TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE			COMPLIANCE		MAX LIMIT
TEST/INSPECT PRIMARY AT	C TRANSPONDER						
622-9210-008 2LB8X REF : See Workcard	MOS 24 HRS/MSC AFL				12-MAR-2021	12-MAR-2023	
SECONDARY ATC TRANSPO	NDER						
622-9210-008 3V2RV REF: AMM 34-56-01	MOS HRS/MSC O/C AFL				12-FEB-2014 1670		
TEST/INSPECT SECONDARY	ATC TRANSPONDER						
622-9210-008 3V2RV REF: See Workcard	MOS 24 HRS/MSC AFL				12-MAR-2021	12-MAR-2023	
NO. 1 ATC TRANSPONDER C	CONTROL ADAPTER						
PN SN-UNKNOWN REF: AMM 34-56-03	MOS HRS/MSC O/C AFL	N:0 N:0 N:0			09-DEC-2007 0 0		
NO. 2 ATC TRANSPONDER C	CONTROL ADAPTER						
PN	MOS	N:0			09-DEC-2007		
SN-UNKNOWN REF: AMM 34-56-03	HRS/MSC O/C AFL	N:0 N:0			0		
NO. 1 TRANSPONDER ANTEI	NNA						
CI100-2	MOS	N:0			26-JUN-2012		
364195 REF : AMM 34-56-02	HRS/MSC O/C AFL	N:0 N:0			3024.7 1489		
NO. 2 TRANSPONDER ANTEI	NNA						
CI100-2	MOS	N:0			09-DEC-2007		
153726 REF: AMM 34-56-02	HRS/MSC O/C AFL	N:0 N:0			0		
ADF PRIMARY ANTENNA							
PN	MOS HRS/MSC O/C	N:0 N:0			09-DEC-2007		
SN-UNKNOWN					0		
	PART/SERIAL TEST/INSPECT PRIMARY AT 622-9210-008 2LB8X REF: See Workcard SECONDARY ATC TRANSPO 622-9210-008 3V2RV REF: AMM 34-56-01 TEST/INSPECT SECONDARY 622-9210-008 3V2RV REF: See Workcard NO. 1 ATC TRANSPONDER OF PN SN-UNKNOWN REF: AMM 34-56-03 NO. 2 ATC TRANSPONDER OF PN SN-UNKNOWN REF: AMM 34-56-03 NO. 1 TRANSPONDER ANTEI C1100-2 364195 REF: AMM 34-56-02 NO. 2 TRANSPONDER ANTEI C1100-2 153726 REF: AMM 34-56-02	### PART/SERIAL TEST/INSPECT PRIMARY ATC TRANSPONDER 622-9210-008	## PART/SERIAL TEST/INSPECT PRIMARY ATC TRANSPONDER 622-9210-008	PART/SERIAL	PART/SERIAL	PART/SERIAL	TASK DESCRIPTION



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

							port Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
45605	NO. 1 DME ANTENNA						
	CI100-2	MOS		N:0		26-JUN-2012	
	361647	HRS/MSC	O/C	N:0		3024.7	
	REF : AMM 34-55-02	AFL		N:0		1489	
345606	NO. 2 DME ANTENNA						
	N813-9011/CI100-2	MOS		N:0		09-DEC-2007	
	176122	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-55-02	AFL		N:0		0	
346004	DATA BASE - DBU-4000 UNIT	-					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-60-04	AFL		N:0		0	
346007	DATA LOAD (DLP) PANEL						
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-60-07	AFL		N:0		0	
346011	NO. 1 FLIGHT MANAGEMENT	COMPUTER					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-60-09	AFL		N:0		0	
346012	NO. 2 FLIGHT MANAGEMENT	COMPUTER					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 34-60-09	AFL		N:0		0	
346015	NO. 1 FLIGHT MANAGEMENT	SYSTEM CDU					
	822-1485-562	MOS				30-JAN-2008	
	2CNVM	HRS/MSC	O/C	N:0		173.1	
	REF: See Workcard	AFL		N:0		75	
346016	NO. 2 FLIGHT MANAGEMENT	SYSTEM CDU					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: See Workcard	AFL		N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				101		te: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
46017	NO. 3 FLIGHT MANAGEMEN	T SYSTEM CDU				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
46021	PRIMARY FMS DATA TRANS	FER (DTU) UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-61-04	AFL	N:0		0	
346022	SECONDARY FMS DATA TRA	ANSFER (DTU) UNIT				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 34-61-04	AFL	N:0		0	
346025	NO. 1 FMS CONFIGURATION	I MODULE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
346026	NO. 2 FMS CONFIGURATION	I MODULE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: GENERIC NO REF	AFL	N:0		0	
346031	PILOT ALTITUDE AWARENES	SS PANEL				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
346032	COPILOT ALTITUDE AWARE	NESS PANEL				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: See Workcard	AFL	N:0		0	
46041	COURSE HEADING PANEL					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owller: SERVICIO	JS AEKEUS P	LATINUM C.A.	Operator: AERONAUTI	C SOLUTIONS) JUANK	IGER, S.A DE C.V.	Rei	oort Date: 10-SEP	P-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE		WARR EXP	COMPLIANCE NE		MAX LIMIT	
346055	CONFIGURATION, AFIS MOD	ULE								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
346071	UNILINK CONFIGURATION M	IODULE								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
346090	AFIS DATA MANAGEMENT U	NIT								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
346091	DATA TRANSFER, AFIS UNIT	-								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
346092	AFIS ANTENNA									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL		N:0			0			
347510	FORWARD GPS ANTENNA									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF : AMM 34-54-02	AFL		N:0			0			
347511	AFT GPS ANTENNA									
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF : AMM 34-54-02	AFL		N:0			0			
352040A	DETAILED VISUAL INSPECTI	ON PROTECTIVE	E BREATHING (PBE) EQUIPMENT (PBE) - (SMM	35-30-00-601)					
	802300-14	MOS					16-JUL-2017			
	E15040321	HRS/MSC	600				3849.9	4449.9		
SMM	REF:	AFL					2207			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	OWNER SERVICE			operator: AERONAOTI				Rej	oort Date: 10-SEP-20		
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT		
HAPTER 35	OXYGEN										
350003	NOSE OXYGEN SYSTEM PRI	ESSURE TRANSC	UCER								
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0				
	REF: AMM 35-00-02	AFL		N:0			0				
350004	DORSAL OXYGEN SYSTEM F	PRESSURE TRAN	SDUCER								
	124058-2000	MOS		N:0			09-DEC-2007				
	42933	HRS/MSC	O/C	N:0			0				
	REF: AMM 35-00-02	AFL		N:0			0				
350005	NOSE OXYGEN SHUTOFF V	ALVE AND REGUL	ATOR ASSEMBLY								
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0				
	REF: AMM 35-00-03	AFL		N:0			0				
350006	DORSAL OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY										
	172180	MOS		N:0			09-DEC-2007				
	0786	HRS/MSC	O/C	N:0			0				
	REF: AMM 35-00-03	AFL		N:0			0				
350007	NOSE OXYGEN PRESSURE INDICATOR										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0				
	REF: AMM 35-00-04	AFL		N:0			0				
350008	DORSAL OXYGEN PRESSUR	E INDICATOR									
	820-707	MOS		N:0			09-DEC-2007				
	393	HRS/MSC	O/C	N:0			0				
	REF: AMM 35-00-04	AFL		N:0			0				
351001	PILOT OXYGEN MASK										
	174262-11	MOS		O:3			06-MAR-2020				
	11436	HRS/MSC	O/C				4262.1				
	REF: AMM 35-10-01	AFL					2723				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

				оп орс	rator: AERONAUTI				Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTER	VAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
351001A	OVERHAUL PILOT OXYGEN I	MASK								
	174262-11 11436 REF : GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d	l:3			06-MAR-2020 4262.1 2723	06-DEC-2025	20-DEC-2025
351002	COPILOT OXYGEN MASK									
	174262-11 21270 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C		O:6			06-MAR-2020 4262.1 2723		
351002A	OVERHAUL COPILOT OXYGE	EN MASK								
	174262-11 21270 REF : GENERIC NO REF	MOS HRS/MSC AFL	72	+14d/-14d	l:6			06-MAR-2020 4262.1 2723	06-SEP-2025	20-SEP-2025
351025	OXYGEN SYSTEM PRESSUR	E SWITCH								
	P24028 4093 REF: AMM 35-00-07	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			09-DEC-2007 0 0		
351071	PILOT CREW OXYGEN MASK	СВОХ								
	PN	MOS			N:0			09-DEC-2007		
	SN-UNKNOWN REF: AMM 35-10-01	HRS/MSC AFL	O/C		N:0 N:0			0		
351072	COPILOT CREW OXYGEN MA	ASK BOX								
	PN	MOS			N:0			09-DEC-2007		
	SN-UNKNOWN REF: AMM 35-10-01	HRS/MSC AFL	O/C		N:0 N:0			0		
352000	FUNCTIONAL TEST OF THE F	PASSENGER OX	YGEN SY	STEM						
		MOS	005					22-FEB-2018		
SMM	REF:	HRS/MSC AFL	600					3974.8 2358	4574.8	
352001	GENERAL VISUAL INSPECTION	ON OF THE PAS	SENGER	OXYGEN MAS	KS					
SMM	REF:	MOS HRS/MSC AFL	600					22-FEB-2018 3974.8 2358	4574.8	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICIO	S AEREUS P	LATINOM	.A. Ope	HALDI: AERUNAUTI	C SOLUTIO	15 JUAN	ilder, S.A DE C	v. Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL		TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
352002	RESTORATION PASSENGER	OXYGEN MASK	(S							
SMM	REF:	MOS HRS/MSC AFL	600					22-FEB-2018 3974.8 2358	4574.8	
SIMIM	KEF.	AFL						2336		
352006	NOSE OXYGEN CYLINDER									
	PN	MOS			N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	-		N:0			0		
NOT INSTALLED	REF: AMM 35-00-01	AFL			N:0			0		
352006A	HYDROSTATIC TEST NOSE C	XYGEN CYLINE	DER							
	PN	MOS						09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	-							
NOT INSTALLED	REF: GENERIC NO REF	AFL								
352007	DORSAL OXYGEN CYLINDER									
	176194-76	MOS	288 +	14d/-14d	N:51			11-OCT-2010	08-OCT-2031	22-OCT-2031
	0789-K600736	HRS/MSC						2412.8		
LIFE LIMIT Manufacture Date: 08-OC	REF : AMM 35-00-01	AFL APH						1123		
Manadata Bata. 00 00	7. 2007	ACH								
352007A	HYDROSTATIC TEST DORSA	OXYGEN CYLI	INDER							
	176194-76	MOS		14d/-14d		-3		06-MAR-2020	06-DEC-2022	20-DEC-2022
	0789-K600736	HRS/MSC	30 .	144/-144		-3		00-IVIAI (-2020	00-010-2022	20-010-2022
	REF: GENERIC NO REF	AFL								
352027	PASSENGER OXYGEN CONT	ROL VALVE								
	P21004-3	MOS			N:0			09-DEC-2007		
	0235	HRS/MSC	O/C		N:0			0		
	REF : AMM 35-20-03	AFL			N:0			0		
352031	FORWARD SELECTOR, OXYO	SEN VALVE								
	ZCV256	MOS			N:0			09-DEC-2007		
	06-051070	HRS/MSC	O/C		N:0			0		
	REF: AMM 35-00-05	AFL			N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO)3 AEKEUS P	LATINUM C.A. O	DEFATOR: AEKUNAUI	IC SOLUTIONS JOAN	IKIGEK, S.A DE C.V.	Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT D (ENG/APU)	OUE MAX
352032	AFT SELECTOR, OXYGEN VA	LVE					
	ZCV256	MOS		N:0		09-DEC-2007	
	07-0426330	HRS/MSC	O/C	N:0		0	
	REF: AMM 35-00-05	AFL		N:0		0	
352033	RIGHT AFT SELECTOR, OXY	GEN VALVE					
	ZCV179	MOS		N:0		09-DEC-2007	
	04-110671	HRS/MSC	O/C	N:0		0	
	REF: AMM 35-00-06	AFL		N:0		0	
352040	PROTECTIVE BREATHING (P	BE) EQUIPMENT	Г				
	802300-14	MOS	120 +14d/-14	d N:0		16-JUL-2017 01-APR-	2025 15-APR-2025
	E15040321	HRS/MSC				3849.9	
LIFE LIMIT Manufacture Date: 01-Al	REF: GENERIC NO REF	AFL APH				2207	
Manufacture Bate. 617/11/12010		ACH					
353001	L1 OXYGEN MASK DROP BOX	MOS	0.0	N:0		09-DEC-2007	
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0		0	
353002	R1 OXYGEN MASK DROP BO	х					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC AFL	O/C	N:0		0 0	
	REF: GENERIC NO REF	AFL		N:0		0	
353003	L2 OXYGEN MASK DROP BOX	X					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0		0 0	
		A []					
	REF: GENERIC NO REF	AFL		N.U			
353004				N.U			
353004	REF: GENERIC NO REF			N:0		09-DEC-2007	
353004	REF: GENERIC NO REF	x	O/C				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS P	LATINUM C.A.	operator. ALKONAO 11	C SOLUTIONS JOAN	Rei	oort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP		MAX LIMIT
353005	L3 OXYGEN MASK DROP BC	X					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
353006	R4 OXYGEN MASK DROP BO	ΟX					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
353007	R2 OXYGEN MASK DROP BO	ΟX					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF: GENERIC NO REF	AFL		N:0		0	
HAPTER 36	PNEUMATIC						
05-11-00-W3610011	REPLACE ENGINE BLEED AI	IR CHECK VALVE	S				
		MOS				24-AUG-2010	
		HRS/MSC	O/C			2317.85	
	REF: AMM 36-10-06	AFL				1066	
360001	REPLACE LEFT ENGINE PYL	ON BLEED AIR S	EALS				
		MOS				09-DEC-2007	
		HRS/MSC	O/C			0	
	REF: AMM 36-10-01	AFL				0	
360002	REPLACE RIGHT ENGINE PY	/LON BLEED AIR	SEALS				
		MOS				09-DEC-2007	
		HRS/MSC	O/C			0	
						•	
	REF: AMM 36-10-01	AFL				0	
360003	REF: AMM 36-10-01 REPLACE TAILCONE BLEED AIR MANIFOLD) (REFER TO	AIR SEALS (LOC	ATED BETWEEN T	HE FORWARD BLEED AIR M	ANIFOLD AND AFT BLEED	·	
360003	REPLACE TAILCONE BLEED	AIR SEALS (LOC	ATED BETWEEN T	HE FORWARD BLEED AIR M	ANIFOLD AND AFT BLEED	·	
360003	REPLACE TAILCONE BLEED	AIR SEALS (LOC 36-10-01)		HE FORWARD BLEED AIR M	ANIFOLD AND AFT BLEED)	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PLATINUM C.A.	Operator: AEKONAUII	IC SOLUTIONS JOANI	Report Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	
361001	NO. 1 BLEED AIR REGULATI	NG/SHUTOFF VALVE			
	7608071-1	MOS			24-NOV-2008
	323 REF : AMM 36-10-04	HRS/MSC O/C AFL			1048.03 450
361002	NO. 2 BLEED AIR REGULATI	NG/SHUTOFF VALVE			
	7608071-1	MOS	N:0		09-DEC-2007
	DUK0132 REF : AMM 36-10-04	HRS/MSC O/C AFL	N:0 N:0		0
361007	LEFT MIXING VALVE CONTR	ROL BOX			
	PN	MOS	N:0		09-DEC-2007
	SN-UNKNOWN REF: AMM 36-10-05	HRS/MSC O/C AFL	N:0 N:0		0
361008	RIGHT MIXING VALVE CONT	TROL BOX			
	PN	MOS	N:0		09-DEC-2007
	SN-UNKNOWN REF: AMM 36-10-05	HRS/MSC O/C AFL	N:0 N:0		0
361011	LEFT BLEED AIR MIXING VA	LVE			
	1H106-9	MOS			19-NOV-2010
	8AM4U REF : AMM 36-10-02	HRS/MSC O/C AFL			2487.42 1164
361012	RIGHT BLEED AIR MIXING V	ALVE			
	1H106-9	MOS			19-NOV-2010
	2AL5 REF : AMM 36-10-02	HRS/MSC O/C AFL			2487.42 1164
361013	NO. 1 BLEED AIR CHECK VA	NLVE			
	6608295-3	MOS	N:0		24-AUG-2010
	3291 REF : AMM 36-10-06	HRS/MSC O/C AFL	N:0 N:0		2317.85 1066
361014	NO. 2 BLEED AIR CHECK VA	NLVE			
	6608295-3	MOS	N:0		24-AUG-2010
	3322	HRS/MSC O/C	N:0		2317.85



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 361017 NO. 1 BLEED AIR (1 1/4) CHECK VALVE 1H95-8 MOS N:0 09-DEC-2007 6858AC HRS/MSC O/C N:0 0 0 **REF:** AMM 36-10-03 AFL N:0 361018 NO. 2 BLEED AIR (1 1/4) CHECK VALVE 1H95-8 MOS N:0 09-DEC-2007 3BC8 HRS/MSC O/C N:0 0 **REF:** AMM 36-10-03 AFL N:0 0 361037 * NO. 1 EMERGENCY AIR BOTTLE (AWL*) MOS 180 N:0 10-FEB-2017 13-MAY-2025 23111425 1124 HRS/MSC 3795.8 SCRAP **REF:** AMM 36-15-01 AFL 2153 Manufacture Date: 13-MAY-2010 APH ACH PERFORM NO. 1 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST 361037A 23111425 MOS 36 -3 06-MAR-2020 06-DEC-2022 20-DEC-2022 +14d/-14d 1124 HRS/MSC **REF:** AMM 36-15-01 AFL 361037B PERFORM NO. 1 EMERGENCY AIR BOTTLE X-RAY INSPECTION 36 06-DEC-2022 23111425 MOS +14d/-14d I:3 06-MAR-2020 20-DEC-2022 1124 HRS/MSC 4262.1 2723 **REF:** AMM 36-15-01 AFL 361038 * NO. 2 EMERGENCY AIR BOTTLE (AWL*) MOS N:0 10-FEB-2017 13-MAY-2025 23111425 180 HRS/MSC 3795.8 1130 **SCRAP REF:** AMM 36-15-01 AFL 2153 Manufacture Date: 13-MAY-2010 APH ACH PERFORM NO. 2 EMERGENCY AIR BOTTLE VISUAL INSPECTION AND HYDROSTATIC TEST 361038A 23111425 MOS 36 -3 06-MAR-2020 20-DEC-2022 +14d/-14d 06-DEC-2022 HRS/MSC 1130 REF: AMM 36-15-01 AFL



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

	Owner: SERVICE							Re	port Date: 10-SEP-202		
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	NTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT		
861038B	PERFORM NO. 2 EMERGENO	CY AIR BOTTLE X-R/	AY INSPECTION								
	23111425	MOS 36	6 +14d/-14d	1:3			06-MAR-2020	06-DEC-2022	20-DEC-2022		
	1130	HRS/MSC					4262.1				
	REF : AMM 36-15-01	AFL					2723				
361125	LEFT TAILCONE BLEED AIR	CHECK VALVE									
	M942-2	MOS		N:0			09-DEC-2007				
	1357	HRS/MSC O)/C	N:0			0				
	REF: AMM 36-10-03	AFL		N:0			0				
361126	RIGHT TAILCONE BLEED AIF	R CHECK VALVE									
	M942-2	MOS		N:0			09-DEC-2007				
	1363	HRS/MSC O)/C	N:0			0				
	REF: AMM 36-10-03	AFL		N:0			0				
362001	LANDING GEAR/BRAKE AIR	PRESSURE INDICAT	TOR								
	820-666	MOS		N:0			09-DEC-2007				
	530	HRS/MSC O)/C	N:0			0				
	REF : AMM 36-20-01	AFL		N:0			0				
362003	PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER										
	124058-5000	MOS		N:0			09-DEC-2007				
	42927	HRS/MSC O)/C	N:0			0				
	REF : AMM 36-20-02	AFL		N:0			0				
362004	SECONDARY EMERGENCY A	AIR SYSTEM PRESS	SURE TRANSDUCER								
	124058-5000	MOS		N:0			09-DEC-2007				
	42933	HRS/MSC O)/C	N:0			0				
	REF : AMM 36-20-02	AFL		N:0			0				
362011	NO. 1 ENGINE HI-LIMIT BLEE	D AIR THERMOSTA	τ								
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O)/C	N:0			0				
	REF : AMM 36-20-03	AFL		N:0			0				
362012	NO. 2 ENGINE HI-LIMIT BLEE	D AIR THERMOSTA	ιΤ								
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O)/C	N:0			0				
	REF: AMM 36-20-03	AFL		N:0			0				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICE	OS ALKLOS PL	ATTION C.A.	operator. AEKONAOTI	C SOLUTIONS JOAN	Rej	port Date: 10-SEP-2021				
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT				
362019	NO. 1 INBOARD OVERHEAT	SWITCH									
	M2001-559	MOS		N:0		09-DEC-2007					
	000164	HRS/MSC	O/C	N:0		0					
	REF: GENERIC NO REF	AFL		N:0		0					
362020	NO. 2 INBOARD OVERHEAT	SWITCH									
	M2001-559	MOS		N:0		09-DEC-2007					
	000197	HRS/MSC	O/C	N:0		0					
	REF: GENERIC NO REF	AFL		N:0		0					
CHAPTER 38	WATER/WASTE										
381009	FORWARD TOILET DRAIN, H	IEATED MAST									
	116393-101E	MOS		N:0		09-DEC-2007					
	2238	HRS/MSC	O/C	N:0		0					
	REF : AMM 38-32-01	AFL		N:0		0					
381010	AFT TOILET DRAIN, HEATED	AFT TOILET DRAIN, HEATED MAST									
	116393-101E	MOS		N:0		09-DEC-2007					
	2240	HRS/MSC	O/C	N:0		0					
	REF : AMM 38-32-01	AFL		N:0		0					
381020	TOILET WATER PUMP										
	PN	MOS		N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0					
	REF: GENERIC NO REF	AFL		N:0		0					
381030	TOILET TIMER										
	9060-2	MOS		N:0		09-DEC-2007					
	T5246	HRS/MSC	O/C	N:0		0					
	REF: GENERIC NO REF	AFL		N:0		0					
381050	TOILET MACERATOR										
	PN	MOS		N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0					
	REF: GENERIC NO REF	AFL		N:0		0					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TACK NO	TACK DECORPTION	LINUE	INITEDIAL	TIME OWNER		\//A-D-D	ACMBI MARGE	ке	port Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NE	G/APU) A/C	MAX LIMIT
381060	LAVATORY ON-DEMAND WATE	R SYSTEM VO	DLTAGE REGULATOR	R					
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC AFL	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
381070	LAVATORY SINK PUMP								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
382015	NO. 1 HOT WATER TANK								
	AR9061-3	MOS					05-MAY-2008		
	0221	HRS/MSC	O/C	N:0			435.73		
	REF: GENERIC NO REF	AFL		N:0			187		
382016	NO. 2 HOT WATER TANK								
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
383101	LAVATORY TOILET ASSEMBLY								
	9060-4A	MOS		N:0			22-OCT-2009		
	B2530	HRS/MSC	O/C	N:0			1756.3		
	REF: AMM 38-31-01	AFL		N:0			799		
HAPTER 44	CABIN SYSTEMS								
44-29-00-M100495ICT	GENERAL VISUAL INSPECTION ST01450WI-D, IFCA M100495ICT		SHOW 4000 SYSTEM	COMPONENTS (STC					
		MOS					09-DEC-2007		
		HRS/MSC	4800				0	4800	
STC-SUPPLEMENTAL TYPE CERTIFICATE	REF:	AFL							
441000	FUNCTIONAL TEST OF THE PA	SSENGER AD	DRESS SYSTEM						
		MOS					06-MAR-2020		
		HRS/MSC	300				4262.1	4562.1	
SMM	REF:	AFL					2723		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIOS	AEREUS P	LATINOM C.A. C	perator: AERONAUTI	SOLUTIONS	OANRIGER, S.A DE C.V.	Report Date: 10-SEP-202:
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE		ARR COMPLIANCE NEXT KP (ENG/AF	DUE MAX
442401	ANTENNA, DUAL GPS/XM AFT						
	CI401-460 189344 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C			23-MAR-2011 2668.32 1272	
442403	GPS/XM ANTENNA						
	CI-401-460 189346 REF : AMM 34-54-02	MOS HRS/MSC AFL	O/C			03-MAR-2011 2668.32 1272	
HAPTER 45	CENTRAL MAINT SYSTEM						
451001	MAINTENANCE DIAGNOSTIC (MDC) COMPUT	TER				
	822-1987-005 340MD REF : AMM 45-10-00	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0		31-AUG-2018 4067 2472	
CHAPTER 49	AIRBORNE AUXILIARY PO	WER					
490101	COCKPIT APU CONTROL PANE	EL					
	201-6-035-9 003908 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0		14-APR-2018 3981.3 2361	
490102	APU RELAY BOX						
	201-6-028-9 4872-33 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0		01-JUN-2011 2785.83 1342	
490103	(ESU / DESU) ELECTRONIC SE	QUENCE UNIT	-				
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		09-DEC-2007 0 0	
490105	APU (GCU) GENERATOR CON	FROL UNIT					
	GCSG505-16G 50447 REF : See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0		25-JUL-2016 3709.5 2046	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021

							Re _l	oort Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
490106	BITE ANNUNCIATOR BOX							
	161212-100	MOS		N:0			09-DEC-2007	
	0645-0835	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
490109	UPPER CURRENT TRANSFOR	MER						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
493101	APU FUEL SHUTOFF VALVE							
	EM91-41	MOS		N:0			09-DEC-2007	
	06-050489	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
493102	APU FUEL BOOST PUMP							
	1500-00-22	MOS					24-JUN-2010	
	2090	HRS/MSC	O/C	O:0			2199.58	
	REF: See Workcard	AFL		O:0			1012	
496103	APU FIRE HORN							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: See Workcard	AFL		N:0			0	
498010	EXHAUST (APU) DUCT							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
49APU1	APU							
	4503135	MOS					26-JAN-2016	
49.APU1	SP-E980299	HRS/MSC	E/C	N:1727 R:0			3583.3	
	REF: GENERIC NO REF	AFL					1916	

APU Model: T-20G-10C3A (CIMMS) Serial # SP-E980299 Part # 4503135



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE NEXT DUE	ort Date: 10-SEP-20 MAX
	PART/SERIAL					EXP	(ENG/APU) A/C	LIMIT
90102	APU - BYTE BOX							
	161212-100	MOS		N:0			13-JAN-1999	
	V66-T0633	HRS/MSC	O/C	N:0			0	
	REF:	APUS		N:0			0	
190103	APU - ELECTRONIC SENSOR	R (ESU) UNIT						
	160935-203B	MOS		N:0			13-JAN-1999	
	0110	HRS/MSC	O/C	N:0			0	
	REF:	APUS		N:0			0	
91000-01	APU - FUEL PUMP							
	161627-2	MOS		R:0			14-AUG-2015	
	V21T0295	HRS/MSC	O/C	R:0			1726	
	REF:	APUS		R:0			3359	
492001	APU - COMBUSTOR HOUSIN	IG ASSEMBLY						
	PN	MOS		N:0			13-JAN-1999	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF:	APUS		N:0			0	
192002	APU - APU EXHAUST THERN	MOCOUPLE						
	PN	MOS		N:0			13-JAN-1999	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF:	APUS		N:0			0	
192005	APU - APU COMBUSTION LIN	NER						
	163416-100A	MOS		R:0			15-APR-2016	
	SN-UNKNOWN	HRS/MSC	O/C	R:0			1751	
	REF:	APUS		R:0			3497	
92020	APU - IGNITER							
	160544-1	MOS					14-AUG-2015	
	NSN	HRS/MSC	O/C				1726	
	REF:	APUS					3359	
92201	APU - ROTOR BEARING							
	161623-1	MOS		N:0			14-AUG-2015	
	N186	HRS/MSC	O/C	N:0			1726	
	REF:	APUS		N:0			3359	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

		DS AEREOS PLATINUM C.A.	_		F	Report Date: 10-SEP-202
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP		MAX
92202	APU - ROTOR BEARING					
	161623-1	MOS	N:0		14-AUG-2015	
	N195	HRS/MSC O/C	N:0		1726	
	REF:	APUS	N:0		3359	
92300	APU - PRESSURE (LOW OIL)	SWITCH				
	161628-1	MOS			27-JUL-2006	
	256	HRS/MSC O/C			1127	
	REF:	APUS			2026	
92320	APU - SPEED (MAGNETIC PIC	CK-UP) SENSOR				
	169080-1	MOS	N:0		13-JAN-1999	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF:	APUS	N:0		0	
193001	APU - FUEL CONTROL					
	160962-6	MOS			14-AUG-2015	
	2494153	HRS/MSC O/C			1726	
	REF:	APUS			3359	
93003	APU - PUMP ASSEMBLY, FUE	EL CONTROL				
	4502863	MOS	N:0		13-JAN-1999	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF:	APUS	N:0		0	
193005	APU - FUEL ATOMIZER INTEI	RCONNECT HARNESS				
	161627-1	MOS	N:0		13-JAN-1999	
	0217	HRS/MSC O/C	N:0		0	
	REF:	APUS	N:0		0	
93007	APU - ASSEMBLY, FUEL ATO	MIZER				
	4504283A	MOS			20-AUG-2013	
	10-03-31	HRS/MSC O/C			1634	
	REF:	APUS			3147	
93055	APU - ATOMIZER CUP MOTO	PR				
	161612-7	MOS	N:0		13-JAN-1999	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICIO	US AEREUS P	LATINOM C.A.	Operator. AERONAOTI	.C SOLUTION	3 JUANK	IGER, S.A DE C	Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493102	APU - FUEL PUMP								
	1500-00-22	MOS		O:0			28-SEP-2010		
	0179	HRS/MSC	O/C	O:0			1612		
	REF:	APUS		O:0			3041		
494001	APU - IGNITION EXCITER								
	4951302	MOS		N:0			13-JAN-1999		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF:	APUS		N:0			0		
495001	APU - TURBINE WHEEL								
	164253-3	MOS		N:0			14-AUG-2015		
	HB109	HRS/MSC		N:0			1726		
LIFE LIMIT	REF:	APUS	3500	N:0			3359	6859	
495005	APU - COMPRESSOR WHEEL	L							
	160915-4	MOS		N:1			13-JAN-1999		
	V63-H375A	HRS/MSC		N:8			0		
LIFE LIMIT	REF:	APUS	7000	N:54			0	6946	
497010	APU - HOURMETER/EVENT (COUNTER INDICA	ATOR						
	4950959	MOS		N:0			13-JAN-1999		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF:	APUS		N:0			0		
HAPTER 52	DOORS								
05-10-29-L5210025	VISUAL INSPECTION EXTER	IOR LWR DOOR	STRUCTURE/HING	E FOR CORROSION					
		MOS HRS/MSC	24 +14d/-	14d	-39		06-MAR-2020 4262.1	26-JAN-2022	09-FEB-2022
	REF: GENERIC NO REF	AFL					2723		
521001	UPPER PASSENGER/CREW	DOOR							
	5410501-128	MOS		N:0			09-DEC-2007		
	W275	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-10-00	AFL		N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	DS AEREOS F	LATINUM C.	A. Operator: AERONAUTI	C SOLUTIONS	JOANK	IGER, S.A DE C.	v. Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE		WARR EXP	COMPLIANCE		MAX LIMIT
521002	LOWER PASSENGER/CREW	DOOR							
	5410536-033	MOS		N:0			09-DEC-2007		
	W383	HRS/MSC	O/C	N:0			0		
	REF : AMM 52-10-00	AFL		N:0			0		
521003	UPPER PASSENGER/CREW	DOOR HANDLE							
	6600480-1	MOS		N:0			09-DEC-2007		
	399	HRS/MSC	O/C	N:0			0		
	REF : AMM 52-10-02	AFL		N:0			0		
521004	UPPER PASSENGER/CREW	DOOR LOCK AS	SEMBLY						
	ASL 426	MOS		N:0			26-FEB-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			3430.9		
	REF : AMM 52-10-03	AFL		N:0			1765		
5210054	CABIN DOOR AND EMERGE	NCY EXIT/BAGG	AGE DOOR HAN	IDLE - REPLACE					
		MOS HRS/MSC		4d/-14d	-88		06-MAR-2020 4262.1	09-DEC-2031	23-DEC-2031
	REF: See Workcard	AFL	6000 +2	5/-25			2723	8723	8748
521006	UPPER PASSENGER/CREW	DOOR DAMPER							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : AMM 52-10-06	AFL		N:0			0		
521008	LOWER PASSENGER/CREW	DOOR HANDLE							
	PN	MOS		N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-10-08	AFL		N:0			0		
521010	FORWARD PASSENGER/CRI	EW LOWER DO	OR CABLE						
	6015550-003HP	MOS		N:0			01-AUG-2014		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			3366.65		
	REF : AMM 52-10-10	AFL		N:0			1685		
521011	AFT PASSENGER/CREW LOV	WER DOOR CAE	BLE						
	6015550-002	MOS		N:0			15-FEB-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0			2586.6		
	REF : AMM 52-10-10	AFL					1224		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TACK NO	TACK DESCRIPTION	LINIT -INTERVAL	TIME CINCE	AD I WARR		oort Date: 10-SEP-20
ASK NU	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE (ENG/APU) A/C	MAX LIMIT
002	LOWER PASSENGER/CREW	DOOR DAMPER				
	1025-9400-2	MOS	N:0		09-DEC-2007	
	1173	HRS/MSC O/C	N:0		0	
	REF : AMM 52-10-11	AFL	N:0		0	
522000	EMERGENCY EXIT / BAGGA	GE DOOR				
	6011501-015	MOS	N:0		09-DEC-2007	
	W346	HRS/MSC O/C	N:0		0	
	REF : AMM 52-20-00	AFL	N:0		0	
22002	EMERGENCY EXIT / BAGGA	GE DOOR HANDLE				
	6600480-2	MOS	N:0		09-DEC-2007	
	385	HRS/MSC O/C	N:0		0	
	REF : AMM 52-20-02	AFL	N:0		0	
522007	EMERGENCY EXIT DOOR FO	DRWARD SNUBBER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 52-20-07	AFL	N:0		0	
522008	EMERGENCY EXIT DOOR AF	T SNUBBER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 52-20-07	AFL	N:0		0	
22025	EMERGENCY EXIT/BAGGAG	E DAMPER				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 52-20-00	AFL	N:0		0	
522032	EMERGENCY EXIT/BAGGAG	E DOOR WINDOW ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 52-20-06	AFL	N:0		0	
22032A	PRISM CHECK EMERGENCY	EXIT/BAGGAGE DOOR WINDOW	ASSEMBLY 05-10-29-M560000	8		
	PN	MOS			20-JUN-2008	
	SN-UNKNOWN	HRS/MSC C/C			564.8	
	REF : NDT 56-30-01	AFL			243	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ WA	RR COMPLIANCE NEX	Report Date: 10-SEP-20
ASK NU	PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ WA		FDUE MAX PU) A/C LIMIT
523101	TAILCONE BAGGAGE DOOR						
	6011552-17	MOS		N:0		09-DEC-2007	
	1000039152	HRS/MSC	O/C	N:0		0	
	REF : AMM 52-31-01	AFL		N:0		0	
523102	TAILCONE BAGGAGE HANDLE	<u> </u>					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
	REF : AMM 52-31-01	AFL		N:0		0	
524001	PERFORM AFT AVIONICS DO	OR GAP AND M	ISMATCH INSPECT	ION (RVSM) (REFER TO 52-4	0-01)		
		MOS	24 +14d/-1	4d	-47		N-2023 07-FEB-2023
	DEE: ANNA 50 40 04	HRS/MSC				4286.9	
	REF : AMM 52-40-01	AFL				2754	
524003	LEFT FORWARD NOSE AVION	ICS DOOR					
	6010430-003-903	MOS		N:0		09-DEC-2007	
	0296	HRS/MSC	O/C	N:0		0	
	REF : AMM 52-40-01	AFL		N:0		0	
524004	RIGHT FORWARD NOSE AVIO	NICS DOOR					
	6010430-004-904	MOS		N:0		09-DEC-2007	
	0296	HRS/MSC	O/C	N:0		0	
	REF : AMM 52-40-01	AFL		N:0		0	
524005	LEFT AFT NOSE AVIONICS DO	OOR					
	6010431-003-903	MOS		N:0		09-DEC-2007	
	0296	HRS/MSC	O/C	N:0		0	
	REF : AMM 52-40-01	AFL		N:0		0	
524006	RIGHT AFT NOSE AVIONICS D	OOR					
	6010431-004-904	MOS		N:0		09-DEC-2007	
	0296	HRS/MSC	O/C	N:0		0	
	REF : AMM 52-40-01	AFL		N:0		0	
524007	TAILCONE AVIONICS DOOR						
	5412500-021	MOS		N:0		09-DEC-2007	
	0250	HRS/MSC	O/C	N:0		09-520-2007	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	OS AEREOS PLATINUM C.A.	operator: AEKONAU II	C SOLUTIONS JUANE	Report Date: 10-SEP-2					
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP						
527005	CREW DOOR WARNING BOX	X ASSEMBLY								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 52-70-05	AFL	N:0		0					
527006	EMERGENCY EXIT DOOR W	ARNING BOX ASSEMBLY								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 52-70-05	AFL	N:0		0					
528001	LEFT INBOARD MAIN LANDII	NG GEAR DOOR								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 52-80-01	AFL	N:0		0					
528002	RIGHT INBOARD MAIN LAND	DING GEAR DOOR								
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 52-80-01	AFL	N:0		0					
528003	LEFT OUTBOARD MAIN LANDING GEAR DOOR									
	PN	MOS	N:0		09-DEC-2007					
	SN-UNKNOWN	HRS/MSC O/C	N:0		0					
	REF : AMM 52-80-01	AFL	N:0		0					
528004	RIGHT OUTBOARD MAIN LAI	NDING GEAR DOOR								
	6022151-802	MOS	R:0		26-JUN-2012					
	SN-UNKNOWN	HRS/MSC O/C	R:0		3024.7					
	REF : AMM 52-80-01	AFL	R:0		1489					
528101	LEFT NOSE LANDING GEAR	DOOR								
	5410450-19	MOS	N:0		09-DEC-2007					
	60-333	HRS/MSC O/C	N:0		0					
	REF : AMM 52-81-01	AFL	N:0		0					
528102	RIGHT NOSE LANDING GEA	R DOOR								
	5410450-20	MOS	N:0		09-DEC-2007					
	60-333	HRS/MSC O/C	N:0		0					
	REF: AMM 52-81-01	AFL	N:0		0					



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT CABIN DOOR AND EMERGENCY EXIT/BAGGAGE DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATION PKG AA5210056 (s) PKG 18 MOS 48 +14d/-14d 06-MAR-2020 HRS/MSC 1200 +25/-25 4262.1 **REF:** AMM 12-21-03 AFL 2723 CHAPTER 53 **FUSELAGE** INSPECTION OF UPPER FUSELAGE SKIN UNDER THE AFT OXYGEN LINE FAIRING 05-10-29-Y5331017 MOS 144 +14d/-14d 10-FEB-2017 10-FEB-2029 24-FEB-2029 HRS/MSC 3808.9 **REF:** AMM 53-50-06 AFL 2164 05-10-30-RVSM-N5313000 PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (RVSM) (REFER TO 53-11-01) MOS 24 +14d/-14d -47 12-MAR-2021 24-JAN-2023 07-FEB-2023 HRS/MSC 4286.9 AFL 2754 **REF:** AMM 53-11-01 05-11-00-T5322000 REPLACE KEELBEAM ATTACHMENT BOLTS MOS -88 06-MAR-2020 23-DEC-2031 144 +14d/-14d 09-DEC-2031 HRS/MSC 4262.1 **REF:** AMM 53-10-02 AFL 6000 +25/-25 2723 8723 8748 531001 AFT PRESSURE BULKHEAD PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 53-10-01 **AFL** N:0 0 534001 NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING PΝ N:0 09-DEC-2007 MOS SN-UNKNOWN HRS/MSC O/C N:0 0 REF: AMM 53-40-02 AFL N:0 0 534002 NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0

N:0

AFL

0

REF: AMM 53-40-02



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 534003 NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 0 **REF:** AMM 53-40-02 AFL N:0 534004 NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING PΝ MOS N:0 09-DEC-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** AMM 53-40-02 AFL N:0 0 535001 **RADOME** MOS N:0 09-DEC-2007 5410420-039-539 020R HRS/MSC O/C N:0 0 N:0 **REF:** AMM 53-50-01 AFL 0 U5331012 * REMOVE ACCESS PANELS (TOP OF FUSELAGE) AND PERFORM VISUAL INSPECTION OF ELECTRICAL BOXES FOR SECURITY OF ATTACHMENT, CORROSION, AND GENERAL CONDITION. INSPECT DOUBLERS, FUSELAGE SKIN, INTERIOR FRAMES, AND INTERCOSTALS FOR FATIGUE CRACKS AND GENERAL CONDITION. (AWL*) MOS 49 22-FEB-2018 22-MAR-2022 HRS/MSC 3974.8 **AIRWORTHINESS** REF: GENERIC NO REF AFL 2358 CHAPTER 55 **STABILIZERS** 553001 VERTICAL STABILIZER 5431000-030 MOS N:0 09-DEC-2007 W532 HRS/MSC O/C N:0 0 REF: GENERIC NO REF AFL N:0 0 CHAPTER 56 **WINDOWS** 05-10-29-C5610022L PRISM CHECK LEFT MOS 24-AUG-2010 6600394-609 HRS/MSC C/C 487 2317.85 AFL 1066 **REF: NDT 56-10-01** 05-10-29-C5610022R PRISM CHECK RIGHT 6600394-608 MOS 24-AUG-2010

AFL

486

REF: NDT 56-10-01

HRS/MSC C/C

2317.85

1066



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	. TIME SINCE	ADJ WARF EXP	R COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
61001	LEFT WINDSHIELD ASSY					
	6600394-609	MOS	N:0		09-DEC-2007	
	487	HRS/MSC O/C	N:0		0	
	REF : AMM 56-10-01	AFL	N:0		0	
61002	RIGHT WINDSHIELD ASSY					
	6600394-608	MOS	N:0		09-DEC-2007	
	486	HRS/MSC O/C	N:0		0	
	REF: AMM 56-10-01	AFL	N:0		0	
61009	LEFT COCKPIT CREW WINDO	DW .				
	6600512-001	MOS	N:0		09-DEC-2007	
	183	HRS/MSC O/C	N:0		0	
	REF: AMM 56-10-02	AFL	N:0		0	
561010	RIGHT COCKPIT CREW WIND	DOW				
	6600512-002	MOS	N:0		09-DEC-2007	
	208	HRS/MSC O/C	N:0		0	
	REF : AMM 56-10-02	AFL	N:0		0	
562011	LEFT NO. 1 CABIN WINDOW					
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 56-20-01	AFL	N:0		0	
562011A	PRISM CHECK LEFT NO. 1 CA	ABIN WINDOW 05-10-29-M5600	0008			
	PN	MOS			24-AUG-2010	
	SN-UNKNOWN	HRS/MSC C/C			2317.85	
	REF : NDT 56-30-01	AFL			1066	
62013	LEFT NO. 2 CABIN WINDOW					
	LA6600405-20	MOS	N:0		12-DEC-2011	
	3192	HRS/MSC O/C	N:0		3011.9	
	REF: AMM 56-20-01	AFL	N:0		1487	
62013A	PRISM CHECK LEFT NO. 2 CA	ABIN WINDOW 05-10-29-M5600	0008			
	LA6600405-20	MOS			25-JUL-2016	
	3192	HRS/MSC C/C		-97.6	3709.5	
	REF : NDT 56-30-01	AFL			2046	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	S AEREUS P		perator: AERONAUTI	C SOLUTIO		•	Re	port Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
62015	LEFT NO. 3 CABIN WINDOW								
	LA6600405-20	MOS					04-MAR-2010		
	2694	HRS/MSC	O/C				1997.87		
	REF: AMM 56-20-01	AFL					916		
562015A	PRISM CHECK LEFT NO. 3 CA	BIN WINDOW 0	5-10-29-M5600008						
	LA6600405-20	MOS					16-FEB-2011		
	2694	HRS/MSC	C/C				2586.6		
	REF: NDT 56-30-01	AFL					1224		
562017	LEFT NO. 4 CABIN WINDOW								
	LA6600405-20	MOS					24-JUN-2010		
	2796	HRS/MSC	O/C	N:0			2199.58		
	REF : AMM 56-20-01	AFL		N:0			1012		
562017A	PRISM CHECK LEFT NO. 4 CA	BIN WINDOW 0	5-10-29-M5600008						
	LA6600405-20	MOS					16-FEB-2011		
	2796	HRS/MSC	C/C				2586.6		
	REF: NDT 56-30-01	AFL					1224		
562019	LEFT NO. 5 CABIN WINDOW								
	LA6600405-19	MOS		N:0			12-DEC-2011		
	2396	HRS/MSC	O/C	N:0			3011.9		
	REF : AMM 56-20-01	AFL		N:0			1487		
562019A	PRISM CHECK LEFT NO. 5 CA	BIN WINDOW 0	5-10-29-M5600008						
	LA6600405-19	MOS					25-JUL-2016		
	2396	HRS/MSC	C/C				3709.5		
	REF: NDT 56-30-01	AFL					2046		
562022	RIGHT NO. 1 CABIN WINDOW								
	LA6600405-20	MOS					04-MAR-2010		
	2703	HRS/MSC	O/C				1997.87		
	REF: AMM 56-20-01	AFL					916		
562022A	PRISM CHECK RIGHT NO. 1 C	ABIN WINDOW	05-10-29-M5600008						
	LA6600405-20	MOS					16-FEB-2011		
	2703	HRS/MSC	C/C				2586.6		
	REF : NDT 56-30-01	AFL					1224		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owller: SERVICIO	OS AEREUS P		Operator: AERONAUTI	C SOLUTIO		R	eport Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP		MAX
62024	RIGHT NO. 2 CABIN WINDOW	1						
	LA6600405-20	MOS		N:0			22-OCT-2009	
	2572	HRS/MSC	O/C	N:0			1756.3	
	REF : AMM 56-20-01	AFL		N:0			799	
62024A	PRISM CHECK RIGHT NO. 2 C	CABIN WINDOW	05-10-29-M5600008					
	LA6600405-20	MOS					24-AUG-2010	
	2572	HRS/MSC	C/C				2317.85	
	REF: NDT 56-30-01	AFL					1066	
62026	RIGHT NO. 3 CABIN WINDOW	I						
	LA6600405-20	MOS		N:0			01-JUN-2011	
	2651	HRS/MSC	O/C	N:0			2785.83	
	REF: AMM 56-20-01	AFL		N:0			1342	
562026A	PRISM CHECK RIGHT NO. 3 (CABIN WINDOW	05-10-29-M5600008					
	LA6600405-20	MOS						
	2651	HRS/MSC	C/C					
	REF: NDT 56-30-01	AFL						
662028	RIGHT NO. 4 CABIN WINDOW	I						
	LA6600405	MOS		N:0			24-AUG-2010	
	2831	HRS/MSC	O/C	N:0			2317.85	
	REF: AMM 56-20-01	AFL		N:0			1066	
562028A	PRISM CHECK RIGHT NO. 4 (CABIN WINDOW	05-10-29-M5600008					
	LA6600405	MOS					16-FEB-2011	
	2831	HRS/MSC	C/C				2586.6	
	REF:	AFL					1224	
662030	RIGHT NO. 5 CABIN WINDOW	ı						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: AMM 56-20-01	AFL		N:0			0	
62030A	PRISM CHECK RIGHT NO. 5 C	CABIN WINDOW	05-10-29-M5600008					
	PN	MOS					24-AUG-2010	
	SN-UNKNOWN	HRS/MSC	C/C				2317.85	
	REF:	AFL					1066	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Report Date: 10-SEP-202										
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	TERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT		
CHAPTER 57	WINGS										
570001	LEFT WING										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/	С	N:0			0				
	REF : AMM 57-00-01	AFL		N:0			0				
570002	RIGHT WING										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/	С	N:0			0				
	REF : AMM 57-00-01	AFL		N:0			0				
572001	LEFT WINGLET ASSEMBLY										
	2822650-43	MOS					03-MAR-2008				
	457	HRS/MSC O/	C	N:0			238.65				
	REF : AMM 57-20-01	AFL		N:0			107				
572002	RIGHT WINGLET ASSEMBLY										
	2822650-44	MOS		N:0			09-DEC-2007				
	441	HRS/MSC O/	C	N:0			0				
	REF : AMM 57-20-01	AFL		N:0			0				
572003	LEFT WING LEADING EDGE										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/	C	N:0			0				
	REF : AMM 57-20-02	AFL		N:0			0				
572004	RIGHT WING LEADING EDGE										
	PN	MOS		N:0			09-DEC-2007				
	SN-UNKNOWN	HRS/MSC O/	С	N:0			09-DEC-2007 0				
	REF : AMM 57-20-02	AFL		N:0			0				
572025	LEFT FRONT WINGLET SPAR	R FITTING									
	6022621-1	MOS		N:0			09-DEC-2007				
	H0081	HRS/MSC O/	С	N:0			09-DEC-2007				
	REF: GENERIC NO REF	AFL		N:0			0				



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

							ANRIGER, S.A DE C.V.	Report Date:	10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTER\	AL TIME S	INCE A	DJ WAR EXP			
572026	RIGHT FRONT WINGLET SPA	AR FITTING							
	6022621-2	MOS		N:0			09-DEC-2007		
	6879/016	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
572027	LEFT AFT WINGLET SPAR FI	TTING							
	6022622-1	MOS		N:0			09-DEC-2007		
	6894/014	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
572028	RIGHT AFT WINGLET SPAR F	TITTING							
	6022622-2	MOS		N:0			09-DEC-2007		
	6806/018	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
C5720020 (s)	VISUALLY INSPECT INTERNA ATTENTION TO THE MAIN LA AT WS 53.04. (REFER TO 5-1)	ANDING GEAR A							
	PKG 27	MOS	144	+14d/-14d			06-MAR-2020		
		HRS/MSC					4262.1		
	REF: GENERIC NO REF	AFL	6000	+25/-25			2723		
C5720025 (s)	X-RAY INSPECT THE OUTBO 2, 57-30-01.)	ARD LOWER WI	NG SKIN F	ROM WS 31 TO WS 61.	(REFER TO NDI MANUA	AL [NDI-2], PA	RT PKG		
	PKG 27	MOS	144	+14d/-14d			06-MAR-2020		
		HRS/MSC					4262.1		
	REF : NDT 57-30-01	AFL	6000	+25/-25			2723		
C5720040 (s)	INSPECT THE JOINT AT WS FOR LOOSE OR MISSING FA 5-10-00.)						PKG		
	PKG 27	MOS	144	+14d/-14d			06-MAR-2020		
	REF: GENERIC NO REF	HRS/MSC AFL	6000	+25/-25			4262.1 2723		
5740001 (s)	WITH LEADING EDGE ASSEM CRACKS, OVERHEAT (DISCO	DLORED PRIMER							
55740001 (S)	CORROSION, AND GENERAL	CONDITION.							
.5740001 (S)	CORROSION, AND GENERAL PKG 27	MOS	144	+14d/-14d			06-MAR-2020		
55740001 (S)	•		144	+14d/-14d			06-MAR-2020 4262.1		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 WARR TASK NO TASK DESCRIPTION UNIT TIME SINCE **COMPLIANCE NEXT DUE** INTERVAL ADJ MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT WITH LEADING EDGE LOWER CUFF FAIRING ASSEMBLIES REMOVED, INSPECT LOWER WING SKIN COVERED BY PKG C5740002 (s) CUFF FAIRING AND INNER SURFACE OF CUFF FOR EVIDENCE OF FATIGUE CRACKS. LOOSE OR MISSING FASTENERS, CORROSION, AND GENERAL CONDITION. PKG 27 MOS 144 +14d/-14d 06-MAR-2020 HRS/MSC 4262.1 REF: GENERIC NO REF AFL 6000 +25/-25 2723 CHAPTER 71 **POWER PLANT** 05-11-00-E7120049L REPLACE * NO. 1 ENGINE AFT MOUNT ATTACH BOLTS (AWL*) MOS 09-DEC-2007 HRS/MSC 20000 0 20000 LIFE LIMIT **REF:** AMM 71-20-10 AFL 0 05-11-00-E7120049R REPLACE * NO. 2 ENGINE AFT MOUNT ATTACH BOLTS (AWL*) 09-DEC-2007 MOS HRS/MSC 20000 0 20000 LIFE LIMIT **REF:** AMM 71-20-10 **AFL** 0 REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA 05-11-00-G7110021L MOS 09-DEC-2007 HRS/MSC O/C 0 **REF:** AMM 28-00-00 **TEFLON** AFL 0 REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA 05-11-00-G7110021R MOS 09-DEC-2007 HRS/MSC O/C 0 **TEFLON** AFL 0 **REF:** AMM 28-00-00 REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES 05-11-00-G7110022L ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL) MOS 09-DEC-2007 HRS/MSC O/C 0 **TEFLON** REF: GENERIC NO REF AFL 0 REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES 05-11-00-G7110022R ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL) 09-DEC-2007 MOS HRS/MSC O/C 0 **TEFLON REF:** GENERIC NO REF AFL 0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

			LATINOTI CIAI	Operator. AERONAUTI			CIOLITY SIA DE C	Re _l	ort Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
05-11-00-M7120048L	REPLACE NO. 1 ENGINE * FOR RA22021-8-69, AIC457-8-69, AIC	DRWARD ENGIN AND PBF1340-8-0	E MOUNT ATTACH 69) (AWL*)	BOLTS (70315-12-986, 83648	-8-18, 77458-8-6	69,			
		MOS					09-DEC-2007		
		HRS/MSC	20000				0	20000	
LIFE LIMIT	REF: AMM 71-20-05	AFL					0		
05-11-00-M7120048R	REPLACE NO. 2 ENGINE * FO RA22021-8-69, AIC457-8-69, A	ORWARD ENGIN AND PBF1340-8-0	E MOUNT ATTACH 69) (AWL*)	BOLTS (70315-12-986, 83648	-8-18, 77458-8-6	69,			
		MOS					09-DEC-2007		
		HRS/MSC	20000				0	20000	
LIFE LIMIT	REF : AMM 71-20-05	AFL					0		
711005	LEFT ENGINE INLET COWL								
	282-0211-505	MOS		N:0			09-DEC-2007		
	32-100	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-05	AFL		N:0			0		
711006	RIGHT ENGINE INLET COWL								
	282-0211-507	MOS		N:0			09-DEC-2007		
	32-150	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-05	AFL		N:0			0		
711011	LEFT ENGINE UPPER ACCES	SS COWL							
	266-0208-1	MOS		N:0			09-DEC-2007		
	32-300	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-10	AFL		N:0			0		
711012	RIGHT ENGINE UPPER ACCI	ESS COWL							
	266-0208-2	MOS		N:0			09-DEC-2007		
	32-350	HRS/MSC	O/C	N:0			09-DEC-2007		
	REF: AMM 71-10-10	AFL	2	N:0			0		
711013	LEFT ENGINE LOWER ACCE	SS COWL							
•	266-0209-1	MOS		N:0			09-DEC-2007		
	32-400	HRS/MSC	O/C	N:0 N:0			09-DEC-2007		
	5	AFL	J, J	N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		ort Date: 10-SEP-20 MAX
AOR NO	PART/SERIAL	ONII INTERVAL	TIME SINCE	EXP	(ENG/APU) A/C	LIMIT
11014	RIGHT ENGINE LOWER ACC	ESS COWL				
	266-0209-2	MOS	N:0		09-DEC-2007	
	32-450	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-10	AFL	N:0		0	
711015	LEFT ENGINE PYLON APRO	N ASSEMBLY				
	266-0213-511	MOS	N:0		09-DEC-2007	
	32-510	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-15	AFL	N:0		0	
711016	RIGHT ENGINE PYLON APRO	ON ASSEMBLY				
	266-0213-512	MOS	N:0		09-DEC-2007	
	32-560	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-15	AFL	N:0		0	
11021	LEFT ENGINE OUTER FAN D	DUCT				
	282-0075-5	MOS	N:0		09-DEC-2007	
	32-610	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-20	AFL	N:0		0	
711022	RIGHT ENGINE OUTER FAN	DUCT				
	282-0075-7	MOS	N:0		09-DEC-2007	
	33-660	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-20	AFL	N:0		0	
11023	LEFT ENGINE LEFT FORWAI	RD CORE COWL				
	266-0261-501	MOS	N:0		09-DEC-2007	
	66-710	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
11024	RIGHT ENGINE LEFT FORW	ARD CORE COWL				
	266-0261-501	MOS	N:0		09-DEC-2007	
	67-710	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
11025	LEFT ENGINE RIGHT FORW	ARD CORE COWL				
	266-0261-503	MOS	N:0		09-DEC-2007	
	64-720	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		ort Date: 10-SEP-20 MAX
TOR NO	PART/SERIAL	ONT	TIME SINGL	EXP	(ENG/APU) A/C	LIMIT
11026	RIGHT ENGINE RIGHT FORV	VARD CORE COWL				
	266-0261-503	MOS	N:0		09-DEC-2007	
	63-720	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
11027	LEFT ENGINE UPPER AFT C	ORE COWL				
	266-0263-511	MOS	N:0		09-DEC-2007	
	62-730	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
11028	RIGHT ENGINE UPPER AFT	CORE COWL				
	266-0263-511	MOS	N:0		09-DEC-2007	
	63-730	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
711029	LEFT ENGINE LOWER AFT C	ORE COWL				
	266-0263-509	MOS	N:0		09-DEC-2007	
	58-740	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
711030	RIGHT ENGINE LOWER AFT	CORE COWL				
	266-0263-509	MOS	N:0		09-DEC-2007	
	59-740	HRS/MSC O/C	N:0		0	
	REF : AMM 71-10-25	AFL	N:0		0	
12001	LEFT ENGINE FORWARD IN	TERMEDIATE FITTING				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 71-20-01	AFL	N:0		0	
712002	RIGHT ENGINE FORWARD II	NTERMEDIATE FITTING				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 71-20-01	AFL	N:0		0	
12005	LEFT ENGINE FORWARD UP	PPER VIBRATION ISOLATOR				
	266D0820-501	MOS	N:0		09-DEC-2007	
	1408	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-05	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR		rt Date: 10-SEP-20 MAX
	PART/SERIAL	ONI INTERVAL	TIME ON OE	EXP		LIMIT
12006	RIGHT ENGINE FORWARD U	PPER VIBRATION ISOLATOR				
	266D0820-505	MOS	N:0		09-DEC-2007	
	1403	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-05	AFL	N:0		0	
12007	LEFT ENGINE FORWARD LO	WER VIBRATION ISOLATOR				
	266D0820-505	MOS	N:0		09-DEC-2007	
	LK1402	HRS/MSC O/C	N:0		0	
	REF: AMM 71-20-05	AFL	N:0		0	
12008	RIGHT ENGINE FORWARD L	OWER VIBRATION ISOLATOR				
	266D0820-501	MOS	N:0		09-DEC-2007	
	LK1407	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-05	AFL	N:0		0	
12009	LEFT ENGINE FORWARD MO	OUNT YOKE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-05	AFL	N:0		0	
712010	RIGHT ENGINE FORWARD IN	OUNT YOKE				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-05	AFL	N:0		0	
712011	LEFT ENGINE AFT VIBRATIO	N ISOLATOR				
	266D0820-503	MOS	N:0		09-DEC-2007	
	1066	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-10	AFL	N:0		0	
12012	RIGHT ENGINE AFT VIBRATI	ON ISOLATOR				
	266D0820-503	MOS	N:0		09-DEC-2007	
	LK1062	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-10	AFL	N:0		0	
12013	LEFT ENGINE UPPER AFT M	OUNT LINK				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 71-20-10	AFL	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

ASK NO	TASK DESCRIPTION	UNIT	INTER	VAL	TIME SINCE	ADJ	WARR	COMPLIANCE I		port Date: 10-SEP-20
	PART/SERIAL						EXP	(E	ENG/APU) A/C	LIMIT
'12014	RIGHT ENGINE UPPER AFT I	MOUNT LINK								
	266-0807-507	MOS			N:0			26-FEB-2015		
	0654BJ	HRS/MSC	O/C		N:0			3430.9		
	REF: AMM 71-20-10	AFL			N:0			1765		
712015	LEFT ENGINE LOWER AFT M	OUNT LINK								
	PN	MOS			N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0		
	REF : AMM 71-20-10	AFL			N:0			0		
712016	RIGHT ENGINE LOWER AFT	MOUNT LINK								
-	PN	MOS			N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C		N:0 N:0			09-DEC-2007 0		
	REF: AMM 71-20-10	AFL	0.0		N:0			0		
71EN1	NO. 1 ENGINE									
	31B4067-04	MOS						24-JUN-2011		
71.EN1	PCE-CA0525	HRS/MSC	E/C		N:2586.6			2844.73		
	REF: See Workcard	AFL						1382		
71EN2	NO. 2 ENGINE									
	31B4067-04	MOS						12-DEC-2011		
71.EN2	PCE-CA0526	HRS/MSC	E/C		N:3022.9			3011.9		
	REF: See Workcard	AFL						1487		
M7120068A	INSPECT NO. 1 ENGINE FOR	WARD AND AFT	MOUNT I	SOLATORS A	AND ASSOCIATED PARTS					
		MOS						16-JUL-2017		
		HRS/MSC	3600	+25/-25		-249.	9	3849.9	7200	7225
	REF: See Workcard	AFL	3000	_0, _0		_10.	-	2207	30	
M7120068B	INSPECT NO. 2 ENGINE FOR	WARD AND AFT	MOUNT I	SOLATORS A	ND ASSOCIATED PARTS					
		MOS						26-JAN-2016		
		HRS/MSC	3600	+25/-25		16.7		3583.3	7200	7225
	REF: See Workcard	AFL						1916		

ENGINE_NO. 1 Model : PW305/PW305A/PW305B (CIMMS) Serial #_PCE-CA0525 Part #_31B4067-0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

					perator: AERONAUT				Re	eport Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERV	AL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
05-P&W-710001	NO. 1 ENGINE - PERFORM OVE	ERHAUL ENGI	NE							
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50				08-JUL-2007 0 0	(7200) 7458	7250
05-P&W-710006	NO. 1 ENGINE - PERFORM HO	T SECTION INS	SPECTION							
INSPECT	REF: GENERIC NO REF	MOS HRS/MSC ENC	3600	+50				15-JUN-2017 3592 2049	(7192) 7450	7242
05-P&W-710015	NO. 1 ENGINE - PERFORM CHE	ECK AND CLEA	AN PMA HA	RNESS CO	ONNECTORS					
	REF: GENERIC NO REF	MOS HRS/MSC ENC	1200	+25/-25				30-JUL-2019 3960.5 2514	(5160.5) 5418.5	5185.5
05-P&W-710017	NO. 1 ENGINE - INSPECT AND	CLEAN P1/T1	SENSOR C	ONNECTO	PR					
	REF: GENERIC NO REF	MOS HRS/MSC ENC	600	+25/-25				24-JAN-2019 3809 2314	(4409) 4667	4434
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEI	ED OFF VALVE	SOLENOI	D						
	31B4197-05 ARK0137T REF : EMM 75-30-02	MOS HRS/MSC ENC	1500	+300/-30	00			15-JUN-2017 3592 2049	(5092) 5350	5392
05-P&W-710020	NO. 1 ENGINE - DO A VISUAL II SECURITY OF CONNECTORS -			CONDITIC	ON OF ACCESSIBLE WIRIN	IG HARNESSES	AND			
	REF: GENERIC NO REF	MOS HRS/MSC ENC	3600	+50				10-JUN-2011 2586.6 1224	(6186.6) 6444.6	6236.6
710000	NO. 1 ENGINE - COMPRESSOR	R WASH								
	REF : EMM 71-00-00	MOS HRS/MSC ENC	A/R					30-JUL-2019 3960.5 2514		
710050	NO. 1 ENGINE - RUN ENGINES									
	REF : EMM 72-00-00	MOS HRS/MSC ENC	N/A					10-JUN-2014 3108.65 1527		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 715020 NO. 1 ENGINE - ENGINE WIRE HARNESS 30B3089-03 MOS N:0 08-JUL-2007 AA79737 HRS/MSC O/C N:0 0 0 **REF:** EMM 73-20-03 **ENC** N:0 715025 NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR PΝ MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** EMM 72-60-01 **ENC** N:0 0 ENGINE NO. 2 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0526 Part # 31B4067-04 05-P&W-710001 NO. 2 ENGINE - PERFORM OVERHAUL ENGINE MOS 21-JUL-2007 (7200) 7200 HRS/MSC 7200 +50 0 7250 **OVERHAUL** REF: GENERIC NO REF 0 **ENC** 05-P&W-710006 NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION MOS 13-JAN-2016 HRS/MSC 3600 +50 3583.3 (7183.3) 7183.3 7233.3 INSPECT REF: GENERIC NO REF **ENC** 1916 05-P&W-710015 NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS MOS 30-JUL-2019 HRS/MSC 1200 +25/-25 4218.5 (5418.5) 5418.5 5443.5 **REF: GENERIC NO REF ENC** 2672 05-P&W-710017 NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR MOS 24-JAN-2019 HRS/MSC 600 +25/-25 4067 4692 (4667) 4667 REF: GENERIC NO REF **ENC** 2472 05-P&W-710019 NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID MOS 03-FEB-2014 31B4197-05 ARK0255T HRS/MSC 1500 +300/-300 3333 (4833) 4833 5133 **REF:** EMM 75-30-02 **ENC** 1670



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO							Re	port Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANC	E NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-P&W-710020	NO. 2 ENGINE - DO A VISUAL SECURITY OF CONNECTORS			ION OF ACCESSIBLE WIRI	NG HARNESSES	SAND			
	REF: GENERIC NO REF	MOS HRS/MSC ENC	3600 +50				13-JAN-2016 3583.3 1916	(7183.3) 7183.3	7233.3
710000	NO. 2 ENGINE - COMPRESSO	OR WASH							
	REF : EMM 71-00-00	MOS HRS/MSC ENC	A/R				30-JUL-2019 4218.5 2672		
710050	NO. 2 ENGINE - RUN ENGINE	:S							
	REF : EMM 72-00-00	MOS HRS/MSC ENC	N/A				10-JUN-2014 3366.65 1685		
715020	NO. 2 ENGINE - ENGINE WIR	E HARNESS							
	30B3089-03 AA80673 REF : EMM 73-20-03	MOS HRS/MSC ENC	O/C				13-JAN-2016 3583.3 1916		
715025	NO. 2 ENGINE - PERMANENT	MAGNET (PMA) ALTERNATOR						
	30B3088-02 0501 REF : EMM 72-60-01	MOS HRS/MSC ENC	O/C				13-JAN-2016 3583.3 1916		
HAPTER 72	ENGINE								
IGINE NO. 1 Model:	PW305/PW305A/PW305B (CIM	MS) Serial #	PCE-CA0525	Part # 31B4067-04					
720000	NO. 1 ENGINE - IN SERVICE I	LOW UTILIZATION	ON INSPECTION						
	REF : EMM 72-00-00	MOS HRS/MSC ENC	180 +12m				08-JUL-2007	08-JUL-2022	08-JUL-2023
720095	NO. 1 ENGINE - DISCARD LP	COMPRESSOR	FAN BLADES						
	PN	MOS					08-JUL-2007		
LIFE LIMIT	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	15000				0 0	(15000) 15158	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	O Willer DERVICE			operator: AEKONAU I I	C SOLO 1101	15 JOAN	IGEN, SIA DE C	Re	oort Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	ΓERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23001	NO. 1 ENGINE - FAN HUB								
LIFE LIMIT	30B2863-01 A00258M2 REF: EMM 72-30-01	MOS HRS/MSC ENC ACCCYC 120	000	R:0 N:1756.3 R:0 N:799 R:0 N:799			22-OCT-2009 1756.3 799		
723003	NO. 1 ENGINE - CENTRIFUGA	AL IMPELLER							
	30B4565-01 A0025KKL REF: EMM 72-30-01	MOS HRS/MSC ENC ACCCYC 700	00	N:0 N:0 N:0 N:0			08-JUL-2007 0 0		
723004	NO. 1 ENGINE - PRESSURE (CHECK IMPELLER SH	IROUD						
	REF: GENERIC NO REF	MOS HRS/MSC N/A ENC	A				08-JUL-2007 0 0		
723005	NO. 1 ENGINE - STAGE 1 COI	MPRESSOR ROTOR							
LIFE LIMIT	30B6551-01 TXA1C2278 REF : EMM 72-30-01	MOS HRS/MSC ENC ACCCYC 120	000	N:0 N:0			10-JUN-2011 2586.6 1224	(13224) 13382 M	
723005A	NO. 1 ENGINE - EDDY CURRI	ENT INSPECT STAGE	1 COMPRESS	OR ROTOR (IBR)					
NOT APPLICABLE	30B6551-01 TXA1C2278 REF : EMM 72-00-00	MOS HRS/MSC N/A ENC					10-JUN-2011 2586.6 1224		
723008	NO. 1 ENGINE - HPC (2ND-,3F	RD- AND 4TH STAGE)) ROTOR						
LIFE LIMIT	30B4745-01 56B081 REF: GENERIC NO REF	MOS HRS/MSC ENC ACCCYC 850	00	N:0 N:0 N:0 N:0			08-JUL-2007 0 0	(8500) 8658 N	
723008A	NO. 1 ENGINE - BORESCOPE	E HPC (2ND-,3RD- AN	D 4TH STAGE)	ROTOR DRUM					
	30B4745-01 56B081 REF : GENERIC NO REF	MOS HRS/MSC O/O ENC					08-JUL-2007 0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT I	NTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE	NEXT DUE	MAX	P-202
	PART/SERIAL					EXP		(ENG/APU) A/C	LIMIT	
23040	NO. 1 ENGINE - LP COMPRE	SSOR BLADES								
	PN	MOS		N:0			08-JUL-2007			
	SN-UNKNOWN	HRS/MSC (O/C	N:0			0			
	REF: GENERIC NO REF	ENC		N:0			0			
724010	NO. 1 ENGINE - BORESCOPE	E WORKSCOPE EN	IGINE CONDITION	I TREND MONITORING (ECT	M)					
		MOS					08-JUL-2007			
		HRS/MSC N	N/A				0			
	REF: GENERIC NO REF	ENC					0			
725001	NO. 1 ENGINE - STAGE 2 TUI	RBINE ASSEMBLY	VANE-RING							
	PN	MOS		N:0			08-JUL-2007			
	SN-UNKNOWN	HRS/MSC (O/C	N:0			0			
	REF : EMM 72-50-01	ENC		N:0			0			
725003	NO. 1 ENGINE - TURBINE EX	HAUST CASE ASSI	EMBLY							
	PN	MOS		N:0			08-JUL-2007			
	SN-UNKNOWN	HRS/MSC (O/C	N:0			0			
	REF : EMM 72-50-03	ENC		N:0			0			
725101	NO. 1 ENGINE - STAGE 1 TUI	RBINE DISC								
	30B2981-01	MOS		N:0			15-JUN-2017			
	A003WDE6	HRS/MSC		N:0			3592			
LIFE LIMIT	REF: EMM 72-50-01	ENC		N:0			2049			
		ACCCYC 3	3100	N:0						
725102	NO. 1 ENGINE - STAGE 2 TUI	RBINE DISC								
	30B2912-01	MOS		N:0			15-JUN-2017			
	A003RXL2	HRS/MSC		N:0			3592			
LIFE LIMIT	REF : EMM 72-50-01	ENC		N:0			2049	(5349) 5507 M		
		ACCCYC 3	3300	N:0						
725103	NO. 1 ENGINE - STAGE 3 TUI	RBINE DISC								
	30A1853	MOS		N:0			08-JUL-2007			
	MAA13108	HRS/MSC		N:0			0			
LIFE LIMIT	REF : EMM 72-50-01	ENC	40000	N:0			0			
		ACCCYC 1	10000	N:0						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICIO	US MEREUS P	LATINUM C.A.	Operator: AERONAUTI	C 30LU I IUI	NO JUANA		Repo	ort Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25104	NO. 1 ENGINE - STAGE 4 TU	RBINE DISC							
	30A1854	MOS		N:0			08-JUL-2007		
	MAA13423	HRS/MSC		N:0			0		
IFE LIMIT	REF : EMM 72-50-01	ENC		N:0			0		
		ACCCYC	10000	N:0					
25105	NO. 1 ENGINE - STAGE 5 TU	RBINE DISC							
	30A1835	MOS		N:0			08-JUL-2007		
	MAA29373	HRS/MSC		N:0			0		
IFE LIMIT	REF : EMM 72-50-01	ENC		N:0			0		
		ACCCYC	10000	N:0					
25107	NO. 1 ENGINE - FRONT HIGH	H PRESSURE TU	RBINE COVER						
	30B2748-01	MOS		N:0			08-JUL-2007		
	A0025C6T	HRS/MSC		N:0			0		
IFE LIMIT	REF : EMM 72-50-01	ENC		N:0			0		
		ACCCYC	4800	N:0					
25109	NO. 1 ENGINE - REAR HIGH	PRESSURE TUR	BINE COVER						
	30B6726-01	MOS		N:0			08-JUL-2007		
	A0025R06	HRS/MSC		N:0			0		
IFE LIMIT	REF : EMM 72-50-01	ENC		N:0			0		
		ACCCYC	4400	N:0					
25111	NO. 1 ENGINE - HIGH PRESS	SURE TURBINE F	OTOR AIR SEAL						
	30B2793-01	MOS		N:0			15-JUN-2017		
	PKAAA646451	HRS/MSC		N:0			3592		
IFE LIMIT	REF : EMM 72-50-01	ENC		N:0			2049	(6049) 6207 M	
		ACCCYC	4000	N:0					
26001	NO. 1 ENGINE - ACCESSORY	Y GEARBOX HOU	ISING						
	PN	MOS		N:0			08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : EMM 72-60-01	ENC		N:0			0		
26011	NO. 1 ENGINE - GENERAL VI	ISUAL INSPECTION	ON OF THE AC GEN	NERATOR (PMA)					
		MOS		·			08-JUL-2007		
		HRS/MSC	7200 +50				0	(7200) 7458 M 7	250
								\. = , · · • • · · · ·	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO WARR TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ **COMPLIANCE NEXT DUE** MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 727001 NO. 1 ENGINE - COMBUSTION CHAMBER LINER PΝ MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 0 **REF:** EMM 72-40-01 **ENC** N:0 727001A NO. 1 ENGINE - INSPECT FOR DAMAGE - COMBUSTION CHAMBER LINER PΝ MOS 15-JUN-2017 SN-UNKNOWN HRS/MSC 3600 +50 3592 (7192) 7450 7242 **REF:** EMM 72-40-01 **ENC** 2049 NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY 727002 PΝ MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 N:0 **REF:** EMM 72-40-01 **ENC** 0 727003 NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** EMM 72-40-01 N:0 0 **ENC** ENGINE NO. 2 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0526 Part # 31B4067-04 720000 NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION MOS 180 21-JUL-2007 21-JUL-2022 21-JUL-2023 +12m HRS/MSC 0 **REF:** EMM 72-00-00 **ENC** 0 NO. 2 ENGINE - DISCARD LP COMPRESSOR FAN BLADES 720095 PΝ 21-JUL-2007 MOS SN-UNKNOWN HRS/MSC 0 **LIFE LIMIT** REF: GENERIC NO REF **ENC** 15000 0 (15000) 15000 723001 NO. 2 ENGINE - FAN HUB 30B2256 MOS N:0 21-JUL-2007 A0025X7T HRS/MSC N:0 0 **LIFE LIMIT** N:0 0 **REF:** EMM 72-30-01 **ENC** ACCCYC 12000 N:0



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO	JS AEKEUS P		Operator: AEKONAUII	C SOLUTION	IS JUANK	IGEK, S.A DE C	.v. Rep	ort Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT
723003	NO. 2 ENGINE - CENTRIFUGA	AL IMPELLER							
	30B4565-01	MOS		N:0			21-JUL-2007		
	A0025KKN	HRS/MSC		N:0			0		
	REF : EMM 72-30-01	ENC		N:0			0		
		ACCCYC	7000	N:0					
723004	NO. 2 ENGINE - PRESSURE (CHECK IMPELLE	R SHROUD						
		MOS					21-JUL-2007		
		HRS/MSC	N/A				0		
	REF: GENERIC NO REF	ENC					0		
723005	NO. 2 ENGINE - STAGE 1 CO	MPRESSOR RO	TOR						
	30B6551-01	MOS		N:0			13-JAN-2016		
	TXA1D4935	HRS/MSC		N:0			3583.3		
LIFE LIMIT	REF : EMM 72-30-01	ENC		N:0			1916	(13916) 13916 M	
		ACCCYC	12000	N:0					
723005A	NO. 2 ENGINE - EDDY CURR	ENT INSPECT S	TAGE 1 COMPRESS	SOR ROTOR (IBR)					
	30B6551-01	MOS					13-JAN-2016		
	TXA1D4935	HRS/MSC	N/A				3583.3		
NOT APPLICABLE	REF: EMM 72-00-00	ENC					1916		
723008	NO. 2 ENGINE - HPC (2ND-,31	RD- AND 4TH ST	AGE) ROTOR						
	30B4745-01	MOS		N:0			21-JUL-2007		
	56B083	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(8500) 8500 M	
		ACCCYC	8500	N:0					
723008A	NO. 2 ENGINE - BORESCOPE	E HPC (2ND-,3RD)- AND 4TH STAGE)	ROTOR DRUM					
	30B4745-01	MOS					21-JUL-2007		
	56B083	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		
723040	NO. 2 ENGINE - LP COMPRES	SSOR BLADES							
23040				Nico			21-JUL-2007		
723040	PN	MOS		N:U					
723040	PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTER	RVAL TIME SINCE	ADJ WARR EXP	COMPLIANCE I	NEXT DUE MAX Eng/apu) a/c LIMIT
724010	NO. 2 ENGINE - BORESCOPE	WORKSCOPE ENGINE	CONDITION TREND MONITORING (EC	TM)		
		MOS			21-JUL-2007	
		HRS/MSC N/A			0	
	REF: GENERIC NO REF	ENC			0	
25001	NO. 2 ENGINE - STAGE 2 TUI	RBINE ASSEMBLY VANE	RING			
	PN	MOS	N:0		21-JUL-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : EMM 72-50-01	ENC	N:0		0	
725003	NO. 2 ENGINE - TURBINE EX	HAUST CASE ASSEMBLY	,			
	PN	MOS	N:0		21-JUL-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : EMM 72-50-03	ENC	N:0		0	
725101	NO. 2 ENGINE - STAGE 1 TUI	RBINE DISC				
	30B2981-01	MOS	N:0		21-JUL-2007	
	A0026EXD	HRS/MSC	N:0		0	
LIFE LIMIT	REF : EMM 72-50-01	ENC	N:0		0	
		ACCCYC 3100	N:0			
725102	NO. 2 ENGINE - STAGE 2 TUI	RBINE DISC				
	30B2912-01	MOS	N:0		21-JUL-2007	
	A0026EK0	HRS/MSC	N:0		0	
JFE LIMIT	REF : EMM 72-50-01	ENC	N:0		0	(3300) 3300 M
		ACCCYC 3300	N:0			
725103	NO. 2 ENGINE - STAGE 3 TUI	RBINE DISC				
	30A1853	MOS	N:0		21-JUL-2007	
	MAA13092	HRS/MSC	N:0		0	
IFE LIMIT	REF : EMM 72-50-01	ENC	N:0		0	
		ACCCYC 10000	N:0			
25104	NO. 2 ENGINE - STAGE 4 TUI	RBINE DISC				
	30A1854	MOS	N:0		21-JUL-2007	
	MAA13426	HRS/MSC	N:0		0	
LIFE LIMIT	REF : EMM 72-50-01	ENC	N:0		0	
		ACCCYC 10000	N:0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ACK NO	TACK DECORIDION	LINUT	INTEDVAL	TIME CINCE	AD	WARR	COMPLIANCE		ort Date: 10-SEP-2
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
25105	NO. 2 ENGINE - STAGE 5 TUI	RBINE DISC							
	30A1835	MOS		N:0			21-JUL-2007		
	MAA29344	HRS/MSC		N:0			0		
LIFE LIMIT	REF : EMM 72-50-01	ENC		N:0			0		
		ACCCYC	10000	N:0					
725107	NO. 2 ENGINE - FRONT HIGH	I PRESSURE TUI	RBINE COVER						
	30B2748-01	MOS		N:0			21-JUL-2007		
	A0025C73	HRS/MSC		N:0			0		
LIFE LIMIT	REF: EMM 72-50-01	ENC		N:0			0		
	KET : EMM 72 00 01		4800	N:0					
725109	NO. 2 ENGINE - REAR HIGH I	PRESSURE TURI	BINE COVER						
	30B6726-01	MOS		N:0			21-JUL-2007		
	A0025C6N	HRS/MSC		N:0			0		
LIFE LIMIT	REF: EMM 72-50-01	ENC		N:0			0		
		ACCCYC	4400	N:0					
725111	NO. 2 ENGINE - HIGH PRESS	SURE TURBINE R	OTOR AIR SEAL						
	30B2793-01	MOS		N:0			21-JUL-2007		
	AWE010423	HRS/MSC		N:0			0		
LIFE LIMIT	REF: EMM 72-50-01	ENC		N:0			0	(4000) 4000 M	
		ACCCYC	4000	N:0				(,	
726001	NO. 2 ENGINE - ACCESSORY	Y GEARBOX HOU	SING						
	PN	MOS		N:0			21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : EMM 72-60-01	ENC	5.5	N:0			0		
726011	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION	ON OF THE AC GEN	ERATOR (PMA)					
		MOS		` '			21-JUL-2007		
		HRS/MSC	7200 +50				21-JUL-2007 0	(7200) 7200 M	7250
	REF: GENERIC NO REF	ENC	1200 +30				0	(1200) 1200 W	1200
727001	NO. 2 ENGINE - COMBUSTIO	N CHAMBER LIN	FR						
501				Nio			12 IAN 2242		
	30B6146-01	MOS	0/0	N:0			13-JAN-2016		
	A003NA31	HRS/MSC	U/U	N:0			3583.3		
	REF : EMM 72-40-01	ENC		N:0			1916		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE		port Date: 10-SEP-2 MAX
TASK NO	PART/SERIAL	UNII	INTERVAL	TIME SINCE	— ADJ	EXP	COMPLIANCE	(ENG/APU) A/C	MAX LIMIT
727001A	NO. 2 ENGINE - INSPECT FO	R DAMAGE - CC	MBUSTION CHAMBE	R LINER					
	30B6146-01 A003NA31 REF : EMM 72-40-01	MOS HRS/MSC ENC	3600 +50				13-JAN-2016 3583.3 1916	(7183.3) 7183.3	7233.3
727002	NO. 2 ENGINE - INNER COME	BUSTION LINER	ASSEMBLY						
	PN	MOS		N:0			21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : EMM 72-40-01	ENC		N:0			0		
727003	NO. 2 ENGINE - OUTER COM	BUSTION LINER	ASSEMBLY						
	PN	MOS		N:0			21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : EMM 72-40-01	ENC		N:0			0		
HAPTER 73	ENGINE FUEL AND CON	TROL							
733010	DUAL FUEL FLOW CONVERT								
	10540B08F07	MOS		N:0			09-DEC-2007		
	07051051A	HRS/MSC	O/C	N:0			0		
	REF : AMM 73-31-03	AFL		N:0			0		
733101	LEFT ENGINE FUEL FLOW TI	RANSMITTER							
	7600021-1	MOS		N:0			09-DEC-2007		
	601430	HRS/MSC	O/C	N:0			0		
	DEE ANAL 70 04 04	AFL		N:0			0		
	REF: AMM 73-31-01	AIL							
733102	RIGHT ENGINE FUEL FLOW			14.0					
733102	RIGHT ENGINE FUEL FLOW						09-DEC-2007		
733102		TRANSMITTER	O/C	N:0 N:0			09-DEC-2007 0		
733102	RIGHT ENGINE FUEL FLOW 7600021-1	TRANSMITTER MOS	O/C	N:0					
733102	RIGHT ENGINE FUEL FLOW 7600021-1 602000	TRANSMITTER MOS HRS/MSC AFL	O/C	N:0 N:0			0		
	RIGHT ENGINE FUEL FLOW 7600021-1 602000 REF: AMM 73-31-01	TRANSMITTER MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			0		
	RIGHT ENGINE FUEL FLOW 7600021-1 602000 REF: AMM 73-31-01 LEFT ENGINE FUEL FLOW IN	TRANSMITTER MOS HRS/MSC AFL		N:0 N:0			0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCI		port Date: 10-SEP-20 MAX LIMIT
733104	RIGHT ENGINE FUEL FLOW	INDICATOR							
	PN SN-UNKNOWN REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2007 0 0		
GINE NO.1 Model	: PW305/PW305A/PW305B (CIM	IMS) Serial # I	PCE-CA0525	Part # 31B4067-04					
05-P&W-730001	NO. 1 ENGINE - REPLACE EN	NGINE FUEL FILTE	R ELEMENT						
	REF : EMM 73-10-03	MOS HRS/MSC ENC	12 1200 +25/-25				12-MAR-2021 4028.9 2596	12-MAR-2022 (5228.9) 5486.9	5253.9
05-P&W-730005	NO. 1 ENGINE - CLEAN THE	PRIMARY FUEL NO	OZZLE						
	REF : EMM 73-10-04	MOS HRS/MSC ENC	1800 +600/-60	0			15-JUN-2017 3592 2049	(5392) 5650	5992
731001	NO. 1 ENGINE - FUEL PUMP								
	30B1910 MX708624A REF : EMM 73-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			08-JUL-2007 0 0		
731002	NO. 1 ENGINE - MOTIVE FLC	W VALVE							
	30B2062 C37647 REF : EMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			08-JUL-2007 0 0		
731003	NO. 1 ENGINE - FUEL FILTER		OD SWITCH						
	30B3500-03 HE1416 REF : EMM 73-10-03	MOS HRS/MSC ENC					10-JUN-2011 2586.6 1224		
731004	NO. 1 ENGINE - UPPER PRIM	/ARY FUEL NOZZL	E						
	31B5832-04 1BDM1716 REF : EMM 73-10-04	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			15-JUN-2017 3592 2049		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** MAX **PART/SERIAL EXP** (ENG/APU) A/C LIMIT NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE 731005 31B5832-04 MOS 0:0 15-JUN-2017 1BDM1714 HRS/MSC O/C 0:0 3592 **REF:** EMM 73-10-04 **ENC** 0:0 2049 731010 NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY PΝ MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** EMM 73-10-05 **ENC** N:0 0 + 731012 NO. 1 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP 08-JUL-2007 30B1910 MOS MX708624A HRS/MSC 7200 +50 0 (7200) 7458 M 7250 **OVERHAUL REF:** EMM 73-10-02 **ENC** 0 + 731013 NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 30B3500-03 MOS 08-JUL-2007 HE1416 HRS/MSC 7200 +50 0 (7200) 7458 M 7250 REF: GENERIC NO REF 0 **ENC** NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY + 731014 MOS 08-JUL-2007 HRS/MSC 7200 +50 0 (7200) 7458 M 7250 **OVERHAUL** REF: EMM 73-10-04 **ENC** 0 + 731022 NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) 30B2062 MOS 08-JUL-2007 C37647 HRS/MSC 7200 +50 0 (7200) 7458 M 7250 REF: GENERIC NO REF 0 **ENC** + 731023 NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 26100-8 MOS 08-JUL-2007 9959510282 HRS/MSC 7200 +50 0 (7200) 7458 M 7250 REF: GENERIC NO REF **ENC** 0 + 731024 NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY MOS 08-JUL-2007 HRS/MSC 7200 0 +50 (7200) 7458 M 7250 0 **OVERHAUL REF:** EMM 73-10-04 **ENC**



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTER	VAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	Report Date: 10-SEP- NEXT DUE MAX (ENG/APU) A/C LIMIT
731025	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTION	ON OF TH	E FUEL DU	MP/START VALVE				(_non=e) /recnon=
	26240-07 0747 REF : GENERIC NO REF	MOS HRS/MSC ENC		+50				08-JUL-2007 0 0	(7200) 7458 M 7250
731026	NO. 1 ENGINE - FUEL WASTE	EEJECTOR							
	26100-8 9959510282 REF : EMM 73-10-03	MOS HRS/MSC ENC	O/C		O:0 N:1565 O:0 O:0			24-AUG-2010 2317.85 1066	
731044	NO. 1 ENGINE - OVERHAUL -	FUEL NOZZLE -	·INLET						
OVERHAUL	REF : EMM 73-10-04	MOS HRS/MSC ENC	7200	+50				08-JUL-2007 0 0	(7200) 7458 M 7250
731045	NO. 1 ENGINE - DISCARD - F	UEL SHUT-OFF	CABLE						
DISCARD	REF : EMM 73-10-05	MOS HRS/MSC ENC	7200	+50				08-JUL-2007 0 0	(7200) 7458 M 7250
731051	NO. 1 ENGINE - FUEL START	& DUMP VALVE							
	26240-07 0747 REF : EMM 73-10-05	MOS HRS/MSC ENC	O/C					25-JAN-2011 2579.02 1222	
731055	NO. 1 ENGINE - OVERHAUL -	· VALVE FUEL SH	HUT-OFF						
OVERHAUL	REF : EMM 73-10-05	MOS HRS/MSC ENC	7200	+50				08-JUL-2007 0 0	(7200) 7458 M 7250
732001	NO. 1 ENGINE - HYDRO MEC	HANICAL FUEL	CONTROL						
	31B4469-07 SHU07-018 REF : EMM 73-20-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			08-JUL-2007 0 0	
732002	NO. 1 ENGINE - REPLACE TF	RIM PLUG							
	PKG 0 REF : EMM 73-20-02	MOS HRS/MSC ENC	120					08-JUL-2007 0 0	31-AUG-2020 M (4409) 4667 M



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

						·	Rep	ort Date: 10-SEP-20
TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
NO. 1 ENGINE - ELECTRICAL	FRONT HARNESS	S						
31B3767-01 AA79901 REF : See Workcard	MOS HRS/MSC ENC	O/C	N:3592 N:2049			15-JUN-2017 3592 2049		
NO. 1 ENGINE - ELECTRICAL	REAR HARNESS							
31B3766-01 EMA101134 REF : EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			08-JUL-2007 0 0		
NO. 1 ENGINE - ELECTRONIC	ENGINE CONTRO	OL EEC						
PN	MOS		N:0			08-JUL-2007		
SN-UNKNOWN REF: EMM 73-20-02	HRS/MSC ENC	O/C	N:0 N:0			0		
NO. 1 ENGINE - VISUALLY IN	SPECT OF THE (P	'RE-SB24589) HN	1U					
31B4469-07 SHU07-018 REF : GENERIC NO REF	MOS HRS/MSC ENC	7200 +50				08-JUL-2007 0 0	(7200) 7458 M	7250
NO. 1 ENGINE - GENERAL VI	SUAL INSPECTION	N OF THE EEC						
PN	MOS					08-JUL-2007		
SN-UNKNOWN REF : GENERIC NO REF	HRS/MSC ENC	7200 +50				0	(7200) 7458 M	7250
NO. 1 ENGINE - GENERAL VI	SUAL INSPECTION	N OF THE WIRIN	G HARNESSES (OUTER, INNE	ER, FRONT AND	REAR)			
30B3089-03	MOS					08-JUL-2007		
AA79737 REF : GENERIC NO REF	HRS/MSC ENC	7200 +50				0	(7200) 7458 M	7250
NO. 1 ENGINE - VISUALLY IN	SPECT THE (POS	T-SB24589) HMU						
31B4469-07	MOS					08-JUL-2007		
SHU07-018 REF : EMM 73-20-01	HRS/MSC ENC	N/A				0		
NO. 1 ENGINE - ENGINE FAD	EC							
822821-6-004	MOS HRS/MSC		R:24			24-JUN-2011		
02077372			R:1144.03			2586.6		
	TASK DESCRIPTION PART/SERIAL NO. 1 ENGINE - ELECTRICAL 31B3767-01 AA79901 REF: See Workcard NO. 1 ENGINE - ELECTRICAL 31B3766-01 EMA101134 REF: EMM 73-20-03 NO. 1 ENGINE - ELECTRONIC PN SN-UNKNOWN REF: EMM 73-20-02 NO. 1 ENGINE - VISUALLY IN: 31B4469-07 SHU07-018 REF: GENERIC NO REF NO. 1 ENGINE - GENERAL VISUAL PN SN-UNKNOWN REF: GENERIC NO REF NO. 1 ENGINE - GENERAL VISUAL PN SN-UNKNOWN REF: GENERIC NO REF NO. 1 ENGINE - GENERAL VISUAL PN SN-UNKNOWN REF: GENERIC NO REF NO. 1 ENGINE - GENERAL VISUAL PN SN-UNKNOWN REF: GENERIC NO REF NO. 1 ENGINE - VISUALLY IN: 31B4469-07 SHU07-018 REF: EMM 73-20-01	TASK DESCRIPTION PART/SERIAL NO. 1 ENGINE - ELECTRICAL FRONT HARNES: 31B3767-01 MOS AA79901 HRS/MSC REF: See Workcard ENC NO. 1 ENGINE - ELECTRICAL REAR HARNESS 31B3766-01 MOS EMA101134 HRS/MSC REF: EMM 73-20-03 ENC NO. 1 ENGINE - ELECTRONIC ENGINE CONTRIPN MOS SN-UNKNOWN HRS/MSC REF: EMM 73-20-02 ENC NO. 1 ENGINE - VISUALLY INSPECT OF THE (PS) 31B4469-07 MOS SHU07-018 HRS/MSC REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION PN MOS SN-UNKNOWN HRS/MSC REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION 30B3089-03 MOS AA79737 HRS/MSC REF: GENERIC NO REF ENC NO. 1 ENGINE - VISUALLY INSPECT THE (POS) 31B4469-07 MOS SHU07-018 HRS/MSC REF: GENERIC NO REF ENC	TASK DESCRIPTION UNIT INTERVAL PART/SERIAL NO. 1 ENGINE - ELECTRICAL FRONT HARNESS 31B3767-01 MOS AA79901 HRS/MSC O/C REF: See Workcard ENC NO. 1 ENGINE - ELECTRICAL REAR HARNESS 31B3766-01 MOS EMA101134 HRS/MSC O/C REF: EMM 73-20-03 ENC NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN MOS SN-UNKNOWN HRS/MSC O/C REF: EMM 73-20-02 ENC NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HN 31B4469-07 MOS SN-UNKNOWN HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN MOS SN-UNKNOWN HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRIN 30B3089-03 MOS SN-UNKNOWN HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRIN 30B3089-03 MOS AA79737 HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-07 MOS SHU07-018 HRS/MSC N/A REF: EMM 73-20-01 ENC	TASK DESCRIPTION UNIT INTERVAL NO. 1 ENGINE - ELECTRICAL FRONT HARNESS 3183767-01 MOS A479901 HRS/MSC O/C N:3592 REF: See Workcard ENC N:2049 NO. 1 ENGINE - ELECTRICAL REAR HARNESS 3183766-01 MOS N:0 EMA101134 HRS/MSC O/C N:0 EMA101134 HRS/MSC O/C N:0 REF: EMM 73-20-03 ENC N:0 NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN MOS N:0 NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN MOS N:0 REF: EMM 73-20-02 ENC N:0 NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 3184469-07 MOS REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN MOS SN-UNIKNOWN HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSES (OUTER, INNE 3083089-03 MOS REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSES (OUTER, INNE 3083089-03 MOS A479737 HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 3184469-07 MOS REF: GENERIC NO REF ENC NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 3184469-07 MOS SHUD7-018 HRS/MSC N/A REF: EMM 73-20-01 ENC	TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ PART/SERIAL NO. 1 ENGINE - ELECTRICAL FRONT HARNESS 31B3767-01 MOS AA79901 HRS/MSC O/C N:3592 REF: See Workcard ENC N:2049 NO. 1 ENGINE - ELECTRICAL REAR HARNESS 31B3766-01 MOS N:0 EMA/101134 HRS/MSC O/C N:0 REF: EMM 73-20-03 ENC N:0 NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN MOS N:0 NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL EEC PN MOS N:0 REF: EMM 73-20-02 ENC N:0 NO. 1 ENGINE - VISUALLY INSPECT OF THE (PRE-SB24589) HMU 31B4469-07 MOS REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE EEC PN MOS N:UNKNOWN HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE WIRING HARNESSES (OUTER, INNER, FRONT AND 30B3089-03 MOS AA79737 HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-07 MOS AA79737 HRS/MSC 7200 +50 REF: GENERIC NO REF ENC NO. 1 ENGINE - VISUALLY INSPECT THE (POST-SB24589) HMU 31B4469-07 MOS SHU07-018 HRS/MSC N/A ENC	TASK DESCRIPTION	TASK DESCRIPTION	TASK DESCRIPTION



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021

				-				•	Re	port Date: 10-SEP-2021	
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERV	AL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
NGINE NO. 2 Model: P	W305/PW305A/PW305B (CIMI	MS) Serial #	PCE-CA	0526	Part # 31B4067-04						
05-P&W-730001	NO. 2 ENGINE - REPLACE EN	GINE FUEL FILT	ER ELEME	NT							
	REF: EMM 73-10-03	MOS HRS/MSC ENC	12 1200	+25/-25				12-MAR-2021 4286.9 2754	12-MAR-2022 (5486.9) 5486.9	5511.9	
+ 05-P&W-730005	NO. 2 ENGINE - CLEAN THE PRIMARY FUEL NOZZLE										
	REF: EMM 73-10-04	MOS HRS/MSC ENC	1800	+600/-600				13-JAN-2016 3583.3 1916	(5383.3) 5383.3	5983.3	
731001	NO. 2 ENGINE - FUEL PUMP										
	30B1910 MX708626A REF : EMM 73-10-02	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			21-JUL-2007 0 0			
731002	NO. 2 ENGINE - MOTIVE FLO	W VALVE									
	30B2062 C37643 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			21-JUL-2007 0 0			
731003	NO. 2 ENGINE - FUEL FILTER	BYPASS INDICA	ATOR SWIT	СН							
	30B3500-03 E1417 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C					13-JAN-2016 3583.3 1916			
731004	NO. 2 ENGINE - UPPER PRIM	ARY FUEL NOZZ	<u>Z</u> LE								
	31B5832-04 1BER1655 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C		N:75 O:0 N:1827 O:0 N:1117 O:0			13-JAN-2016 3583.3 1916			
731005	NO. 2 ENGINE - LOWER PRIM	IARY FUEL NOZ	ZLE								
	31B5832-04 1BDU0535 REF : EMM 73-10-04	MOS HRS/MSC ENC	O/C		O:0 O:0 O:0			13-JAN-2016 3583.3 1916			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** MAX **PART/SERIAL EXP** (ENG/APU) A/C LIMIT 731010 NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY 30B5892-01 MOS 13-JAN-2016 N/A HRS/MSC O/C 3583.3 1916 **REF:** EMM 73-10-05 **ENC** + 731012 NO. 2 ENGINE - OVERHAUL - (PRE-SB24589) FUEL PUMP 30B1910 21-JUL-2007 MOS MX708626A HRS/MSC 7200 +50 0 (7200) 7200 M 7250 **OVERHAUL REF:** EMM 73-10-02 **ENC** 0 + 731013 NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL FILTER BYPASS SWITCH 21-JUL-2007 30B3500-03 MOS E1417 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 **REF: GENERIC NO REF ENC** 0 + 731014 NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - PRIMARY MOS 21-JUL-2007 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 **OVERHAUL** 0 **REF:** EMM 73-10-04 **ENC** NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (PRE-SB24589) MOTIVE FLOW VALVE (PW305 ONLY) + 731022 30B2062 MOS 21-JUL-2007 C37643 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 REF: GENERIC NO REF **ENC** 0 + 731023 NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL WASTE EJECTOR TANK 31B5132-01 MOS 21-JUL-2007 995910614 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 0 **REF: GENERIC NO REF ENC** + 731024 NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE - SECONDARY MOS 21-JUL-2007 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 **OVERHAUL REF:** EMM 73-10-04 **ENC** 0 + 731025 NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DUMP/START VALVE 31B5131-03 MOS 21-JUL-2007 HRS/MSC 7200 0 9959516564 +50 (7200) 7200 M 7250 0 **REF: GENERIC NO REF ENC**



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		ort Date: 10-SEP-2 MAX LIMIT
731026	NO. 2 ENGINE - FUEL WASTE	EJECTOR						·	
	31B5132-01 995910614 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C				13-JAN-2016 3583.3 1916		
731044	NO. 2 ENGINE - OVERHAUL -	FUEL NOZZLE - I	NLET						
OVERHAUL	REF : EMM 73-10-04	MOS HRS/MSC ENC	7200 +50				21-JUL-2007 0 0	(7200) 7200 M	7250
731045	NO. 2 ENGINE - DISCARD - F	UEL SHUT-OFF C	ABLE						
DISCARD	REF: EMM 73-10-05	MOS HRS/MSC ENC	7200 +50				21-JUL-2007 0 0	(7200) 7200 M	7250
731051	NO. 2 ENGINE - FUEL START	& DUMP VALVE							
	31B5131-03 9959516564 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0			13-JAN-2016 3583.3 1916		
731055	NO. 2 ENGINE - OVERHAUL -	VALVE FUEL SH	UT-OFF						
		MOS					21-JUL-2007	(=====	
OVERHAUL	REF : EMM 73-10-05	HRS/MSC ENC	7200 +50				0	(7200) 7200 M	7250
732001	NO. 2 ENGINE - HYDRO MEC	HANICAL FUEL C	ONTROL						
	31B4469-07 SHU07-019 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-JUL-2007 0 0		
732002	NO. 2 ENGINE - REPLACE TF	IM PLUG							
	PKG 0	MOS HRS/MSC	120				21-JUL-2007 0	13-JAN-2020 M	
	REF : EMM 73-20-02	ENC					0	(4667) 4667 M	
732003	NO. 2 ENGINE - ELECTRICAL	FRONT HARNES	S						
	31B3767-01 AA79883 REF: See Workcard	MOS HRS/MSC ENC	O/C				13-JAN-2016 3583.3 1916		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

	Owner: SERVICIO	S AEREOS PLATINOM C.	A. Operator. ALKONAO	TIC SOLUTIONS JOANI	CIGER, S.A DE C	Report Date: 10-SEP-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE	
732004	NO. 2 ENGINE - ELECTRICAL	REAR HARNESS				
	31B3766-01 EMA100611 REF : EMM 73-20-03	MOS HRS/MSC O/C ENC			13-JAN-2016 3583.3 1916	
732005	NO. 2 ENGINE - ELECTRONIC	ENGINE CONTROL EEC				
	PN SN-UNKNOWN REF : EMM 73-20-02	MOS HRS/MSC O/C ENC	N:0 N:0 N:0		21-JUL-2007 0 0	
732011	NO. 2 ENGINE - VISUALLY IN	SPECT OF THE (PRE-SB24589) I	HMU			
	31B4469-07 SHU07-019 REF : GENERIC NO REF	MOS HRS/MSC 7200 +50 ENC			21-JUL-2007 0 0	(7200) 7200 M 7250
732012	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION OF THE EEC				
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC 7200 +50 ENC)		21-JUL-2007 0 0	(7200) 7200 M 7250
732013	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION OF THE WIR	ING HARNESSES (OUTER, IN	NER, FRONT AND REAR)		
	30B3089-03 AA80673 REF : GENERIC NO REF	MOS HRS/MSC 7200 +50 ENC			21-JUL-2007 0 0	(7200) 7200 M 7250
732021	NO. 2 ENGINE - VISUALLY IN	SPECT THE (POST-SB24589) HN	1 U			
	31B4469-07 SHU07-019 REF : EMM 73-20-01	MOS HRS/MSC N/A ENC			21-JUL-2007 0 0	
732101	NO. 2 ENGINE - ENGINE FAD	EC				
	822821-6-004 07052431 REF : EMM 73-20-03	MOS HRS/MSC O/C ENC			20-JUN-2008 564.8 243	
HAPTER 74	IGNITION					

CHAPTER 74

IGNITION



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ WARI	R COMPLIANCE		ort Date: 10-SEP-20 MAX
	PART/SERIAL				EXP		(ENG/APU) A/C	LIMIT
13003	ENGINE WARNING LIGHT BO							
	PN	MOS		N:0		09-DEC-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF : AMM 74-30-03	AFL		N:0		0		
GINE NO.1 Mod	el : PW305/PW305A/PW305B (CIM	MS) Serial#	PCF-CA0525	Part # 31B4067-04				
741001	NO. 1 ENGINE - NO. 1 IGNITI							
	9047980-21	MOS		N:0		08-JUL-2007		
	NNA07226667	HRS/MSC	O/C	N:0		0		
	REF : EMM 74-10-01	ENC		N:0		0		
741002	NO. 1 ENGINE - NO. 2 IGNITI	ON EXCITER						
	9047980-21	MOS		N:0		08-JUL-2007		
	NNA07226671	HRS/MSC	O/C	N:0		0		
	REF : EMM 74-10-01	ENC		N:0		0		
741003	NO. 1 ENGINE - NO. 1 IGNITI	ON CABLE						
	PN	MOS		N:0		08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF : EMM 74-10-01	ENC		N:0		0		
741004	NO. 1 ENGINE - NO. 2 IGNITIO	ON CABLE						
	PN	MOS		N:0		08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0		
	REF : EMM 74-10-01	ENC		N:0		0		
741011	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTIO	N OF THE NO. 1 IG	NITION EXCITER BOX				
	9047980-21	MOS				08-JUL-2007		
	NNA07226667	HRS/MSC	7200 +50			00-301-2007	(7200) 7458 M 7	7250
	REF: GENERIC NO REF	ENC				0	,	
741012	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTIO	N OF THE NO. 2 IG	NITION EXCITER BOX				
	9047980-21	MOS				08-JUL-2007		
	NNA07226671	HRS/MSC	7200 +50			06-JUL-2007 0	(7200) 7458 M 7	7250
	REF: GENERIC NO REF	ENC				0	(e e) e e iii /	===



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR COMPLIANCE NEXT DUE MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT

+ 741021	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 IGNITER CABLES									
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC 7200 ENC	+50	08-JUL-2007 0 (7200) 7458 M 7250 0						
+ 741022	NO. 1 ENGINE - GENERAL V	VISUAL INSPECTION OF THE	NO. 2 IGNITER CABLES							
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC 7200 ENC	+50	08-JUL-2007 0 (7200) 7458 M 7250 0						
+ 741031	NO. 1 ENGINE - REPLACE -	NO. 1 IGNITER PLUGS								
REPLACE	CH34682 SN-UNKNOWN REF : EMM 74-10-01	MOS HRS/MSC 7200 ENC	+50	06-MAR-2020 4004.1 (11204.1) 11462.1 11254.1 2565						
+ 741032	NO. 1 ENGINE - REPLACE -	NO. 2 IGNITER PLUGS								
REPLACE	CH34682 SN-UNKNOWN REF : EMM 74-10-01	MOS HRS/MSC 7200 ENC	+50	06-MAR-2020 4004.1 (11204.1) 11462.1 11254.1 2565						
742025	NO. 1 ENGINE - NO. 1 IGNIT	FER PLUG								
	CH34682 SN-UNKNOWN REF : EMM 74-10-01	MOS HRS/MSC O/C ENC	N:0 N:0 N:0	06-MAR-2020 4004.1 2565						
742026	NO. 1 ENGINE - NO. 2 IGNIT	TER PLUG								
	CH34682 SN-UNKNOWN REF : EMM 74-10-01	MOS HRS/MSC O/C ENC	N:0 N:0 N:0	06-MAR-2020 4004.1 2565						
ENGINE NO. 2 Mod	del : PW305/PW305A/PW305B (CII	MMS) Serial # PCE-CA	0526 Part # 31B4067-04							
741001	NO. 2 ENGINE - NO. 1 IGNIT	TION EXCITER								
	31B4636-02 NNA05392301 REF : EMM 74-10-01	MOS HRS/MSC O/C ENC		13-JAN-2016 3583.3 1916						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION	UNIT I	NTERVAL		TIME SINCE	ADJ	WARR	COMPLIANCE		ort Date: 10-SEP-20 MAX
NOT NO	PART/SERIAL		WI ENVAL		THIL SINGE		EXP	COMIT EIANCE	(ENG/APU) A/C	LIMIT
41002	NO. 2 ENGINE - NO. 2 IGNITIO	ON EXCITER								
	31B4636-02	MOS						13-JAN-2016		
	NNA07226670	HRS/MSC (O/C					3583.3		
	REF : EMM 74-10-01	ENC						1916		
741003	NO. 2 ENGINE - NO. 1 IGNITIO	ON CABLE								
	PN	MOS			N:0			21-JUL-2007		
	SN-UNKNOWN	HRS/MSC (O/C		N:0			0		
	REF : EMM 74-10-01	ENC			N:0			0		
741004	NO. 2 ENGINE - NO. 2 IGNITIO	ON CABLE								
	PN	MOS			N:0			21-JUL-2007		
	SN-UNKNOWN	HRS/MSC (O/C		N:0			0		
	REF : EMM 74-10-01	ENC			N:0			0		
741011	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION	OF THE NO	. 1 IGNIT	ION EXCITER BOX					
	31B4636-02	MOS						21-JUL-2007		
	NNA05392301	HRS/MSC 7	7200 +	50				0	(7200) 7200 M	7250
	REF: GENERIC NO REF	ENC						0		
741012	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 IGNITION EXCITER BOX									
	31B4636-02	MOS						21-JUL-2007		
	NNA07226670	HRS/MSC 7	7200 +	50				0	(7200) 7200 M	7250
	REF: GENERIC NO REF	ENC						0		
741021	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION	OF THE NO	. 1 IGNIT	ER CABLES					
	PN	MOS						21-JUL-2007		
	SN-UNKNOWN	HRS/MSC 7	7200 +	50				0	(7200) 7200 M	7250
	REF: GENERIC NO REF	ENC						0		
741022	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION	OF THE NO	. 2 IGNIT	ER CABLES					
	PN	MOS						21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	7200 +	50				0	(7200) 7200 M	7250
	REF: GENERIC NO REF	ENC						0		
741031	NO. 2 ENGINE - REPLACE - N	IO. 1 IGNITER PLU	GS							
	CH34682	MOS						06-MAR-2020		
	SN-UNKNOWN	HRS/MSC 7	7200 +	50					11462.1) 11462.1	11512.1
REPLACE	REF : EMM 74-10-01	ENC						2723	-	

© CAMP SYSTEMS



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR COMPLIANCE NEXT DUE MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT + 741032 NO. 2 ENGINE - REPLACE - NO. 2 IGNITER PLUGS CH34682 MOS 06-MAR-2020 (11462.1) 11462.1 SN-UNKNOWN HRS/MSC 7200 +50 4262.1 11512.1 REPLACE **REF:** EMM 74-10-01 **ENC** 2723

742025	NO. 2 ENGINE - NO. 1 IGNITER PLUG									
	CH34682	MOS	N:0	06-MAR-2020						
	SN-UNKNOWN	HRS/MSC O/C	N:0	4262.1						
	REF : EMM 74-10-01	ENC	N:0	2723						
742026	NO. 2 ENGINE - NO. 2 IGNIT	ER PLUG								
	CH34682	MOS	N:0	06-MAR-2020						
	SN-UNKNOWN	HRS/MSC O/C	N:0	4262.1						
	REF : EMM 74-10-01	ENC	N:0	2723						
HAPTER 75	AIR									
NGINE NO. 1 Mode	el : PW305/PW305A/PW305B (CIN	MMS) Serial # PCE-CA05	25 Part # 31B4067-04							
751001	NO. 1 ENGINE - ANTI-ICING	SOLENOID VALVE								
	31B5108-04	MOS	N:0	08-JUL-2007						
	AL1469	HRS/MSC O/C	N:0	0						
	REF : EMM 75-10-01	ENC	N:0	0						
751011	NO. 1 ENGINE - OVERHAUL	- ANTI-ICING VALVE								
	31B5108-04	MOS		08-JUL-2007						
	AL1469	HRS/MSC 7200 +	-50	0	(7200) 7458 M 7250					
OVERHAUL	REF : EMM 75-10-01	ENC		0						
753001	NO. 1 ENGINE - OVERHAUL	- COMPRESSOR BLEED VALVE	≣S							
		MOS		08-JUL-2007						
		HRS/MSC 7200 +	-50	0	(7200) 7458 M 7250					
OVERHAUL	REF : EMM 75-30-01	ENC		0						
753002	NO. 1 ENGINE - DISCARD - ((PRE-SB24645) COMPRESSOR	BOV SOLENOID							
		MOS		08-JUL-2007						
			-50	0	(7200) 7458 M 7250					
DISCARD	REF: GENERIC NO REF	ENC		0						



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner: SERVICIO								Report Date: 10-SEP-	
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERV	'AL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE MAX (ENG/APU) A/C LIMIT	
53003	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTION	ON OF THE	(POST-S	B24434) P3 TRANSDUCER					
		MOS						08-JUL-2007		
		HRS/MSC	7200	+50				0	(7200) 7458 M 7250	
	REF: GENERIC NO REF	ENC						0		
753004	NO. 1 ENGINE - LINEAR STA	TOR VANE (POS	T SB24369)) ACTUAT	OR					
	2600-1	MOS			N:0			08-JUL-2007		
	SAU07-096	HRS/MSC	O/C		N:0			0		
	REF : EMM 75-30-04	ENC			N:0			0		
53005	NO. 1 ENGINE - ROTARY STA	ATOR VANE (PRE	E SB24369)	ACTUAT(OR					
	PN	MOS			N:0			08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0		
	REF : EMM 75-30-04	ENC			N:0			0		
753012	NO. 1 ENGINE - OVERHAUL -	(POST-SB24645	i) COMPRE	SSOR BO	V SOLENOID					
		MOS						08-JUL-2007		
		HRS/MSC	N/A					0		
DISCARD	REF : EMM 75-30-02	ENC						0		
753014	NO. 1 ENGINE - DISCARD - (F	PRE-SB24369) R	OTARY STA	ATOR VAN	I ACTUATOR					
	PN	MOS						08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	N/A					0		
DISCARD	REF: GENERIC NO REF	ENC						0		
753024	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24369) LINER STATOR VANE ACTUATOR									
DISCARD 53014 DISCARD	2600-1	MOS						08-JUL-2007		
	SAU07-096	HRS/MSC	7200	+50				0	(7200) 7458 M 7250	
	REF: GENERIC NO REF	ENC						0		
753081	NO. 1 ENGINE - (BOV) COMP	RESSOR BLEED	VALVE SC	DLENOID						
	31B4197-05	MOS			N:0			15-JUN-2017		
	ARK0137T	HRS/MSC	O/C		N:0			3592		
	REF : EMM 75-30-02	ENC			N:0			2049		
752002	NO. 1 ENGINE - BOV SOLENOID STRAINER ELEMENT									
53082	NO. 1 ENGINE - BOV SOLENO									
753082					N:0			08-JUL-2007		
753082	NO. 1 ENGINE - BOV SOLENO PN SN-UNKNOWN	MOS HRS/MSC	O/C		N:0 N:0			08-JUL-2007 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICE	JS AEREUS PLATIN	OFI C.A. O	peratori AERONAOTI	3010110	INS JUAIN	IGER, S.A DE C	Re	eport Date: 10-SEP-20	
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTE	RVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
753083	NO. 1 ENGINE - BOV SOLEN									
	PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC N/A ENC					08-JUL-2007 0 0			
753101 (s)	NO. 1 ENGINE - INBOARD CO	OMPRESSOR BLEED - P2	2.5 VALVE							
REPLACE	31B5759-01 AHX008616 REF: EMM 75-30-01	MOS HRS/MSC 3600 ENC	+50	N:120 O:0 N:3592 O:0 N:2049 O:0			15-JUL-2017 3592 2049			
753102 (s)	NO. 1 ENGINE - OUTBOARD	COMPRESSOR BLEED -	P2.5 VALVE							
REPLACE	31B5759-01 AHX008438 REF: EMM 75-30-01	MOS HRS/MSC 3600 ENC	+50	N:120 O:0 N:3592 O:0 N:2049 O:0			15-JUL-2017 3592 2049			
753105 (s)	NO. 1 ENGINE - COMPRESSO	OR BLEED - P2.8 VALVE								
REPLACE	31B5756-01 AHX008803 REF : EMM 75-30-01	MOS HRS/MSC 3600 ENC	+50	N:120 O:0 N:3592 O:0 N:2049 O:0			15-JUL-2017 3592 2049			
753111	NO. 1 ENGINE - INSPECT AND CLEAN INBOARD COMPRESSOR BLEED - P2.5 VALVE									
	31B5759-01 AHX008616 REF : See Workcard	MOS HRS/MSC 1500 ENC	+300/-30	00			15-JUL-2017 3592 2049	(5092) 5350	5392	
753112	NO. 1 ENGINE - INSPECT AN	D CLEAN OUTBOARD C	OMPRESSOR	R BLEED - P2.5 VALVE						
	31B5759-01 AHX008438 REF: See Workcard	MOS HRS/MSC 1500 ENC	+300/-30	00			15-JUL-2017 3592 2049	(5092) 5350	5392	
753115	NO. 1 ENGINE - INSPECT AN									
	31B5756-01 AHX008803 REF: See Workcard	MOS HRS/MSC 1500 ENC	+300/-30	00			15-JUL-2017 3592 2049	(5092) 5350	5392	
754001	NO. 1 ENGINE - PRESSURE I	P3 TRANSDUCER								
	30B3033-02 KL0766376 REF : EMM 75-30-03	MOS HRS/MSC O/C ENC					15-JUN-2017 3592 2049			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021

TASK NO	TACK DECODED TO A								oort Date: 10-SEP	
	TASK DESCRIPTION PART/SERIAL	UNIT INT	ERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT	
NGINE NO. 2 Mode	I : PW305/PW305A/PW305B (CIM	MS) Serial # PC	E-CA0526	Part # 31B4067-04						
751001	NO. 2 ENGINE - ANTI-ICING S	SOLENOID VALVE								
	31B5108-04 AL1461 REF : EMM 75-10-01	MOS HRS/MSC O/C ENC					13-JAN-2016 3583.3 1916			
+ 751011	NO. 2 ENGINE - OVERHAUL -	- ANTI-ICING VALVE								
OVERHAUL	31B5108-04 AL1461 REF: EMM 75-10-01	MOS HRS/MSC 720 ENC	0 +50				21-JUL-2007 0 0	(7200) 7200 M	7250	
+ 753001	NO. 2 ENGINE - OVERHAUL -	- COMPRESSOR BLEE	D VALVES							
OVERHAUL	REF : EMM 75-30-01	MOS HRS/MSC 720 ENC	0 +50				21-JUL-2007 0 0	(7200) 7200 M	7250	
+ 753002	NO. 2 ENGINE - DISCARD - (F	PRE-SB24645) COMPF	RESSOR BOV	SOLENOID						
DISCARD	REF: GENERIC NO REF	MOS HRS/MSC 720 ENC	0 +50				21-JUL-2007 0 0	(7200) 7200 M	7250	
+ 753003	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTION O	THE (POST-	SB24434) P3 TRANSDUCER						
	REF: GENERIC NO REF	MOS HRS/MSC 720 ENC	0 +50				21-JUL-2007 0 0	(7200) 7200 M	7250	
753004	NO. 2 ENGINE - LINEAR STA	TOR VANE (POST SB2	4369) ACTUA	TOR						
	31B5255-01 SAU06-083 REF : EMM 75-30-04	MOS HRS/MSC O/C ENC					13-JAN-2016 3583.3 1916			
753005	NO. 2 ENGINE - ROTARY STA	ATOR VANE (PRE SB2	4369) ACTUA	ГOR						
	PN SN-UNKNOWN REF: EMM 75-30-04	MOS HRS/MSC O/C ENC		N:0 N:0 N:0			21-JUL-2007 0 0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	ort Date: 10-SEP-20 MAX LIMIT
753012	NO. 2 ENGINE - OVERHAUL -	(POST-SB24645) COMPRESSOR	BOV SOLENOID		— L XI		(ENGIALO) AIC	ENVILL
		MOS	,				21-JUL-2007		
		HRS/MSC	N/A				0		
DISCARD	REF : EMM 75-30-02	ENC					0		
753014	NO. 2 ENGINE - DISCARD - (F	PRE-SB24369) RC	OTARY STATOR \	/AN ACTUATOR					
	PN	MOS					21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	N/A				0		
DISCARD	REF: GENERIC NO REF	ENC					0		
753024	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTIO	ON OF THE (POST	T-SB24369) LINER STATOR VA	NE ACTUATOF	₹			
	31B5255-01	MOS					21-JUL-2007		
	SAU06-083	HRS/MSC	7200 +50				0	(7200) 7200 M	7250
	REF: GENERIC NO REF	ENC					0		
753081	NO. 2 ENGINE - (BOV) COMP	RESSOR BLEED	VALVE SOLENO	D					
	31B4197-05	MOS		O:0			03-FEB-2014		
	ARK0255T	HRS/MSC	O/C	O:0			3333		
	REF : EMM 75-30-02	ENC		O:0			1670		
753082	NO. 2 ENGINE - BOV SOLEN	DID STRAINER EI	LEMENT						
	PN	MOS		N:0			21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
753083	NO. 2 ENGINE - BOV SOLEN	OID STRAINER EI	LEMENT - REPLA	CE					
	PN	MOS					21-JUL-2007		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF : EMM 75-30-02	ENC					0		
753101 (s)	NO. 2 ENGINE - INBOARD CO	MPRESSOR BLE	EED - P2.5 VALVE						
	31B5759-01	MOS					13-JAN-2016		
	AHX008403	HRS/MSC	3600 +50				3583.3		
REPLACE	REF : EMM 75-30-01	ENC					1916		
753102 (s)	NO. 2 ENGINE - OUTBOARD	COMPRESSOR B	BLEED - P2.5 VAL	VE					
` '	31B5759-01	MOS					13-JAN-2016		
	AHX008617	HRS/MSC	3600 +50				3583.3		
	,,		.00				2000.0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. Servici								Re	port Date: 10-SEP-202
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERV	AL	TIME SINCE	ADJ	WARR EXP	COMPLIANCI	E NEXT DUE (ENG/APU) A/C	MAX LIMIT
753105 (s)	NO. 2 ENGINE - COMPRESSO	OR BLEED - P2.8 \	VALVE							
	31B5756-01	MOS						13-JAN-2016		
REPLACE	AHX008723 REF : EMM 75-30-01	HRS/MSC ENC	3600	+50				3583.3 1916		
+ 753111	NO. 2 ENGINE - INSPECT AN	D CLEAN INBOAF	RD COMPF	RESSOR BLE	ED - P2.5 VALVE					
	31B5759-01	MOS						13-JAN-2016		
	AHX008403 REF: See Workcard	HRS/MSC ENC	1500	+300/-300				3583.3 1916	(5083.3) 5083.3	5383.3
+ 753112	NO. 2 ENGINE - INSPECT AN	D CLEAN OUTBO	ARD COM	IPRESSOR BL	EED - P2.5 VALVE					
	31B5759-01	MOS	4500					13-JAN-2016	/==== a\ ==== =	5000 0
	AHX008617 REF: See Workcard	HRS/MSC ENC	1500	+300/-300				3583.3 1916	(5083.3) 5083.3	5383.3
+ 753115	NO. 2 ENGINE - INSPECT AN	D CLEAN COMPR	ESSOR B	LEED - P2.8 V	'ALVE					
	31B5756-01 AHX008723	MOS HRS/MSC	4500	. 200/ 200				13-JAN-2016	(5000 0) 5000 0	5000.0
	REF: See Workcard	ENC	1500	+300/-300				3583.3 1916	(5083.3) 5083.3	5383.3
754001	NO. 2 ENGINE - PRESSURE	P3 TRANSDUCER								
	30B3303-03	MOS						13-JAN-2016		
	KL0766365 REF : EMM 75-30-03	HRS/MSC ENC	O/C					3583.3 1916		
HAPTER 76	ENGINE CONTROLS									
761001	THROTTLE/THRUST REVERS	SER QUADRANT A	ASSEMBL	Y						
	PN	MOS	0/0		N:0			09-DEC-2007		
	SN-UNKNOWN REF: AMM 76-10-01	HRS/MSC AFL	U/C		N:0 N:0			0		
761003	LEFT ENGINE ROTARY VARI	ABLE DIFFERENT	TAL (RVD	T) TRANSFOR	RMER					
	PN	MOS			N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC			N:0			0		



TASK NO

761004

761201

ENGINE NO. 1

761101

PART/SERIAL

SN-UNKNOWN

SN-UNKNOWN

6008016-029

207

REF: AMM 76-12-01

REF: AMM 76-10-02

PΝ

PΝ

Status Report

LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK DESCRIPTION UNIT TIME SINCE ADJ WARR COMPLIANCE NEXT DUE INTERVAL MAX **EXP** (ENG/APU) A/C LIMIT RIGHT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER MOS N:0 09-DEC-2007 HRS/MSC O/C N:0 0 AFL N:0 0 **ENGINE FADEC SLAVE/MASTER SWITCH** MOS N:0 09-DEC-2007 HRS/MSC O/C N:0 0 N:0 AFL 0 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0525 Part # 31B4067-04 NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS MOS N:0 08-JUL-2007 LIDE/MCC O/C NI-O

	207 REF: EMM 73-20-03	HRS/MSC O/C ENC	N:0 N:0	0	
	REF. LIVIN 70 20 00	LIVO	14.0	· ·	
761103	NO. 1 ENGINE - FADEC, EN	IGINE HARNESS			
	6008016-031	MOS	N:0	08-JUL-2007	
	68	HRS/MSC O/C	N:0	0	
	REF : EMM 73-20-03	ENC	N:0	0	
761105	NO. 1 ENGINE - CHANNEL	A FADEC, ENGINE NACELLE HAR	NESS		
	6008408-041	MOS	N:0	08-JUL-2007	
	011	HRS/MSC O/C	N:0	0	
	REF : EMM 73-20-03	ENC	N:0	0	
761107	NO. 1 ENGINE - CHANNEL	B FADEC, ENGINE NACELLE HAR	NESS		
	6008408-033	MOS	N:0	08-JUL-2007	
	007	HRS/MSC O/C	N:0	0	
	REF : EMM 73-20-03	ENC	N:0	0	

ENGINE NO. 2	Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0526	Part # 31B4067-04		
761101	NO. 2 ENGINE - FADEC, ENGINE	TAILCONE HARNESS			
	6008016-030	MOS	N:0	21-JUL-2007	
	207	HRS/MSC O/C	N:0	0	
	REF : EMM 73-20-03	ENC	N:0	0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ WARR	COMPLIANCE NEXT DUE	
	PART/SERIAL				EXP	(ENG/APU) A/C	LIMIT
761103	NO. 2 ENGINE - FADEC, ENG	INE HARNESS					
	6008016-032	MOS		N:0		21-JUL-2007	
	69	HRS/MSC	O/C	N:0		0	
	REF : EMM 73-20-03	ENC		N:0		0	
761105	NO. 2 ENGINE - CHANNEL A	FADEC, ENGINE N	IACELLE HARNES	3			
	6008408-038	MOS		N:0		21-JUL-2007	
	0188	HRS/MSC	O/C	N:0		0	
	REF : EMM 73-20-03	ENC		N:0		0	
761107	NO. 2 ENGINE - CHANNEL B	FADEC, ENGINE N	ACELLE HARNES	5			
	6008408-032	MOS		N:0		21-JUL-2007	
	0270	HRS/MSC	O/C	N:0		0	
	REF : EMM 73-20-03	ENC		N:0		0	
HAPTER 77	ENGINE INDICATING						
770A01	DOWNLOAD EDS ON ENGIN	E NO. 1					
		MOS				06-MAR-2020	
		HRS/MSC	75 +25/-25			4262.1 4337.1	4362.1
	REF:	AFL				2723	
770A02	DOWNLOAD EDS ON ENGIN	E NO. 2					
		MOS				06-MAR-2020	
		HRS/MSC	75 +25/-25			4262.1 4337.1	4362.1
	REF:	AFL				2723	
771001	LEFT ENGINE N1 INDICATOR	₹					
	PN	MOS		N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0		0	
		AFL		N:0		0	
	REF : AMM 77-10-01						
771002	REF: AMM //-10-01 RIGHT ENGINE N1 INDICATO						
771002				N:0		09-DEC-2007	
771002	RIGHT ENGINE N1 INDICATO	DR	O/C	N:0 N:0 N:0		09-DEC-2007 0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR		eport Date: 10-SEP-20
ASK NO	PART/SERIAL	UNII	INTERVAL	TIME SINCE		EXP	(ENG/APU) A/C	MAX LIMIT
71003	LEFT ENGINE N2 INDICATOR							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF: AMM 77-10-02	AFL		N:0			0	
771004	RIGHT ENGINE N2 INDICATOR	२						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 77-10-02	AFL		N:0			0	
771012	LEFT DATA CONCENTRATOR	(DCU) UNIT						
	822-1483-350	MOS					31-MAY-2013	
	2K5BL	HRS/MSC	O/C				3203.4	
	REF: GENERIC NO REF	AFL					1600	
771012	RIGHT DATA CONCENTRATO	R (DCU) UNIT						
	822-1483-350	MOS					31-MAY-2013	
	2K58J	HRS/MSC	O/C				3203.4	
	REF: GENERIC NO REF	AFL					1600	
771014	LEFT ENGINE DATA CONCEN	TRATOR (EDC) U	JNIT					
	822-1483-350	MOS		N:0			09-DEC-2007	
	2K5BL	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
771014	RIGHT ENGINE DATA CONCE	NTRATOR (EDC)	UNIT					
	822-1483-350	MOS		N:0			09-DEC-2007	
	2K58H	HRS/MSC	O/C	N:0			0	
	REF: GENERIC NO REF	AFL		N:0			0	
72001	LEFT ENGINE ITT INDICATOR							
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 77-20-01	AFL		N:0			0	
772002	RIGHT ENGINE ITT INDICATO	R						
	PN	MOS		N:0			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0	
	REF : AMM 77-20-01	AFL		N:0			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

									port Date: 10-SI	EP-ZU
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
774001	ENGINE DIAGNOSTIC UNIT									
	9-361-06	MOS		R:0			31-AUG-2018			
	8	HRS/MSC	O/C	R:0			4067			
	REF : AMM 77-40-01	AFL		R:0			2472			
774002	CONTROL AND DISPLAY (CDI	J) UNIT								
	9-362-03	MOS		N:0			09-DEC-2007			
	C242	HRS/MSC	O/C	N:0			0			
	REF: AMM 77-40-02	AFL		N:0			0			
774003	LEFT ENGINE ISOLATION INT	ERFACE UNIT								
	9-343-04	MOS		N:0			09-DEC-2007			
	C-328	HRS/MSC	O/C	N:0			09-DEC-2007			
	REF : AMM 77-40-03	AFL	0.0	N:0			0			
774004	RIGHT ENGINE ISOLATION IN	TERFACE UNIT								
	9-343-04	MOS		N:0			09-DEC-2007			
	C-314	HRS/MSC	O/C	N:0			0			
	REF : AMM 77-40-03	AFL		N:0			0			
774101	SIGNAL CONDITIONING BOX									
	6600504-5	MOS		N:0			09-DEC-2007			
	AC13297	HRS/MSC	O/C	N:0			0			
	REF : AMM 77-41-01	AFL		N:0			0			
774103	LEFT ENGINE VIBRATION ACC	CELEROMETER	2							
	6600504-2	MOS		N:0			09-DEC-2007			
	1580	HRS/MSC	O/C	N:0			0			
	REF: AMM 77-41-02	AFL		N:0			0			
774104	RIGHT ENGINE VIBRATION AG	CCELEROMETE	:R							
	6600504-2	MOS		N:0			09-DEC-2007			
	1680	HRS/MSC	O/C	N:0			0			
	REF : AMM 77-41-02	AFL		N:0			0			

?-Insufficient Information +-Task exists in Inspection Manual (s (ENG/APU) = Engine/APU Units



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT INTERVAL TIME SINCE ADJ WARR COMPLIANCE NEXT DUE MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT + 771001 NO. 1 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS MOS 08-JUL-2007

DIOCARD	DEE OFNEDIO NO DEE	MOS HRS/MSC 7200	+50	08-JUL-2007 0	(7200) 7458 M 7250
DISCARD	REF: GENERIC NO REF	ENC		0	
771011	NO. 1 ENGINE - GENERAL VI SENSORS	ISUAL INSPECTION OF TH	IE (POST-SB24545, POST-SB24546 &	PRE-SB24579) N1 SPEED	
		MOS		08-JUL-2007	
		HRS/MSC 7200	+50	0	(7200) 7458 M 7250
	REF: EMM 77-10-01	ENC		0	
771021	NO. 1 ENGINE - GENERAL V	ISUAL INSPECTION OF TH	IE CHANNEL A N2 SPEED SENSOR		
	30B1449	MOS		08-JUL-2007	
	CH4251	HRS/MSC 7200	+50	0	(7200) 7458 M 7250
	REF: GENERIC NO REF	ENC		0	
771022	NO. 1 ENGINE - GENERAL VI	ISUAL INSPECTION OF TH	IE CHANNEL B N2 SPEED SENSOR		
	30B1449	MOS		08-JUL-2007	
	CH4280	HRS/MSC 7200	+50	0	(7200) 7458 M 7250
	REF: GENERIC NO REF	ENC		0	
771027	NO. 1 ENGINE - CHANNEL A	N1 SPEED SENSOR			
	30B6150-05	MOS		10-JUN-2011	
	CH3061	HRS/MSC A/R		2586.6	
	REF : EMM 77-10-01	ENC		1224	
771028	NO. 1 ENGINE - CHANNEL B	N1 SPEED SENSOR			
	30B6152-04	MOS		10-JUN-2011	
	CH1519	HRS/MSC A/R		2586.6	
	REF : EMM 77-10-01	ENC		1224	
771040	NO. 1 ENGINE - CHANNEL A	N2, TURBINE SPEED SEN	SOR		
	30B1449	MOS		10-JUN-2011	
	CH4251	HRS/MSC O/C		2586.6	
	REF : EMM 77-10-01	ENC		1224	
771041	NO. 1 ENGINE - CHANNEL B	N2, TURBINE SPEED SEN	SOR		
	30B1449	MOS		10-JUN-2011	
	CH4280	HRS/MSC O/C		2586.6	
	REF : EMM 77-10-01	ENC		1224	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021 TASK NO TASK DESCRIPTION UNIT TIME SINCE ADJ WARR **COMPLIANCE NEXT DUE** INTERVAL MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT 772010 NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNESS 30B2749-02 MOS 10-JUN-2011 EM99786/EM100619 HRS/MSC O/C 2586.6 1224 **REF:** EMM 77-20-01 **ENC** + 772013 NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 2 P1/T1 SENSORS PΝ MOS 08-JUL-2007 SN-UNKNOWN HRS/MSC 7200 +50 0 (7200) 7458 M 7250 **REF: GENERIC NO REF ENC** 0 772014 NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PΝ MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 **REF:** EMM 77-20-02 **ENC** N:0 0 772015 NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR MOS N:0 08-JUL-2007 SN-UNKNOWN HRS/MSC O/C N:0 0 N:0 0 **REF:** EMM 77-20-02 **ENC** NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK OF THE T4.5 HARNESSES AND T4.5 TERMINAL BOX + 772021 30B2749-02 MOS 08-JUL-2007 EM99786/EM100619 HRS/MSC 7200 +50 0 (7200) 7458 M 7250 REF: EMM 77-20-01 **ENC** 0 + 772022 NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE NO. 1 P1/T1 SENSORS PΝ 08-JUL-2007 MOS SN-UNKNOWN HRS/MSC 7200 +50 0 (7200) 7458 M 7250 0 **REF: GENERIC NO REF ENC** ENGINE NO. 2 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0526 Part # 31B4067-04 + 771001 NO. 2 ENGINE - DISCARD - (PRE-SB24545 & PRE-SB24546) N1 SPEED SENSORS MOS 21-JUL-2007 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 REF: GENERIC NO REF 0 DISCARD **ENC**



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V. Report Date: 10-SEP-2021 **COMPLIANCE NEXT DUE** TASK NO TASK DESCRIPTION UNIT TIME SINCE WARR INTERVAL ADJ MAX PART/SERIAL **EXP** (ENG/APU) A/C LIMIT NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE (POST-SB24545, POST-SB24546 & PRE-SB24579) N1 SPEED + 771011 **SENSORS** MOS 21-JUL-2007 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 **REF:** EMM 77-10-01 **ENC** 0 + 771021 NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL A N2 SPEED SENSOR 30B1449 MOS 21-JUL-2007 CH4372 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 REF: GENERIC NO REF 0 **ENC** + 771022 NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE CHANNEL B N2 SPEED SENSOR 30B1449 MOS 21-JUL-2007 CH4294 HRS/MSC 7200 +50 0 (7200) 7200 M 7250 REF: GENERIC NO REF **ENC** 0 771027 NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR 30B6150-05 MOS 13-JAN-2016 CH2060 HRS/MSC A/R 3583.3 1916 **REF:** EMM 77-10-01 **ENC** 771028 NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR 30B6152-05 MOS 13-JAN-2016 CH2590 HRS/MSC A/R 3583.3 **REF:** EMM 77-10-01 **ENC** 1916 771040 NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449 MOS 13-JAN-2016 CH4372 HRS/MSC O/C 3583.3 **REF:** EMM 77-10-01 **ENC** 1916 771041 NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 MOS 13-JAN-2016 CH4294 HRS/MSC O/C 3583.3 REF: EMM 77-10-01 **ENC** 1916 772010 NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNESS 30B2749-02 MOS 13-JAN-2016 EM100620/EM103591 HRS/MSC O/C 3583.3 **REF:** EMM 77-20-01 **ENC** 1916



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

									Report Date: 10-SEP-20
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTER\	/AL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	
772013	NO. 2 ENGINE - GENERAL VI	SUAL INSPECTIO	N OF THE	E NO. 2 P1/	T1 SENSORS				
	PN	MOS						21-JUL-2007	
	SN-UNKNOWN	HRS/MSC	7200	+50				0	(7200) 7200 M 7250
	REF: GENERIC NO REF	ENC						0	
772014	NO. 2 ENGINE - PRESSURE	AND TEMPERATU	RE SENS	SOR					
	PN	MOS			N:0			21-JUL-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF : EMM 77-20-02	ENC			N:0			0	
772015	NO. 2 ENGINE - PRESSURE A	AND TEMPERATU	RE SENS	OR					
	PN	MOS			N:0			21-JUL-2007	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF : EMM 77-20-02	ENC			N:0			0	
772021	NO. 2 ENGINE - EXAMINE AN	ID DO A FUNCTIC	NAL CHE	CK OF THE	E T4.5 HARNESSES AND T	4.5 TERMINAL B	OX		
	30B2749-02	MOS						21-JUL-2007	
	EM100620/EM103591	HRS/MSC	7200	+50				0	(7200) 7200 M 7250
	REF : EMM 77-20-01	ENC						0	
772022	NO. 2 ENGINE - GENERAL VI	ISUAL INSPECTIO	N OF THI	E NO. 1 P1/	T1 SENSORS				
	PN	MOS							
								21-JUL-2007	
	SN-UNKNOWN	HRS/MSC	7200	+50				21-JUL-2007 0	(7200) 7200 M 7250
	SN-UNKNOWN REF : GENERIC NO REF	HRS/MSC ENC	7200	+50					(7200) 7200 M 7250
HAPTER 78			7200	+50				0	(7200) 7200 M 7250
HAPTER 78 780001	REF: GENERIC NO REF		7200	+50		_		0	(7200) 7200 M 7250
-	REF: GENERIC NO REF		7200	+50	N:0	_	_	0	(7200) 7200 M 7250
-	REF: GENERIC NO REF EXHAUST LEFT THRUST REVERSER	ENC		+50	N:0 N:0	_	_	0	(7200) 7200 M 7250
-	REF: GENERIC NO REF EXHAUST LEFT THRUST REVERSER 282-0052-519	ENC		+50				0 0 0 09-DEC-2007	(7200) 7200 M 7250
-	EXHAUST LEFT THRUST REVERSER 282-0052-519 32-230	MOS HRS/MSC AFL		+50	N:0			0 0 0 09-DEC-2007 0	(7200) 7200 M 7250
780001	EXHAUST LEFT THRUST REVERSER 282-0052-519 32-230 REF: AMM 78-30-05	MOS HRS/MSC AFL		+50	N:0 N:0			0 0 09-DEC-2007 0	(7200) 7200 M 7250
780001	EXHAUST LEFT THRUST REVERSER 282-0052-519 32-230 REF: AMM 78-30-05	MOS HRS/MSC AFL	O/C	+50	N:0			0 0 0 09-DEC-2007 0	(7200) 7200 M 7250



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TACK NO	TACK DESCRIPTION	LINIT -INTERVAL	TIME CINCE	AD I WARR	Report Date: 10-SE	P-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT	
83001	LEFT THRUST REVERSER R	ELAY BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-01	AFL	N:0		0	
783002	RIGHT THRUST REVERSER	RELAY BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-01	AFL	N:0		0	
83005	LEFT THRUST REVERSER H	YDRAULIC CONTROL UNIT				
	282D0007-507	MOS	N:0		09-DEC-2007	
	0763	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-03	AFL	N:0		0	
783006	RIGHT THRUST REVERSER	HYDRAULIC CONTROL UNIT				
	282D0007-507	MOS	N:0		09-DEC-2007	
	0762	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-03	AFL	N:0		0	
783008	HYDRAULIC CONTROL RELA	AY BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-06	AFL	N:0		0	
783009	THRUST REVERSER INTERF	FACE BOX				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-07	AFL	N:0		0	
783013	LEFT ENGINE THRUST REVI	ERSER UPPER DOOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-10	AFL	N:0		0	
83014	RIGHT ENGINE THRUST RE	VERSER UPPER DOOR				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

ASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE NE		oort Date: 10-SEP-20 MAX
ASK NO	PART/SERIAL	ONII INTERVAL	TIME SINCE	ADJ	EXP		G/APU) A/C	MAX LIMIT
83015	LEFT ENGINE THRUST REVE	ERSER LOWER DOOR						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 78-30-10	AFL	N:0			0		
7 83016	RIGHT ENGINE THRUST RE\	/ERSER LOWER DOOR						
	266-0004-514	MOS	R:0			12-FEB-2014		
	LR0032-270	HRS/MSC O/C	R:0					
	REF : AMM 78-30-10	AFL	R:0			1670		
83025	LEFT ENGINE THRUST REVE	ERSER SWITCH CABLE						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 78-30-25	AFL	N:0			0		
783026	RIGHT ENGINE THRUST RE\	/ERSER SWITCH CABLE						
	PN	MOS	N:0			09-DEC-2007		
	SN-UNKNOWN	HRS/MSC O/C	N:0			0		
	REF : AMM 78-30-25	AFL	N:0			0		
783105	LEFT OUTBOARD THRUST R	EVERSER ACTUATOR						
	282D0006-501	MOS	N:0			09-DEC-2007		
	1422R	HRS/MSC O/C	N:0			0		
	REF : AMM 78-31-05	AFL	N:0			0		
783106	LEFT INBOARD THRUST RE\	/ERSER ACTUATOR						
	282D0006-501	MOS	N:0			09-DEC-2007		
	1420R	HRS/MSC O/C	N:0			0		
	REF : AMM 78-31-05	AFL	N:0			0		
'83107	RIGHT INBOARD THRUST RE	EVERSER ACTUATOR						
	282D0006-501	MOS	N:0			09-DEC-2007		
	1452R	HRS/MSC O/C	N:0			0		
	REF : AMM 78-31-05	AFL	N:0			0		
83108	RIGHT OUTBOARD THRUST	REVERSER ACTUATOR						
	282D0006-501	MOS	N:0			09-DEC-2007		
	1453R	HRS/MSC O/C	N:0			0		
	REF : AMM 78-31-05	AFL	N:0			0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

		OS AEREOS PLATINUM C.A.				Report Date: 10-SEP-20
ASK NO	TASK DESCRIPTION PART/SERIAL	UNIT INTERVAL	TIME SINCE	ADJ WA EXF	RR COMPLIANCE	
33115	LEFT UPPER SECONDARY L	OCK ACTUATOR				
	266D0486-507	MOS	N:0		09-DEC-2007	
	1618	HRS/MSC O/C	N:0		0	
	REF : AMM 78-31-15	AFL	N:0		0	
83116	RIGHT UPPER SECONDARY	LOCK ACTUATOR				
	266D0486-507	MOS	N:0		09-DEC-2007	
	1645	HRS/MSC O/C	N:0		0	
	REF : AMM 78-31-15	AFL	N:0		0	
83117	LEFT LOWER SECONDARY L	OCK ACTUATOR				
	266D0486-507	MOS	N:0		09-DEC-2007	
	1619	HRS/MSC O/C	N:0		0	
	REF : AMM 78-31-15	AFL	N:0		0	
783118	RIGHT LOWER SECONDARY	LOCK ACTUATOR				
	266D0486-507	MOS	N:0		09-DEC-2007	
	1650	HRS/MSC O/C	N:0		0	
	REF: AMM 78-31-15	AFL	N:0		0	
83132	LEFT OUTBOARD STANG FA	IRING ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF : AMM 78-30-15	AFL	N:0		0	
'83132A	INSPECT LEFT OUTBOARD S	STANG FAIRING ASSEMBLY IAW ST	02209AT-D IFCA REV. D			
	PN	MOS			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C			0	
	REF:	AFL			0	
83136	RIGHT OUTBOARD STANG F	AIRING ASSEMBLY				
	PN	MOS	N:0		09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C	N:0		0	
	REF: AMM 78-30-15	AFL	N:0		0	
'83136A	INSPECT RIGHT OUTBOARD	STANG FAIRING ASSEMBLY IAW S	ST02209AT-D IFCA REV. D			
	PN	MOS			09-DEC-2007	
	SN-UNKNOWN	HRS/MSC O/C			0	



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

	Owner. SERVICIO	JS AEREUS PLA	I INOM C.A.	Operator: AERONAUT.	IC SOLUTION	IS JUAIN	ddek, S.A DE C	Re	port Date: 10-SEP-202	
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	ITERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE		MAX LIMIT	
783142	LEFT INBOARD STANG FAIRI	ING ASSEMBLY								
	19350001-03	MOS		N:0			12-DEC-2011			
	0205	HRS/MSC O	C C	N:0			3011.9			
	REF : AMM 78-30-15	AFL		N:0			1487			
783142A	INSPECT LEFT INBOARD STA	ANG FAIRING ASSEI	MBLY IAW ST0	2209AT-D IFCA REV. D						
	19350001-03	MOS					12-DEC-2011			
	0205	HRS/MSC O	C C				3011.9			
	REF:	AFL					1487			
783146	RIGHT INBOARD STANG FAII	RING ASSEMBLY								
	PN	MOS		N:0			09-DEC-2007			
	SN-UNKNOWN	HRS/MSC O	/C	N:0			0			
	REF : AMM 78-30-15	AFL		N:0			0			
783146A	INSPECT RIGHT INBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D									
	PN	MOS					09-DEC-2007			
	SN-UNKNOWN	HRS/MSC O	/C				0			
	REF:	AFL					0			
U7830010A (s)	INSPECT NO. 1 ENGINE UPP TWISTING, LOOSE OR FAILE						PKG			
	PKG 29	MOS					12-DEC-2011			
		HRS/MSC 36	600 +50				3011.9			
	REF: GENERIC NO REF	AFL					1487			
U7830010B (s)	INSPECT NO. 2 ENGINE UPP TWISTING, LOOSE OR FAILE						PKG			
	PKG 30	MOS					12-DEC-2011			
		HRS/MSC 36	600 +50				3011.9			
	REF: GENERIC NO REF	AFL					1487			
U7830012A (s)	INSPECT NO. 1 ENGINE THR COMPONENTS ATTACHED T						PKG			
	PKG 29	MOS					12-DEC-2011			
		HRS/MSC 36	600 +50				3011.9			
	REF: GENERIC NO REF	AFL					1487			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SFP-2021

DMPONENTS ATTACHED TO KG 30 IF: GENERIC NO REF FT ENGINE OIL PRESSURE III-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR III-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE III-UNKNOWN IF: AMM 79-30-01	MOS HRS/MSC AFL E/TEMPERATURI MOS HRS/MSC AFL RE/TEMPERATURI MOS HRS/MSC AFL E TRANSDUCER MOS	ASSEMBLY AND SE 3600 +50 E INDICATOR O/C RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0 N:0	TY, AND DAMAGE T TO FAN DUCT FLAI	NGE 1 3 1 0 0 0	09-DEC-2007			
F: GENERIC NO REF FT ENGINE OIL PRESSURE I-UNKNOWN F: AMM 79-30-01 GHT ENGINE OIL PRESSUR I-UNKNOWN F: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	HRS/MSC AFL E/TEMPERATURI MOS HRS/MSC AFL RE/TEMPERATURI MOS HRS/MSC AFL E TRANSDUCER MOS	E INDICATOR O/C RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		000000000000000000000000000000000000000	09-DEC-2007 09-DEC-2007			
FT ENGINE OIL PRESSURE I-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	AFL E/TEMPERATURI MOS HRS/MSC AFL RE/TEMPERATURI MOS HRS/MSC AFL E TRANSDUCER MOS	E INDICATOR O/C RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		000000000000000000000000000000000000000	09-DEC-2007 009-DEC-2007			
FT ENGINE OIL PRESSURE I-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	E/TEMPERATURI MOS HRS/MSC AFL RE/TEMPERATURI MOS HRS/MSC AFL E TRANSDUCER MOS	O/C RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		0000	09-DEC-2007 0) 09-DEC-2007			
FT ENGINE OIL PRESSURE I-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	MOS HRS/MSC AFL RE/TEMPERATUI MOS HRS/MSC AFL E TRANSDUCER MOS	O/C RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		0000	09-DEC-2007			
I I-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	MOS HRS/MSC AFL RE/TEMPERATUI MOS HRS/MSC AFL E TRANSDUCER MOS	O/C RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		0000	09-DEC-2007			
I-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	HRS/MSC AFL RE/TEMPERATUR MOS HRS/MSC AFL E TRANSDUCER MOS	RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		0000	09-DEC-2007			
I-UNKNOWN IF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	HRS/MSC AFL RE/TEMPERATUR MOS HRS/MSC AFL E TRANSDUCER MOS	RE INDICATOR O/C	N:0 N:0 N:0 N:0 N:0		0000	09-DEC-2007			
FF: AMM 79-30-01 GHT ENGINE OIL PRESSUR I-UNKNOWN FF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	AFL RE/TEMPERATUI MOS HRS/MSC AFL E TRANSDUCER MOS	RE INDICATOR O/C	N:0 N:0 N:0 N:0		0	09-DEC-2007			
I I-UNKNOWN IF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	MOS HRS/MSC AFL E TRANSDUCER MOS	O/C	N:0 N:0		0)			
I-UNKNOWN F: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	HRS/MSC AFL E TRANSDUCER MOS		N:0 N:0		0)			
I-UNKNOWN F: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	HRS/MSC AFL E TRANSDUCER MOS		N:0 N:0		0)			
FF: AMM 79-30-01 FT ENGINE OIL PRESSURE PTE-250L-1000-225D 82-8-704	AFL TRANSDUCER MOS		N:0						
PTE-250L-1000-225D 82-8-704	MOS								
82-8-704									
	1100/1400		N:0		0	09-DEC-2007			
	HRS/MSC	O/C	N:0		0)			
F: AMM 79-30-02	AFL		N:0		0				
RIGHT ENGINE OIL PRESSURE TRANSDUCER									
TE-250L-1000-225D	MOS		N:0		0	09-DEC-2007			
65-9-128	HRS/MSC	O/C	N:0		0				
F: AMM 79-30-02	AFL		N:0		0)			
LEFT ENGINE OIL TEMPERATURE BULB									
628034-3	MOS		N:0		0	09-DEC-2007			
491		O/C	N:0		0				
F: AMM 79-30-03	AFL		N:0		0				
GHT ENGINE OIL TEMPERA	ATURE BULB								
			N:O		0	09-DEC-2007			
		O/C			0				
		0.0			0				
	F: AMM 79-30-02 FT ENGINE OIL TEMPERAT 328034-3 491 F: AMM 79-30-03	F: AMM 79-30-02 AFL FT ENGINE OIL TEMPERATURE BULB 528034-3 MOS 491 HRS/MSC F: AMM 79-30-03 AFL GHT ENGINE OIL TEMPERATURE BULB 528034-3 MOS 5254 HRS/MSC	F: AMM 79-30-02 AFL FT ENGINE OIL TEMPERATURE BULB 528034-3 MOS 491 HRS/MSC O/C F: AMM 79-30-03 AFL SHT ENGINE OIL TEMPERATURE BULB 528034-3 MOS 4254 HRS/MSC O/C	F: AMM 79-30-02 AFL N:0 FT ENGINE OIL TEMPERATURE BULB 528034-3 MOS N:0 491 HRS/MSC O/C N:0 F: AMM 79-30-03 AFL N:0 SHT ENGINE OIL TEMPERATURE BULB 528034-3 MOS N:0 254 HRS/MSC O/C N:0	F: AMM 79-30-02	F: AMM 79-30-02 AFL N:0 FT ENGINE OIL TEMPERATURE BULB 128034-3 MOS N:0 491 HRS/MSC O/C N:0 F: AMM 79-30-03 AFL N:0 CHT ENGINE OIL TEMPERATURE BULB 128034-3 MOS N:0 1254 HRS/MSC O/C N:0 130 140 150 160 160 160 160 160 160 160 160 160 16			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTER\	/AL	TIME SINCE	ADJ	WARR EXP	COMPLIANC	E NEXT DUE (ENG/APU) A/C	eport Date: 10-SEP-2 MAX LIMIT
05-P&W-790001	NO. 1 ENGINE - REPLACE EN	GINE OIL FILTER	R ELEMEN	IT.						
	REF : EMM 79-20-01	MOS HRS/MSC ENC	12 1200	+25/-25				12-MAR-2021 4028.9 2596	12-MAR-2022 (5228.9) 5486.9	5253.9
05-P&W-790002	NO. 1 ENGINE - PERFORM EI	NGINE OIL CHAN	IGE							
	REF : EMM 72-00-00	MOS HRS/MSC ENC	12 600	+50/-50				12-MAR-2021 4028.9 2596	12-MAR-2022 (4628.9) 4886.9	4678.9
792001	NO. 1 ENGINE - OIL PUMP									
	30B4857-01 EC01A001A089 REF : EMM 79-20-05	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			08-JUL-2007 0 0		
792005	NO. 1 ENGINE - OIL PRESSUI	RE DIFFERENTIA	AL SWITCH	4						
	30B1506 1954 REF : EMM 79-20-01	MOS HRS/MSC ENC	O/C		N:3592			15-JUN-2017 3592 2049		
792010	NO. 1 ENGINE - ENGINE OIL I	PRESSURE LIGH	IT SWITCH	1						
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			08-JUL-2007 0 0		
792011	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTIO	ON OF THE	E OIL FILTER	R BYPASS SWITCH					
	PN SN-UNKNOWN REF : GENERIC NO REF	MOS HRS/MSC ENC	7200	+50				08-JUL-2007 0 0	(7200) 7458	VI 7250
792012	NO. 1 ENGINE - VISUALLY INSPECT THE FUEL/OIL HEAT EXCHANGER									
	REF: GENERIC NO REF	MOS HRS/MSC ENC	7200	+50				08-JUL-2007 0 0	(7200) 7458	VI 7250
792020	NO. 1 ENGINE - OIL PUMP HO	DUSING								
	PN SN-UNKNOWN REF : EMM 79-20-05	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0			08-JUL-2007 0 0		



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR	COMPLIANCE	NEXT DUE	ort Date: 10-SEP-2 MAX
	PART/SERIAL					EXP		(ENG/APU) A/C	LIMIT
792035	NO. 1 ENGINE - OIL FILTER E	BYPASS SWITCH							
	PN	MOS		N:0			08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
793001	NO. 1 ENGINE - DISCARD - C	HIP DETECTOR							
		MOS					08-JUL-2007		
		HRS/MSC	7200 +50				0	(7200) 7458 M	7250
DISCARD	REF : EMM 79-30-01	ENC					0		
793002	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTIO	N OF THE LOW OI	L PRESSURE SWITCH					
		MOS					08-JUL-2007		
		HRS/MSC	7200 +50				0	(7200) 7458 M	7250
	REF : EMM 79-30-02	ENC					0		
793003	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTIO	N OF THE OIL TAN	IK FILLER CAP					
		MOS					08-JUL-2007		
		HRS/MSC	7200 +50				0	(7200) 7458 M	7250
	REF : EMM 79-30-03	ENC					0		
793005	NO. 1 ENGINE - CHIP DETEC	TOR							
	PN	MOS		N:0			08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
REPLACE	REF : EMM 79-30-01	ENC		N:0			0		
793013	NO. 1 ENGINE - GENERAL VI	SUAL INSPECTIO	N OF THE OIL PRE	ESSURE DIFFERENTIAL IND	DICATOR (POP-U	JP)			
	PN	MOS					08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	7200 +50				0	(7200) 7458 M	7250
	REF: GENERIC NO REF	ENC					0		
793030	NO. 1 ENGINE - OIL PRESSU	RE DIFFERENTIA	L INDICATOR						
	PN	MOS		N:0			08-JUL-2007		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF : EMM 79-30-03	ENC		N:0			0		

ENGINE NO. 2 Model: PW305/PW305A/PW305B (CIMMS) Serial # PCE-CA0526 Part # 31B4067-04



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

TASK NO	TASK DESCRIPTION	UNIT	INTER\	/AI	TIME SINCE	ADJ	WARR	COMPLIANC	E NEXT DUE	Report Date: 10-SEP-202	
AGN NO	PART/SERIAL	— UNII		/AL	TIVIL SINCE	— ADJ	EXP	COMPLIANC	(ENG/APU) A/C	MAX LIMIT	
5-P&W-790001	NO. 2 ENGINE - REPLACE EN	IGINE OIL FILTE	R ELEMEN	I T							
		MOS	12					12-MAR-2021	12-MAR-2022		
		HRS/MSC	1200	+25/-25				4286.9	(5486.9) 5486.9	5511.9	
	REF: EMM 79-20-01	ENC						2754			
05-P&W-790002	NO. 2 ENGINE - PERFORM EI	NGINE OIL CHA	NGE								
		MOS	12					12-MAR-2021	12-MAR-2022		
		HRS/MSC		+50/-50				4286.9	(4886.9) 4886.9	4936.9	
	REF : EMM 72-00-00	ENC						2754			
92001	NO. 2 ENGINE - OIL PUMP										
	30B4857-01	MOS			N:0			21-JUL-2007			
	EC01A001A104	HRS/MSC	O/C		N:0			0			
	REF : EMM 79-20-05	ENC			N:0			0			
792005	NO. 2 ENGINE - OIL PRESSUI	RE DIFFERENT	IAL SWITCI								
	30B1948	MOS						13-JAN-2016			
	1189	HRS/MSC	O/C					3583.3			
	REF : EMM 79-20-01	ENC	0.0					1916			
792010	NO. 2 ENGINE - ENGINE OIL I	PRESSURE LIG	HT SWITCI	1							
	PN	MOS			N:0			21-JUL-2007			
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0			
	REF: GENERIC NO REF	ENC			N:0			0			
92011	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL FILTER BYPASS SWITCH										
	PN	MOS			-			21-JUL-2007			
	SN-UNKNOWN	HRS/MSC	7200	+50				0	(7200) 7200	M 7250	
	REF: GENERIC NO REF	ENC						0	(, -200		
792012	NO. 2 ENGINE - VISUALLY IN:	SPECT THE FU	EL/OIL HEA	T EXCHANG	SER						
		MOS						21-JUL-2007			
		HRS/MSC	7200	+50				0	(7200) 7200	M 7250	
	REF: GENERIC NO REF	ENC						0	(13,1=30		
792020	NO. 2 ENGINE - OIL PUMP HO	DUSING									
	PN	MOS			N:0			21-JUL-2007			
			0/0		N:0						
	SN-UNKNOWN	HRS/MSC	0/0		IN.U			0			



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

TASK NO	TASK DESCRIPTION	UNIT INTERVAL	TIME SINCE	ADJ WARR	COMPLIANCE	Report Date: 10-SEP-202 E NEXT DUE MAX					
	PART/SERIAL			EXP		(ENG/APU) A/C LIMIT					
792035	NO. 2 ENGINE - OIL FILTER I	BYPASS SWITCH									
	PN	MOS	N:0		21-JUL-2007						
	SN-UNKNOWN REF : GENERIC NO REF	HRS/MSC O/C ENC	N:0 N:0		0 0						
793001	NO. 2 ENGINE - DISCARD - C	CHIP DETECTOR									
		MOS			21-JUL-2007						
DIGG 4 DD	PEE ENN 70 00 04	HRS/MSC 7200 +50			0	(7200) 7200 M 7250					
DISCARD	REF: EMM 79-30-01	ENC			0						
793002	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LOW OIL PRESSURE SWITCH										
		MOS			21-JUL-2007						
		HRS/MSC 7200 +50			0	(7200) 7200 M 7250					
	REF: EMM 79-30-02	ENC			0						
793003	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL TANK FILLER CAP										
		MOS			21-JUL-2007						
		HRS/MSC 7200 +50			0	(7200) 7200 M 7250					
	REF: EMM 79-30-03	ENC			0						
793005	NO. 2 ENGINE - CHIP DETEC	CTOR									
	30B3756-02	MOS	N:0		10-FEB-2017						
	AB1738J	HRS/MSC O/C	N:0		3795.8						
REPLACE	REF: EMM 79-30-01	ENC	N:0		2153						
793013	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL PRESSURE DIFFERENTIAL INDICATOR (POP-UP)										
	PN	MOS			21-JUL-2007						
	SN-UNKNOWN	HRS/MSC 7200 +50			0	(7200) 7200 M 7250					
	REF: GENERIC NO REF	ENC			0						
793030	NO. 2 ENGINE - OIL PRESSU	IRE DIFFERENTIAL INDICATOR									
	PN	MOS	N:0		21-JUL-2007						
	SN-UNKNOWN	HRS/MSC O/C	N:0		0						
	REF : EMM 79-30-03	ENC	N:0		0						
LADTED 00	OT A DTINO										
HAPTER 80	STARTING										

(ENG/APU) = Engine/APU Units



LEARJET 60XR S/N 60 333 (YV3167): 4301.5 HRS, 2772 AFL as of 24-Jun-2021

Owner: SERVICIOS AEREOS PLATINUM C.A. Operator: AERONAUTIC SOLUTIONS JOANRIGER, S.A DE C.V.

Report Date: 10-SEP-2021

							Report Date: 10-3LF-2021
TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT IN	NTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE NEXT DUE MAX (ENG/APU) A/C LIMIT
801001	CROSS START RELAY BOX						
	PN SN-UNKNOWN REF: AMM 80-10-01	MOS HRS/MSC O AFL	V/C	N:0 N:0 N:0			09-DEC-2007 0 0
801002	AIR START RELAY BOX						
	6018358-002-602 A0074235-01 REF: AMM 80-10-02	MOS HRS/MSC O AFL	WC				22-OCT-2009 1756.3 799