

Thermal Imaging Analysis

Property: Sunshine Apartments, Block A
Date: April 25, 2026

Thermal Findings:

Area: Living Room Ceiling

Finding: Significant moisture detected behind the drywall. Temperature 14°C (Ambient 22°C).

Area: Master Bedroom Wall

Finding: No significant thermal anomalies detected. Surface temperature uniform at 21.5°C.

Area: Electrical Panel

DDR Report Generator

Upload your inspection and thermal reports below to generate a formatted DOCX report.

Inspection Report (PDF)

Choose File

No file chosen

Thermal Report (PDF)

Choose File

No file chosen

Generate Report

Finding: Circuit breaker #4 is showing signs of overheating (45°C). Immediate inspection required.