Linear

raw error: $e = ||V \in R^3||$

low-pass filtered error magnitude: $\bar{e}$

bias

gain * sign(e)

u

x axis distribution

y axis distribution

z axis distribution