




1. r3/r4 改為 1700



2.r1/r2 改為 8



3.r1=6900 , r4=50 , r6=1400



4.0.02V