DTC P1260:00 [SKYACTIV-G 2.0, SKYACTIV-G 2.5]

id0102h4856800

| DTC P1260:00 | Immobilizer system problem | |
|-----------------------------|---|--|
| DETECTION CONDITION | The start stop unit detects an immobilizer system malfunction. Diagnostic support note This is a continuous monitor (other). The check engine light does not illuminate. FREEZE FRAME DATA (Mode 2)/Snapshot data is not available. DTC is not stored in the PCM memory. | |
| FAIL-SAFE FUNCTION | Not applicable | |
| POSSIBLE CAUSE | Immobilizer system malfunction | |
| SYSTEM WIRING DIAGRAM | Not applicable | |

Diagnostic Procedure

| STEP | INSPECTION | | ACTION |
|------|--|-----|--|
| 1 | VERIFY RELATED SERVICE INFORMATION | Yes | Perform repair or diagnosis according to the available |
| | AVAILABILITY | | Service Information. |
| | Verify related Service Information availability. | | If the vehicle is not repaired, go to the next step. |
| | Is any related Service Information available? | No | Go to the next step. |
| 2 | VERIFY IMMOBILIZER SYSTEM DTC | Yes | Go to the applicable DTC inspection. |
| | Verify the immobilizer system DTC. | | (See DTC TABLE [IMMOBILIZER SYSTEM].) |
| | (See DTC INSPECTION [IMMOBILIZER | No | DTC troubleshooting completed. |
| | SYSTEM].) | | |
| | Are any DTCs present? | | |