REAR PILLAR (OUTER) INSTALLATION [PANEL REPLACEMENT]

id098008747300


Symbol Mark

SYMBOL MARK	MEANING
	SPOT WELDING
	PLUG WELDING (ARC WELDING)
	CONTINUOUS ARC WELDING (CUT-AND-JOIN LOCATION)

ac5wzb00000227

Installation Procedure

- When installing new parts, measure and adjust the body as necessary to conform with standard dimensions.
 Drill holes for the plug welding before installing the new parts.
- 3. After temporarily installing new parts, make sure the related parts fit properly.
- Cut and join the area location indicated by (A) shown in the figure.
 Plug weld the 1 location indicated by (B) shown in the figure.
- 6. Spot weld the 12 locations indicated by (C) shown in the figure, then install the rear pillar (outer).



ac5wzb00000294