EXCESSIVE CREEP [FW6A-EL, FW6AX-EL]

id050317100700

TROUBLESHO OTING ITEM	Excessive creep		
DESCRIPTION	Vehicle accelerates in D and R position when accelerator pedal is not depressed.		
POSSIBLE CAUSE	Not within idle speed specification		

Diagnostic procedure

Diagnostic procedure				
STEP	P INSPECTION		ACTION	
1	INSPECT ENGINE CONTROL SYSTEM FOR	Yes	Repair or replace any malfunctioning parts according to the	
	MALFUNCTION		inspection result.	
	 Perform the symptom troubleshooting "NO.9 FAST IDLE/RUNS ON". 	No	Symptom troubleshooting is completed.	
	(See NO.9 FAST IDLE/RUNS ON [SKYACTIV-G			
	2.0, SKYACTIV-G 2.5].)			
	Is there any malfunction?			