LOW MAXIMUM SPEED AND POOR ACCELERATION [GW6A-EL, GW6AX-EL]

id050320100900

TROUBLESHO OTING ITEM	Low maximum speed and poor acceleration	
DESCRIPTION	Vehicle acceleration is poor at start.	
DESCRIPTION	Delayed acceleration when accelerator pedal is depressed while driving.	
	Engine control system malfunction	
POSSIBLE	Signal malfunction	
CAUSE	APP sensor malfunction	
CAUSE	CKP sensor malfunction	
	MAF sensor malfunction	

Diagnostic procedure

STEP	INSPECTION		ACTION
1	INSPECT ENGINE CONTROL SYSTEM FOR	Yes	Repair or replace any malfunctioning parts according to the
	MALFUNCTION		inspection result.
	 Perform the symptom troubleshooting "NO.17 	No	Go to the next step.
	LACK/LOSS OF POWER-ACCELERATION/		
	CRUISE".		
	(See NO.17 LACK/LOSS OF POWER-		
	ACCELERATION/CRUISE [SKYACTIV-D 2.2].)		
	Is there any malfunction?		
2	INSPECT SIGNAL PARTS FOR MALFUNCTION	Yes	Repair or replace any malfunctioning parts according to the
	Inspect the value at the following PCM PIDs using		inspection result.
	the M-MDS.	No	Explain to the customer that the vehicle is not malfunctioning
	(See ON-BOARD DIAGNOSTIC TEST		and they should keep an eye on it.
	[SKYACTIV-D 2.2].)		
	APP (APP sensor)		
	— MAF (MAF sensor)		
	— RPM (CKP sensor)		
	Is there any malfunction?		