DTC P188A:00

DTC P188A:00	Differential oil temperature is out of range		
DETECTION CONDITION	4WD CM detects the differential oil temperature is out of range.		
FAIL-SAFE	4WD protection condition (4WD control paused)		
FUNCTION	4WD warning light: Flashed		
POSSIBLE CAUSE	Detects high differential oil temperature to switch to 2WD and protect the system		

Diagnostic procedure

STEP	INSPECTION		ACTION	
1	SWITCH THE IGNITION TO OFF AND ALLOW 4WD CM TO COOL DOWN.			
2	VERIFY THAT THE SAME DTC IS NOT PRESENT	Yes	Repeat the inspection from Step 1.	
	Clear the DTCs from the memory.	No	Go to the next step.	
	(See ELECTRONIC 4WD CONTROL SYSTEM ON-			
	BOARD DIAGNOSIS.)			
	Is the same DTC present?			
3	VERIFY THAT NO OTHER DTCS ARE PRESENT	Yes	Go to the applicable DTC inspection.	
	Are any other DTCs output?		(See ELECTRONIC 4WD CONTROL SYSTEM ON-	
			BOARD DIAGNOSIS.)	
		No	DTC troubleshooting completed.	