CORNER PLATE INSTALLATION [PANEL REPLACEMENT]

id098008610500

Symbol Mark


| SYMBOL MARK | MEANING |
|-------------|----------------------------|
| | SPOT WELDING |
| | PLUG WELDING (ARC WELDING) |

ac5wzb00000216

Installation Procedure

- 1. When installing new parts, measure and adjust the body as necessary to conform with standard dimensions.
- 2. Drill holes for the plug welding before installing the new parts.
- After temporarily installing new parts, make sure the related parts fit properly.
 Plug weld the 3 locations indicated by (A) shown in the figure.

5. Spot weld the 11 locations by (B) shown in the figure, then install the corner plate.



ac5wzb00000326