## SHROUD UPPER REINFORCEMENT INSTALLATION [PANEL REPLACEMENT]

id098008928000


## **Symbol Mark**

SYMBOL MARK	MEANING
	PLUG WELDING (ARC WELDING)

ac5wzb00000213

## **Installation Procedure**

- 1. When installing new parts, measure and adjust the body as necessary to conform with standard dimensions.
- 2. Drill holes for the plug welding before installing the new parts.
- After temporarily installing new parts, make sure the related parts fit properly.
  Plug weld the 4 locations shown in the figure, then install the shroud upper reinforcement.



ac5wzb00000241