DTC U0001:00/U0100:00/U0121:00/U0131:00/U0155:00 [LASER SENSOR]

id0402c4894900

DTC		, U0100:00, U0121:00, , U0155:00	CAN line
DETECTION CONDITION		• U0001:00	
		Open or short circuit in CAN system wiring harness is detected.	
		• U0100:00	
		 Communication error with PCM is detected in CAN communication. 	
		• U0121:00	
		 Communication error with DSC HU/CM is detected in CAN communication. 	
		• U0131:00	
		 Communication error with EPS CM is detected in CAN communication. 	
		• U0155:00	
		 Communication error with instrument cluster is detected in CAN communication. 	
FAIL FUN	CAEE	Inhibits the smart city brake support (SCBS) controls.	
	- 0,	Illuminates the master warning light	
	CTION	The message "SCBS Inspection Required" is indicated in the display.	
		CAN system wiring harness open or short circuit	
		CAN system wiring harness open or short circuit with PCM	
	SIBLE	CAN system wiring harness open or short circuit with DSC HU/CM	
	AUSE	CAN system wiring harness open or short circuit with EPS CM	
		CAN system wiring harness open or short circuit with instrument cluster	
		instrument cluster malfunction	
SY	STEM		
WIRING DIAGRAM		-	

Diagnostic procedureInspect according to diagnostic procedure in BODY & ACCESSORIES.