CORNER PLATE REMOVAL [PANEL REPLACEMENT]

id098008610400


Symbol Mark

SYMBOL MARK	MEANING
•	SPOT WELDING

ac5wzb00000076

Removal Procedure

1. Drill the 11 location shown in the figure.



2. Remove the corner plate.

ac5wzb00000130