
FRONT ACCESSORY SOCKET INSPECTION

id092100900800

- - If it cannot be verified, replace the front accessory socket. (See FRONT ACCESSORY SOCKET REMOVAL/INSTALLATION.)



ac5wzw00001122