FUEL CHECK VALVE INSPECTION [SKYACTIV-D 2.2]

id0114z7706000

• The fuel check valve cannot be inspected as a single unit.