WIPER BRACKET REMOVAL [PANEL REPLACEMENT]

id098008968900

Symbol Mark

SYMBOL MARK	MEANING
	PLUG WELDING (ARC WELDING)

ac5wzb00000215

Installation Procedure

- 1. When installing new parts, measure and adjust the body as necessary to conform with standard dimensions.
- 2. Drill holes for the plug welding before installing the new parts.
- After temporarily installing new parts, make sure the related parts fit properly.
 Plug weld the 9 locations indicated by (A) shown in the figure.
- 5. Plug weld the 3 locations indicated by (B) from the inside shown in the figure, then install the wiper bracket.

