## DTC P073D:00 [FW6A-EL, FW6AX-EL]

id050227905700

DTC P073D: 00	Neutral incorrect ratio		
	• In P or N position, the following phenomenon occurs:		
	<ul> <li>Speed ratio is 0.5 or less for 2 s while vehicle is stopped in P or N position.</li> </ul>		
	Diagnostic support note		
DETECTION	l • The check engine light does not illuminate.		
CONDITION	The automatic transaxle warning light does not illuminate.		
	PENDING CODE is available.		
	FREEZE FRAME DATA is not available.		
	DTC is stored in the TCM memory.		
FAIL-SAFE	Netonalizable		
FUNCTION	Not applicable		
POSSIBLE	Clutch stuck		
CAUSE	Turbine/input shaft speed sensor malfunction		
SYSTEM			
WIRING	Not applicable		
DIAGRAM			

**Diagnostic procedure** 

STEP	INSPECTION		ACTION
1	VERIFY DTC OUTPUT STATUS	Yes	Go to the applicable DTC inspection.
	Are any the following DTCs displayed?		(See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE
	— P0705:00, P0706:00, P0715:00, P0716:00,		[FW6A-EL, FW6AX-EL].)
	P0717:00	No	Replace the automatic transaxle.
			(See AUTOMATIC TRANSAXLE REMOVAL/
			INSTALLATION [FW6A-EL].)
			(See AUTOMATIC TRANSAXLE REMOVAL/
			INSTALLATION [FW6AX-EL].)