COWL UPPER PLATE INSTALLATION [PANEL REPLACEMENT]

id098008957200

Symbol Mark

SYMBOL MARK	MEANING
	PLUG WELDING (ARC WELDING)

ac5wzb00000214

Installation Procedure

- 1. When installing new parts, measure and adjust the body as necessary to conform with standard dimensions.
- 2. Drill holes for the plug welding before installing the new parts.

- After temporarily installing new parts, make sure the related parts fit properly.
 Plug weld the 9 locations indicated by (A) shown in the figure.
 Plug weld the 2 locations indicated by (B) from the front wheel housing side shown in the figure.
- 6. Plug weld the 2 locations indicated by (C) from the inside shown in the figure, then install the cowl upper plate.

