REAR FENDER PANEL REMOVAL [PANEL REPLACEMENT]

id098008744900

Symbol Mark


SYMBOL MARK	MEANING
•	SPOT WELDING
	ROUGH CUT LOCATION

ac5wzb00000074

Removal Procedure


Caution

• Avoid cutting with a blowtorch or similar tools as the insulator (shaded area) is flammable.




ac5wzb00000234

- Rough cut the 3 locations indicated by (A) shown in the figure.
 Drill the 90 locations indicated by (B) shown in the figure.



ac5uub00000071



3. Remove the cabin side outer frame (rear fender panel).