DTC P073D:00 [GW6A-EL, GW6AX-EL]

id050230905700

DTC P073D: 00	Neutral incorrect ratio		
	• In P or N position, the following phenomenon occurs:		
	 Speed ratio is 0.5 or less for 2 s while vehicle is stopped in P or N position. 		
	Diagnostic support note		
DETECTION	N ○ The check engine light does not illuminate.		
CONDITION	• The automatic transaxle warning light does not illuminate.		
	PENDING CODE is available.		
	FREEZE FRAME DATA is not available.		
	DTC is stored in the TCM memory.		
FAIL-SAFE	Netonalizable		
FUNCTION	Not applicable		
POSSIBLE	Clutch stuck		
CAUSE	Turbine/input shaft speed sensor malfunction		
SYSTEM			
WIRING	Not applicable		
DIAGRAM			

Diagnostic procedure

STEP	INSPECTION		ACTION
1	VERIFY DTC OUTPUT STATUS	Yes	Go to the applicable DTC inspection.
	Are any the following DTCs displayed?		(See ON-BOARD DIAGNOSTIC SYSTEM DTC TABLE
	— P0705:00, P0706:00, P0715:00, P0716:00,		[GW6A-EL, GW6AX-EL].)
	P0717:00	No	Replace the automatic transaxle.
			(See AUTOMATIC TRANSAXLE REMOVAL/
			INSTALLATION [GW6A-EL].)
			(See AUTOMATIC TRANSAXLE REMOVAL/
			INSTALLATION [GW6AX-EL].)