EXCESSIVE CREEP [GW6A-EL, GW6AX-EL]

id050320100700

TROUBLESHO OTING ITEM	Excessive creep		
DESCRIPTION	Vehicle accelerates in D and R position when accelerator pedal is not depressed.		
POSSIBLE CAUSE	Not within idle speed specification		

Diagnostic procedure

Diagnostic procedure				
STEP	INSPECTION		ACTION	
1	INSPECT ENGINE CONTROL SYSTEM FOR	Yes	Repair or replace any malfunctioning parts according to the	
	MALFUNCTION		inspection result.	
	Perform the symptom troubleshooting "NO.14 FAST IDLE/RUNS ON".	No	Symptom troubleshooting is completed.	
	(See NO.14 FAST IDLE/RUNS ON [SKYACTIV-			
	D 2.2].)			
	Is there any malfunction?			