## MASS AIR FLOW (MAF) SENSOR DATA RESET [SKYACTIV-D 2.2]

id0140z7810100

- 1. Connect the M-MDS to the DLC-2.
- 2. After the vehicle is identified, select the following item from the initial screen of the M-MDS.
  - (1) Select the "Powertrain".
- Then, select the items from the screen menu in the following order.
  Select the "Data Reset".
  Select the "MAF sensor".
  Perform the procedure according to the directions on the screen.