


8. Level 3 Repair

8-1. Components Layout






8-2. Block Diagram




8-3. PCB Diagrams

8-3-1. Top




8-3-2. Bottom



8-4. Flow Chart of Troubleshooting

Equipments




↑ Oscilloscope



↑ Digital Multimeter








A 502 % to \$4.00


↑ + driver, ESD Safe Tweezer



















8-4-2. Initial

















8-4-3. No Service




WWW.AliFixit.COM


Level 3 Repair










8-4-4. Sim Part - Sim Card













8-4-5. Charging Part













8-4-6. OTG










8-4-7. Proxy Sensor










8-4-8 Microphone Part - Main MIC







Main MIC













8-4-9. Speaker Part











8-4-10. Receiver Part















8-4-11. BT/WIFI







8-4-12. GPS













8-4-13. NFC









8-4-14. OCTA




DISPLAY PART








OCTA DCDC




8-4-15. 13M CAM











8-4-16. VT CAM

























8-4-17. Touch Key FPCB








EARJACK + HOME KEY + TOUCH KEY





8-4-18. Motor















8-4-19. GSM 850,900,1800,1900 / WCDMA 1,2,5,8 / LTE 1,3,5,7,8,20 RX













8-4-20. GSM 850,900,1800,1900 / WCDMA 1,2,5,8 / LTE 1,3,5,7,8,20 TX













data from this document without Samsung's written authorization is strictly prohibited.

8-4-21. LTE B7 TRX









8-5. Service Schematics

NC point(Top view)UCP3000(AP)

