

## [A5] SM-A500W REV0.3

2015.09.10

sheet01: RF PAM

sheet02: WTR1605L or WTR1605(TRANCEIVER), BT/WIFI, GPS, NFC

sheet03: MSM8916 or MSM8216(AP)


sheet04: PM8916(PMIC),eMCP


sheet05 : AUDIO, SUB PBA CONNECTOR


sheet06: 5" HD OCTA, CAM PART, SD CARD, MOT


sheet07 : SENSOR, Charger, MUIC


user49|swcad49|10.253.51.244|20151006-132239




















Model : Revision :

Manufacture Count:

Polarity possibilit y. Check the Pin1 2007-010856(R7006) : Check! Bottom Su rface of Component

| Model : Revision : Manufacture Count : Charge : Contact : |
|---|
| Date : Routing : Resin :                                  |
| Setup(2015-04-02)_H<br>HP                                 |
|   |
| U2004 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1                 |
| S.G. 2000 000 000 000 000 000 000 000 000 0               |
|   |
| U2001   |
| \$C2@03   |

LFD182G45DP4B889(F2 Polarity possibilit y. Check the Pin1 2007-010856(R7006) : Check! Bottom Su rface of Component

metraces ( M(T1002)

