

8. Level 3 Repair

8-1. Components Layout


PBA (Top Side)




PBA (Bottom Side)




8-2. Block Diagram



8-3. PCB Diagrams 8-3-1. Top




8-3-2. Bottom



8-4. Flow Chart of Troubleshooting

Equipments



↑ Oscilloscope




á Digital Multi-meter



á Power Supply



á + driver, ESD Safe Tweezer





↑ 8960 & Spectrum Analyzer




á Soldering iron


8-4-1. Power On







8-4-2. Initial










8-4-3. No Service









8-4-4. Sim Part




8-4-5. Charging Part







8-4-6. Microphone Part




8-4-7. Speaker Part







8-4-8 Receiver Part




8-4-9. LCD







8-4-10. TSP




8-4-11. 5M CAM





8-4-12. 2M CAM







8-4-13. FM radio







8-4-14. GSM850 / WCDMA Band5 / LTE Band5 Rx












data from this document without Samsung's written authorization is strictly prohibited.


8-4-15. GSM900 / WCDMABand8 / LTE B8 Rx






data from this document without Samsung's written authorization is strictly prohibited.








data from this document without Samsung's written authorization is strictly prohibited.

8-4-16. GSM1800 / LTE B3 Rx













data from this document without Samsung's written authorization is strictly prohibited.

8-4-17. WCDMA Band1 / LTE Band1 Rx













data from this document without Samsung's written authorization is strictly prohibited.

8-4-18. GSM1900 / WCDMA band1900 Rx













8-4-19. LTE Band20 Rx














8-4-20. LTE B40 Rx
















8-4-21. GSM850 / GSM900 Tx


















8-4-22. GSM1800 / GSM1900 Tx










8-4-23. WCDMA Band1 / LTE Band1 Tx













8-4-24. WCDMA Band5 / LTE B5 Tx










8-4-25. WCDMA Band8 / LTE Band8 Tx










8-4-26. LTE Band3 Tx










8-4-27. WCDMA Band2 Tx









8-4-28. LTE Band20 Tx







WWW.AliFixit.COM


Level 3 Repair




8-4-29. LTE Band40 Tx












WWW.AliFixit.COM


Level 3 Repair




8-4-30. BT/WLAN









8-4-31. GPS

