



Product : GSM

### **SUBJECT: Second Edition of Model SGH-E840**

## 1. Purpose:

- In order to inform repair engineers of information about technical TIP.

#### 2. Reason:

- Second Edition of Model SGH-E840 was launched.
- Some spare parts of Original(SGH-E840) and Second Edition(SGH-E840B) are not compatible with each other.
- 3. The difference between Original and Second Edition.
  - DO NOT NEED TO OPEN THE CASE to check Edition: Refer to "B" silk screen at SIM slot.

	"B" Silk at SIM slot
Original Edition SGH-E840	
Second Edition SGH-E840B	

#### 4. Difference of Software

EXAMPLE	★ USE "appropriate" Software, ini file and Downloader					
TYPE	Original Edition(SGH-E840)	Second Edition(SGH-E840B)				
S/W VERSION	E840XEGK5	E840BXEGK5				
INI FILE	E840_Russia(SER)_071108_1.ini	E840B_Russia(SER)_071114_1.ini				
Multi D/L	GE840_DEFAULT_MDL_V001.exe	GE840B_DEFAULT_MDL_V001.exe				
Single D/L	20062H_HIGH_Optiflash_061013.zip	E840B_20062H_HIGH_Optiflash_061013.zip				
Calibration and Final PGM	E840_CAL_V107_MonCell_DTM_Setup.zip					

Published By [Pete Kang]

# 5. The way to distinguish Spare part

_	<u> </u>		0 + 4 1/5/ 5				/
SGH-E840	INTENNA	FRONT ASS'Y	3 * 4 KEY F- PCB	CAMERA	TOUCH KEY	PCB	UPPER
	GH42-01159A	GH98-03697A (FRONT UNIT GH72-37441A)	GH59-04331A (INCLUDED FRONT ASS'Y)	GH59-04333A	GH59-04332A	GH41-01657A	GH98-03695A
		4 - 2- 3- 3- 3- 3- 3- 3- 3- 3- 3- 3- 3- 3- 3-		SGH-E840 Roy I.5 0 7 19	SGH-E840 R0.97 0715 20 🖋 📆	TE : 1 TO TO THE REAL PROPERTY OF THE REAL PROPERTY	
SGH-E840B	GH42-01388A (GRAY COLOR)	GH98-07031A (FRONT UNIT GH72-45929A)	GH59-05104A (SGH-E840VE SILK, INCLUDED FRONT ASS'Y)	GH59-05087A (SGH-E840B SILK)	GH59-05089A (SGH-E840B SILK)	GH41-01963A ("B" SILK)	GH98-06600A (Removed coating)
		Different Shape of Bottom.	SCH-E84 M REVO.1 3 777 "E840VE" SILK	SGH-E840B Rev .0 0 1333_	SGH-E8408 R0.41 R0	"B"SILK	Removed coating

\* Above spare parts of Original and Second Edition are not compatible with each other.