Tutorial 9

Question 1

Perform the bit stuffing procedure for the following binary sequence:

110111111110111111110101


Question 2

Perform the bit de-stuffing procedure for the following binary sequence:

11101111110111111001111110

Question 3

The following corresponds to an HDLC ABM frame exchange with no errors.



Complete the diagram by completing the labeling of the frame exchanges.