





Screw Terminals Leading to M12 Panel +12VD 1 C J18 GNDD 2 C Conn_01x02_Female GND GND GND +12V +5٧ +24V +24V +24V +24V GND GND GND +12V GND +24V +12V +24V +12V +12V Fan_PC_Chassis +5V J24 Extra M12 GND

Sheet: /Connectors/ File: Connectors.kicad_sch

Title: