

Architecture Project

Objective

To design and implement a simple 6-stage pipelined processor, Harvard. The design should conform to the ISA specification described in the following sections.

Introduction

The processor in this project has a RISC-like instruction set architecture. There are eight 2-byte general purpose registers; Ro, till R7. Another two general purpose registers, One works as a program counter (PC). And the other, works as a stack pointer (SP); and hence; points to the top of the stack. The initial value of SP is (2^10-2). The data memory address space is 1 KB of 16-bit width and is word addressable. (N.B. word = 2 bytes). You are allowed to make the data bus 32 bits to access two consecutive words.

The data memory in our processor is slow, so we split the memory stage into two stages and the new pipeline should be Fetch, Decode, Execute, Memory1, Memory2, writeback. Because we have only one Data Memory, no two consecutive memory instructions could be performed (structural hazard). The first stage of the memory should read the address and the data, the result won't be available until the second stage of the memory finishes.

When an interrupt occurs, the processor finishes the currently fetched instructions (instructions that have already entered the pipeline), then the address of the next instruction (in PC) is saved on top of the stack as well as the flags, and PC is loaded from address 1 of the instruction memory (Address 1 of the instruction memory contains the address of the interrupt service routine). To return from an interrupt, an RTI instruction loads the PC from the top of stack as well as the flags, and the flow of the program resumes from the instruction after the interrupted instruction. Take care of corner cases like Branching.

ISA Specifications

A) Registers

R[0:7]<15:0> ; Eight 16-bit general purpose register

PC<15:0>; 16-bit program counter SP<15:0>; 16-bit stack pointer

CCR<2:0> ; condition code register

; zero flag, change after arithmetic, logical, or shift operations Z<0>:=CCR<0> N<0>:=CCR<1>; negative flag, change after arithmetic, logical, or shift operations

; carry flag, change after arithmetic or shift operations. C<0>:=CCR<2>

B) Input-Output

IN.PORT<15:0> ; 16-bit data input port OUT.PORT<15:0> ; 16-bit data output port

; a single, non-maskable interrupt INTR.IN<0>

RESET.IN<0> ; reset signal

C) Mnemonics convention

Rsrc1 ; 1st operand register Rsrc2 ; 2nd operand register Rdst ; result register field

Imm ; Immediate Value 16-bits unless stated otherwise.

Take Care that Some instructions will Occupy more than one memory location

Mnemonic	Function		
NOP	PC ← PC + 1		
SETC	C ←1, make sure other flags don't get affected		
CLRC	C ←0, make sure other flags don't get affected		
	NOT value stored in register Rsrc and store it in Rdst		
NOT Rdst, Rsrc1	$R[Rdst] \leftarrow 1$'s Complement($R[Rsrc1]$);		
	If (1's Complement(R[Rsrc1]) = 0): $Z \leftarrow 1$; else: $Z \leftarrow 0$;		
	If (1's Complement(R[Rsrc1]) < 0): N \leftarrow 1; else: N \leftarrow 0		
	Don't change carry flag		
INC Rdst, Rsrc1	Increment value stored in Rsrc1		
	$R[Rdst] \leftarrow R[Rsrc1] + 1;$		
	If $((R[Rsrc1] + 1) = 0)$: $Z \leftarrow 1$; else: $Z \leftarrow 0$;		
	If $((R[Rsrc1] + 1) < 0)$: N \leftarrow 1; else: N \leftarrow 0		
	Update carry flag as appropriate		
DEC Rdst,Rsrc1	Decrement value stored in Rsrc1		
	$R[Rdst] \leftarrow R[Rsrc1] - 1;$		
	If $((R[Rsrc1] - 1) = 0): Z \leftarrow 1$; else: $Z \leftarrow 0$;		
	If $((R[Rsrc1]-1)<0)$: N \leftarrow 1; else: N \leftarrow 0		
	Update carry flag as appropriate		
OUT Rsrc1	$OUT.PORT \leftarrow R[Rsrc1]$		
IN Rdst	$R[Rdst] \leftarrow IN.PORT$		
MOV D det Demo 1	Move value from register Rsrc1 to register Rdst		
MOV Rdst, Rsrc1	DON'T change flags		
	Add the values stored in registers Rsrc1, Rsrc2		
ADD Rdst, Rsrc1,Rsrc2	and store the result in Rdst and updates carry		
	If the result =0 then $Z \leftarrow 1$; else: $Z \leftarrow 0$;		
	If the result <0 then $N \leftarrow 1$; else: $N \leftarrow 0$		
	Update carry flag as appropriate		
	Add the values stored in registers Rsrc1 to Immediate Value and store the result in Rdst and updates carry		
IADD Rdst, Rsrc1, Imm	If the result =0 then $Z \leftarrow 1$; else: $Z \leftarrow 0$;		
	If the result <0 then $N \leftarrow 1$; else: $N \leftarrow 0$		
	Update carry flag as appropriate		
	Subtract the values stored in registers Rsrc1-Rsrc2		
	and store the result in Rdst and updates carry		
SUB Rdst, Rsrc1,Rsrc2	If the result =0 then Z \leftarrow 1; else: $\overline{Z} \leftarrow$ 0;		
	If the result <0 then $N \leftarrow 1$; else: $N \leftarrow 0$		
	Update carry flag as appropriate		
AND Rdst, Rsrc1,Rsrc2	AND the values stored in registers Rsrc1, Rsrc2		
	and store the result in Rdst		
	If the result =0 then $Z \leftarrow 1$; else: $Z \leftarrow 0$;		
	If the result <0 then $N \leftarrow 1$; else: $N \leftarrow 0$		
	Don't change carry flag		
OR Rdst, Rsrc1, Rsrc2	OR the values stored in registers Rsrc1, Rsrc2		
	and store the result in Rdst		

	If the result =0 then $Z \leftarrow 1$; else: $Z \leftarrow 0$;			
	If the result <0 then $N \leftarrow 1$; else: $N \leftarrow 0$			
	Don't change carry flag			
PUSH Rsrc1	$DataMemory[SP] \leftarrow R[\ Rsrc\];SP-=1$			
POP Rdst	$SP+=1$; $R[Rdst] \leftarrow DataMemory[SP]$;			
LDM Rdst, Imm	Load immediate value (16 bit) to register Rdst			
	$R[Rdst] \leftarrow Imm<15:0>$			
LDD Rdst, Rsrc1	Load value from memory address Rsrc1			
	$R[Rdst] \leftarrow DataMemory[R[Rsrc1]];$			
STD Rsrc2, Rsrc1	Store value that is in register Rsrc1 to memory location Rsrc2 +			
	offset mesh 3lina			
	DataMemory [R[Rsrc2]] \leftarrow R[Rsrc1];			
JZ Rdst	Jump if zero			
	If $(Z=1)$: PC \leftarrow R[Rdst]; $(Z=0)$			
JC Rdst	Jump if negative			
	If $(C=1)$: PC \leftarrow R[Rdst]; $(C=0)$			
JMP Rdst	Jump			
JIVIF KUST	$PC \leftarrow R[Rdst]$			
CALL Rdst	(DataMemory[SP] \leftarrow PC + 1; sp-=1; PC \leftarrow R[Rdst])			
RET	$sp+=1, PC \leftarrow DataMemory [SP]$			
RTI	$sp+=1$; PC \leftarrow DataMemory [SP];			
	Then restore Flags			

Input Signals			
Reset	PC ← M[0] //memory location of zero		
Interrupt	DataMemory[Sp]←PC; sp-=1;PC ← M[1]; Store Flags ins stack		

Phase1 Requirement: Design and Implement (50%)

- Printed Report Containing: (20%)
 - Instruction format of your design
 - Opcode of each instruction
 - Instruction bits details
 - Control Signal Table
 - Create a table that contains all the control signals vs Instructions. For each instruction mark the corresponding control signals.
 - Schematic diagram of the processor with data flow details.
 - ALU / Registers / Memory Blocks / control block / Muxes/ Adders outside ALU
 ...etc
 - Dataflow Interconnections between Blocks & its sizes. (show control buses, data buses, address buses)
 - PC and SP update circuits
 - Pipeline stages design
 - Pipeline registers details (Size, Input, Connection, ...)
 - Pipeline hazards and your solution including
 - i. Data Forwarding
 - ii. Static Branch Prediction
 - Code : (30%)
 - Implement and integrate your architecture without any hazards for the given instructions only
 - i. VHDL Implementation of each component of the processor
 - ii. VHDL file that integrates the different components in a single module
 - iii. Instructions:

1. NOP 4. IN 2. INC 5. LDD 3. AND 6. STD

- Simulation Test code that reads a program file and executes it on the processor.
- Setup the simulation wave using a do file, and show the following signals: Clk,Rst,PC, Registers Values, Inport, MemoryOutput, Flags
 - O Load Memory File & Run the given test program

Phase2 Requirement: Assembler (5%)

- Assembler code that converts assembly program (Text File) into machine code according to your design (Memory File)
- The assembler can shuffle or rename the Rsrc/Rdst register but It can't split one instruction into multiple instructions.

Phase3 Requirement: Full processor (45%)

- Implement and integrate your architecture
 - VHDL Implementation of each component of the processor
 - VHDL file that integrates the different components in a single module
- Report that contains any design changes after phase1

Project Testing

- You will be given different test programs. You are required to compile and load it onto the Instruction and Data Memories and **reset** your processor to start executing from the memory location written in address 0000h (PC = M[0] not 0). Each program would test some instructions (you should notify the TA if you haven't implemented or have logical errors concerning some of the instruction set).
- You MUST prepare a waveform using do files with the main signals showing that your processor is working correctly (R0-R7, PC,SP,Flags,CLK,Reset,Interrupt, IN.port,Out.port).

Evaluation Criteria

- Each project will be evaluated according to the number of instructions that are implemented, and Pipelining hazards handled in the design. Check Table 2 for the distribution of grades.
- Failing to implement a working processor will nullify your project grade. <u>No credits will be given to individual modules or a non-working processor</u>.
- Unnecessary latching or very poor understanding of underlying hardware will be penalized.
- Your processor should be **synthesizable**, else it will be strongly penalized.
- Individual Members of the same team can have different grades, you can get a zero grade if you didn't work while the rest of the team can get fullmark, Make sure you balance your Work distribution.

Table 2: Evaluation Criteria

Marks	Design	20 %
Distribution	Instructions without hazard	50 %
Distribution	Handling Hazards (Data + Control + Structural Hazard)	30 %

Team Members

• Each team shall consist of a maximum of four members

Phase 1 Due Date

- Sunday of Week 10 (16th of April), Delivery of hardcopy report to TAs or Dr and Code should be uploaded to elearning.
- Week 10, Discussion will be on the Lab slots.

Phase 2 Due Date

• Sunday of Week 12 (30th of April), upload to elearn with a readme explaining how it works

Project Due Date

• Sunday of Week 14(14th of May), Delivery a softcopy on elearn and discussion on the same day.

General Advice

- 1. Compile your design on regular basis (after each modification) so that you can figure out new errors early. Accumulated errors are harder to track.
- 2. Synthesize your processor on regular basis as well, accumulation of non-synthesizable code could me it hard to fix.

- 3. Start by finishing a working processor that does all one operands only. Integrating early will help you find a lot of errors. You can then add each type of instructions and integrate them into the working processor.
- 4. Use the engineering sense to back trace the error source.
- 5. As much as you can, don't ignore warnings.
- 6. Read the transcript window messages in Modelsim/Quartus carefully.
- 7. After each major step, and if you have a working processor, save the design before you modify it (use a versioning tool if you can as git & svn).
- 8. Always save the ram files to easily export and import them.
- 9. Start early and give yourself enough time for testing.
- 10. Integrate your components incrementally (i.e: Integrate the RAM with the Registers, then integrate with them the ALU ...).
- 11. Use coding conventions to know each signal functionality easily.
- 12. Try to simulate your control signals sequence for an instruction (i.e: Add) to know if your timing design is correct.
- 13. There is no problem in changing the design after phase1, but justify your changes.
- 14. Always reset all components at the start of the simulation.
- 15. Don't leave any input signal float "U", set it with 0 or 1.
- 16. Remember that your VHDL code is a HW system (logic gates, Flipflops and wires).
- 17. Use Do files instead of re-forcing all inputs each time.