

## **LEXIQUE**

Terme	Position de l'initiation	Initiation position
S	Surface	Surface
SS	Sous la Surface	Sub Surface

Terme	Résultat	Result
F	Fracture	Fracture
F(CS)	Fracture (Complete Separation)	Fracture (Complete Separation)
RTL / ERT	Effort Résiduel de Traction	Residual Tensile Load
NR	Non Rompue	Run Out
VOID	Essai nul	Void test

Terme	Position de la fissure	Fracture position
BF	Bouton	Button
IW	Soudure Inertie	Inertia Weld
Thread	Filets	Thread
TC	Thermo Couple	Thermo Couple
AR / RAD	Rayon	At Radius
AX	Couteaux Extensomètre	At eXtensometer probes
IX	entre Couteaux Extensomètre	Inside eXtensometer probes
OX	en dehors des Couteaux	Outside eXtensometer probes

## **END OF REPORT**