پروژه نهایی سیستم های کنترل خطی

نيمسال دوم ۱۴۰۲

نام دانشجو: درسا امیری ابیانه

شماره دانشجویی: ۴۰۱۴۱۱۲۲۸

نام استاد: دكتر سهيل گنجه فر

مقدمه


پروژه ی حاضر به بررسی و طراحی کنترل کننده در سیستمهای کنترل خطی میپردازد. هدف این پروژه بهبود پاسخ زمانی سیستمی مشخص با استفاده از روشهای مختلف طراحی کنترل کننده است. در ابتدا سیستم بدون کنترل کننده شبیه سازی شده و پاسخ آن به ورودی پله واحد بررسی می شود. سپس با طراحی و اعمال کنترل کننده های مناسب، سعی در بهبود مشخصات دینامیکی سیستم داریم.

فهرست مطالب


۴	
۵	طراحی کنترل کننده
۵	الف) بالازدگی حداکثر ۳۰٪ و زمان نشست ۳ ثانیه
v	$K\simeq 1.2$ با گین 1.2
٧	پیش فاز یا Phase Lead:
1.	
ولز:	کنترل کننده تناسبی- انتگرالگیر (PI) با روش زیگلر نیکو
ش زیگلر نیکولز:	کنترل کننده تناسبی- مشتقگیر – انتگرالگیر (PID) با رو
17	: Kv ≥ 34 (ب
17	پس فاز یا Phase Lag برای:
14	Root Locus سيستم
14	الف) پیش از اعمال کنترل کننده
19	ب) پس از اعمال کنترل کننده
19	$:K \simeq 1.2$ گین 2.2
17	پیش فاز
71	پس فاز
Y9	پاسخ سیستم به ورودی پله واحد
٣۶	پاسخ سیستم به ورودی شیب
۴۶	
۴۸	تحلیل کلی پاسخ ها
۵۲	کل کد متلب جهت ران کردن در Matlab Live Editor کل کد متلب

شبیه سازی سیستم پیش از طراحی کنترل کننده

در این قسمت سیستم شبیه سازی شده و پاسخ آن به ورودی پله واحد پیش از طراحی کنترل کننده بررسی گشته است .



شکل ۱_شبیه سازی سیستم پیش از طراحی کنترل کننده در Simulink



شکل ۲_ زمان نشست سیستم پیش از طراحی کنترل کننده

همان طور که مشاهده می شود زمان نشست سیستم (با شاخص ۲٪) پیش از طراحی کنترل کننده برابر ۱۰ ثانیه و زمان ثانیه می باشد. همچنین پاسخ زمانی سیستم فاقد بالازدگی می باشد. زمان صعود سیستم تقریبا برابر ۵ ثانیه و زمان تقریبا ۱٫۱۷ ثانیه میباشد.

همانطور که مشاهده میشود مقادیر بدست آمده برای زمان نشست و صعود زیاد میباشند پس با طراحی کنترل کننده های متفاوت تلاش شده تا پاسخ سیستم بهبود داده شود.

طراحي كنترل كننده

الف) بالازدگی حداکثر ۳۰٪ و زمان نشست ۳ ثانیه

وقتی گفته می شود بالازدگی حداکثر ۳۰٪ برای اینکه پاسخ سریعتر باشد، بالازدگی همان ۳۰٪ درنظر گرفته می شود پس باتوجه به محاسبات زیر خواهیم داشت :

l Equation بالازدگی

overshoot = $e^{\frac{-\pi}{\tan \beta}} \times 100\%$

2 Equation_ زاویه با محور حقیقی

$$\tan\beta = \frac{\sqrt{1-\xi^2}}{\xi}$$

$$\Rightarrow 30\% = e^{-\frac{\pi}{\tan \beta}} \times 100\%$$

$$\Rightarrow \ln 0.3 = -\frac{\pi}{\tan \beta}$$

$$\Rightarrow \beta \simeq 69.03^{\circ} \simeq 1.20 \text{ rad}$$

(Damping ratio) نسبت ميرايي 3 Equation

$$\beta = \cos^{-1} \xi$$

$$\Rightarrow \xi = \cos \beta$$

$$\Rightarrow \xi \simeq 0.36$$

(Settling Time) زمان نشست _4 Equation

$$t_S = \frac{4}{\xi \omega_n} \Big|_{2\%} = 3$$

$$\Rightarrow \xi \omega_n = \frac{4}{3} \simeq 1.33$$

Raise Time) مان صعود; 5 Equation

$$t_r = \frac{\pi \cdot \beta}{\omega_d}$$

(Pick Time) زمان پیک _6 Equation

$$t_p = \frac{\pi}{\omega_d}$$


(Damped Natural Frequency) فركانس طبيعي ميرا _7 Equation

$$\omega_d = \omega_n \sqrt{1 - \xi^2}$$

$$\Rightarrow \omega_d = \frac{4}{3\xi} \sqrt{1 - \xi^2} = \frac{4}{3} \tan \beta = 3.48$$

$$\Rightarrow t_r = 1.09 \text{ sec}$$

$$\Rightarrow t_p = 0.90 \text{ sec}$$



شكل Root Locus _ ۳ سيستم با اعمال شروط بالازدگي ۳۰٪ و زمان نشست ۳ ثانيه

همانطور که مشاهده میشود مکان هندسی ریشه ها در سمت راست نقاط برخورد واقع شده اند پس برای \star اینکه \star ها روی نمودار قرار گیرند، باید نمودار به سمت چپ منتقل شود که این امر با یک بهره \star به تنهایی ممکن نیست.

$K \simeq 1.2$ با گین

دقت شود از آنجایی که بالازدگی حداکثر ۳۰ درصد است باتوجه اطلاعات نقاط در شکل ۳ پیداست به ازای vershoot = $4.2 \sim 4.3\%$ ، $K \simeq 1.2$ باید انتظار داشت بدلیل کاهش مقدار بلازدگی، پاسخ سیستم کندتر از حالاتی که کنترل کننده را به ازای حداکثر مقدار vershoot طراحی میکنیم باشد.


پیش فاز یا Phase Lead:

از آنجایی که در طراحی پیش فاز قطب ها و صفرهای اعمالی به سیستم هر جایی می توانند باشد پس در حالات مختلف بای در نظر گرفتن این صفر و قطب ها این کنترل کننده را طراحی کرده و پاسخ سیستم را با در نظر گرفتن هرکدام از انها بررسی میکنیم:

۸ Equation _شرط زوایا در طراحی پیش فاز

$$\begin{split} &\theta_z - \theta_p + \theta_{z_1} - \theta_{p_1} - \theta_{p_2} - \theta_{p_3} = 180 \\ \Rightarrow &\varphi = \theta_z - \theta_p = 180 + \theta_{p_1} + \theta_{p_2} + \theta_{p_3} - \theta_{z_1} \\ \Rightarrow &\varphi = 180 + 110.97 + 95.44 + 79.07 - 103.46 \\ &\Rightarrow &\varphi = 2.02^\circ \end{split}$$

پس زاویه ای که پیش فاز به سیستم اضافه خواهد کرد برابر $arphi=2.02^\circ$ خواهد بود.



شکل ۴ _ زوایای مشخص شده جهت محاسبه زاویه اعمال شونده به سیستم از طرف پیش فاز در حالات دیگر

a) صفر اعمال شونده به سیستم روی قطب ۲- قرار گیرد (کنترل کننده پیش فاز ۱):

پس در این حالت Z=2 \leftarrow را نیز محاسبه کرد: Z=2 است. حال میتوان مقادیر Z=2 را نیز محاسبه کرد:

$$\varphi = \theta_z - \theta_p = 2.02^{\circ}$$
 , $\theta_z = \theta_{p_q} = 79.07^{\circ}$ $\Rightarrow \theta_p = 77.05^{\circ}$

$$\frac{3.47}{P-1.33} = \tan 77.05 \Rightarrow P = 0.80$$

$$\Rightarrow G_c(s) = k_c \frac{s+2}{s+2.13}$$

$$k_c \left| \frac{2s+1}{s(s+1)(s+2.13)} \right|_{s=-1.33+3.47i} = 1 \Rightarrow k_c \simeq 6.46$$

b) صفر اعمال شونده به سیستم روی نقطه ۱٫۵ – قرار گیرد (کنترل کننده پیش فاز ۲):

یس در این حالت K, P است. حال می توان مقادیر Z = 1.5 \leftarrow -Z = -1.5 را نیز محاسبه کرد:

$$\theta_z - \theta_v = 2.02^\circ \Rightarrow \theta_v = 85.18$$

$$\frac{3.47}{P-1.33}$$
 = tan 85.18 \Rightarrow P = 1.62

$$\Rightarrow G_c(s) = k_c \frac{s + 1.5}{s + 1.62}$$

$$k_c \left| \frac{(s+1.5)(2s+1)}{s(s+1)(s+2)(s+1.62)} \right|_{s=-1.33+3.47j} = 1 \Rightarrow k_c \simeq 6.43$$

c) صفر اعمال شونده به سیستم روی نقطه ۲٫۵ - قرار گیرد (کنترل کننده پیش فاز ۳):

یس در این حالت K , P را نیز محاسبه کرد: Z=2.5 \longleftarrow -Z=-2.5 را نیز محاسبه کرد: $\theta_2=\arctan\left(\frac{3.47}{2.5-1.33}\right)=71.37^\circ$

$$\theta_z - \theta_v = 2.02, \theta_z = 71.37^\circ \Rightarrow \theta_v = 69.35$$


$$\frac{3.47}{P-1.33}$$
 = tan 69.35 $\Rightarrow P = 2.64$

$$G_c(s) = k_c \frac{s + 2.5}{s + 2.64}$$

$$K_c \left| \frac{(s+2.5)(2s+1)}{s(s+1)(s+2)(s+2.64)} \right|_{s=-1.33+3.47i} = 1 \Rightarrow k_c \simeq 6.50$$

d) روش هندسی (کنترل کننده پیش فاز با روش هندسی):

در این روش باید پس از رسم نیمساز و اعمال زاویه $\frac{\varphi}{2}$ در جهت ساعت گرد و پادساعتگرد از نیمساز، مقادیر Z , P را از روی زوایای محاسبه شده برای صفر ها و قطب ها و X را همانند موارد فوق از شرط اندازه محاسبه Z .



شکل ۵ _ زوایای مشخص شده جهت محاسبه زاویه اعمال شونده به سیستم از طرف پیش فاز در روش هندسی

$$\frac{180 - 69.03}{2} = 55.485$$

$$\frac{\varphi}{2} = 1.01 \Longrightarrow \begin{cases} \theta_p = 55.485 - 1.01 = 54.475 \\ \theta_z = 55.485 + 1.01 = 56.495 \end{cases}$$

$$\tan 54.475^\circ = \frac{3.47}{P - 1.33} \Rightarrow P \simeq 3.81$$


$$\tan 56.495^\circ = \frac{3.47}{z - 1.33} \Rightarrow z \simeq 3.63$$

$$\Rightarrow G_c(s) = k_c \frac{s + 3.63}{s + 3.81}$$

$$K_c \left| \frac{(s + 3.63)(2s + 1)}{s(s + 1)(s + 2)(s + 3.81)} \right|_{s = -1.33 \pm 3.47j} = 1 \Rightarrow k_c \simeq 6.57$$

کنترل کننده تناسبی (P) با روش زیگلر نیکولز

در این روش سعی می شود تا با تعریف تابع انتقالی از روی پاسخ پله سیستم، سیستم اصلی را با سیستم مرتبه اولی سپس با توجه به پارامتر های محاسبه شده، کنترل کننده ای طراحی کرد. از شکل ۱ می توان برداشت کرد پاسخ نهایی سیستم به ورودی پله واحد در حالت گذرا برابر ۱ خواهد بود حال برای محاسبه باقی پارامتر های مورد نیاز داریم:



شكل ۶ بررسي قسمتي از پاسخ پله سيستم اوليه جهت تقريب زدن آن با تابع انتقال مرتبه اول

$$\tau_d \simeq 0.2$$
 , $T_+ \tau_d \simeq 1.54 \implies T = 1.34$ $k' = 1 = k$

$$\Rightarrow G(s) = \frac{e^{-0.2S}}{1 + 1.34S} \qquad G_c(S) = K_p \left(1 + T_d S + \frac{1}{T_i S} \right)$$

$$(P): \begin{cases} K_{P_1} = \frac{T}{\tau_d} = \frac{1.34}{0.2} \\ T_i = \infty \\ T_d = 0 \end{cases} \Rightarrow G_c(s) = 6.7$$

کنترل کننده تناسبی- انتگرالگیر (PI) با روش زیگلر نیکولز:

$$(PI)$$
:
$$\begin{cases} K_{p_2} = 0.9 K_{p_1} = 6.03 \\ T_i = \frac{\tau_d}{0.3} \approx 0.67 \end{cases} \Rightarrow G_c(s) = 6.03 \left(1 + \frac{1}{0.67S}\right)$$
 $T_d = 0$

کنترل کننده تناسبی- مشتقگیر – انتگرالگیر (PID) با روش زیگلر نیکولز:

$$\text{(PID):} \begin{cases} K_{p_3} = 1.2 k_{p_1} = 8.04 \\ T_i = 2 \tau_d = 0.4 \\ T_d = 0.5 \tau_d = 0.1 \end{cases} \Rightarrow G_c(s) = 8.04 \left(1 + 0.1 \text{S} + \frac{1}{0.4 \text{S}} \right)$$

```
% Define the transfer function G(s) = 1 / (1 + 1.34s)
numerator = 1; % Numerator of the transfer function
denominator = [1 1.34]; % Denominator of the transfer function
G = tf(numerator, denominator); % Create transfer function G(s)
% Define the delay
delay = 0.2; % Time delay in seconds
% Pade approximation for the delay
[num_delay, den_delay] = pade(delay, 1); % 1st-order Pade approximation
Delay_approx = tf(num_delay, den_delay); % Create transfer function for
delay approximation
% Combine transfer function with delay approximation
G with delay = series(G, Delay approx); % Series combination of G(s) and
delay
% Define controllers
% P Controller
Kp1 = 1.34 / 0.2; % Proportional gain for P controller
Gc1 = Kp1; % Transfer function of P controller
% PI Controller
Kp2 = 0.9 * Kp1; % Proportional gain for PI controller
Ti2 = 0.2 / 0.3; % Integral time constant for PI controller
Gc2 = Kp2 * (1 + tf(1, [Ti2 0])); % Transfer function of PI controller
% PID Controller
Kp3 = 1.2 * Kp1; % Proportional gain for PID controller
Ti3 = 2 * 0.2; % Integral time constant for PID controller
Td3 = 0.5 * 0.2; % Derivative time constant for PID controller
Gc3 = Kp3 * (1 + tf([Td3 0], 1) + tf(1, [Ti3 0])); % Transfer function of
PID controller
```

: K_{11} ≥ 34 ($\dot{\neg}$

همواره سعی میشود که کنترل کننده ای طراحی شود تا پاسخ سیستم به ازای ماکزیمم خطای ممکن بهبود یابد، از آنجایی که در رابطه خطای حالت دائم با ورودی شیب داریم $K_{v,\,\mathrm{new}}=34$ پس $e_{ss}=\frac{1}{k_v}$ په ازای کمترین مقدار خود، بیشترین خطای ممکن را بوجود می آورد و از آنجایی که تلاش بر تغییر خطای حالت دائم میباشد پس باید یک Phase Lag طراحی کنیم پس خواهیم داشت:

$$\frac{k_{v, \text{ New}}}{k_{v, \text{ old}}} = \frac{z}{P}$$

$$k_{v, \text{ New}} = 34$$

$$k_v \geqslant 34 \Rightarrow \frac{1}{k_v} \leqslant \frac{1}{34} \simeq 0.03$$

$$z = \frac{\alpha}{10}$$

$$\alpha = \xi \omega_n \simeq 1.333$$

$$\Rightarrow z = 0.1333$$

$$k_{v,\, \mathrm{old}} = \lim_{s \to 0} SG(s)G_c(s)H(s)$$

پس فاز یا Phase Lag برای: $K \simeq 1.2$ کنتر U کننده

$$\begin{split} k_{v,\,\text{old}} &= \lim_{s \to 0} s \times \frac{1.2(2s+1)}{s(s+1)(s+2)} \simeq 0.6 \\ &\Rightarrow \frac{34}{0.6} = \frac{0.1333}{P} \to P \simeq 0.0024 \\ &\Rightarrow \hat{G}_c(s) = \frac{S+0.1333}{S+0.0024} \end{split}$$

كنترل كننده بيش فاز ١

$$k_{v, \text{ old}} = \lim_{s \to 0} s \times \frac{6.46(s+2)(2s+1)}{s(s+1)(s+2)(s+2.13)} \simeq 3.03$$

$$\Rightarrow \frac{34}{3.03} = \frac{0.1333}{P} \Rightarrow P \simeq 0.0119$$

$$\Rightarrow \hat{G}_c(S) = \frac{S + 0.1333}{S + 0.0119}$$

$$\begin{aligned} k_{v, \text{ old}} &= \lim_{s \to 0} s \times \frac{6.43(s+1.5)(2s+1)}{s(s+1)(s+2)(s+1.62)} &\simeq 2.98 \\ &\Rightarrow \frac{34}{2.98} = \frac{0.1333}{P} \to P &\simeq 0.0117 \\ &\Rightarrow \hat{G}_c(s) &= \frac{S+0.1333}{S+0.0117} \end{aligned}$$

کنترل کننده بیش فاز ۳

$$\begin{split} k_{v,\,\text{old}} &= \lim_{s \to 0} s \times \frac{6.5(s+2.5)(2s+1)}{s(s+1)(s+2)(s+2.64)} \simeq 3.08 \\ &\Rightarrow \frac{34}{3.08} = \frac{0.1333}{P} \Rightarrow P \simeq 0.0121 \\ &\Rightarrow \hat{G}_c(s) = \frac{S+0.1333}{S+0.0121} \end{split}$$

کنترل کننده بیش فاز با روش هندسی

$$k_{v, \text{ old}} = \lim_{s \to 0} s \times \frac{6.57(s + 3.63)(2s + 1)}{s(s + 1)(s + 2)(s + 3.81)} \simeq 3.13$$

$$\Rightarrow \frac{34}{3.13} = \frac{0.1333}{P} \Rightarrow P \simeq 0.0123$$

$$\hat{G}_c(s) = \frac{S + 0.1333}{S + 0.0123}$$

الف) بیش از اعمال کنترل کننده

```
***Matlab Code***

%% Define the numerator and denominator of the transfer function
num = [2 1]; % Numerator coefficients of '2s+1'
den = conv([1 0], conv([1 1], [1 2])); % Denominator coefficients of
's(s+1)(s+2)'


% Create the transfer function model
sys = tf(num, den)
```

```
sys =

2 s + 1
-----s^3 + 3 s^2 + 2 s

Continuous-time transfer function.
Model Properties
```

```
% Generate and plot the root locus
figure;
rlocus(sys);
hold on
points = [-1.33+3.47j, -1.33-3.47j]; % Points to mark on the root locus plot
plot(points, '*'); % Plotting points on the root locus plot
title('Root Locus of G(s) = (2s+1) / (s(s+1)(s+2))');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```




شکل ۲ _ Root Locus سیستم حلقه بسته با فیدبک منفی واحد پیش از طراحی کنترل کننده


باتوجه root locus در این حالت مشاهده می شود که سیستم به ازای تمامی مقادیر حقیقی K همواره پایدار بوده

```
ب) پس از اعمال کنترل کننده K \simeq 1.2
```

```
% Root locus plot for sys_0 (Controller with K = 1.2)
figure;
rlocus(sys_0);
hold on
points = [-1.33+3.47j, -1.33-3.47j]; % Points to mark on the root locus
plot
plot(points, '*');
title('Root Locus of sys K = 1.2);
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```




```
% Root locus plots for systems with phase-lead compensators
% Root locus plot for sys_A
figure;
rlocus(sys_A);
hold on
plot(points, '*');
title('Root Locus of sys A');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
```




شکل Root Locus _ 9 سیستم پس از اعمال کنترل کننده پیش فاز ۱

```
% Root locus plot for sys_B
figure;
rlocus(sys_B);
hold on
plot(points, '*');
title('Root Locus of sys B');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```




شكل Root Locus_ 10 سيستم پس از اعمال كنترل كننده پيش فاز ۲

```
% Root locus plot for sys_C
figure;
rlocus(sys_C);
hold on
plot(points, '*');
title('Root Locus of sys C');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```



شکل Root Locus _ 11 سیستم پس از اعمال کنترل کننده پیش فاز ۳

```
% Root locus plot for sys_D
figure;
rlocus(sys_D);
hold on
plot(points, '*');
title('Root Locus of sys D');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```



شكل Root Locus _ 12 سيستم پس از اعمال كنترل كننده پيش فاز با روش هندسي

```
% Define systems with added phase-lag controllers
sys_00 = series(tf([1 0.1333], [1 0.0041]), sys_0);
sys_AA = series(tf([1 0.1333], [1 0.0119]), sys_A);
sys_BB = series(tf([1 0.1333], [1 0.0117]), sys_B);
sys_CC = series(tf([1 0.1333], [1 0.0121]), sys_C);
sys_DD = series(tf([1 0.1333], [1 0.0123]), sys_D);
```

 $K \simeq 1.2$ کنترل کننده

```
% Root locus plot for sys_00
figure;
rlocus(sys_00);
hold on
plot(points, '*');
title('Root Locus of sys K = 1.2 with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```

Root Locus of sys K = 1.2 with Phase-Lag Controller 5 0.46 4 3 0.62 3 Imaginary Axis (seconds⁻¹) 2 0.84 0.84 -3 0.62 3 -4 0.17 0.11 0.05 0.34 0.24 -5 -2 -2.5-1.5-0.50.5 Real Axis (seconds⁻¹)


شكل Root Locus _ 13 سيستم پس از اعمال كنترل كننده پس فاز ۱ به پيشفاز ۱

```
% Root locus plot for sys_AA
figure;
rlocus(sys_AA);
hold on
plot(points, '*');
title('Root Locus of sys A with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```

Root Locus of sys A with Phase-Lag Controller 5 0.46 0.1:1 0.05 4 3 0.62 3 Imaginary Axis (seconds⁻¹) 0.84 0.84 2 -3 0.62 3 0.11 0.05 0.17-5 50 -1.5 -0.5 0.5 -2.5-2 Real Axis (seconds⁻¹)


شکل Root Locus _ 14 سیستم پس از اعمال کنترل کننده پس فاز ۲ به پیشفاز ۲

```
% Root locus plot for sys_BB
figure;
rlocus(sys_BB);
hold on
plot(points, '*');
title('Root Locus of sys B with Phase-Lead Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```



```
% Root locus plot for sys_CC
figure;
rlocus(sys_CC);
hold on
plot(points, '*');
title('Root Locus of sys C with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```

Root Locus of sys C with Phase-Lag Controller



شکل ۱۵ _ Root Locus سیستم پس از اعمال کنترل کننده پس فاز ۳ به پیشفاز ۳

```
% Root locus plot for sys_DD
figure;
rlocus(sys_DD);
hold on
plot(points, '*');
title('Root Locus of sys D with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```

Root Locus of sys D with Phase-Lag Controller 0.093.5 0.7 0.56 0.42 0.2 3 2.5 0.84 2 Imaginary Axis (seconds⁻¹) 1.5 0.95 1 0.5 0.5 1 0.95 1.5 2 0.84 2.5 -3 0.56 0.2 0.093.5 4 -3.5 -2.5 -1.5 -0.5 0.5 -3 Real Axis (seconds⁻¹)

شکلRoot Locus _ 16 سیستم پس از اعمال کنترل کننده پس فاز به پیشفاز با روش هندسی

کد متلب

```
% Create closed-loop systems with unit feedback
cl_sys_0 = feedback(sys_0, 1); % Closed-loop system with initial gain
adjustment
cl sys A = feedback(sys A, 1); % Closed-loop system with compensator A
cl_sys_B = feedback(sys_B, 1); % Closed-loop system with compensator B
cl_sys_C = feedback(sys_C, 1); % Closed-loop system with compensator C
cl_sys_D = feedback(sys_D, 1); % Closed-loop system with compensator D
cl sys = feedback(sys, 1);% Closed-loop Main system
% Time vector for simulation
t = 0:0.01:10;
%% Step responses
[y_0, t_0] = step(cl_sys_0, t); % Step response of closed-loop system with
initial gain adjustment
[y_A, t_A] = step(cl_sys_A, t); % Step response of closed-loop system with
compensator A
[y_B, t_B] = step(cl_sys_B, t); % Step response of closed-loop system with
compensator B
[y_C, t_C] = step(cl_sys_C, t); % Step response of closed-loop system with
compensator C
[y_D, t_D] = step(cl_sys_D, t); % Step response of closed-loop system with
compensator D
[y, t] = step(cl sys, t);% Step response of closed-loop Main system
% Display step information
info_0 = stepinfo(cl_sys_0, 'SettlingTimeThreshold', 0.02) % Step information
of closed-loop system with initial gain adjustment
info 0 =
         RiseTime: 3.6800
    TransientTime: 8.7277
      SettlingMin: 0.9003
             Peak: 0.9998
         PeakTime: 22.1264
```

```
info_A = stepinfo(cl_sys_A, 'SettlingTimeThreshold', 0.02) % Step information
of closed-loop system with compensator A
```

```
info_A =
     RiseTime: 0.4016
TransientTime: 3.6489
SettlingTime: 3.6489
SettlingMin: 0.8867
SettlingMax: 1.2334
     Overshoot: 23.3444
Undershoot: 0
     Peak: 1.2334
     PeakTime: 0.8996
```

info_B = stepinfo(cl_sys_B, 'SettlingTimeThreshold', 0.02) % Step information
of closed-loop system with compensator B

```
info_B =
    RiseTime: 0.4030
TransientTime: 3.6993
SettlingTime: 3.6993
SettlingMin: 0.8855
SettlingMax: 1.2304
    Overshoot: 23.0399
Undershoot: 0
    Peak: 1.2304
    PeakTime: 0.9014
```


info_C = stepinfo(cl_sys_C, 'SettlingTimeThreshold', 0.02) % Step information
of closed-loop system with compensator C

info_D = stepinfo(cl_sys_D, 'SettlingTimeThreshold', 0.02) % Step information
of closed-loop system with compensator D

```
info_D =
    RiseTime: 0.3978
TransientTime: 2.3797
SettlingTime: 2.3797
SettlingMin: 0.8867
SettlingMax: 1.2403
Overshoot: 24.0295
```

```
Peak: 1.2403
         PeakTime: 0.9004
info = stepinfo(cl sys, 'SettlingTimeThreshold', 0.02) % Step information of
closed-loop Main system
info =
         RiseTime: 4.5641
    TransientTime: 9.9974
      SettlingMin: 0.9003
             Peak: 0.9983
         PeakTime: 17.7866
% Display step response plots
figure;
subplot(6,1,1);
plot(t_0, y_0);
grid on;
title('Step Response of Closed-Loop sys_0');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_0.RiseTime, info_0.SettlingTime, info_0.Overshoot));
subplot(6,1,2);
plot(t_A, y_A);
grid on;
title('Step Response of Closed-Loop sys A');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_A.RiseTime, info_A.SettlingTime, info_A.Overshoot));
subplot(6,1,3);
plot(t_B, y_B);
grid on;
title('Step Response of Closed-Loop sys_B');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_B.RiseTime, info_B.SettlingTime, info_B.Overshoot));
subplot(6,1,4);
plot(t_C, y_C);
```

```
grid on;
title('Step Response of Closed-Loop sys C');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_C.RiseTime, info_C.SettlingTime, info_C.Overshoot));
subplot(6,1,5);
plot(t_D, y_D);
grid on;
title('Step Response of Closed-Loop sys_D');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_D.RiseTime, info_D.SettlingTime, info_D.Overshoot));
subplot(6,1,6);
plot(t, y);
grid on;
title('Step Response of Closed-Loop Main sys');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info.RiseTime, info.SettlingTime, info.Overshoot));
```



شكل 17 _ پاسخ بله سيستم هاى بدون كنترل كننده، با كنترل كننده بيشفاز و گين ١/٢

```
% Create closed-loop systems with unit feedback
cl sys 00 = feedback(sys 00, 1); % Closed-loop system with initial gain
adjustment
cl_sys_AA = feedback(sys_AA, 1); % Closed-loop system with compensator A
cl sys BB = feedback(sys BB, 1); % Closed-loop system with compensator B
cl_sys_CC = feedback(sys_CC, 1); % Closed-loop system with compensator C
cl_sys_DD = feedback(sys_DD, 1); % Closed-loop system with compensator D
% Time vector for simulation
t = 0:0.01:10;
% Compute step responses
[y_00, t_00] = step(cl_sys_00, t);
[y_AA, t_AA] = step(cl_sys_AA, t);
[y_BB, t_BB] = step(cl_sys_BB, t);
[y CC, t CC] = step(cl sys CC, t);
[y_DD, t_DD] = step(cl_sys_DD, t);
% Compute step response characteristics
info_00 = stepinfo(y_00, t_00);
info_AA = stepinfo(y_AA, t_AA);
info_BB = stepinfo(y_BB, t_BB);
info_CC = stepinfo(y_CC, t_CC);
info_DD = stepinfo(y_DD, t_DD);
% Plot step responses
figure;
subplot(5,1,1);
plot(t_00, y_00);
grid on;
title('Step Response with Lag Controller sys_00');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_00.RiseTime, info_00.SettlingTime, info_00.Overshoot));
subplot(5,1,2);
plot(t_AA, y_AA);
grid on;
title('Step Response with Lag Controller sys_AA');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_AA.RiseTime, info_AA.SettlingTime, info_AA.Overshoot));
subplot(5,1,3);
plot(t_BB, y_BB);
grid on;
```


```
title('Step Response with Lag Controller sys_BB');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info BB.RiseTime, info BB.SettlingTime, info BB.Overshoot));
subplot(5,1,4);
plot(t_CC, y_CC);
grid on;
title('Step Response with Lag Controller sys_CC');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_CC.RiseTime, info_CC.SettlingTime, info_CC.Overshoot));
subplot(5,1,5);
plot(t_DD, y_DD);
grid on;
title('Step Response with Lag Controller sys DD');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_DD.RiseTime, info_DD.SettlingTime, info_DD.Overshoot));
                                 Step Response with Lag Controller sys, 0
                                                RiseTime: 2.41, SettlingTime: 5.27, Overshoot: 0.55%
                                            Time (seconds)
                                 Step Response with Lag Controller sys A
                                                RiseTime: 0.40, SettlingTime: 2.91, Overshoot: 26.23%
                                                                                      10
                                            Time (seconds)
                                 Step Response with Lag Controller sys B
                                                RiseTime: 0.40, SettlingTime: 2.90, Overshoot: 25.89%
                                                                                      10
                                            Time (seconds)
                                 Step Response with Lag Controller sys C
                                                RiseTime: 0.39, SettlingTime: 2.92, Overshoot: 26.53%
                                            Time (seconds)
                                 Step Response with Lag Controller sys D
                                                RiseTime: 0.39, SettlingTime: 2.93, Overshoot: 26.91%
                                  3
                                                 5
                                                                               9
                                                                                      10
                                            Time (seconds)
                                      شكل 18 پاسخ بله پس فاز ها
```

```
% Closed-loop transfer functions
T1 = feedback(Gc1 * G with delay, 1); % Closed-loop transfer function with P
controller
T2 = feedback(Gc2 * G_with_delay, 1); % Closed-loop transfer function with PI
controller
T3 = feedback(Gc3 * G with delay, 1); % Closed-loop transfer function with PID
controller
% Time vector for simulation
t = 0:0.01:10; % Time vector for simulation, from 0 to 10 seconds with 0.01
second steps
% Step responses
[y1, t1] = step(T1, t); % Step response of system with P controller
[y2, t2] = step(T2, t); % Step response of system with PI controller
[y3, t3] = step(T3, t); % Step response of system with PID controller
% Display step information (2% settling time criteria)
info_T1 = stepinfo(T1, 'SettlingTimeThreshold', 0.02) % Step response
information for P controller
info_T1 =
         RiseTime: 0.1033
    TransientTime: 1.6383
     SettlingTime: 1.6586
      SettlingMin: 0.6355
      SettlingMax: 1.2922
        Overshoot: 55.0678
             Peak: 1.2922
        PeakTime: 0.4367
info_T2 = stepinfo(T2, 'SettlingTimeThreshold', 0.02) % Step response
information for PI controller
info_T2 =
         RiseTime: 0.1233
    TransientTime: 1.9139
     SettlingTime: 2.2700
      SettlingMin: 0.7542
      SettlingMax: 1.5755
        Overshoot: 57.5510
       Undershoot: 22.1497
             Peak: 1.5755
         PeakTime: 0.4882
```

info_T3 = stepinfo(T3, 'SettlingTimeThreshold', 0.02) % Step response


```
TransientTime: 0.6171
SettlingTime: 1.0210
SettlingMin: 0.9014
SettlingMax: 1.1281
Overshoot: 12.8098
Undershoot: 410.2041
Peak: 4.1020
PeakTime: 0
```

```
% Plot the step responses
figure;
subplot(3,1,1);
plot(t1, y1); % Plot step response of P controller
title('Step Response with P Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info T1.RiseTime, info T1.SettlingTime, info T1.Overshoot));
subplot(3,1,2);
plot(t2, y2); % Plot step response of PI controller
grid on;
title('Step Response with PI Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_T2.RiseTime, info_T2.SettlingTime, info_T2.Overshoot));
subplot(3,1,3);
plot(t3, y3); % Plot step response of PID controller
grid on;
title('Step Response with PID Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_T3.RiseTime, info_T3.SettlingTime, info_T3.Overshoot));
```



```
% Define the ramp input signal
ramp input = t; % Ramp input signal over time
% Simulate ramp response for closed-loop sys_0
[y_r0, t_r0] = lsim(cl_sys_0, ramp_input, t); % Simulate response using lsim
figure;
subplot(6,1,1);
plot(t_r0, y_r0, 'b', t_r0, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys_0');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys_A
[y_rA, t_rA] = lsim(cl_sys_A, ramp_input, t); % Simulate response using lsim
subplot(6,1,2);
plot(t_rA, y_rA, 'b', t_rA, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys A');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys_B
[y_rB, t_rB] = lsim(cl_sys_B, ramp_input, t); % Simulate response using lsim
subplot(6,1,3);
plot(t_rB, y_rB, 'b', t_rB, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys B');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys C
[y_rC, t_rC] = lsim(cl_sys_C, ramp_input, t); % Simulate response using lsim
subplot(6,1,4);
plot(t_rC, y_rC, 'b', t_rC, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys_C');
xlabel('Time (seconds)');
```

```
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys D
[y_rD, t_rD] = lsim(cl_sys_D, ramp_input, t); % Simulate response using lsim
subplot(6,1,5);
plot(t_rD, y_rD, 'b', t_rD, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys_D');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop Main sys
[y_r, t_r] = lsim(cl_sys, ramp_input, t); % Simulate response using lsim
subplot(6,1,6);
plot(t_r, y_r, 'b', t_r, ramp_input, 'r--'); % Plot system response and ramp
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop Main sys');
xlabel('Time (seconds)');
ylabel('Amplitude');
```




شکل ۲۰ _ پاسخ به ورودی شیب سیستم بدون کنترل کننده، با کنترل کننده پیش فاز ، با گین ۱/۲

```
% Time vector for simulation
t = 0:0.01:10;
ramp input = t; % Ramp input signal over time 't'
% Ramp response for cl sys 00 (Lag Controller)
[y_r_00, t_r_00] = lsim(cl_sys_00, ramp_input, t);
[y_r_{00}] = 1sim(sys_0, ramp_input, t);
figure;
subplot(5,1,1);
plot(t_r_00, y_r_00, 'b', t_r_00_sys, ramp_input, 'r--'); % Plot ramp response
for cl_sys_00
legend('With Lag Controller 00', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller 00');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_AA (Lag Controller)
[y_r_AA, t_r_AA] = lsim(cl_sys_AA, ramp_input, t);
[y_r_AA_sys, t_r_AA_sys] = lsim(sys_A, ramp_input, t);
subplot(5,1,2);
plot(t_r_AA, y_r_AA, 'b', t_r_AA_sys, ramp_input, 'r--'); % Plot ramp response
for cl sys AA
legend('With Lag Controller AA', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller AA');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_BB (Lag Controller)
[y_r_BB, t_r_BB] = lsim(cl_sys_BB, ramp_input, t);
[y_r_BB_sys, t_r_BB_sys] = lsim(sys_B, ramp_input, t);
subplot(5,1,3);
plot(t_r_BB, y_r_BB, 'b', t_r_BB_sys, ramp_input, 'r--'); % Plot ramp response
for cl sys BB
legend('With Lag Controller BB', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller BB');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_CC (Lag Controller)
[y_r_CC, t_r_CC] = lsim(cl_sys_CC, ramp_input, t);
[y_r_CC_sys, t_r_CC_sys] = lsim(sys_C, ramp_input, t);
subplot(5,1,4);
plot(t_r_CC, y_r_CC, 'b', t_r_CC_sys, ramp_input, 'r--'); % Plot ramp response
for cl_sys_CC
legend('With Lag Controller CC', 'Without Controller');
```

```
grid on;
title('Ramp Response with Lag Controller CC');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_DD (Lag Controller)
[y_r_DD, t_r_DD] = lsim(cl_sys_DD, ramp_input, t);
[y_r_DD_sys, t_r_DD_sys] = lsim(sys_D, ramp_input, t);
subplot(5,1,5);
plot(t_r_DD, y_r_DD, 'b', t_r_DD_sys, ramp_input, 'r--'); % Plot ramp response
for cl_sys_DD
legend('With Lag Controller DD', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller DD');
xlabel('Time (seconds)');
ylabel('Amplitude');
                              Ramp Response with Lag Controller 00
 Amplitude
2 0,
                                                                         With Lag Controller 00
                                                                        Without Controller
                                                                                           10
                                          Time (seconds)
                              Ramp Response with Lag Controller AA
 Amplitude
2 0
                                                                        With Lag Controller AA
                                                                        Without Controller
     0
                       2
                               3
                                                5
                                                         6
                                                                          8
                                                                                   9
                                                                                           10
                                          Time (seconds)
                              Ramp Response with Lag Controller BB
    10
 Amplitude
                                                                        With Lag Controller BB
     5
                                                                        Without Controller
                               3
                                                                          8
                                                                                           10
                                          Time (seconds)
                              Ramp Response with Lag Controller CC
 Amplitude
2 0
                                                                        With Lag Controller CC
                                                                        Without Controller
      o
                       2
                               3
                                                                          8
                                                                                   9
                                                                                           10
                                          Time (seconds)
                              Ramp Response with Lag Controller DD
 Amplitude
2 0
                                                                        With Lag Controller DD
                                                                        Without Controller
                               3
                                                                                           10
                                          Time (seconds)
```

شكل 21 پاسخ به ورودي شيب پس فاز ها

```
ramp input = t; % Ramp input signal over time 't'
% Ramp response for T1 (P Controller)
[y r1, t r1] = lsim(T1, ramp input, t); % Simulate ramp response with T1 (P
Controller)
[y_r1_sys, t_r1_sys] = lsim(G_with_delay, ramp_input, t); % Simulate ramp
response without controller
figure;
subplot(3,1,1);
plot(t_r1, y_r1, 'b', t_r1_sys, ramp_input, 'r--'); % Plot ramp response for
legend('With P Controller', 'Without Controller');
grid on;
title('Ramp Response with P Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for T2 (PI Controller)
[y_r2, t_r2] = lsim(T2, ramp_input, t); % Simulate ramp response with T2 (PI
Controller)
[y_r2_sys, t_r2_sys] = lsim(G_with_delay, ramp_input, t); % Simulate ramp
response without controller
subplot(3,1,2);
plot(t_r2, y_r2, 'b', t_r2_sys, ramp_input, 'r--'); % Plot ramp response for
legend('With PI Controller', 'Without Controller');
grid on;
title('Ramp Response with PI Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for T3 (PID Controller)
[y_r3, t_r3] = lsim(T3, ramp_input, t); % Simulate ramp response with T3 (PID
Controller)
[y_r3_sys, t_r3_sys] = lsim(G_with_delay, ramp_input, t); % Simulate ramp
response without controller
subplot(3,1,3);
plot(t_r3, y_r3, 'b', t_r3_sys, ramp_input, 'r--'); % Plot ramp response for
T3
legend('With PID Controller', 'Without Controller');
title('Ramp Response with PID Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
```



P,PI,PID پاسخ به ورودی شیب سیستم ها با کنترل کننده های TT

```
% Display poles and zeros of the system
pole(sys)
ans = 3 \times 1
zero(sys)
ans = -0.5000
% Calculate damping ratio (zetha) and natural frequency (Wn)
Mp = log(0.3); % Desired percentage overshoot in logarithm form
zetha = -Mp/sqrt(Mp^2 + pi^2) % Damping ratio calculation
zetha = 0.3579
tp = 3; % Desired settling time
Wn = 4/(tp*zetha) % Natural frequency calculation
Wn = 3.7259
beta = acos(zetha); % Angle beta calculation
betaa = rad2deg(beta); % Convert angle beta to degrees
betaa = 69.0313
% Calculate gains for different compensators
s = -1.33 + 3.47j; % Point in the complex plane for compensator calculations
num0 = (2*s+1); % Numerator of the original transfer function at point s
den0 = s*(s+1)*(s+2);%Denominator of the original transfer function at point s
% Calculating gains K for different compensators
num_A = num0 * (s+2);
den_A = den0 * (s+2.13);
K A = abs(den_A / num_A)
K A = 6.4642
num_B = num0 * (s+1.5);
den_B = den0 * (s+1.62);
K_B = abs(den_B / num_B);
K B = 6.4299
num_C = num0 * (s+2.5);
den_C = den0 * (s+2.64);
K_C = abs(den_C / num_C)
K C = 6.4978
num_D = num0 * (s+3.63);
den_D = den0 * (s+3.81);
```

```
K_D = abs(den_D / num_D)
KD = 6.5726
% Create open-loop systems with compensators
sys 0 = tf(1.2*num, den) % Open-loop system with initial gain adjustment
sys_0 =
     2.4 s + 1.2
Continuous-time transfer function.
Model Properties
sys_A = tf(K_A*[2 1], [1 3.13 2.13 0]); % Open-loop system with compensator A
sys_A =
     12.93 s + 6.464
  s^3 + 3.13 s^2 + 2.13 s
Continuous-time transfer function.
Model Properties
sys_B = tf(K_B*[2 \ 4 \ 1.5], [1 \ 4.62 \ 6.86 \ 3.24 \ 0]); % Open-loop system with
compensator B
sys_B =
     12.86 \text{ s}^2 + 25.72 \text{ s} + 9.645
  s^4 + 4.62 s^3 + 6.86 s^2 + 3.24 s
Continuous-time transfer function.
Model Properties
sys_C = tf(K_C*[2 6 2.5], [1 5.64 9.92 5.28 0]); % Open-loop system with
compensator C
sys_C =
       13 s^2 + 38.99 s + 16.24
  s^4 + 5.64 s^3 + 9.92 s^2 + 5.28 s
Continuous-time transfer function.
Model Properties
```

 $sys_D = tf(K_D*[2 8.26 3.63], [1 6.81 13.43 7.62 0]); % Open-loop system with compensator D$


استفاده از sisotool برای طراحی کنترل کننده

برای طراحی و تنظیم کنترل کنندهها، از ابزار SISOtool در MATLAB استفاده شده است. این ابزار امکان تنظیم پارامترهای کنترل کننده و مشاهده تاثیرات آن بر پاسخ سیستم را فراهم می کند.


برای استفاده از این ابزار، ابتدا تابع انتقال سیستم را در MATLAB تعریف کرده و سپس با اجرای دستور 'sisotool(sys)' محیط گرافیکی SISOtool باز می شود. در این محیط می توان پارامترهای مختلف کنترل کننده ها را تنظیم و نتایج را به صورت نموداری مشاهده کرد.

New Design Requirement					_		×
Design requireme	ent type:	Step respon	se bound				•
Design requirement parameters							
Initial value		0		Final value			1
Step time		0	seconds				
_							
Rise time		1	seconds	% Rise			90
Settling time		3	seconds	% Settling			2
% Overshoot		30		% Undershoot			2
Help					ок	Can	icel

شكل 23 _ پارامتر هاى SISOtool



شکل ۲۴ _ نتایج نمودار های حاصل از SISOtool



شکل ۲۵ _ Root Locus حاصل از SISOtool

نقاط برخورد دو خط مشکی همان نقاط مطلوب برای طراحی کنترل کننده ما میباشند.

تحلیل کلی پاسخ ها

سيستم بدون كنترل كننده

- پایداری :سیستم بدون کنترلکننده پایدار است زیرا همه قطبها (مکان هندسی ریشه ها) در ناحیه چپ صفحه s قرار دارند.
 - مشخصات پاسخ پله:
 - o **زمان نشست** 10 ثانیه
 - o **زمان صعود** 4.56 ثانیه
 - o **بالازدگی** ندارد

این سیستم دارای زمان نشست طولانی، پاسخ کند و بدون بالازدگی است.

K = 1.2 كنترل كننده با

- پایداری :سیستم با گین ۱٫۲ پایدار است و نسبت به سیستم بدون کنترل کننده، پاسخ سریعتری دارد.
 - مشخصات ياسخ يله:
 - a. **زمان نشست** 8.73 ثانیه
 - b. **زمان صعود** 3.68 ثانیه
 - c. **بالازدگی** ندارد

مشخصات:

در حالت کلی تمام این کنترل کننده باعث بهبود در زمان نشست و زمان صعود شده اند و تاثیری در میزان بالازدگی ندارد.

کنترل کننده پیشفاز (Lead Controller)

• مشخصات یاسخ یله:

- پیشفاز اول:
- o **زمان نشست** 3.65 ثانیه
 - o **زمان صعود** 0.4 ثانیه
 - و بالازدگی %23.34
 - 🌣 پیشفاز دوم:
 - o **زمان نشست** 3.7 ثانیه

- o **زمان صعود** 0.4 ثانیه
 - o بالازدگى %23.04

💸 پیشفاز سوم:

- o **زمان نشست** 3.61 ثانیه
 - o **زمان صعود** 0.4 ثانیه
 - o بالازدگى %23.64

🌣 پیشفاز با روش هندسی:

- o **زمان نشست** 2.38 ثانیه
 - o **زمان صعود** 0.4 ثانیه
 - o بالازدگى %24.03
- پایداری :سیستم با کنترل کننده های پیشفاز پایدار است و نسبت به سیستم بدون کنترل کننده، پاسخ سریع تری دارد.

مشخصات:

در حالت کلی تمام این کنترل کننده ها باعث بهبود در زمان نشست و زمان صعود شده اند. دقت شود در تقریبا تمام حالات زمان نشست و بالازدگی تقریبا به یک مقدار میباشند و این تفاوت به دلیل تقریبی بودن یکسری از پارامترهای محاسبه شده میباشد اما بهترین پاسخ بدست امده که باعث شده زمان نشست کمی کمتر و بالازدگی آن کمی بیشتر از حالات دیگر شود حالت هندسی میباشد که پاسخ نسبتا سریع تر و مطلوب تری را به ما می دهد.

کنترل کننده پسفاز (Lag Controller)

• مشخصات پاسخ پله:

🖈 پسفاز برای گین 1.2

- o **زمان نشست** 5.27 ثانیه
- o **زمان صعود** 2.41 ثانیه
 - 0.55% بالازدگی \circ

❖ پسفاز اول:

- o **زمان نشست** 2.91 ثانیه
 - نانیه 0.4 و زمان معود 0.4
 - o بالازدگى %26.23

🌣 پسفاز دوم:

o **زمان نشست** 2.9 ثانیه

- o **زمان صعود** 0.4 ثانیه
 - o بالازدگى %25.89

- o **زمان نشست** 2.92 ثانیه
- o **زمان صعود** 0.39 ثانیه
 - 0 بالازدگى %26.53

💠 پسفاز برای روش هندسی:

- o **زمان نشست** 2.93 ثانیه
 - o **زمان صعود** 0.39 ثانیه
 - o بالازدگى %26.91
- پایداری :سیستم با کنترل کننده پسفاز نیز پایدار است و پاسخ آن نسبت به سیستم بدون کنترل کننده بهبود یافته است.

• مشخصات:

با اعمال این کنترل کننده ها به سیستمی که برای آن کنترل کننده پیش فاز طراحی شده سعی در کاهش خطای حالت دائم این سیستم ها داشتیم اما انتظار می رود، با اعمال این کنترل کننده ها به سیستم، مکان هندسی ریشه جابه جا شود که همین اتفاق میوفتد حال برای انکه دوباره سیستم در محل قبلی خود قرار گیرد میتوانیم پس از بررسی مجدد سیستم، کنترل کننده پیش فاز جدیدی طراحی کنیم.

در شکل ۲۱ مشاهده میشود تمام پس فاز ها خطای حالت دائم به ورودی شیب را صفر کرده اند به جز پس فاز برای گین ۱٫۲ که به این دلیل نامناسب است چون گین ۱٫۲ از اول پاسخ پله مناسبی به ما نداد.

کنترل کننده PID (روش زیگلر-نیکولز)

از انجایی که طراحی با این روش دقیق نیست و برای تقریبی از سیستم نوشته شده پس انتظار میرود پاسخ دقیقی را در واقعیت به ما ندهد.

• مشخصات پاسخ پله:

- زمان نشست 1.02 ثانیه
 - o **زمان صعود** 0.1 ثانیه
 - بالازدگی %12.81

سیستم با استفاده از کنترل کننده PID توانسته است زمان نشست و زمان صعود را کاهش دهد اما با بالازدگی بیشتری مواجه شده است. دقت شود که پاسخ سیستم بهتر از حد انتظار ما (۳ ثانیه) است .

کنترل کننده PI (روش زیگلر-نیکولز)

• مشخصات پاسخ:

- o **زمان نشست** 2.27 ثانیه
 - نانیه
 - بالازدگي %57.55

با استفاده از کنترل کننده PI ، زمان نشست و زمان صعود بهبود یافته و بالازدگی نیز در حدود قابل قبولی قرار دارد.

کنترل کننده P (روش زیگلر-نیکولز)

- مشخصات پاسخ پله:
- o **زمان نشست** 1.66 ثانیه
 - o **زمان صعود** 0.1 ثانیه
 - بالازدگي %55.07%بالازدگي %65.07%

این کنترل کننده توانسته است زمان نشست و زمان صعود را بهبود بخشد و بالازدگی را نیز کنترل کند.

نتيجهگيري

- بهترین عملکرد: کنترل کننده PID (روش زیگلر-نیکولز) از نظر زمان نشست و زمان صعود عملکرد بهتری دارد، اما با بالازدگی بیشتری همراه است.
- عملکرد مناسب: کنترل کننده PI و تناسبی (روش زیگلر-نیکولز) از نظر زمان نشست و زمان صعود بهبود یافته و بالازدگی قابل قبولی دارند. درمیان سایر کنترل کننده ها پیش فاز با روش هندسی مطلوب تر است.
- پیشفاز و پسفاز :کنترل کنندههای پیشفاز باعث بهبود سریعتر زمان نشست و زمان صعود میشوند، اما با بالازدگی بیشتری همراه هستند. کنترل کنندههای پسفاز زمان نشست و زمان صعود طولانی تری دارند اما بالازدگی کمتری دارند همچنین باعث بهبود خطای حالت دائم به ورودی شیب میشوند. در صورتی کنترل کننده های پس فاز بهتر هستند که، یک کنترل کننده پیش فاز دیگر نیز طراحی شود تا مکان هندسی ریشه ها دوباره روی نقاط مطلوب قرار گیرد.
 - بدون کنترلکننده :سیستم پایدار است ولی پاسخ کند دارد.

این تحلیلها نشان میدهند که انتخاب کنترل کننده مناسب بستگی به اولویتهای سیستم دارد. اگر زمان نشست و زمان صعود مهمتر است، کنترل کنندههای PID و PI مناسب هستند. اگر بالازدگی و خطای حالت دائم کمتر اهمیت دارد، کنترل کنندههای پسفاز (پس از طراحی پیش فاز ها) بهتر عمل می کنند.

```
%% Define the numerator and denominator of the transfer function
num = [2 1]; % Numerator coefficients of '2s+1'
den = conv([1 0], conv([1 1], [1 2])); % Denominator coefficients of
s(s+1)(s+2)'
% Create the transfer function model
sys = tf(num, den)
% Generate and plot the root locus
figure;
rlocus(sys);
hold on
points = [-1.33+3.47], -1.33-3.47]; % Points to mark on the root locus plot
plot(points, '*'); % Plotting points on the root locus plot
title('Root Locus of G(s) = (2s+1) / (s(s+1)(s+2))');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Display poles and zeros of the system
pole(sys)
zero(sys)
% Calculate damping ratio (zetha) and natural frequency (Wn)
Mp = log(0.3); % Desired percentage overshoot in logarithm form
zetha = -Mp/sqrt(Mp^2 + pi^2) % Damping ratio calculation
tp = 3; % Desired settling time
Wn = 4/(tp*zetha) % Natural frequency calculation
beta = acos(zetha); % Angle beta calculation
betaa = rad2deg(beta) % Convert angle beta to degrees
% Calculate gains for different compensators
s = -1.33 + 3.47j; % Point in the complex plane for compensator calculations
num0 = (2*s+1); % Numerator of the original transfer function at point s
den0 = s*(s+1)*(s+2); % Denominator of the original transfer function at point
% Calculating gains K for different compensators
num A = num0 * (s+2);
den_A = den0 * (s+2.13);
K_A = abs(den_A / num_A)
num_B = num0 * (s+1.5);
den_B = den0 * (s+1.62);
K_B = abs(den_B / num_B)
```

```
num C = num0 * (s+2.5);
den C = den0 * (s+2.64);
K_C = abs(den_C / num_C)
num_D = num0 * (s+3.63);
den_D = den0 * (s+3.81);
K_D = abs(den_D / num_D)
% Create open-loop systems with compensators
sys_0 = tf(1.2*num, den) \% Open-loop system with initial gain adjustment
sys A = tf(K A*[2 1], [1 3.13 2.13 0]) % Open-loop system with compensator A
sys_B = tf(K_B*[2 4 1.5], [1 4.62 6.86 3.24 0]) % Open-loop system with
compensator B
sys C = tf(K C*[2 6 2.5], [1 5.64 9.92 5.28 0]) % Open-loop system with
compensator C
sys_D = tf(K_D*[2 8.26 3.63], [1 6.81 13.43 7.62 0]) % Open-loop system with
compensator D
% Create closed-loop systems with unit feedback
cl_sys_0 = feedback(sys_0, 1); % Closed-loop system with initial gain
adjustment
cl_sys_A = feedback(sys_A, 1); % Closed-loop system with compensator A
cl_sys_B = feedback(sys_B, 1); % Closed-loop system with compensator B
cl_sys_C = feedback(sys_C, 1); % Closed-loop system with compensator C
cl_sys_D = feedback(sys_D, 1); % Closed-loop system with compensator D
cl_sys = feedback(sys, 1);% Closed-loop Main system
% Time vector for simulation
t = 0:0.01:10;
%% Step responses
[y_0, t_0] = step(cl_sys_0, t); % Step response of closed-loop system with
initial gain adjustment
[y_A, t_A] = step(cl_sys_A, t); % Step response of closed-loop system with
compensator A
[y_B, t_B] = step(cl_sys_B, t); % Step response of closed-loop system with
compensator B
[y_C, t_C] = step(cl_sys_C, t); % Step response of closed-loop system with
compensator C
[y_D, t_D] = step(cl_sys_D, t); % Step response of closed-loop system with
[y, t] = step(cl_sys, t);% Step response of closed-loop Main system
% Display step information
info_0 = stepinfo(cl_sys_0, 'SettlingTimeThreshold', 0.02) % Step information
of closed-loop system with initial gain adjustment
```

```
info_A = stepinfo(cl_sys_A) % Step information of closed-loop system with
compensator A
info B = stepinfo(cl sys B) % Step information of closed-loop system with
compensator B
info C = stepinfo(cl sys C) % Step information of closed-loop system with
compensator C
info_D = stepinfo(cl_sys_D) % Step information of closed-loop system with
compensator D
info = stepinfo(cl sys) % Step information of closed-loop Main system
% Display step response plots
figure;
subplot(6,1,1);
plot(t_0, y_0);
grid on;
title('Step Response of Closed-Loop sys 0');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info 0.RiseTime, info 0.SettlingTime, info 0.Overshoot));
subplot(6,1,2);
plot(t_A, y_A);
grid on;
title('Step Response of Closed-Loop sys A');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info A.RiseTime, info A.SettlingTime, info A.Overshoot));
subplot(6,1,3);
plot(t_B, y_B);
grid on;
title('Step Response of Closed-Loop sys_B');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_B.RiseTime, info_B.SettlingTime, info_B.Overshoot));
subplot(6,1,4);
plot(t_C, y_C);
grid on;
title('Step Response of Closed-Loop sys_C');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_C.RiseTime, info_C.SettlingTime, info_C.Overshoot));
```

```
subplot(6,1,5);
plot(t D, y D);
grid on;
title('Step Response of Closed-Loop sys_D');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_D.RiseTime, info_D.SettlingTime, info_D.Overshoot));
subplot(6,1,6);
plot(t, y);
grid on;
title('Step Response of Closed-Loop Main sys');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info.RiseTime, info.SettlingTime, info.Overshoot));
%% Ramp input response
% Define the ramp input signal
ramp input = t; % Ramp input signal over time
% Simulate ramp response for closed-loop sys_0
[y_r0, t_r0] = lsim(cl_sys_0, ramp_input, t); % Simulate response using lsim
figure;
subplot(6,1,1);
plot(t_r0, y_r0, 'b', t_r0, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
title('Ramp Response of Closed-Loop sys 0');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys_A
[y_rA, t_rA] = lsim(cl_sys_A, ramp_input, t); % Simulate response using lsim
subplot(6,1,2);
plot(t_rA, y_rA, 'b', t_rA, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
title('Ramp Response of Closed-Loop sys_A');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys_B
[y_rB, t_rB] = lsim(cl_sys_B, ramp_input, t); % Simulate response using lsim
```

```
subplot(6,1,3);
plot(t rB, y rB, 'b', t rB, ramp input, 'r--'); % Plot system response and
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys B');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys_C
[y_rC, t_rC] = lsim(cl_sys_C, ramp_input, t); % Simulate response using lsim
subplot(6,1,4);
plot(t_rC, y_rC, 'b', t_rC, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys C');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop sys_D
[y_rD, t_rD] = lsim(cl_sys_D, ramp_input, t); % Simulate response using lsim
subplot(6,1,5);
plot(t_rD, y_rD, 'b', t_rD, ramp_input, 'r--'); % Plot system response and
ramp input
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop sys_D');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Simulate ramp response for closed-loop Main sys
[y_r, t_r] = lsim(cl_sys, ramp_input, t); % Simulate response using lsim
subplot(6,1,6);
plot(t_r, y_r, 'b', t_r, ramp_input, 'r--'); % Plot system response and ramp
legend('With Controller', 'Ramp Input');
grid on;
title('Ramp Response of Closed-Loop Main sys');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Define the transfer function G(s) = 1 / (1 + 1.34s)
numerator = 1; % Numerator of the transfer function
denominator = [1 1.34]; % Denominator of the transfer function
G = tf(numerator, denominator); % Create transfer function G(s)
% Define the delay
```

```
delay = 0.2; % Time delay in seconds
% Pade approximation for the delay
[num_delay, den_delay] = pade(delay, 1); % 1st-order Pade approximation
Delay approx = tf(num delay, den delay); % Create transfer function for delay
approximation
% Combine transfer function with delay approximation
G_with_delay = series(G, Delay_approx); % Series combination of G(s) and delay
% Define controllers
% P Controller
Kp1 = 1.34 / 0.2; % Proportional gain for P controller
Gc1 = Kp1; % Transfer function of P controller
% PI Controller
Kp2 = 0.9 * Kp1; % Proportional gain for PI controller
Ti2 = 0.2 / 0.3; % Integral time constant for PI controller
Gc2 = Kp2 * (1 + tf(1, [Ti2 0])); % Transfer function of PI controller
% PID Controller
Kp3 = 1.2 * Kp1; % Proportional gain for PID controller
Ti3 = 2 * 0.2; % Integral time constant for PID controller
Td3 = 0.5 * 0.2; % Derivative time constant for PID controller
Gc3 = Kp3 * (1 + tf([Td3 0], 1) + tf(1, [Ti3 0])); % Transfer function of PID
controller
% Closed-loop transfer functions
T1 = feedback(Gc1 * G with delay, 1); % Closed-loop transfer function with P
controller
T2 = feedback(Gc2 * G_with_delay, 1); % Closed-loop transfer function with PI
controller
T3 = feedback(Gc3 * G with delay, 1); % Closed-loop transfer function with PID
controller
% Time vector for simulation
t = 0:0.01:10; % Time vector for simulation, from 0 to 10 seconds with 0.01
second steps
% Step responses
[y1, t1] = step(T1, t); % Step response of system with P controller
[y2, t2] = step(T2, t); % Step response of system with PI controller
[y3, t3] = step(T3, t); % Step response of system with PID controller
% Display step information (2% settling time criteria)
info_T1 = stepinfo(T1, 'SettlingTimeThreshold', 0.02) % Step response
information for P controller
```

```
info_T2 = stepinfo(T2, 'SettlingTimeThreshold', 0.02) % Step response
information for PI controller
info T3 = stepinfo(T3, 'SettlingTimeThreshold', 0.02) % Step response
information for PID controller
% Plot the step responses
figure;
subplot(3,1,1);
plot(t1, y1); % Plot step response of P controller
grid on;
title('Step Response with P Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info T1.RiseTime, info T1.SettlingTime, info T1.Overshoot));
subplot(3,1,2);
plot(t2, y2); % Plot step response of PI controller
grid on;
title('Step Response with PI Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_T2.RiseTime, info_T2.SettlingTime, info_T2.Overshoot));
subplot(3,1,3);
plot(t3, y3); % Plot step response of PID controller
grid on;
title('Step Response with PID Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_T3.RiseTime, info_T3.SettlingTime, info_T3.Overshoot));
%% Confirming the steady-state value
steady_state_value = dcgain(G);
disp(['Steady-state value of the plant G: ', num2str(steady_state_value)]);
%% Confirming the steady-state value of the controllers
steady_state_value1 = dcgain(feedback(Gc1 * G_with_delay, 1));
disp(['Steady-state value with P Controller: ',
num2str(steady_state_value1)]);
steady_state_value2 = dcgain(feedback(Gc2 * G_with_delay, 1));
disp(['Steady-state value with PI Controller: ',
num2str(steady_state_value2)]);
steady_state_value3 = dcgain(feedback(Gc3 * G_with_delay, 1));
```

```
disp(['Steady-state value with PID Controller: ',
num2str(steady state value3)]);
%% Ramp input response
ramp input = t; % Ramp input signal over time 't'
% Ramp response for T1 (P Controller)
[y_r1, t_r1] = lsim(T1, ramp_input, t); % Simulate ramp response with T1 (P
Controller)
[y_r1_sys, t_r1_sys] = lsim(G_with_delay, ramp_input, t); % Simulate ramp
response without controller
figure;
subplot(3,1,1);
plot(t_r1, y_r1, 'b', t_r1_sys, ramp_input, 'r--'); % Plot ramp response for
legend('With P Controller', 'Without Controller');
grid on;
title('Ramp Response with P Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for T2 (PI Controller)
[y_r2, t_r2] = lsim(T2, ramp_input, t); % Simulate ramp response with T2 (PI
Controller)
[y_r2_sys, t_r2_sys] = lsim(G_with_delay, ramp_input, t); % Simulate ramp
response without controller
subplot(3,1,2);
plot(t_r2, y_r2, 'b', t_r2_sys, ramp_input, 'r--'); % Plot ramp response for
legend('With PI Controller', 'Without Controller');
grid on;
title('Ramp Response with PI Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for T3 (PID Controller)
[y_r3, t_r3] = lsim(T3, ramp_input, t); % Simulate ramp response with T3 (PID
Controller)
[y_r3_sys, t_r3_sys] = lsim(G_with_delay, ramp_input, t); % Simulate ramp
response without controller
subplot(3,1,3);
plot(t_r3, y_r3, 'b', t_r3_sys, ramp_input, 'r--'); % Plot ramp response for
legend('With PID Controller', 'Without Controller');
grid on;
title('Ramp Response with PID Controller');
xlabel('Time (seconds)');
ylabel('Amplitude');
```

```
%% Root locus plots
% Root locus plot for sys 0 (Controller with K = 1.2)
figure;
rlocus(sys_0);
hold on
points = [-1.33+3.47j, -1.33-3.47j]; % Points to mark on the root locus plot
plot(points, '*');
title('Root Locus of sys K = 1.2');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plots for systems with phase-lead compensators
% Root locus plot for sys_A
figure;
rlocus(sys_A);
hold on
plot(points, '*');
title('Root Locus of sys A');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plot for sys_B
figure;
rlocus(sys_B);
hold on
plot(points, '*');
title('Root Locus of sys B');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plot for sys_C
figure;
rlocus(sys_C);
hold on
plot(points, '*');
title('Root Locus of sys C');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
```

```
% Root locus plot for sys_D
figure;
rlocus(sys_D);
hold on
plot(points, '*');
title('Root Locus of sys D');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
%% Add phase-lag controllers and their root locus plots
% Define systems with added phase-lag controllers
sys 00 = series(tf([1 0.1333], [1 0.0024]), sys 0);
sys_AA = series(tf([1 0.1333], [1 0.0119]), sys_A);
sys_BB = series(tf([1 0.1333], [1 0.0117]), sys_B);
sys_CC = series(tf([1 0.1333], [1 0.0121]), sys_C);
sys_DD = series(tf([1 0.1333], [1 0.0123]), sys_D);
% Root locus plot for sys_00
figure;
rlocus(sys_00);
hold on
plot(points, '*');
title('Root Locus of sys K = 1.2 with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plot for sys AA
figure;
rlocus(sys_AA);
hold on
plot(points, '*');
title('Root Locus of sys A with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plot for sys_BB
figure;
rlocus(sys_BB);
hold on
plot(points, '*');
title('Root Locus of sys B with Phase-Lead Controller');
```

```
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plot for sys CC
figure;
rlocus(sys_CC);
hold on
plot(points, '*');
title('Root Locus of sys C with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Root locus plot for sys DD
figure;
rlocus(sys_DD);
hold on
plot(points, '*');
title('Root Locus of sys D with Phase-Lag Controller');
xlabel('Real Axis');
ylabel('Imaginary Axis');
grid on;
hold off
% Create closed-loop systems with unit feedback
cl sys 00 = feedback(sys 00, 1); % Closed-loop system with initial gain
adjustment
cl_sys_AA = feedback(sys_AA, 1); % Closed-loop system with compensator A
cl_sys_BB = feedback(sys_BB, 1); % Closed-loop system with compensator B
cl_sys_CC = feedback(sys_CC, 1); % Closed-loop system with compensator C
cl_sys_DD = feedback(sys_DD, 1); % Closed-loop system with compensator D
% Time vector for simulation
t = 0:0.01:10;
% Compute step responses
[y_00, t_00] = step(cl_sys_00, t);
[y_AA, t_AA] = step(cl_sys_AA, t);
[y_BB, t_BB] = step(cl_sys_BB, t);
[y_CC, t_CC] = step(cl_sys_CC, t);
[y_DD, t_DD] = step(cl_sys_DD, t);
% Compute step response characteristics
info_00 = stepinfo(y_00, t_00);
info_AA = stepinfo(y_AA, t_AA);
```

```
info_BB = stepinfo(y_BB, t_BB);
info CC = stepinfo(y CC, t CC);
info_DD = stepinfo(y_DD, t_DD);
% Plot step responses
figure;
subplot(5,1,1);
plot(t_00, y_00);
grid on;
title('Step Response with Lag Controller sys_00');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_00.RiseTime, info_00.SettlingTime, info_00.Overshoot));
subplot(5,1,2);
plot(t_AA, y_AA);
grid on;
title('Step Response with Lag Controller sys AA');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_AA.RiseTime, info_AA.SettlingTime, info_AA.Overshoot));
subplot(5,1,3);
plot(t_BB, y_BB);
grid on;
title('Step Response with Lag Controller sys_BB');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info BB.RiseTime, info BB.SettlingTime, info BB.Overshoot));
subplot(5,1,4);
plot(t_CC, y_CC);
grid on;
title('Step Response with Lag Controller sys_CC');
xlabel('Time (seconds)');
ylabel('Amplitude');
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info_CC.RiseTime, info_CC.SettlingTime, info_CC.Overshoot));
subplot(5,1,5);
plot(t_DD, y_DD);
grid on;
title('Step Response with Lag Controller sys_DD');
xlabel('Time (seconds)');
ylabel('Amplitude');
```

```
legend(sprintf('RiseTime: %.2f, SettlingTime: %.2f, Overshoot: %.2f%%',
info DD.RiseTime, info DD.SettlingTime, info DD.Overshoot));
% Time vector for simulation
t = 0:0.01:10;
ramp input = t; % Ramp input signal over time 't'
% Ramp response for cl_sys_00 (Lag Controller)
[y_r_00, t_r_00] = lsim(cl_sys_00, ramp_input, t);
[y_r_00_sys, t_r_00_sys] = lsim(sys_0, ramp_input, t);
figure;
subplot(5,1,1);
plot(t_r_00, y_r_00, 'b', t_r_00_sys, ramp_input, 'r--'); % Plot ramp response
for cl sys 00
legend('With Lag Controller 00', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller 00');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_AA (Lag Controller)
[y_r_AA, t_r_AA] = lsim(cl_sys_AA, ramp_input, t);
[y_r_AA_sys, t_r_AA_sys] = lsim(sys_A, ramp_input, t);
subplot(5,1,2);
plot(t_r_AA, y_r_AA, 'b', t_r_AA_sys, ramp_input, 'r--'); % Plot ramp response
for cl sys AA
legend('With Lag Controller AA', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller AA');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_BB (Lag Controller)
[y_r_BB, t_r_BB] = lsim(cl_sys_BB, ramp_input, t);
[y_r_BB_sys, t_r_BB_sys] = lsim(sys_B, ramp_input, t);
subplot(5,1,3);
plot(t_r_BB, y_r_BB, 'b', t_r_BB_sys, ramp_input, 'r--'); % Plot ramp response
for cl sys BB
legend('With Lag Controller BB', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller BB');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_CC (Lag Controller)
[y_r_CC, t_r_CC] = lsim(cl_sys_CC, ramp_input, t);
[y_r_CC_sys, t_r_CC_sys] = lsim(sys_C, ramp_input, t);
subplot(5,1,4);
```

```
plot(t_r_CC, y_r_CC, 'b', t_r_CC_sys, ramp_input, 'r--'); % Plot ramp response
for cl sys CC
legend('With Lag Controller CC', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller CC');
xlabel('Time (seconds)');
ylabel('Amplitude');
% Ramp response for cl_sys_DD (Lag Controller)
[y_r_DD, t_r_DD] = lsim(cl_sys_DD, ramp_input, t);
[y_r_DD_sys, t_r_DD_sys] = lsim(sys_D, ramp_input, t);
subplot(5,1,5);
plot(t_r_DD, y_r_DD, 'b', t_r_DD_sys, ramp_input, 'r--'); % Plot ramp response
for cl_sys_DD
legend('With Lag Controller DD', 'Without Controller');
grid on;
title('Ramp Response with Lag Controller DD');
xlabel('Time (seconds)');
ylabel('Amplitude');
```