Rizzetta & Company

Bobcat Trail
Community Development District

Board of Supervisors' Meeting
May 6, 2025

District Office:
9530 Marketplace Road, Suite 206
Fort Myers, Florida 33912
(239) 936-0913

www.bobcatcdd.com

BOBCAT TRAIL
COMMUNITY DEVELOPMENT DISTRICT

Bobcat Trail Community Center, 1352 Bobcat Trail Blvd., North Port, FL 34288

www.bobcatcdd.com

Board of Supervisors	Steven Ball	Chairperson
	Jeffrey Brall	Vice Chairperson
	Paul Fisher	Assistant Secretary
	Michael SanAntonio	Assistant Secretary
	Robert Branch	Assistant Secretary
District Manager	Belinda Blandon	Rizzetta & Company, Inc.
District Counsel	David Jackson	Persson, Cohen, Mooney, Fernandez & Jackson, P.A.
District Engineers	Robert Dvorak	BDI Engineers

All cellular phones must be placed on mute while in the meeting room.

The Audience Comment portion of the agenda is where individuals may make comments on matters that concern the District. Individuals are limited to a total of three (3) minutes to make comments during this time.

Pursuant to provisions of the Americans with Disabilities Act, any person requiring special accommodations to participate in this meeting/hearing/workshop is asked to advise the District Office at least forty-eight (48) hours before the meeting/hearing/workshop by contacting the District Manager at (239) 936-0913. If you are hearing or speech impaired, please contact the Florida Relay Service by dialing 7-1-1, or 1-800-955-8771 (TTY) 1-800-955-8770 (Voice), who can aid you in contacting the District Office.

A person who decides to appeal any decision made at the meeting/hearing/workshop with respect to any matter considered at the meeting/hearing/workshop is advised that person will need a record of the proceedings and that accordingly, the person may need to ensure that a verbatim record of the proceedings is made including the testimony and evidence upon which the appeal is to be based.

BOBCAT TRAIL COMMUNITY DEVELOPMENT DISTRICT
District Office · Ft. Myers, Florida · (239) 936-0913
Mailing Address · 3434 Colwell Avenue, Suite 200, Tampa, Florida 33614

www.bobcatcdd.com

April 29, 2025

Board of Supervisors
Bobcat Trail Community
Development District

REVISED AGENDA

Dear Board Members:

The regular meeting of the Board of Supervisors of Bobcat Trail Community Development District will be held on **Tuesday, May 06, 2025, at 3:00 p.m.** at the Bobcat Trail Community Center located at 1352 Bobcat Trail Blvd., North Port, Florida 34288. The following is the revised agenda for this meeting:

1. **CALL TO ORDER/ROLL CALL**
2. **PLEDGE OF ALLEGIANCE**
3. **APPROVAL OF AGENDA**
4. **PUBLIC COMMENTS – AGENDA ITEMS ONLY**
5. **BUSINESS ADMINISTRATION**
   - A. Consideration of the Minutes of the Board of Supervisors' Meeting Held on April 01, 2025 ..... Tab 1
   - B. Ratification of the Operations and Maintenance Expenditures for the Month of March 2025 ..... Tab 2

6. **OLD BUSINESS**
   - None

7. **NEW BUSINESS**
   - A. Resident Concerns
   - B. Consideration of City Wide Facility Solutions Proposal for Tennis Court Resurfacing..... Tab 3
   - C. Consideration of Pond Bank Repair at 3408 Royal Palm Drive
   - D. Acceptance of Revised Reserve Study Report ..... Tab 4
   - E. Maintenance Position

8. **CONSENT ITEMS**
   - A. Acceptance of Committee Meeting Minutes ..... Tab 5
     1. Landscape Committee Meeting held on February 18, 2025
     2. Landscape Committee Meeting Held on March 18, 2025
     3. Infrastructure-Asset Committee Meeting Held on April 17, 2025

9. **STAFF REPORTS**
   - A. Field Manager
   - B. District Engineer
   - C. District Counsel
   - D. District Manager ..... Tab 6
     1. Presentation of Registered Voter Count ..... Tab 7

10. OTHER REPORTS
- A. Infrastructure/Asset Management Committee (Board Workshop)
- B. Landscape Committee
- C. Newsletter Supervisor
- D. Finance Supervisor
- E. Lakes and Roads Supervisor
  - i. Solitude Waterway Inspection Report
  - ii. Solitude Monitoring Reports
- F. Maintenance Supervisor
- G. Facilities Supervisor
- H. HOA Updates
- I. Commercial Properties

11. PUBLIC COMMENTS
12. SUPERVISOR REQUESTS
13. ADJOURNMENT

We look forward to seeing you at the meeting. In the meantime, if you have any questions, please do not hesitate to contact me at (239) 936-0913.

Very truly yours,
Belinda Blandon
Belinda Blandon
District Manager

cc:David Jackson: Persson, Cohen, Mooney, Fernandez & Jackson, P.A.

Tab 1

MINUTES OF MEETING

Each person who decides to appeal any decision made by the Board with respect to any matter considered at the meeting is advised that the person may need to ensure that a verbatim record of the proceedings is made, including the testimony and evidence upon which such appeal is to be based.

BOBCAT TRAIL
COMMUNITY DEVELOPMENT DISTRICT

The regular meeting of the Board of Supervisors of the Bobcat Trail Community Development District was held on **Tuesday, April 01, 2025, at 3:00 p.m.** at the Bobcat Trail Community Center, 1352 Bobcat Trail Blvd., North Port, FL 34288.

Present and constituting a quorum:

Steven Ball	**Board Supervisor, Chairman**
Jeffrey Brall	**Board Supervisor, Vice Chairman**
Paul Fisher	**Board Supervisor, Assistant Secretary**
Michael SanAntonio	**Board Supervisor, Assistant Secretary**
Robert Branch	**Board Supervisor, Assistant Secretary**

Also present were:

Belinda Blandon	**District Manager, Rizzetta & Company, Inc.**
David Jackson	**District Counsel, Persson, Cohen, Mooney, Fernandez & Jackson, P.A.**
Tyler Gibben	**Custom Reserves (via Teams)**
Audience	

FIRST ORDER OF BUSINESS **Call to Order/Roll Call**

Ms. Blandon called the meeting to order and read roll call.

SECOND ORDER OF BUSINESS **Pledge of Allegiance**

The Board, Staff, and Audience recited the Pledge of Allegiance.

THIRD ORDER OF BUSINESS **Approval of Agenda**

Ms. Blandon presented the agenda and asked the Board if there were any additions or changes to the agenda as presented. No modifications were requested. The review of the Reserve Study was moved as the first business item to be discussed.

On a Motion by Mr. Brall, seconded by Mr. SanAntonio, with all in favor, the Board Approved the Agenda for the April 01, 2025 Board of Supervisors Meeting for the Bobcat Trail Community Development District.

DRAFT

FOURTH ORDER OF BUSINESS **Public Comments – Agenda Items Only**

Ms. Blandon opened the floor for public comment for agenda items only. There were no additional public comments.

FIFTH ORDER OF BUSINESS **Review of Draft Reserve Study Report and Discussion with Custom Reserves**

The Board discussed the reserve study, with Mr. Tyler Gidden from Custom Reserves attending via Teams. Mr. Gidden was informed that certain areas missing from the study needed to be added and that Phases 1 and 2 of the paving projects had been completed, requiring an update to the report. Mr. Ball agreed to send the paving information to Ms. Blandon, who would then provide it to Mr. Gidden.

SIXTH ORDER OF BUSINESS **Consideration of the Minutes of the Board of Supervisors' Meeting held on March 04, 2025**

Ms. Blandon presented the Minutes of the Board of Supervisors meeting held on March 04, 2025, and asked if there were any questions, comments, and/or changes. There were none.

On a Motion by Mr. SanAntonio, seconded by Mr. Brall, with all in favor, the Board Approved the Minutes of the Board of Supervisors Meeting held on March 04, 2025, for the Bobcat Trail Community Development District.

SEVENTH ORDER OF BUSINESS **Consideration of the Minutes of the Board Workshops held on March 20, 2025**

Ms. Blandon presented the Minutes of the Workshop held on March 20, 2025, and asked if there were any questions, comments, and/or changes. There were none.

On a Motion by Mr. Brall, seconded by Mr. Branch, with all in favor, the Board approved the Minutes of the Board of Supervisors Workshops held on March 20, 2025, for the Bobcat Trail Community Development District.

EIGHTH ORDER OF BUSINESS **Ratification of Operations and Maintenance Expenditures for the Month of February 2025**

Ms. Blandon advised that operations and maintenance expenditures for the period of February 1-28, 2025 totaled $53,988.82 and asked if there were any questions, comments, and/or changes. There were none.

DRAFT

On a Motion by Mr. Brall, seconded by Mr. SanAntonio, with all in favor, the Board Ratified the Operations and Maintenance Expenditures for the Month of February 2025, totaling $53,988.82, for the Bobcat Trail Community Development District.

NINTH ORDER OF BUSINESS **Community Center Audio System**

Ms. Blandon introduced the topic of the Community Center Audio System. Mr. SanAntonio provided an overview of the proposals he obtained, including a detailed review of a proposal from Pro Audio Services totaling $19,694.99. District staff opened the floor for public comments; none were received. Following discussion and a vote, the Board approved the proposal, contingent upon the preparation of an addendum by District Counsel.

On a Motion by Mr. SanAntonio, seconded by Mr. Brall, with all in favor, the Board Approved the Proposal from Pro Audio Services totaling $19,694.99, with Subject of Preparation of an Addendum by the District Counsel, for the Bobcat Trail Community Development District.

TENTH ORDER OF BUSINESS **Resident Concerns**

Mr. Branch informed the Board that a resident had contacted him with a request to install an AED device at the pool. The Board discussed the matter, including concerns about identifying a suitable location for the device. After consideration, the Board agreed to conduct further research before making a decision.

ELEVENTH ORDER OF BUSINESS **Administrative Staff Probation Review**

Mr. SanAntonio discussed the 90-day probation review for the Administrative Staff Members and recommended proceeding with permanent placement along with a $0.50 wage increase. After discussion and a vote, the Board approved the recommendation, with the raise to take effect on April 01, 2025.

On a Motion by Mr. SanAntonio, seconded by Mr. Brall, with all in favor, the Board Approved the Administrative Staff Probation review with permanent placement along with a $0.50 wage increase, for the Bobcat Trail Community Development District.

TWELFTH ORDER OF BUSINESS **Staff Reports**

A. Field Manager

Mr. Ball addressed a note in the Aquatics Report regarding an individual using one of the lakes as a landfill by disposing of palm fronds and sandbags. He informed the Board that he would follow up with the resident to address this matter.

B. District Engineer

Mr. Ball informed the Board that Mr. Dvorak (District Engineer) is coordinating with the South Florida Water Management District (SFWMD) regarding the addition of handicapped parking spots. He is also continuing to assess the stormwater

capacity requirements. Regarding this an update is expected by the next workshop.

C. District Counsel

Mr. Jackson provided an update on the Cloud 10 Litigation. He reported that the Case Management Conference is scheduled for June 27, 2025, the Foreclosure hearing is set for April 14, 2025, and the Motion for Summary Judgment is scheduled for May 29, 2025. He advised the Board that he will continue to monitor the case and provide updates as needed.

D. District Manager

Ms. Blandon advised that the next Board of Supervisors meeting is scheduled for Tuesday, May 06, 2025, at 3:00 p.m.

She informed the Board that Rizzetta & Company has waived the email transfer fees. She also discussed potential dates for the upcoming budget workshop. After consideration, the Board agreed to schedule the workshop for May 06, 2025, at 1:00 p.m. District staff was directed to run a public notice for the workshop.

THIRTEENTH ORDER OF BUSINESS Other Reports

A. Infrastructure/Asset Management Committee (Board Workshop)

Mr. Ball provided an update on the most recent workshop and addressed the issue of overnight parking at the amenity center. He informed the Board that parking permits are now being issued to manage the situation.

B. Landscape Committee

Mr. Brall reported that it has been a busy few months working with Artistree. He noted that preparations are underway to clean the bullnose areas on the commercial side. Landscaping lighting has been added or repaired in several locations, including new lighting installed on the sabal palms at the entrance. Additional lighting is being added at the back entrance near the gate. Upcoming work includes enhancements in front of the guardhouse, where new shrubs will be planted around the flagpole. He also reported that irrigation repairs have been completed and new control boxes with battery backups have been installed.

C. Newsletter Supervisor

Mr. Fisher informed the Board that the newsletter will be distributed after the upcoming workshop and requested that any items for inclusion be sent to him in advance.

D. Finance Supervisor

Mr. Fisher stated that there would be no financial updates until after the workshop.

E. Lakes and Roads Supervisor

Mr. Ball informed the Board that he has obtained three (3) estimates for paving and will be reviewing them. Mr. Jackson stated that it is necessary to proceed with the formal RFP process. Regarding lake maintenance, he reported that he is working

DRAFT

with Solitude on a new product designed to break down muck at the bottom of the pond. He also noted that twenty-six (26) concrete slabs were replaced in February at a total cost of $13,000.00. The District is expected to receive $5,000 through an insurance grant he applied for.

F. Maintenance Supervisor

Mr. Branch reported another issue with a PRV valve resulting in low water pressure, which was caused by a collapsed filter. He informed the Board that he contacted Hoover, and they plan to send a technician to investigate. Additionally, Hoover will be asked to provide a quote for five (5) spare filters. Mr. Branch also updated the Board on efforts to restore the toilet and sink at the guardhouse, noting that work is currently in progress.

G. Facilities Supervisor

Mr. SanAntonio informed the Board that a motorcycle collided with the gate on March 27, 2025. He also provided an update on the tennis court, noting that all hardware has been installed and final work by Envera is pending. Additionally, he reported that the office air conditioning unit was clogged again. He is in the process of obtaining a proposal to rework the drain lines and noted that the unit may also have a Freon leak.

H. HOA Updates

There were no updates.

I. Commercial Properties

There were no updates for commercial properties.

FOURTEENTH ORDER OF BUSINESS Public Comments

A resident asked if the re is any pattern that the contractors are following when they are cleaning the sidewalks. The answer was positive, and the Supervisor explained that the contractor is letting the residents know about the schedule.

FIFTEENTH ORDER OF BUSINESS Supervisor Requests

Ms. Blandon asked if there were any Supervisor requests or comments.

Mr. Brall reported that approximately 800,000 gallons of water were lost during recent landscape repairs near the golf course. He requested that anyone who notices a potential issue report it as soon as possible to help identify the source of the loss.

SIXTEENTH ORDER OF BUSINESS Adjournment

Ms. Blandon stated that there was no further business to come before the Board and asked for a motion to adjourn.

On a Motion by Mr. Brall, seconded by Mr. Branch, with all in favor the Board adjourned the Meeting at 3:44 p.m., for the Bobcat Trail Community Development District.

DRAFT

240
241
242 _____ _____
243 Secretary/Assistant Secretary Chairman/Vice Chairman

DRAFT

Tab 2

BOBCAT TRAIL COMMUNITY DEVELOPMENT DISTRICT

DISTRICT OFFICE · FT. MYERS, FLORIDA
MAILING ADDRESS · 3434 COLWELL AVENUE, SUITE 200 · TAMPA, FLORIDA 33614

Operation and Maintenance Expenditures
March 2025
For Board Approval

Attached please find the check register listing the Operation and Maintenance expenditures paid from March 1, 2025 through March 31, 2025. This does not include expenditures previously approved by the Board.

The total items being presented:	$	60,252.33

Approval of Expenditures:

_____

_____ Chairperson

_____ Vice Chairperson

_____ Assistant Secretary

Bobcat Trail Community Development District

Paid Operation & Maintenance Expenditures

March 1, 2025 Through March 31, 2025

Vendor Name	Check Number	Invoice Number	Invoice Description	Invoice Amount
ADP Easypay	20250307-2	684672272 ACH	ADP Fee PPE 02/23/25	$ 103.20
ADP Easypay	20250321-2	685826958 ACH	ADP Fee PPE 03/09/25	$ 106.65
Artistree Landscape Maintenance & Design STE B	100156	182560	Irrigation Repairs 02/25	$ 142.56
Artistree Landscape Maintenance & Design STE B	100156	182783	Irrigation Repairs 02/25	$ 400.00
Artistree Landscape Maintenance & Design STE B	100164	183165	Monthly Maintenance 03/25	$ 9,970.40
Brletic Dvorak, Inc.	100165	1825	Engineering Services 02/25	$ 1,185.00
City of North Port Utilities	20250321-1	34841-152336 2/25 ACH	1350 Bobcat Trl 2/25	$ 65.59
City of North Port Utilities	20250321-1	34841-153028 2/25 ACH	1350 Bobcat Trl-Pool 2/25	$ 318.00
City of North Port Utilities	20250321-1	34841-175058 2/25 ACH	1352 Bobcat Trl - Office Bld 2/25	$ 357.91
City Wide Facility Solutions	100157	32019030811	Janitorial Services 03/25	$ 1,000.00
Complete IT Corp	100162	13860	Email Services 08/24	$ 181.74
Complete IT Corp	100162	14628	Email Services 11/24	$ 192.38

Bobcat Trail Community Development District

Paid Operation & Maintenance Expenditures

March 1, 2025 Through March 31, 2025

Vendor Name	Check Number	Invoice Number	Invoice Description	Invoice Amount
Complete IT Corp	100162	14879	Email Services 12/24	$ 189.66
Complete IT Corp	100162	15101	Email Services 01/25	$ 186.94
Complete IT Corp	100162	15384	Email Services 02/25	$ 184.22
Complete IT Corp	100162	15681	Email Services 03/25	$ 181.50
Complete IT Corp	100162	15857	Email Services 04/25	$ 181.50
Florida Department of Revenue	20250318-1	68-8015548212-6 02/25 ACH	Sales Tax 02/25	$ 18.94
Florida GymTech, LLC	100166	35251	Quarterly Maintenance 03/25	$ 170.00
Florida Power & Light Company	20250304-2	FPL Summary 2/25 ACH	FPL Summary 2/25	$ 3,275.38
Florida Power & Light Company	20250310-1	00592-38485 02/25 ACH	2975 Bobcat Village 02/25	$ 174.79
Frontier Florida, LLC	20250307-1	941-423-9035-100518-5 02/25	Internet 02/25	$ 125.98
Frontier Florida, LLC	20250307-1	941-426-5773-102122-5 02/25	Internet 02/25	$ 215.98
Frontier Florida, LLC	20250319-1	941-426-0808-022310-5 03/25 ACH	Phone/Internet/Cable Services 03/25	$ 578.78

Bobcat Trail Community Development District

Paid Operation & Maintenance Expenditures

March 1, 2025 Through March 31, 2025

Vendor Name	Check Number	Invoice Number	Invoice Description	Invoice Amount
Frontier Florida, LLC	20250324-1	941-423-6750-122914-5 03/25 ACH	Phone/Internet/Cable Services 03/25	$ 110.05
Hoover Pumping Systems Corp.	100167	187644	Pump Repair 03/25	$ 2,624.47
Jeffrey Brall	100161	030525 Brall	Reimbursement for Supplies 02/25	$ 26.57
Jeffrey Brall	20250312-4	JB030425 ACH	Board of Supervisor Meeting 03/04/25	$ 200.00
Jeffrey Brall	20250326-2	JB032025 ACH	Board of Supervisor Meeting 03/20/25	$ 200.00
Metro PSI Corp	100168	55613	Monthly Services 2/25	$ 145.00
Michael SanAntonio	20250312-5	MS030425 ACH	Board of Supervisor Meeting 03/04/25	$ 200.00
Michael SanAntonio	20250326-1	MS032025 ACH	Board of Supervisor Meeting 03/20/25	$ 200.00
North Port Solid Waste District	20250304-1	131769-191620 1/25 ACH	1352 Bobcat Trl SWD 1/25	$ 271.92
Nostalgic Lampposts & Mailboxes Plus, Inc.	100159	3093	Street Light Maintenance 03/25	$ 611.20
Paramount Asphalt Sealcoating Corporation	100160	6372	Sidewalk Repairs Location 10 02/25	$ 13,000.00

Bobcat Trail Community Development District

Paid Operation & Maintenance Expenditures

March 1, 2025 Through March 31, 2025

Vendor Name	Check Number	Invoice Number	Invoice Description	Invoice Amount
Paramount Asphalt Sealcoating Corporation	100169	6445	Remove and Replace Sidewalks 03/25	$ 7,000.00
Persson, Cohen & Mooney, P.A.	100170	5780	Legal Services 01/25 - 02/25	$ 1,755.40
Rizzetta & Company, Inc.	100151	INV0000097474	District Management Fees 3/25	$ 4,516.00
Robert M Branch Jr	20250312-3	RB030425 ACH	Board of Supervisor Meeting 03/04/25	$ 200.00
Robert M Branch Jr	20250326-5	RB032025 ACH	Board of Supervisor Meeting 03/20/25	$ 200.00
Signet Pool	100158	61043	Filter Grid 02/25	$ 2,542.50
Signet Pool	100163	61295	Monthly Maintenance 03/25	$ 796.00
Solitude Lake Management, LLC	100172	PSI146714	Monthly Maintenance 03/25	$ 136.59
Solitude Lake Management, LLC	100172	PSI148840	Monthly Maintenance 03/25	$ 3,159.67
Solitude Lake Management, LLC	100172	PSI150691	Monthly Maintenance 03/25	$ 160.86
Steven Ball	20250312-1	SB030425 ACH	Board of Supervisor Meeting 03/04/25	$ 200.00
Steven Ball	20250326-3	SB032025 ACH	Board of Supervisor Meeting 03/20/25	$ 200.00

Bobcat Trail Community Development District

Paid Operation & Maintenance Expenditures

March 1, 2025 Through March 31, 2025

Vendor Name	Check Number	Invoice Number	Invoice Description	Invoice Amount
TECO Peoples Gas	20250318-2	211015264685 02/25 ACH	1350 Bobcat Trl 02/25	$ 20.33
Valley National Bank	20250326-6	Bobcat Trail Valley Visa 02/25 ACH	Bobcat Trail Valley Visa 02/25	$ 1,488.67
Walter P Fisher	20250312-2	WF030425 ACH	Board of Supervisor Meeting 03/04/25	$ 200.00
Walter P Fisher	20250326-4	WF032025 ACH	Board of Supervisor Meeting 03/20/25	$ 200.00
Wenzel Electrical Services Incorporated	100171	257302	Quarterly Fire Alarm Services 04/25-06/25	$ 150.00
Wenzel Electrical Services Incorporated	100171	257746	Annual Fire Alarm Services 03/25	$ 230.00
Total Report				**$ 60,252.33**

Tab 3

City Wide Facility Solutions

8950 9th Street North | Suite 103 | St. Petersburg, Florida 33702

RECIPIENT:

BOBCAT TRAIL CDD

1350 Bobcat Trail
North Port, Florida 34288

Quote #1352

Sent on	Apr 04, 2025
Total	**$11,717.50**

Product/Service	Description	Qty.	Unit Price	Total
REFINISH TENNIS COURT	1. Set up working area, clean trash and debris off the court. 2. Grind the court of any surface bumps with industrial grinders, roll the court with a ride on industrial roller. 3. Flood the court with clean water. Those areas we deem necessary will have minimal leveling with non-shrink leveling materials. 4. Examine the surface for existing cracks. Those areas with deem necessary will be filled with special crack patch materials. 5. After all the patching and leveling is complete, we then cover patched or hairline cracks with 1' wide strips of fiberglass membrane. This will slow there return. New cracks may appear in the future due to ground movement. 6. After any patching and leveling is complete, we will install an all-new playing surface. This will consist of two coats of fortified, black resurface, and two coats of fortified acrylic latex colors. (ALL GREEN) All coats to be fortified with silica sand. 7. Install a new set of white 2" Tennis playing lines on the courts. 8. Install 4 new sets of light blue pickleball playing lines, two on each side of the tennis net. 9. Clean the net posts of loose corrosion and apply new, specific industrial paint to net posts. 10. Install 1 new heavy duty tennis net. Provide new replacement nets for the portable pickleball nets systems 11. Clean up the staging area and remove any construction debris.	1	$10,900.00	$10,900.00

Subtotal	$10,900.00
Sales Tax (7.5%)	$817.50
Total	**$11,717.50**

City Wide Facility Solutions

8950 9th Street North | Suite 103 | St. Petersburg, Florida 33702

This CONTRACT (the “Contract”) is made and entered into as of the 04/04/2025, by and between Ally Facility Solutions, Inc. d/b/a City Wide Maintenance of Tampa Bay (“City Wide”) and BOBCAT TRAIL CDD, a partnership / limited partnership / limited liability company / corporation /not-for-profit corporation (circle one), organized under the laws of the State of FL (“Customer”), each sometimes referred to individually as a “Party” and collectively as the “Parties.” 1. Services. The non-janitorial services and related products (if applicable) to be provided by City Wide are as set forth in the attached Exhibit A. 2. Duration of Contract. This is a reoccurring monthly engagement of City Wide by Customer, and the services to be rendered pursuant to this Contract shall be provided on 4/1/2023, or such other date(s) as the Parties may agree. 3. Charges for Services Rendered and Products Delivered. The charge for non-janitorial services rendered and products delivered pursuant to this Contract shall be as agreed upon by City Wide and Customer and invoiced by City Wide pursuant to Section 5 hereof. 4. Performance. Services shall be provided in a professional and workman-like manner. “City Wide Personnel” consists of City Wide’s employees, agents and/or independent contractors. If any of the City Wide Personnel assigned to perform work for Customer are unacceptable to Customer, Customer shall promptly notify City Wide management of same. If the Parties are unable to arrive at a solution that is acceptable to Customer, Customer may request that City Wide replace the individual. City Wide will either replace the individual within a reasonable time frame or terminate the Services provided hereunder effective immediately and City Wide shall have no further obligations under this Contract. 5. Invoices. City Wide will invoice Customer upon commencement of services and payment shall be due within ten (10) days of the date of the invoice. WHEN APPLICABLE, SALES TAX WILL BE ADDED TO THE INVOICE. Additional services and products may be purchased by Customer from City Wide. Invoices for the additional services and products will be sent immediately upon commencement of the additional services or delivery of the additional products, and payment will be due within ten (10) days of the date of the invoice. Any dispute concerning an Invoice or the services rendered by City Wide shall be identified in writing within five (5) days of Customer’s receipt of the invoice or the rendering of the service, as the case may be. City Wide will charge the Customer a late charge of 1½ % per month on all outstanding balances, with the first such late charge assessed 30 days from the invoice date. Customer agrees to pay all costs incurred by City Wide to collect any outstanding invoices or portions thereof, including but not limited to reasonable attorneys’ fees, costs and expenses. 6. Materials. All cleaning materials and equipment necessary for City Wide’s rendition of services will be furnished by City Wide Personnel, except for usable/consumable items. 7. No Warranty; Limitation of Liability; Indemnification. While all services shall be provided in a professional and workman-like manner, City Wide makes no warranty (express or implied) as to any services provided or products sold pursuant to this Agreement. City Wide’s liability to Customer arising from any breach of this Agreement, any services provided or products sold hereunder, or any other claim related to City Wide’s dealings with Customer pursuant to this Agreement shall not exceed the amount actually paid by Customer to City Wide for services provided pursuant to this Agreement. Customer shall fully indemnify, defend and hold harmless City Wide for any and all claims, costs, expenses (including reasonable attorneys’ fees) and damages asserted by anyone other than Customer against City Wide arising as a result of or in any way prevailing party shall be entitled to an award of its reasonable attorneys’ fees and costs from the non-prevailing party.

40% Invoiced and paid up front and balance paid on completion.

This quote is valid for the next 30 days, after which values may be subject to change.

Signature: _____ **Date:** _____

Tab 4

Office: (888) 927-7865
Fax: (813) 200-8448
Contact@customreserves.com
5470 E Busch Blvd., Unit 171
Tampa, FL 33617

BOBCAT TRAIL
COMMUNITY DEVELOPMENT DISTRICT

RESERVE STUDY



For 30-Year Projection Period: FY 2025 through FY 2055

This report contains intellectual property developed by Custom Reserves, LLC specific to this engagement and cannot be reproduced or distributed to those who conduct reserve studies without the written consent of Custom Reserves, LLC. See the proposal for details concerning the use of this report.

CustomReserves

Table of Contents

Table of Contents 2

Property Overview 4

Executive Summary 5

Financial Analysis 6

Property Component Definitions 7

Property Component Model 8

Reserve Expenditures - Table A 9

Pooling Funding Plan - Table B 13

Physical Analysis 14

Exterior Building Components **14**

1. Paint Finish Applications, Clubhouse, Gatehouse, and Pool House 14
2. Roofs, Metal 16
3. Windows and Doors, Clubhouse, Gatehouse, and Pool House 17

Building Services Components **18**

4. Generator, Emergency, Clubhouse, Installation 18
5. HVAC Equipment, Clubhouse 18
6. Security System, Access Control 18
7. Sound System, Clubhouse 19

Interior Building Components **19**

8. Exercise Equipment 19
9. Exercise Room, Renovation 20
10. Kitchen, Renovation 21
11. Party Room, Renovations 21
12. Rest Rooms, Renovations 22

Pool Components **23**

13. Deck, Concrete, Repairs and Coatings 23
14. Fences, Aluminum 24
15. Furniture 25
16. Mechanical Equipment 25
17. Pool Finishes 26

Property Site Components **27**

18. Asphalt Pavement 27
19. Fences, Chain Link, South Perimeter 30
20. Gate Operators 31
21. Gate, Vehicular, Bi-parting 31
22. Irrigation System 32
23. Light Poles and Fixtures 33
24. Pavers, Entrance 34
25. Ponds, Erosion Control 34
26. Stormwater System 37
27. Tennis Court, Fence 38
28. Tennis Court, Surface 39

Condition Model *40*


Expenditure Chart and Funding Graph *41*

Terms and Definitions *42*

Disclosures and Limitations *47*

Report Credentials *47*

Property Overview



North Port, Florida

Latitude: -27° 03' 00"

Longitude: 82° 09' 00"

Executive Summary

Custom Reserves, LLC conducted a site visit on March 5, 2025. There are 28 common area reserve components identified comprising 35 line items that require reserve funding during the noninvasive, visual inspection of the community. Supplemental information to the physical inspection typically includes the following sources:

1. District board members, management and staff
2. Client's vendors
3. Declaration
4. Maintenance records of the reserve components where available
5. Project plans where available

Bobcat Trail Community Development District (Bobcat Trail CDD) is a local unit of special purpose government built in 1997, located in North Port, Florida and is responsible for the common elements shared by commercial units and 550 homeowners. The development contains Building Services, Exterior Building, Interior Building, Pool, and Property Site components.

A Reserve Study comprises two parts:

Physical Analysis	Financial Analysis
• Component Inventory • Condition Assessment • Estimated Useful Life • Remaining Useful Life • Replacement Cost	• Fund Status • Funding Plan

The intention of this Reserve Study is to forecast the District's ability to repair or replace major components as they wear out in future years. This Reserve Study complies with or exceeds all applicable statutes and national standards. Actual expenditures and times of replacements can and/or will vary.

Reference #: 1471.25 **Report by**: Paul Grifoni, PRA, RS

Financial Analysis

The cash flow funding plan is included to project and illustrate the reserve funding plan as depicted in **Table B**. The unaudited cash status of the District's combined reserve funds, as of September 30, 2025, as reported by Management and the Board is $600,000. Bobcat Trail CDD did not budget for reserve contributions in FY[1] 2025. A reserve contribution of $347,000 would be required in 2026 to adequately fund reserves based on this analysis utilizing a threshold funding amount of 10% in the high risk year. In addition, a decrease in the reserve contribution to $183,000 in 2030 is recommended to keep a reasonable and non-excessive amount of reserve funds available in the long term.

External market factors incorporated in this Reserve Study are an inflation rate of 2.8% based on the Consumer Price Index published by the Bureau of Labor Statistics and an interest rate of 2.8%.

The actual timing of the events depicted may not occur exactly as projected. Internal changes such as deferred or accelerated projects, and external changes such as interest and inflation rates, are likely. Updates to the Reserve Study will incorporate these changes. To ensure equity in the adopted funding plan, ongoing annual reviews and either a Non Site visit or Site Visit update of this Reserve Study is recommended in two- to three-years respectively depending on the complexity of the community, and changes in external and internal factors. It is recommended by the American Institute of Certified Public Accountants (AICPA) that your Reserve Study be updated annually.

[1] FY 2025 begins October 1, 2024 and ends September 30, 2025

Property Component Definitions

The analysis began by separating the property components into specific areas of responsibility for replacement and repair. These classes of property are as follows:

1. Reserve Components are defined as follows:
    - District responsibility
    - Limited useful life expectancies
    - Predictable remaining useful life expectancies
    - Replacement cost above a minimum threshold

2. Operating Budget Components are defined as follows:
    - Common area components historically funded through operating funds rather than reserve funds
    - Common area components whose replacement or repair costs fall below a specific dollar amount

3. Long-Lived Components are defined as follows:
    - Common area components without a predictable remaining useful life
    - Common area components with a remaining useful life beyond the 30-year scope of this reserve study

4. Owner Components are defined as follows:
    - Components that are not the responsibility of the District to maintain, repair or replace

5. Other Components are defined as follows:
    - Components that are neither the responsibility of the District nor the Owner to maintain, repair or replace

CustomReserves

Property Component Model

		COMMON COMPONENTS (X)			REMAINING COMPONENTS (O)	
CATEGORY	COMPONENT	RESERVES	OPERATING	LONG-LIVED	OWNER	OTHER
Property Site	Asphalt Pavement, Mill and Overlay, Phased	X				
Property Site	Asphalt Pavement, Repairs	X				
Pool	Deck, Concrete, Repairs and Coatings	X				
Interior Building	Exercise Equipment, Cardiovascular	X				
Interior Building	Exercise Equipment, Strength Training	X				
Interior Building	Exercise Room, Renovation	X				
	Expenses Less Than $10,000		X			
Pool	Fence, Aluminum	X				
Property Site	Fences, Chain Link, South Perimeter	X				
	Foundations, Common Buildings			X		
Pool	Furniture (2026 Planned)	X				
	Gate Entry System, RFID Readers		X			
Property Site	Gate Operators, Phased	X				
Property Site	Gate, Vehicular, Bi-parting	X				
Building Services	Generator, Emergency, Clubhouse, Installation (2028 Planned)	X				
	Homes and Lots				O	
Building Services	HVAC Equipment, Clubhouse, Phased	X				
	HVAC Equipment, Gatehouse		X			
	Interior Renovations, Gatehouse and Office		X			
Property Site	Irrigation System, Deep Well, Installation (2030 Planned)	X				
Property Site	Irrigation System, Renovation	X				
Interior Building	Kitchen, Renovation	X				
	Landscaping		X			
	Lift Stations					O
Property Site	Light Poles and Fixtures	X				
	Mailboxes				O	
Pool	Mechanical Equipment, Phased	X				
	Other Repairs Normally Funded Through the Operating Budget		X			
Exterior Building	Paint Finish Applications, Clubhouse, Gatehouse, and Pool House	X				
Interior Building	Party Room, Renovation, Complete	X				
Interior Building	Party Room, Renovation, Partial	X				
Property Site	Pavers, Entrance	X				
	Pavers, Seal		X			
Property Site	Pond, Erosion Control, Partial	X				
Pool	Pool Finishes	X				
	Railings, Clubhouse and Pool House		X			
Interior Building	Rest Rooms, Clubhouse, Renovation (Incl. Hallway)	X				
Interior Building	Rest Rooms, Pool House, Renovation	X				
Exterior Building	Roof, Metal, Clubhouse	X				
Exterior Building	Roofs, Metal, Gatehouse and Pool House	X				
	Security Surveillance System					O
Building Services	Security System, Access Control	X				
	Sidewalks, Concrete, Repairs and Partial Replacements		X			
	Signage		X			
Building Services	Sound System, Clubhouse (2026 Planned)	X				
Property Site	Stormwater System, Partial	X				
	Structural Frames, Common Buildings			X		
	Subsurface Utilities, Sanitary Waste					O
	Subsurface Utilities, Water Supply					O
Property Site	Tennis Court, Fence	X				
Property Site	Tennis Court, Surface, Color Coat (2026 Budgeted)	X				
Property Site	Tennis Court, Surface, Replacement	X				
Exterior Building	Windows and Doors, Clubhouse, Gatehouse, and Pool House	X				

CustomReserves LLC

Table A

Reserve Expenditures

Bobcat Trail
Community Development District

Projected Inflation Rate 2.8%

Line Item	Reserve Components	Total Quantity	Per Phase Quantity	Unit of Measurement	1st Year of Replacement	Useful Life Years	Age (Year)	Remaining Life Years	2025 Unit Cost	2025 Cost of Replacement per Phase	2025 Cost of Replacement per Total	Total 30 Year Future Costs of Replacement	Fiscal Year 2025	Year 1 2026	Year 2 2027	Year 3 2028	Year 4 2029	Year 5 2030	Year 6 2031	Year 7 2032	Year 8 2033	Year 9 2034
	Exterior Building Components									***$289,410***	***$289,410***	***$569,118***										
1	Paint Finish Applications, Clubhouse, Gatehouse, and Pool House	**6,470**	6,470	Square Feet	2027	5 to 10	varies	2	$3.00	$19,410	$19,410	**$156,669**			$20,512							$24,886
2	Roof, Metal, Clubhouse	**89**	89	Squares	2045	to 35	2010	20	$1,400.00	$124,600	$124,600	**$216,461**										
2.1	Roofs, Metal, Gatehouse and Pool House	**26**	26	Squares	2032	to 35	2010	7	$1,400.00	$36,400	$36,400	**$44,162**								$44,162		
3	Windows and Doors, Clubhouse, Gatehouse, and Pool House	**1,090**	1,090	Square Feet	2037	to 40	varies	12	$100.00	$109,000	$109,000	**$151,825**										
	Building Services Components									***$98,600***	***$125,000***	***$316,824***										
4	Generator, Emergency, Clubhouse, Installation (2028 Planned)	**1**	1	Each	2028	to 30	N/A	3	$50,000.00	$50,000	$50,000	**$54,319**				$54,319						
5	HVAC Equipment, Clubhouse, Phased	**5**	1	Each	2026	10 to 15	varies	1	$6,600.00	$6,600	$33,000	**$101,314**		$6,785			$7,371			$8,007		
6	Security System, Access Control	**1**	1	Allowance	2033	10 to 15	unknown	8	$22,000.00	$22,000	$22,000	**$77,814**									$27,439	
7	Sound System, Clubhouse (2026 Planned)	**1**	1	Allowance	2026	to 10	unknown	1	$20,000.00	$20,000	$20,000	**$83,377**		$20,560								
	Interior Building Components									***$504,250***	***$504,250***	***$1,323,436***										
8	Exercise Equipment, Cardiovascular	**1**	1	Allowance	2027	to 7	unknown	2	$50,000.00	$50,000	$50,000	**$403,579**			$52,839							$64,107
8.1	Exercise Equipment, Strength Training	**1**	1	Allowance	2034	to 15	unknown	9	$35,000.00	$35,000	$35,000	**$110,931**										$44,875
9	Exercise Room, Renovation	**1,750**	1,750	Square Feet	2034	to 10	unknown	9	$17.00	$29,750	$29,750	**$154,685**										$38,144
10	Kitchen, Renovation	**300**	300	Square Feet	2035	to 25	2010	10	$225.00	$67,500	$67,500	**$88,968**										
11	Party Room, Renovation, Complete	**7,000**	7,000	Square Feet	2038	to 30	varies	13	$20.00	$140,000	$140,000	**$200,465**										
11.1	Party Room, Renovation, Partial	**7,000**	7,000	Square Feet	2027	10 to 15	varies	2	$11.00	$77,000	$77,000	**$230,764**			$81,372							
12	Rest Rooms, Clubhouse, Renovation (Incl. Hallway)	**2**	2	Each	2035	to 25	2010	10	$45,000.00	$90,000	$90,000	**$118,624**										
12.1	Rest Rooms, Pool House, Renovation	**2**	2	Each	2026	to 25	1997	1	$7,500.00	$15,000	$15,000	**$15,420**		$15,420								
	Pool Components									***$88,435***	***$99,435***	***$387,678***										
13	Deck, Concrete, Repairs and Coatings	**3,970**	3,970	Square Feet	2026	5 to 7	unknown	1	$3.00	$11,910	$11,910	**$93,514**		$12,243							$14,854	
14	Fence, Aluminum	**290**	290	Linear Feet	2033	to 25	unknown	8	$35.00	$10,150	$10,150	**$12,659**									$12,659	
15	Furniture (2026 Planned)	**1**	1	Allowance	2026	5 to 10	unknown	1	$14,000.00	$14,000	$14,000	**$58,364**		$14,392								
16	Mechanical Equipment, Phased	**1**	1	Allowance	2029	5 to 10	unknown	4	$22,000.00	$11,000	$22,000	**$107,013**					$12,285					$14,104
17	Pool Finishes	**1,655**	1,655	Square Feet	2029	10 to 15	unknown	4	$25.00	$41,375	$41,375	**$116,128**					$46,207					
	Property Site Components									***$917,160***	***$2,354,160***	***$6,475,607***										
18	Asphalt Pavement, Mill and Overlay, Phased (2025-2029 Budgeted)	**65,940**	9,420	Square Yards	2025	15 to 25	varies	0	$25.00	$235,500	$1,648,500	**$4,869,633**	$338,039	$224,797	$456,035	$181,974	$375,884					
18.1	Asphalt Pavement, Repairs	**65,940**	65,940	Square Yards	2030	5 to 8	unknown	5	$0.50	$32,970	$32,970	**$217,380**						$37,852				
19	Fences, Chain Link, South Perimeter	**2,250**	2,250	Linear Feet	2033	to 25	varies	8	$30.00	$67,500	$67,500	**$84,188**									$84,188	
20	Gate Operators, Phased	**8**	4	Each	2029	10 to 15	unknown	4	$6,000.00	$24,000	$48,000	**$146,643**					$26,803					
21	Gate, Vehicular, Bi-parting	**1**	1	Each	2036	20 to 25	unknown	11	$10,000.00	$10,000	$10,000	**$13,550**										
22	Irrigation System, Deep Well, Installation (2030 Planned)	**1**	1	Allowance	2030	N/A	N/A	5	$75,000.00	$75,000	$75,000	**$86,105**						$86,105				
22.1	Irrigation System, Renovation	**1**	1	Allowance	2043	to 40+	varies	18	$150,000.00	$150,000	$150,000	**$246,585**										
23	Light Poles and Fixtures	**40**	40	Each	2033	to 35	1997	8	$2,500.00	$100,000	$100,000	**$124,723**									$124,723	
24	Pavers, Entrance	**4,310**	4,310	Square Feet	2031	15 to 25	1997	6	$9.00	$38,790	$38,790	**$45,780**							$45,780			
25	Pond, Erosion Control, Partial	**1**	1	Allowance	2034	to 15	1997	9	$90,000.00	$90,000	$90,000	**$290,007**										$115,393
26	Stormwater System, Partial	**1**	1	Allowance	2028	5 to 8	1997	3	$20,000.00	$20,000	$20,000	**$118,874**				$21,727						

Table A

Reserve Expenditures

Bobcat Trail
Community Development District

Line Item	Reserve Components	Year 10	Year 11	Year 12	Year 13	Year 14	Year 15	Year 16	Year 17	Year 18	Year 19	Year 20	Year 21	Year 22	Year 23	Year 24	Year 25	Year 26	Year 27	Year 28	Year 29	Year 30
		2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055
	Exterior Building Components																					
1	Paint Finish Applications, Clubhouse, Gatehouse, and Pool House							$30,194							$36,633							$44,445
2	Roof, Metal, Clubhouse											$216,461										
2.1	Roofs, Metal, Gatehouse and Pool House																					
3	Windows and Doors, Clubhouse, Gatehouse, and Pool House			$151,825																		
	Building Services Components																					
4	Generator, Emergency, Clubhouse, Installation (2028 Planned)																					
5	HVAC Equipment, Clubhouse, Phased	$8,699			$9,450			$10,267			$11,154			$12,117			$13,164			$14,300		
6	Security System, Access Control																					$50,375
7	Sound System, Clubhouse (2026 Planned)		$27,099										$35,718									
	Interior Building Components																					
8	Exercise Equipment, Cardiovascular							$77,779							$94,365							$114,489
8.1	Exercise Equipment, Strength Training														$66,056							
9	Exercise Room, Renovation										$50,275										$66,265	
10	Kitchen, Renovation	$88,968																				
11	Party Room, Renovation, Complete				$200,465																	
11.1	Party Room, Renovation, Partial															$149,391						
12	Rest Rooms, Clubhouse, Renovation (Incl. Hallway)	$118,624																				
12.1	Rest Rooms, Pool House, Renovation																					
	Pool Components																					
13	Deck, Concrete, Repairs and Coatings						$18,022							$21,866							$26,528	
14	Fence, Aluminum																					
15	Furniture (2026 Planned)		$18,969										$25,003									
16	Mechanical Equipment, Phased					$16,192					$18,589					$21,342					$24,502	
17	Pool Finishes										$69,921											
	Property Site Components																					
18	Asphalt Pavement, Mill and Overlay, Phased (2025-2029 Budgeted)													$432,354	$444,460	$456,905	$469,698	$482,850	$496,369	$510,268		
18.1	Asphalt Pavement, Repairs				$47,210								$58,881								$73,438	
19	Fences, Chain Link, South Perimeter																					
20	Gate Operators, Phased		$32,519							$39,454							$47,867					
21	Gate, Vehicular, Bi-parting		$13,550																			
22	Irrigation System, Deep Well, Installation (2030 Planned)																					
22.1	Irrigation System, Renovation									$246,585												
23	Light Poles and Fixtures																					
24	Pavers, Entrance																					
25	Pond, Erosion Control, Partial															$174,613						
26	Stormwater System, Partial	$26,361							$31,983							$38,803						

Table A

Reserve Expenditures

Bobcat Trail
Community Development District

Projected Inflation Rate 2.8%

Line Item	Reserve Components	Total Quantity	Per Phase Quantity	Unit of Measurement	1st Year of Replacement	Useful Life Years	Age (Year)	Remaining Life Years	2025 Unit Cost	2025 Cost of Replacement per Phase	2025 Cost of Replacement per Total	Total 30 Year Future Costs of Replacement	Fiscal Year 2025	Year 1 2026	Year 2 2027	Year 3 2028	Year 4 2029	Year 5 2030	Year 6 2031	Year 7 2032	Year 8 2033	Year 9 2034
27	Tennis Court, Fence	**360**	360	Linear Feet	2040	to 30	2010	15	$40.00	$14,400	$14,400	**$21,790**										
28	Tennis Court, Surface, Color Coat (2026 Budgeted)	**800**	800	Square Yards	2026	4 to 6	unknown	1	$18.75	$15,000	$15,000	**$143,770**		$15,420					$17,703			
28.1	Tennis Court, Surface, Replacement	**800**	800	Square Yards	2040	to 30	2010	15	$55.00	$44,000	$44,000	**$66,581**										
	Total Expenditures									$1,897,855	$3,372,255	**$9,072,663**	**$338,039**	**$309,617**	**$610,759**	**$258,020**	**$468,550**	**$123,956**	**$63,483**	**$52,170**	**$263,863**	**$301,510**

Table A

Reserve Expenditures

Bobcat Trail
Community Development District

Line Item	Reserve Components	Year 10	Year 11	Year 12	Year 13	Year 14	Year 15	Year 16	Year 17	Year 18	Year 19	Year 20	Year 21	Year 22	Year 23	Year 24	Year 25	Year 26	Year 27	Year 28	Year 29	Year 30
		2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055
27	Tennis Court, Fence						$21,790															
28	Tennis Court, Surface, Color Coat (2026 Budgeted)		$20,324									$26,059					$29,917					$34,347
28.1	Tennis Court, Surface, Replacement						$66,581															
	Total Expenditures	**$242,653**	**$112,461**	**$151,825**	**$257,125**	**$16,192**	**$106,393**	**$118,239**	**$31,983**	**$286,039**	**$149,939**	**$242,520**	**$119,601**	**$466,336**	**$641,513**	**$841,054**	**$560,646**	**$482,850**	**$496,369**	**$524,568**	**$190,733**	**$243,655**

Table B

Pooling (Cash Flow) Funding Plan

Bobcat Trail
Community Development District

	FY	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Beginning of Year Reserves	**Note 2**	**$600,000**	$261,961	$306,679	$61,207	$171,601	$84,856	$146,275	$274,988	$423,918	$370,725	$283,995	$259,394	$370,196	$450,736	$434,432	$665,004
Recommended Reserve Contributions	**Note 2**	**0**	**347,000**	356,700	366,700	377,000	**183,000**	188,100	193,400	198,800	204,400	210,100	216,000	222,000	228,200	234,600	241,200
Anticipated Interest Earned	**2.8%**	0	7,335	8,587	1,714	4,805	2,376	4,096	7,700	11,870	10,380	7,952	7,263	10,365	12,621	12,164	18,620
Projected Expenditures		(338,039)	(309,617)	(610,759)	(258,020)	(468,550)	(123,956)	(63,483)	(52,170)	(263,863)	(301,510)	(242,653)	(112,461)	(151,825)	(257,125)	(16,192)	(106,393)
Projected Year End Reserves		261,961	306,679	61,207	171,601	84,856	146,275	274,988	423,918	370,725	283,995	259,394	370,196	450,736	434,432	665,004	818,431
				Threshold/ Risk Year													

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055
Beginning of Year Reserves	$818,431	$971,108	$1,221,217	$1,231,372	$1,385,210	$1,458,276	$1,664,107	$1,536,966	$1,239,287	$742,134	$520,168	$378,683	$228,917	$56,158	$222,097
Recommended Reserve Contributions	248,000	254,900	262,000	269,300	276,800	284,600	292,600	300,800	309,200	317,900	326,800	336,000	345,400	355,100	365,000
Anticipated Interest Earned **2.8%**	22,916	27,191	34,194	34,478	38,786	40,832	46,595	43,035	34,700	20,780	14,565	10,603	6,410	1,572	6,219
Projected Expenditures	(118,239)	(31,983)	(286,039)	(149,939)	(242,520)	(119,601)	(466,336)	(641,513)	(841,054)	(560,646)	(482,850)	(496,369)	(524,568)	(190,733)	(243,655)
Projected Year End Reserves	971,108	1,221,217	1,231,372	1,385,210	1,458,276	1,664,107	1,536,966	1,239,287	742,134	520,168	378,683	228,917	56,158	222,097	349,661
													Threshold/ Risk Year		

Financial Notes:

1) FY 2025 Begins October 1, 2024 and Ends September 30, 2025
2) FY 2025 Beginning Reserve Balance and Remaining Contributions are as of September 30, 2025
3) Interest Earned is compounded on the Beginning Year Reserve Balance, the first year is a partial amount earned
4) Taxes on the interest earned are considered negligible

Exterior Building Components

1. Paint Finish Applications, Clubhouse, Gatehouse, and Pool House

The District maintains approximately 6,470 square feet of paint finishes at the clubhouse, gatehouse, and pool house. Periodic applications of a protective paint finish or waterproof coating is essential in order to maintain the appearance and integrity of the buildings.

Comprehensive paint specifications define quality levels and the materials and methods required to achieve them. Construction specifications are written documents that describe the materials and workmanship required for a building project. The purpose is to create certainty in the project and outcome.

The paint finish performance is affected by proper product selection, application, and surface preparation. Coating integrity and useful life will be reduced because of improperly prepared surfaces. The selection and implementation of proper surface preparation ensures coating adhesion to the substrate and prolongs the useful life of the coating system.

The paint finishes are of varied ages and in good to fair overall condition. Paint finishes have a useful life from 5- to 10-years. Bobcat Trail CDD should plan for the next paint finish application by 2027 and every seven years thereafter. The District should plan for weatherizing the window sealants and any exterior penetrations as needed in conjunction with paint finish applications. The window sealants should be replaced with a polyurethane sealant and then painted over for protection from UV light degradation.



Figure 1 – Clubhouse overview



Figure 2 – Exterior paint finishes at clubhouse



Figure 3 – Minor exterior damage at clubhouse



Figure 4 – Gatehouse paint finishes



Figure 5 – Paint finishes at pool house



Figure 6 – Minor paint finish damage at pool house

2. Roofs, Metal

There are approximately 89 squares of standing seam metal roof at the clubhouse and 26 squares of metal roofs at the gatehouse and pool house. Roof panels are crimped together rather than fastened by screws. The clubhouse metal roof is in good overall condition at an age of 15 years. The metal roofs at the gatehouse and pool house are in good to fair overall condition at an age of 28 years. Metal roofs of this type have a useful life of up to 35 years. The District should budget for replacement of the clubhouse metal roof by 2045 and replacement of the gatehouse and pool house metal roofs by 2032.



Figure 1 – Clubhouse metal roof



Figure 2 – Metal roof valley at clubhouse



Figure 3 – Pool house metal roof



Figure 4 – Standing seam metal roof at pool house



Figure 5 – Gatehouse metal roof



Figure 6 – Rust at gatehouse metal roof

3. Windows and Doors, Clubhouse, Gatehouse, and Pool House

The windows and doors of the clubhouse, gatehouse, and pool house comprise approximately 1,090 square feet. The windows and doors are primarily original to construction and in good overall condition. The clubhouse was built in 2010, and the gatehouse and pool house were built in 1997. Windows and doors of this type have a useful life of up to 40 years. The need to replace windows can be due to various reasons such as consistency in style and condition. There will be a cost savings with coordinated replacement. Bobcat Trail CDD should budget for replacement of the windows and doors by 2037.



Figure 1 – Windows and doors at clubhouse



Figure 2 – Gatehouse windows and doors

4. Generator, Emergency, Clubhouse, Installation

Bobcat Trail CDD plans to install a generator to power the clubhouse during a power outage. Generators usually have a useful life of up to 30 years. The District is budgeting $50,000 plus inflation for installation by 2028.

5. HVAC Equipment, Clubhouse

The clubhouse utilizes five split systems for heating, ventilating and air conditioning. A split system comprises an outdoor condensing unit and in indoor air handling unit. The split systems were operational at the time of the site visit. The exact ages are between 2000 and 2020. Split systems typically have a useful life from 10- to 15-years. Bobcat Trail CDD should budget for phased replacements of one system every three years starting 2026.



Figure 1 – Clubhouse split system condensing units

6. Security System, Access Control

The District utilizes an access control system. The access control system is in satisfactory overall condition at an unknown age. Access control systems have a useful life from 10- to 15-years. Based on condition, Bobcat Trail CDD should budget for replacement of the access control system by 2033 and every 12 years thereafter.



Figure 1 – Access point receiver

7. Sound System, Clubhouse

The District utilizes a sound system at the clubhouse. The sound system is reported to be in fair to poor overall condition at an unknown age. Bobcat Trail CDD plans to spend approximate $20,000 plus inflation for replacement of the sound system by 2026. Subsequent cycles are likely every 10 years thereafter.

Interior Building Components

8. Exercise Equipment

Bobcat Trail CDD maintains various pieces of strength training and cardiovascular exercise equipment. The exercise equipment is in good to fair overall condition at unknown ages. The District has been informed by their vendor that the cardiovascular equipment should be planned to be replaced in the near term. Cardiovascular exercise equipment typically has a useful life of up to seven years, and strength training equipment typically has a useful life of up to 15 years. Based on condition, the District should budget for replacement of the cardiovascular exercise equipment by 2027 and replacement of the strength training equipment by 2034.



Figure 1 – Cardiovascular exercise equipment



Figure 2 – Strength training exercise equipment

9. Exercise Room, Renovation

The exercise room at the clubhouse comprises approximately 1,750 square feet of interior finished area. These interior components comprise paint finishes, rubber floor coverings, furnishings, and electrical fixtures. The last renovation date is unknown. These interior components are in good overall condition. The useful lives of these interior components vary. However, in order to maintain continuity, the District should coordinate replacement of these components every 10 years. Bobcat Trail CDD should budget for a renovation by 2034.



Figure 1 – Exercise room



Figure 2 – Exercise room

10. Kitchen, Renovation

The kitchen at the clubhouse comprises approximately 300 square feet of interior finished area. The interior components comprise laminate floor coverings, cabinets and countertops, appliances, and plumbing fixtures. The kitchen is mostly original to 2010 and in fair overall condition with flooring damage evident. These kitchen components have a useful life of up to 25 years. Bobcat Trail CDD should budget for kitchen renovations by 2035.



Figure 1 – Kitchen overview



Figure 2 – Flooring cracks and scuffs

11. Party Room, Renovations

The party room at the clubhouse comprises approximately 7,000 square feet of interior finished area. The interior components comprise paint finishes, carpet and wood floor coverings, furnishings including chairs and tables, and electrical fixtures. The components are of varied ages with many original to 2010. The interior components are in fair overall condition with isolated carpet stains evident. The useful lives of these interior components vary. However, in order to maintain continuity, the District should coordinate replacement of all these components every 30 years. Bobcat Trail CDD should budget for a complete renovation by 2038.



Figure 1 – Party room overview



Figure 2 – Carpet stain at clubhouse party room

A partial renovation includes paint finishes, carpet floor coverings and up to fifty percent (50%) of the furnishings. Bobcat Trail CDD plans to do a partial renovation, including replacing the flooring, within three years. Bobcat Trail CDD should budget for a partial renovation by 2027 and every 10- to 15-years thereafter except when the complete renovation occurs.

12. Rest Rooms, Renovations

There are two rest rooms at the clubhouse and two rest rooms at the pool house. The clubhouse rest rooms and hallway comprise paint finishes, tile wall and floor coverings, partitions, countertops, plumbing and electrical fixtures. The pool house rest rooms comprise paint finishes, partitions, plumbing and electrical fixtures. The clubhouse rest rooms and hallway are in good condition at an age of 15 years, and the pool house rest rooms are in fair to poor condition at an age of 28 years. These rest room components typically have a useful life of up to 25 years. Bobcat Trail CDD should budget for renovations of the clubhouse rest rooms and hallway by 2035 and the pool house rest rooms by 2026. The District should comply with the Americans with Disabilities Act (ADA).



Figure 1 – Clubhouse rest room



Figure 2 – Clubhouse rest room hallway



Figure 3 – Pool house rest room



Figure 4 – Rust at pool house rest room partition

Pool Components

13. Deck, Concrete, Repairs and Coatings

The pool deck comprises 3,970 square feet of concrete. The pool deck is original and the coating is in poor overall condition. Concrete pool decks have a long useful life with the benefit of periodic maintenance. Periodic maintenance includes a slip resistant coating application every five- to seven-years. Based on the condition, Bobcat Trail CDD should budget for the next coating application in 2026 and every seven years thereafter.



Figure 1 – Pool deck overview



Figure 2 – Pool deck cracks and previous repairs

14. Fences, Aluminum

Approximately 290 linear feet of aluminum fence surrounds the pool area. This fence is in good to fair condition at an unknown age. Aluminum fences have an estimated useful life of up to 25 years. Based on condition, Bobcat Trail CDD should budget for replacement of the pool fence by 2033.



Figure 1 – Aluminum pool fence



Figure 2 – Worn fence finish

15. Furniture

The pool furniture includes umbrellas, lounges, tables and chairs. The pool furniture is of unknown age and in fair condition overall. The pool furniture has an estimated useful life from 5- to 10-years. Bobcat Trail CDD plans to replace the furniture by 2026. The District should fund interim restrapping through the operating budget as needed.



Figure 1 – Pool furniture



Figure 2 – Worn lounge straps

16. Mechanical Equipment

The mechanical equipment includes heaters, pumps, filters, and chlorinators. The mechanical equipment is in satisfactory operation condition at various ages. The pool equipment has an estimated useful life from 5- to 10-years with the benefit of ongoing maintenance. This ongoing maintenance includes partial replacements of the pumps, filters and chlorinators as needed. Bobcat Trail CDD should budget for major replacements by 2029 in conjunction with the pool finish. The District may be able to fund most replacements through the operating budget which would allow reserves to build up enough for eventual replacement of the enclosures.



Figure 1 – Pool heaters



Figure 2 – Pool mechanical equipment

17. Pool Finishes

The finish at the pool wall and floor surfaces is of unknown age and in good to fair overall condition. Pool finishes have an anticipated useful life from 10- to 15-years. Based on condition, the District should budget for resurfacing of the wall and floor areas, as well as replacement of the pool waterline tile, as needed, by 2029 and again by 2044. Typically minor upgrades will be needed to bring the pool up to current code. Potential repairs to the underlying pool structure may raise the estimate of cost.



Figure 1 – Pool overview



Figure 2 – Pool plaster and tile finishes

18. Asphalt Pavement

The District maintains approximately 65,944 square yards of asphalt pavement. The asphalt pavement is primarily original and in good to fair overall condition with isolated areas of cracks, delamination, and settlement. Asphalt pavement comprises multiple layers. Typically, the top layer or surface course deteriorates over time and can be milled or removed and overlaid or replaced. The following diagram depicts typical pavement layers.



A mill and overlay is a method of repaving of the surface course where cracked, worn and failed pavement is mechanically removed or milled. A new layer of asphalt is overlaid atop the remaining sound pavement. Milled pavement removes part of the existing pavement and permits the overlay to match the elevation of areas such as adjacent catch basins, curbs and gutters. The milled pavement should be properly bonded to the new overlayment. Overlayment thicknesses range from one to two inches. Variable thicknesses are often necessary for proper drainage.

A combination of area patching, crack repair and milling should occur before the overlayment. Areas that exhibit potholes, alligator cracks and areas of pavement that are deteriorated from vehicle fluids should all be repaired prior to overlayment. Area patching may require total replacement of isolated areas of pavement. The base course for residential subdivision roadways designed for light traffic is often six inches thick. The paving contractor should seal all cracks. Crack repair minimizes the chance of underlying cracks coming through the overlayment.

The estimated useful life of the asphalt pavement surface course varies from 15- to 25-years due to design, quality of construction, materials and maintenance. The District plans to follow the seven-year phased repaving plan created by the pavement assessment completed for the District in

2020. Phases one and two are completed. Phases three and four will be done in 2025. One additional phase will be done each year through 2028. The commercial pavement will be added as an eighth phase in 2029. Bobcat Trail CDD should also budget for pavement repairs by 2033 and every eight years thereafter except when repaving occurs. The District should retain an engineer for quality control.



Figure 1 – Parking lot at pool house



Figure 2 – Cracks and delamination at parking lot



Figure 3 – Pavement overview at Bobcat Trail



Figure 4 – Longitudinal cracks at Silver Palm Road



Figure 5 – Transverse crack at Fishtail Palm Court



Figure 6 – Pavement overview at Royal Palm Drive



Figure 7 – Pavement at Palmetto Palm Way



Figure 8 – Pavement at Kentia Palm Court



Figure 9 – Settlement at Bobcat Trail



Figure 10 – Pavement cracking at Lady Palm Way



Figure 11 – Pavement at Coconut Palm Circle



Figure 12 – Asphalt pavement at Queen Palm Way

19. Fences, Chain Link, South Perimeter

The District maintains approximately 2,250 linear feet of chain link fence at the south perimeter. The fence has been repaired in sections at difference times and in is fair overall condition. The estimated useful life of chain link fences is up to 25 years. Bobcat Trail CDD should budget for complete replacement by 2033.



Figure 1 – Chain link fence overview



Figure 2 – Chain link fence with section replaced

20. Gate Operators

The District maintains eight gate operators comprised of six lift arm operators and two swing arm operators. The gate operators are of unknown ages and in satisfactory operation condition. Gate operators have an estimated useful life from 10- to 15-years. Bobcat Trail CDD should budget for phased replacements of up to four gate operators every seven years beginning in 2029. The District should fund interim repairs and replacement of any gate arms, photo eyes, motors, and battery backups through the operating budget.



Figure 1 – Lift arm operators



Figure 2 – Swing arm operators

21. Gate, Vehicular, Bi-parting

Bobcat Trail CDD also maintains one bi-parting vehicular gate. The gate is of unknown age and in good condition. The metal gate has an estimated useful life from 20- to 25-years. Based on condition, the District should budget for replacement of the gate by 2036.




Figure 1 – Bi-parting vehicular gate

22. Irrigation System

The District maintains irrigation along the three main roads and the amenities area. Irrigation system components typically include pumps, clocks, valves, heads and piping. The piping system is mostly original and the two large pumping systems were replaced in 2023. The system is in satisfactory operation condition overall. The system has a long useful life with the benefit of ongoing maintenance. Over time, the effects of the elements will reduce the flexibility and durability of the underground pipe network and wiring. Bobcat Trail CDD should budget for a renovation of the irrigation system every 20 years or by 2043. The District should fund interim head and controller replacements through the operating budget as needed.

The irrigation system is served by pump systems that draw water from the lake. Bobcat Trail CDD plans to install a deep well in the lake by 2030 for $75,000 plus inflation. The District should also fund motor replacements and pump rebuilding through the operating budget as needed.

23. Light Poles and Fixtures

The District maintains the decorative light poles and fixtures along the three main roads and the amenities area. The light poles and fixtures are original and in satisfactory operation condition. These light poles and fixtures have an estimated useful life of up to 35 years. Bobcat Trail CDD should budget for replacement of the light poles and fixtures by 2033. The cost includes an allowance for replacement of the pole, base, fixture and minor electrical repairs at the time of replacement. Interim replacement of light bulbs and/or fixtures should be funded through the operating budget on an as needed basis.



Figure 1 – Light pole and fixture at street



Figure 2 – Light pole finish deterioration



Figure 3 – Light pole and fixture at amenities area

24. Pavers, Entrance

The main entry includes approximately 4,310 square feet of pavers. Vehicular pavers have an estimated useful life from 15- to 25-years with the benefit of ongoing maintenance that includes pressure washing, resetting as needed, an application of sand between the pavers followed by sealer applications every three- to five-years in order to preserve the color and minimize repairs. Bobcat Trail CDD should budget for this maintenance activity through the operating budget. The District should fund for replacements by 2031. The need to eventually replace the pavers may be desired based on aesthetics.



Figure 1 – Pavers at main entrance

25. Ponds, Erosion Control

The District maintains the ponds in the commercial and residential areas. Bobcat Trail CDD utilizes a wet pond system. Wet ponds treat storm water runoff by utilizing sunlight and vegetation which breaks down, filters and cleanses pollutants. The system includes a series of pipes and drains throughout the property designed to carry storm water directly to the pond system for processing.

The pond shorelines comprise approximately 34,500 linear feet. The ponds are original and in good overall condition. Areas of shoreline erosion and previous repairs with rip rap are noted. Shoreline erosion can be caused by a variety of natural factors including steep slopes, changes in

water elevation and storm water runoff. Erosion can lead to partial dredging of the ponds particularly near the drainage inlet and outlet structures.

Waterbodies of this type should utilize mapping and bathymetry to develop an effective management strategy by knowing the exact surface area, depths, structural locations and sediment accumulation. A bathymetric and sedimentation survey should be conducted every three- to five-years.

State environmental officials urge a 10-foot buffer zone around ponds, where no pesticides, fertilizer, or other chemicals should be used, and native plants are left to flourish. That enables the plants to soak up nitrogen and phosphorus before too much flows to fragile waters, where the two nutrients fuel fish-killing toxic algae blooms.

Any native plants along the pond's littoral shelf should be left in place. Horticulture experts say to choose native plants or if they're already there, let them grow. The right plant in the right place can out-compete problem species such as cattails and torpedo grass that can clog up ponds. Native plants also provide cover for fish and habitat for tiny organisms that small fish eat to colonize. The plant roots also help hold the pond's banks in place.

Bobcat Trail CDD should budget for erosion control of up to five percent (5%) of the shorelines every 15 years or by 2034 and again by 2049 based on the age and condition of the ponds.



Figure 1 – Pond at entrance with rip rap erosion repairs



Figure 2 – Pond south of main entrance



Figure 3 – Pond at west perimeter



Figure 4 – Pond at Solitary Palm Court overview



Figure 5 – Pond at Palmetto Palm Way



Figure 6 – Pond shoreline at Coconut Palm Circle

26. Stormwater System

The District maintains the stormwater system. The visible portion of the stormwater system comprises curbing designed to direct stormwater to catch basins. The system includes a series of pipes throughout the property designed to carry storm water away to a pond system for processing. The streets utilize a concrete curb and gutter system that conveys stormwater runoff into drainage inlets along the outside pavement edge. The District maintains approximately 54,000 linear feet of concrete curbs and gutters. This application of concrete has a useful life of up to 65 years although isolated deterioration of limited areas of concrete is common. Inclement weather, inadequate subsurface preparation and improper concrete mixtures or finishing techniques can result in premature deterioration such as settlement, chips, cracks and spalls. Variable conditions like these result in the need to plan for periodic partial replacements of the concrete flatwork throughout the next 30 years. Bobcat Trail CDD should budget for up to five percent (5%) of the curbs and gutters in conjunction with repaving.

Stormwater systems are low maintenance and often overlooked. However, overlooking systems of this type leads to major problems. Over time, drains can become clogged with leaves and other debris. The District should anticipate occasional displacement of storm water structures and the surrounding pavement from erosion as time goes on. Erosion causes settlement of curb inlets or catch basins. The catch basin can shift and need replacement if left unrepaired. The District should plan to repair any displaced storm water structures and partial pipe replacements concurrently with surrounding pavement or curbs and gutters. The exact times and amount of capital repairs or replacements varies upon natural forces.

The overall reported condition of the stormwater system is good. Stormwater systems have a long useful life with the benefit of ongoing maintenance. Achieving this useful life typically requires interim capital repairs or partial replacements. Maintenance of stormwater systems is required in every municipality as a condition for use of the land to prevent adverse impacts on adjoining properties. Bobcat Trail CDD should budget to routinely keep drains clear, paint the curb inlet metal face plates, and replace up to one percent (1%) of the curbs and gutters every five- to eight-years beginning in 2028.



Figure 1 – Typical concrete street gutter



Figure 2 – Rusted curb inlet at Silver Palm Road

27. Tennis Court, Fence

The tennis court is enclosed by 360 linear feet of chain link fence. The fence was installed in 2010 and in good overall condition. The fence has a useful life of up to 30 years. Bobcat Trail CDD should budget for replacement by 2040 in conjunction with the surface replacement.



Figure 1 – Tennis court fencing



Figure 2 – Minor chain link warped webbing

28. Tennis Court, Surface

The District maintains one tennis court that comprises 800 square yards of asphalt surface area. The tennis court surface is in fair overall condition at an age of 15 years. The age of the last color coat application is known. A tennis court surface has a useful life of up to 30 years with repairs and a color coat application every four- to six-years to maintain the playing surface. Bobcat Trail CDD plans to apply a color coat application by 2026 and should budget for surface replacement by 2040.



Figure 1 – Tennis court overview




Figure 2 – Tennis court surface crack


CustomReserves

Condition Model

ıt Type	Component Name	Condition	Urgency	1st Year of Replacement
Exterior Building	Paint Finish Applications, Clubhouse, Gatehouse, and Pool House	7	!	2027
Exterior Building	Roof, Metal, Clubhouse	9	✓	2045
Exterior Building	Roofs, Metal, Gatehouse and Pool House	6	!	2032
Exterior Building	Windows and Doors, Clubhouse, Gatehouse, and Pool House	9	✓	2037
Building Services	Generator, Emergency, Clubhouse, Installation (2028 Planned)	N/A	N/A	2028
Building Services	HVAC Equipment, Clubhouse, Phased	8	!	2026
Building Services	Security System, Access Control	8	✓	2033
Building Services	Sound System, Clubhouse (2026 Planned)	5	!	2026
Interior Building	Exercise Equipment, Cardiovascular	7	✓	2027
Interior Building	Exercise Equipment, Strength Training	8	✓	2034
Interior Building	Exercise Room, Renovation	9	✓	2034
Interior Building	Kitchen, Renovation	7	✓	2035
Interior Building	Party Room, Renovation, Complete	7	✓	2038
Interior Building	Party Room, Renovation, Partial	7	!	2027
Interior Building	Rest Rooms, Clubhouse, Renovation (Incl. Hallway)	8	✓	2035
Interior Building	Rest Rooms, Pool House, Renovation	4	!	2026
Pool	Deck, Concrete, Repairs and Coatings	4	!	2026
Pool	Fence, Aluminum	7	✓	2033
Pool	Furniture (2026 Planned)	6	!	2026
Pool	Mechanical Equipment, Phased	7	!	2029
Pool	Pool Finishes	7	✓	2029
Property Site	Asphalt Pavement, Mill and Overlay, Phased	7	!	2026
Property Site	Asphalt Pavement, Repairs	7	!	2033
Property Site	Fences, Chain Link, South Perimeter	6	!	2033
Property Site	Gate Operators, Phased	8	✓	2029
Property Site	Gate, Vehicular, Bi-parting	8	✓	2036
Property Site	Irrigation System, Deep Well, Installation (2030 Planned)	N/A	N/A	2030
Property Site	Irrigation System, Renovation	8	✓	2043
Property Site	Light Poles and Fixtures	7	✓	2033
Property Site	Pavers, Entrance	7	✓	2031
Property Site	Pond, Erosion Control, Partial	8	✓	2034
Property Site	Stormwater System, Partial	8	✓	2028
Property Site	Tennis Court, Fence	8	✓	2040
Property Site	Tennis Court, Surface, Color Coat (2026 Budgeted)	6	!	2026
Property Site	Tennis Court, Surface, Replacement	8	✓	2040

Expenditure Chart and Funding Graph





Terms and Definitions

Adequate Reserves - A replacement reserve fund and stable and equitable multiyear funding plan that together provide for the reliable and timely execution of the district's major repair and replacement projects as defined herein without reliance on additional supplemental funding.

Capital Improvements - Additions to the district's common area that previously did not exist. While these components should be added to the reserve study for future replacement, the cost of construction or installation cannot be taken from the reserve fund.

Cash Flow Method (also known as pooling) - A method of calculating Reserve contributions where contributions to the Reserve fund are designed to offset the variable annual expenditures from the Reserve fund. Different Reserve Funding Plans are tested against the anticipated schedule of Reserve expenditures until the desired Funding Goal is achieved.

Common Area - The areas identified in the community district's master deed or declarations of covenant easements and restrictions that the district is obligated to maintain and replace or based on a well-established district precedent.

Component - An individual line item in the Reserve Study developed or updated in the Physical Analysis. These elements form the building blocks of the Reserve Study. Components typically are: 1) District responsibility, 2) The need and schedule for this project can be reasonably anticipated, 3) The total cost for the project is material to the district, can be reasonably estimated, and includes all direct and related costs.

Component Inventory - The task of selecting and quantifying Reserve Components. This task is accomplished through onsite visual observations, review of district design and organizational documents, and a review of established district precedents, and discussion with appropriate representative(s) of the district.

Component Method (also known as Straight Line) - A method of developing a reserve funding plan where the total funding is based on the sum of funding for individual components.

Condition Assessment - The task of evaluating the current condition of the component based on observed or reported characteristics. The assessment is limited to a visual, non-invasive evaluation.

Effective Age - The difference between Useful Life and Remaining Useful Life. Not always equivalent to chronological age since some components age irregularly. Used primarily in computations.

Financial Analysis - The portion of a reserve study in which the current status of the reserves (measured as cash or percent funded) and a recommended reserve funding plan are derived, and the projected reserve income and expense over a period of time are presented. The financial analysis is one of the two parts of a reserve study. A minimum of 30 years of income and expense are to be considered.

Fully Funded - 100% Funded. When the actual (or projected) Reserve balance is equal to the Fully Funded Balance.

Fully Funded Balance (FFB) - An indicator against which the actual (or projected) reserve balance can be compared. The reserve balance that is in direct proportion to the fraction of life "used up" of the current repair or replacement cost. This number is calculated for each component, and then summed for a district total.

Fund Status - The status of the reserve fund reported in terms of cash or percent funded.

Funding Goals - The three funding goals listed below range from the most aggressive to most conservative:

Baseline Funding - Establishing a reserve funding goal of allowing the reserve cash balance to approach but never fall below zero during the cash flow projection. This is the funding goal with the greatest risk of being prepared to fund future repair and replacement of major components, and it is not recommended as a long-term solution/plan. Baseline funding may lead to project delays, the need for a special assessment, and/or a line of credit for the community to fund needed repairs and replacement of major components.

Threshold Funding - Establishing a reserve funding goal of keeping the reserve balance above a specified dollar or percent funded amount. Depending on the threshold selected, this funding goal may be weaker or stronger than "fully funded" with respective higher risk or less risk of cash problems. In determining the threshold, many variables should be considered, including things such as investment risk tolerance, community age, building type, components that are not readily inspected, and components with a remaining useful life of more than 30 years.

Fully Funding - Setting a reserve funding goal to attain and maintain reserves at or near 100 percent funded. Fully funded is when the actual or projected reserve balance is equal to the fully funded balance.

It should be noted that, in certain jurisdictions, there may be statutory funding requirements that would dictate the funding requirements. In all cases, these standards are considered the minimum to be referenced.

Funding Plan - A district's plan to provide income to a Reserve fund to offset anticipated expenditures from that fund. The plan must be a minimum of 30 years of projected income and expenses.

Funding Principles - A funding plan addressing these principles. These funding principles are the basis for the recommendations included within the reserve study:

- Sufficient funds when required.
- Stable funding rate over the years.
- Equitable funding rate over the years.
- Fiscally responsible.

Initial Year - The first fiscal year in the financial analysis or funding plan.

Life Estimates - The task of estimating useful life and remaining useful life of the reserve components.

Life Cycle Cost - The ongoing cost of deterioration which must be offset in order to maintain and replace common area components at the end of their useful life. Note that the cost of preventive maintenance and corrective maintenance determined through periodic structural inspections (if required) are included in the calculation of life cycle costs and often result in overall net lower life cycle costs.

Maintenance - Maintenance is the process of maintaining or preserving something, or the state of being maintained. Maintenance is often defined in three ways: preventive maintenance, corrective maintenance, and deferred maintenance. Maintenance projects commonly fall short of "replacement" but may pass the defining test of a reserve component and be appropriate for reserve funding. Maintenance types are categorized below:

Preventive Maintenance - Planned maintenance carried out proactively at predetermined intervals, aimed at reducing the performance degradation of the component such that it can attain, at minimum, its estimated useful life.

Deferred Maintenance - Maintenance which is not performed and leads to premature deterioration to the common areas due to lack of preventive maintenance. This results in a reduction in the remaining useful life of the reserve components and the potential of inadequate funding. Typically, deferred maintenance creates a need for corrective maintenance.

Corrective Maintenance - Maintenance performed following the detection of a problem, with the goal of remediating the condition such that the intended function and life of the component or system is restored, preserved, or enhanced. Many corrective maintenance projects could be prevented with a proactive, preventive maintenance program. Note that when the scope is minor, these projects may fall below the threshold of cost significance and thus are handled through the operational budget. In other cases, the cost and timing should be included within the reserve study.

Percent Funded - The ratio, at a particular point in time clearly identified as either the beginning or end of the district's fiscal year, of the actual (or projected) reserve balance to the fully funded balance, expressed as a percentage. While percent funded is an indicator of a district's reserve fund size, it should be viewed in the context of how it is changing due to the district's reserve funding plan, in light of the district's risk tolerance and is not by itself a measure of "adequacy."

Periodic Structural Inspection - Structural system inspections aimed at identifying issues when they become evident.

Additional information and recommendations are included within the Condominium Safety Public Policy Report. www.condosafety.com

Physical Evaluation - The portion of the reserve study where the component inventory, condition assessment, and life and valuation estimate tasks are performed. This represents one of the two parts of the reserve study.

Preventive Maintenance Schedule - A summary of the preventive maintenance tasks included within a maintenance manual which should be performed such that the useful lives of the components are attained or exceeded. This schedule should include both the timing and the estimated cost of the task(s).

Remaining Useful Life (RUL) - Also referred to as "remaining life" (RL). The estimated time, in years, that a component can be expected to serve its intended function, presuming timely preventive maintenance. Projects expected to occur in the initial year have zero remaining useful life. Replacement Cost: The cost to replace, repair, or restore the component to its original functional condition during that particular year, including all related expenses (including but not limited to shipping, engineering, design, permits, installation, disposal, etc.).

Reserve Balance - Actual or projected funds, clearly identified as existing either at the beginning or end of the district's fiscal year, which will be used to fund reserve component expenditures. The source of this information should be disclosed within the reserve study.

Also known as beginning balance, reserves, reserve accounts, or cash reserves. This balance is based on information provided and not audited.

Reserve Study - A reserve study is a budget planning tool which identifies the components that a community district is responsible to maintain or replace, the current status of the reserve fund, and a stable and equitable funding plan to offset the anticipated future major common area expenditures.

This limited evaluation is conducted for budget and cash flow purposes. Tasks outside the scope of a reserve study include, but are not limited to, design review, construction evaluation, intrusive or destructive testing, preventive maintenance plans, and structural or safety evaluations.

Reserve Study Provider - An individual who prepares reserve studies. In many instances, the reserve study provider will possess a specialized designation such as the Reserve Specialist. (RS) designation administered by Community Associations Institute (CAI). This designation indicates that the provider has shown the necessary skills to perform a reserve study that conforms to these standards. In some instances, qualifications in excess of the RS designation will be required if supplemental subject matter expertise is required.

Reserve Study Provider Firm - A company that prepares reserve studies as one of its primary business activities.

Responsible Charge - A Reserve Specialist (RS) in responsible charge of a reserve study shall render regular and effective supervision to those individuals' performing services that directly and materially affect the quality and competence of services rendered by the Reserve Specialist. A Reserve Specialist shall maintain such records as are reasonably necessary to establish that the Reserve Specialist exercised regular and effective supervision of a reserve study of which he or she was in responsible charge. A Reserve Specialist engaged in any of the following acts or practices shall be deemed not to have rendered the regular and effective supervision required herein:

1. The regular and continuous absence from principal office premises from which professional services are rendered; except for performance of field work or presence in a field office maintained exclusively for a specific project;

2. The failure to personally inspect or review the work of subordinates where necessary and appropriate;

3. The rendering of a limited, cursory or perfunctory review of plans or projects in lieu of an appropriate detailed review; and

4. The failure to personally be available on a reasonable basis or with adequate advance notice for consultation and inspection where circumstances require personal availability.

Site Visit - A visual assessment of the accessible areas of the components included within the reserve study.

The site visit includes tasks such as, but not limited to, on-site visual observations, a review of the district's design and governing documents, review of district precedents, and discussion with appropriate representative(s) of the district.

Special Assessment - A temporary assessment levied on the members of a district in addition to regular assessments. Note that special assessments are often regulated by governing documents or local statutes.

Special assessments, when used to make up for unplanned reserve fund shortfalls, may be an indicator of deferred maintenance, improper reserve project planning, and unforeseen catastrophes and accidents, as well as other surprises.

Structural System - The structural components within a building that, by contiguous interconnection, form a path by which external and internal forces, applied to the building, are delivered to the ground. This is generally a combination of structural beams, columns, and bracing and is not included within the reserve study, although it is reviewed as part of the recommended periodic structural inspections.

It is important to recognize that individual structural components which are not a part of the structural system, such as decks, balconies, and podium deck components may be included for reserve funding if they otherwise satisfy the three-part test.

Useful Life (UL) - The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed presuming proactive, planned, preventive maintenance. Best practice is that a component's Useful Life should reflect the actual preventive maintenance being performed (or not performed).

Valuation Estimates - The task of estimating the current repair or replacement costs for the reserve components.

Disclosures and Limitations

No destructive testing was performed. Latent defects in design or construction are excluded from this report. There are no material issues to our knowledge that have not been disclosed to the client that would affect the integrity of this Reserve Study report. Custom Reserves has no interests with the client other than this Reserve Study. The Reserve Specialist or other reserve study provider for this project has no familial or marital relationship with the client, no ownership interest in the client, and no ongoing business relationship with the client.

Clear recommendations appear within the reserve study where the district has been advised to retain outside expertise to supplement the evaluation of the Reserve Specialist.

Component quantities and estimates of costs indicated in this Report were developed by Custom Reserves unless otherwise noted in our "Condition Assessment" comments. The sources for the costs outlined in the study include experience and historical information. This report should be used for budget and planning purposes only. The Reserve Specialist shall incur no civil liability for performing the physical or financial portions of a reserve study performed in accordance with these standards.

Report Credentials

PAUL GRIFONI – Senior Engineer, Licensed Home Inspector

EDUCATION - University of Massachusetts - Bachelor of Science in Engineering

PROFESSIONAL AFFILIATIONS / DESIGNATIONS

Professional Reserve Analyst (PRA)
Association of Professional Reserve Analysts

Reserve Specialist (RS)
Community Associations Institute

Tab 5

Bobcat Trail Landscape Committee Meeting Minutes
Tuesday February 18, 2025
Bobcat Trail Community Center
1352 Bobcat Trail Boulevard
North Port Florida 34288

1. Call to Order

The meeting was called to order at 12 PM.

2. Roll Call/Statement of Quorum

Present for the meeting representing the Bobcat Trail Landscape Committee (BCTLC) were Jeff Brall, Val Duemmel, Bill Hadovski, and Laura Filler. Artis Tree was represented by Jeff Tamayo and Scott Acton. There were no residents or members of the public present.

3. Approval/Adoption of Agenda

February 18, 2025 Bobcat Trail Landscape Committee Meeting Agenda was approved as issued (See Attachment 1).

4. Public Comment on Agenda Items

There was no public comment.

5. Meeting Minute Approval

The meeting minutes for January 18, 2025, BCTLC meeting were approved with comments.

6. Old Business

A. Artis Tree Contract matrix review for February 2025. (See Attachment 4). Except for the following clarifications Artis Tree has complied with the February Contract Matrix requirements.

(1) Artis Tree reported that wet checks would be performed on the Commercial Side on February 26.

(2) There seemed to be some confusion with the matrix's separate requirements for "Fertilize the Turf", "Insecticide the Turf", and "Weed Control the Turf". Artis Tree agreed to review these requirements and get back to us on how they met them.

(3) For soil testing Artis Tree stated they only test when there appears to be a problem. Artis Tree feels that the areas that appear stressed are due to lack of water.

(4) It was observed that fire ants have appeared, Artis Tree indicated the dry weather brings them out and they were being treated as part of the Artis Tree overall program.

B. Bobcat Trail Aquatic and Landscape Inspection Report dated January 28th, 2025, by Rizzetta & Company John Fowler Landscape Specialist (Landscape Section Only). (See Attachment 5).

(1) Artis Tree has standing authorization to remove dead plants.

(2) Items 1 through 6 were addressed through general discussion.

(3) Item 7, these trees are not CDD trees.

(4) Number 8 Artis Tree should treat.

(5) Number 9 it was noted that Crotons tend to come back, and we should give them more time.

(6) Fowler report number 10 treat ant mound.

(7) Number 11 install when plants are available.

(8) Number 12 remove all dead plants per general instructions.

(9) Number 13 irrigation has been restored.

(10) Number 14 Artis Tree agreed to diagnose and treat per request.

(11) Number 15 will trim on the next trim cycle.

(12) Number 16 No disposition at this time.

(13) Number 17 No disposition at this time.

(14) Number 18 and 19 will not be worked on at this time.

(15) Number 21 leave stumps.

(16) Number 22 is not a CDD problem.

C. Commercial/Woodhaven/Toledo Blade/Under The Trees

(1) The areas are in good shape and being maintained per the Artis Tree contract. As previously noted, the turf along Bobcat Village Drive is in tough shape.

D. Monuments

(1) It was generally felt that the CDD Landscape areas looked pretty good but were ready for a trim. Especially around the monuments it was felt that the bushes should be more squared off. Gold Mound needs to be trimmed.

E. Miscellaneous

(1) The irrigation well timer across Bobcat Trail near the Community Center has been repaired

7. New Business

A. Shovel Ready Projects

(1) Area in front of guard house (See attachment 6).

- Design complete (See Attachment 3).
- Border for guard house gravel bed will be of concrete type material (See Attachment 4).
- Plan to use the March Annuals for the front and other areas as needed. Will not perform the scheduled Annuals change out until June.
- Project was approved

(2) Commercial side Bull Nose Area, (See attachment 13).

- It was decided that we needed to do both Bull Noses at the same time.
- Primary scope is to take out all plants but leave the Schefflera
- Rake, clean up area
- Project Approved

(3) Sod enhancement

- Plan one more inspection tour of property and then finalize the scope

(4) Pool Area (see Attachment 14).

- Scope and proposal approved. Project authorized

B. Landscape lighting.

(1) Lighting wish list (see Attachment 7) is the bias for the following changes.

(2) South Florida Landscape Lighting Incorporated provided 5 separate quotes.

- Quote 1 Add Lighting to Back Gate $1,450.00 (See attachement 8)
- Quote 2 Monument Lighting on Commercial Side $188.00 (See Attachement 12)
- Quote 3 Street Monuments Electric Plugs and Floods $1,746.00 (See Attachement 11)
- Quote 4 Lights on Guard House Flagpole $550.00 (See Attachement 10)
- Quote 5 Repair Entrance Side Lights $450.00 (See attachement 9)
- All work was authorized

8. Budget

(1) General budget discussion evaluating strategy for accomplishing Phase 5 (Commercial Side Upgrade).

(2) It was also noted that a less expensive source for the sod needed in Phase 5 was being investigated.

9. Public Comment

(1) No public comment.

10. Adjournment

(1) Adjourned at 2:29 PM.

ATTACHMENTS

1. Approved Agenda for February 18, 2025, Bob Cat Trail Landscape Committee Meeting.
2. BCTLC Yearly Contract Schedule Grid.
3. Guard House Landscape Plan
4. Guard House Landscape Boarders
5. Bobcat Trail Aquatic and Landscape Inspection Report dated January 28th, 2025, by Rizzetta & Company John Fowler Landscape Specialist (Landscape Section Only).
6. Artis Tree Quote # 26886 (Guard House Revamp proposal original and revised)
7. Landscape Lighting Wish List
8. South Florida Landscape Lighting Service (Back Gate Lighting)
9. South Florida Landscape Lighting Service (Entrance Side Lighting)
10. South Florida Landscape Lighting Service (Guard House Flagpole Lighting)
11. South Florida Landscape Lighting Service (Street monument Electric Plugs)
12. South Florida Landscape Lighting Service (Commercial Side Monuments Lighting)
13. Artis Tree Quote # 26887 (Commercial Side Bull Nose Revamp proposal original and revised))
14. Artis Tree Quote # 26894 (Pool Area Landscape Enhancement)

ATTACHMENT 1

Bobcat Trail Landscape Committee
2/18/2025 BCT Community Center 12 PM
Agenda (revise as needed at meeting)

1. Call to Order
2. Roll Call/Statement of Quorum
3. Approval/Adoption of Agenda Items
4. Public Comment on Agenda Items
5. Reading/Approval of 1/21/2025 Meeting Minutes

Old Business

6A. Artistrees Matrix Report (Laura)

- Discussion of Current Landscape Status

- John Fowler Report

6B. Street Monuments (Valarie)

- Discussion of Current Landscape Status of Street Monuments

6C. Commercial/Woodhaven/Toledo Blade/ Under The Trees (Bill)

- Discussion of Current Landscape Status of Above Areas

- Hard Cut Back Oaks

6D. Miscellaneous Items (Jeff)

- Irrigation Update

7. **3 Shovel Ready Projects (Part of 5 Year Plan)**

Pool Area

Guard House Bed (Silver Buttonwood, Dwarf Ixora, Lariope, Tai?, & Flowers)

Mulch/Sod Enhancement - areas identified

8. Landscape Lighting Status & Wishlist


- Discussion

9. Budget
10. Public Comment
11. Adjournment

ATTACHMENT 2

BCTLC YEARLY CONTRACT SCHEDULE GRID

TASK	January	February	March	April	May	June	July	August	Septemt	October	Novemb	Decemb	TOT
Mow Line Trim Blow	2	2	4	4	4	4	4	4	4	4	4	2	42
Hard Edge	2	2	4	4	4	4	4	4	4	4	4	2	42
Trash Pickup	2	2	4	4	4	4	4	4	4	4	4	2	42
Bed Edge	1	1	2	2	2	2	2	2	2	2	2	1	21
Fertilize Shrubs			1		1					1			3
Fertilize Palms			1		1					1			3
Fertilize Turf		1		1			1			1		1	5
Fertilize Trees			1		1					1			3
Insecticide Turf	1		1		1		1		1		1		6
Fire Ant Control	1	1	1	1	1	1	1	1	1	1	1	1	12
Insecticide Shrubs	1	1	1	1	1	1	1	1	1	1	1	1	12
Weed Control Beds	1	1	2	2	2	2	2	2	2	2	2	2	22
Pre-Emergent Beds		1				1							2
Prune Shrubs	1	1	1	1	1	1	1	1	1	1	1	1	12
Trim Palms 15' or <	1		1	1	1	1	1	1	1	1	1		10
Trim Palms >15'					1								1
Trim Oaks 17' Max	1		1	1	1	1	1	1	1	1	1	1	10
Soil Sample		1							1				2
Mulch Maintain 3" Depth										1			1
Weed Control Roads	1	1	1	2	2	2	2	2	2	2	2	1	20
Mow Woodhaven Schwb-Road	1	1	1	1	2	2	2	2	2	2	2	1	18
Mow "Under Trees"	1	1	1	1	2	2	2	2	2	2	2	2	18
Commercial Lake Tower @ Hospital			1	1	1	1	1	1	1	1	1	1	10
Weed Control Turf		1									1		2
Irrigation/ Distribution Components	1	1	1	1	1	1	1	1	1	1	1	1	12
Install Annuals 250 4"			1			1					1		3


STONE
Hibiscus?
Ixora
Hibiscus?
Silver button wood
opening
opening
opening
opening
Silver button wood
Ixora
Liriope
IXORA
x Button wood
Flowers
Flowers
Liriope

Internet # 100348831 Model # 14200710 Store SKU # 600465

19

Top Rated

Oldcastle

15.75 in. x 5.5 in. x 2 in. White Straight Scallop Concrete Edger

(283) Questions & Answers (20)










Hover Image to Zoom

Share Print

BULK PRICE ELIGIBLE $2.47

Buy 240 or more $2.22

- Durable weather-resistant straight edging
- Perfect for walkways, landscaping, plant beds, and more
- Easy to install, almost no maintenance, and makes yardwork simple
- View More Details

Internet # 100348832 Model # 14200790 Store SKU # 600466

87

Oldcastle

15.75 in. x 5.5 in. x 2 in. White Curved Scallop Concrete Edger

(131) Questions & Answers (16)



Hover Image to Zoom

Share Print

BULK PRICE ELIGIBLE $2.38

Buy 130 or more $2.14

- Curved edging perfect for durable tree rings
- Rounded design is ideal for paths, gardens, landscaping & more
- Easy installation makes mowing and trimming a breeze
- View More Details

Bobcat Trail

AQUATICS AND LANDSCAPE INSPECTION REPORT



January 28th, 2025
Rizzetta & Company
John Fowler – Landscape Specialist

Rizzetta & Company
Professionals in Community Management

Landscape Summary, Bobcat Village Center Dr.

General Updates, Recent & Upcoming Maintenance Events

- ❑ **Treat ant mounds throughout district.**
- ❑ **Artistree has done a great job cleaning up the monuments on Bobcat Trail.**

The following are action items for LMP to complete. Please refer to the item # in your response listing action already taken or anticipated time of completion. Red text indicates deficient from previous report. **Bold Red text** indicates deficient for more than a month. Green text indicates a proposal has been requested. Blue indicates irrigation. **Bold & Underlined** is info or a question for the BOS. Orange is items for Staff to address.

1. Diagnose and treat declining turf under the light pole on the South median of Bobcat Village Center Dr. (Pic. 1)



2. Treat broadleaf turf weeds in the median islands of Bobcat Village Center Dr. North and South of Bobcat Trail W.
3. Treat ant mounds in the beds on Bobcat Village Center Dr. Once the mound is no longer active, smooth out to surrounding grade and cover with nearby existing mulch.
4. Remove any dead Indian Hawthorn in the median islands on Bobcat Village Center Dr. Need a plan to replace with a different species moving forward. (Pic. 4>)
5. Noting some of the turf and shrubs are showing decline from the cold weather on Bobcat Village Center Dr. and will come out of a dormant phase with warmer weather.
6. Remove a couple small dead hanging Oak limbs in the median island of Bobcat Trail W. at the Bobcat Village Center Dr.
7. Asking if the two Sable palm trees on the entrance side to the gas station is part of the CDD. If so, there are weeds on the trunk that should be removed.
8. Treat an ant mound in the turf overspilling onto the concrete culvert in the median on Bobcat Trail W. at Toledo Blade intersection.



Bobcat Trail

9. Investigate declining Croton on Bobcat Trail E median at Toledo Blade intersection. Will it come back, or does it need to be removed? (Pic. 9)



10. Scout and treat ant mounds in the turf and beds on Bobcat Trail E. Once the mound is inactive, smooth to surrounding grade.

11. There is a dead Croton that needs to be removed in front of The Gardens monument of Royal Palms Dr. and Bobcat Trail intersection. Might want to add a couple for symmetry as the other side has a couple thriving Croton.

12. There are a couple dead Red Sister Ti stalks that should be removed in the medians on Bobcat Trai E. from guard gate to amenities. (Pic. 12)



13. Asking if the irrigation has been restored on Bobcat Trail or if the rains have greened up the turf? Noting a few small areas that should be scouted for possible fungus.

14. Diagnose and treat some declining Ilex Shillings in the roundabout bed of Solitary Palm Ct.

15. Remove dead fronds on the Foxtail palm in the median island of Bobcat Trail E. at the amenity center intersection.

16. Diagnose and treat the declining turf on the entrance side of the South end of Bobcat Trail E and Royal Palms Dr. intersection. May need new turf. (Pic. 16)



17. Diagnose at treat a few declining Copperleaf on the entrance side of the road heading into the amenity center parking lot.

18. Diagnose and treat the Ornamental Grasses on the entrance side of the road heading into the amenity center parking lot. These should be cut back at the same time.

19. Noting the turf directly across the street from the amenity center meeting building is not improving and may need new turf. Could it be a soil issue?

20. Treat a couple ant mounds in the beds at the amenity center.

21. Noting the tree stumps still present on the entrance side of the road heading into the amenity center parking lot. (Pic. 21



22. Need to remove the pile of landscape debris at the parking lot of the pool area. (Pic. 22)



REV 0

ATTACHMENT 6

Sales Quotation

ArtisTree
Irrigation # SCC131152027
Landscape # CGC1525297
Sarasota County, Florida

Phone: (941) 488-8897
Fax: (941) 484-0945
Web: www.artistree.com

Quotation Number: 26886

Quotation Date: 02/06/2025
Valid Until Date: 03/06/2025
Customer Number: C23101
Printed On: 2/6/2025
Contract Ref No:

Customer Information	Jobsite / Contract Information
Bobcat Trail CDD 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager	**Bobcat Trail CDD** 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager

Contract Description:

Quantity	Item Code	Description
Front Entrance Guard House Garden Revamp		
1.00 Hours	LD105-GENL	General Labor
14.00 Each	SS61196	Silver Buttonwood - 3 GAL
22.00 Each	SS60744	Ixora 'Petite Red'- 3 GAL
13.00 Each	SS60834	Liriope 'Evergreen'- 3 GAL
100.00 Per Foot	PT74035	Rainbird Dripline Per Foot
12.00 Each	MH40025	Cocoa Brown-A-2-CU FT
2.00 Each	SS60625	Hawaiian Ti - 3 GAL
1.00 Each	RS78401	Black Diamond Edging 20 FT
		Subtotal for Front Entrance Guard House Garden Revi **1,429.51**
Contract Total		**$1,429.51**

Job Summary:
Plants installed based on provided plan.

ACCEPTED THIS _____ **DAY OF** _____

Salesperson signature

Owner/Client Signature

REV 1

ArtisTree

Irrigation # SCC131152027
Landscape # CGC1525297
Sarasota County, Florida

Phone: (941) 488-8897
Fax: (941) 484-0945
Web: www.artistree.com

Sales Quotation

Quotation Number: 26886

Quotation Date: 02/06/2025
Valid Until Date: 03/06/2025
Customer Number: C23101
Printed On: 2/18/2025
Contract Ref No:

Customer Information	Jobsite / Contract Information
Bobcat Trail CDD 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager	**Bobcat Trail CDD** 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager

Contract Description:

Quantity	Item Code	Description	Extended
Front Entrance Guard House Garden Revamp			
1.00 Hours	LD105-GENL	General Labor	
14.00 Each	SS61196	Silver Buttonwood - 3 GAL	
22.00 Each	SS60744	Ixora 'Petite Red'- 3 GAL	
13.00 Each	SS60834	Liriope 'Evergreen'- 3 GAL	
100.00 Per Foot	PT74035	Rainbird Dripline Per Foot	
12.00 Each	MH40025	Cocoa Brown-A-2-CU FT	
		Subtotal for Front Entrance Guard House Garden Rev:	**1,326.44**
Contract Total			**$1,326.44**

Job Summary:
Plants installed based on provided plan.

ACCEPTED THIS _____ **DAY OF** _____

Salesperson signature **Owner/Client Signature**

ATTACHMENT 7

Landscape Lighting Wishlist

Commercial Side -

- Monument lighting on commercial side needs adjusting
- Is there a timer delay? (Seems they should be lit earlier)

- Light on guard house flagpole needs adjusting

- Entrance side lighting seems dull compared to exit side/needs adjusting/ not shining on Crepe Myrtles

- Add lights to 1 Ligustrum

- Add lighting to new Sable Palms after Guard House

- Add lighting to some of the median bullnoses's

- Add lighting to entrance/exit of C/C

- Add a Foxtail Palm to last bullnose
- Add lighting to Foxtail Palm

- Lights at the Canary Palm Median Island are not working

- Light on one of the Triple Foxtail Isn't working

- Add Lighting to Backgate

- Car Accident Area on Exit Side of Front

- C/C Entrance Rd on the Right Side (where pines were cut down)

- Street Monuments Electric Plugs & Floods

- Bullnose across from C/C entrance

- Phase 5 (+ new irrigation)

ESTIMATE

SOUTH FLORIDA Landscape Lighting Service,LLC
PO Box 20235
Bradenton, FL 34204-0235

service.lighting@24hotmail.com
+1 (941) 225-9128

bobcat trail ommunity development

Bill to
Jeff Brall
Bobcat Trail Community Development
North Port, FL 34288

Estimate details
Estimate no.: 1010
Estimate date: 02/16/2025

#	Description	Qty	Rate
1.	*...Add Lighting to Backgate 6 lights on the outside of the gate ,one light on each side end inside four lights on the left side of the sable palms. total of the six lights .....$120e/a.....$720 Two 150W Transformer .....$125e/a.....$250 4 1/2 hrs. labor $480		$1,450.00
		Total	**$1,450.00**

Accepted date **Accepted by**

ATTACHMENT 9

ESTIMATE

SOUTH FLORIDA Landscape Lighting Service,LLC
PO Box 20235
Bradenton, FL 34204-0235

service.lighting@24hotmail.com
+1 (941) 225-9128

bobcat trail ommunity development

Bill to
Jeff Brall
Bobcat Trail Community Development
North Port, FL 34288

Estimate details
Estimate no.: 1010
Estimate date: 02/16/2025

#	Description	Qty	Rate
1.	*. Entrance side lighting seems dull compared to exit side. . work that needs to be done . It need to replace with two New lights. kichler Accent Brass light with Brillance PAR36 3000k $165 e/a.....$330 1 hr Labor $120		$450.00
		Total	**$450.00**

Accepted date **Accepted by**

ATTACHMENT 10

ESTIMATE

SOUTH FLORIDA Landscape Lighting Service,LLC
PO Box 20235
Bradenton, FL 34204-0235

service.lighting@24hotmail.com
+1 (941) 225-9128

bobcat trail ommunity development

Bill to
Jeff Brall
Bobcat Trail Community Development
North Port, FL 34288

Estimate details
Estimate no.: 1010
Estimate date: 02/16/2025

#	Description	Qty	Rate
1.	*.... Light on guar house flagpole needs adjusting I recommend replacing it with new light Accent Brass light with Brillance PAR36 LED lightbulb .....$165 *..Add lighting to some of the median bullnoses' one Brass light with LED Lightbulb.....$120 *.. add light to 1 ligustrum. one Brass light with LED Lightbulb.....$120 *..light on one of the Triple Foxtail (isn't working) its already fixed. 1 1/2 hr. Labor.. .....$145		$550.00
		Total	**$550.00**

Accepted date **Accepted by**

ATTACHMENT 11

ESTIMATE

SOUTH FLORIDA Landscape Lighting Service,LLC
PO Box 20235
Bradenton, FL 34204-0235

service.lighting@24hotmail.com
+1 (941) 225-9128

bobcat trail ommunity development

Bill to
Jeff Brall
Bobcat Trail Community Development
North Port, FL 34288

Estimate details
Estimate no.: 1010
Estimate date: 02/16/2025

#	Description	Qty	Rate
1.	*... Street Monuments Electric Plugs & floods it needs to replace a new Transformer (one of the Right side has an internal problem end that causes the GFCI to trip occasionally causing the lighting to stop working. New kichler transformer 15PL300AZ 300W.....$375 *...Add lighting to new sable palms after Fuard House. 6 Lights total .... 3 in each side kechler Brass light with Brillance MR16 LED lightbulb .....$120e/a .....$720 500ft wire .....$201 4 hr. labor..... $450		$1,746.00

Total **$1,746.00**

Accepted date **Accepted by**

ATTACHMENT 12

ESTIMATE

SOUTH FLORIDA Landscape Lighting Service,LLC
PO Box 20235
Bradenton, FL 34204-0235

service.lighting@24hotmail.com
+1 (941) 225-9128

bobcat trail ommunity development

Bill to
Jeff Brall
Bobcat Trail Community Development
North Port, FL 34288

Estimate details
Estimate no.: 1010
Estimate date: 02/16/2025

#	Description	Qty	Rate
1.	* Commercial side *..Monument Lighting on commercial side Work that needs to be done . New photocell .....$68 Fix one broken light end pruning end removing shrubs of front of the lights .....$20 Labor.....$120		$188.00
		Total	**$188.00**

Accepted date **Accepted by**

ATTACHMENT 13 REV 0

Sales Quotation

ArtisTree
Irrigation # SCC131152027
Landscape # CGC1525297
Sarasota County, Florida

Phone: (941) 488-8897
Fax: (941) 484-0945
Web: www.artistree.com

DEEPER ROOTS. HIGHER STANDARDS.

Quotation Number: 26887
Quotation Date: 02/06/2025
Valid Until Date: 03/06/2025
Customer Number: C23101
Printed On: 2/6/2025
Contract Ref No:

Customer Information	Jobsite / Contract Information
Bobcat Trail CDD 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager	**Bobcat Trail CDD** 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager

Contract Description:

Quantity	Item Code	Description
Commercial Side Bull Nose Revamp.		
1.00 Hours	LD105-GENL	General Labor
25.00 Each	SS60834	Liriope 'Evergreen'- 3 GAL
44.00 Each	SS60744	Ixora 'Petite Red'- 3 GAL
20.00 Each	MH40025	Cocoa Brown-A-2-CU FT

Subtotal for Commercial Side Bull Nose Revamp. 1,827.84

Contract Total $1,827.84

Job Summary:

Commercial Side Bull Nose Revamp:
(1) Removal of all existing plant material except for the Jatrropha Bushes.
(2) Liriope planted along the perimeter of the garden and Ixora planted throughout spaced evenly.
(3) Graden raked out level and new mulch applied to complete garden.

ACCEPTED THIS _____ **DAY OF** _____

Salesperson signature **Owner/Client Signature**

REQ 1

Sales Quotation

ArtisTree
Irrigation # SCC131152027
Landscape # CGC1525297
Sarasota County, Florida

Phone: (941) 488-8897
Fax: (941) 484-0945
Web: www.artistree.com

Quotation Number: 26887

Quotation Date: 02/06/2025
Valid Until Date: 03/06/2025
Customer Number: C23101
Printed On: 2/18/2025
Contract Ref No:

Customer Information	Jobsite / Contract Information
Bobcat Trail CDD 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager	**Bobcat Trail CDD** 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager

Contract Description:

Quantity	Item Code	Description	Extended
Commercial Side Bull Nose Revamp.			
1.00 Hours	LD105-GENL	General Labor	
17.00 Each	SS60834	Liriope 'Evergreen'- 3 GAL	
27.00 Each	SS60744	Ixora 'Petite Red'- 3 GAL	
20.00 Each	MH40025	Cocoa Brown-A-2-CU FT	
		Subtotal for Commercial Side Bull Nose Revamp.	**1,318.84**
Contract Total			**$1,318.84**

Job Summary:

Commercial Side Bull Nose Revamp:
(1) Removal of all existing plant material except for the Jatrropha Bushes and second row of Schefferlara . The one at the tip of the bed will be removed.
(2) Liriope planted along the perimeter of the garden and Ixora planted throughout spaced evenly.
(3) Graden raked out level and new mulch applied to complete garden.

ACCEPTED THIS _____ **DAY OF** _____

Salesperson signature

Owner/Client Signature

ATTACHMENT 14

From: Laura Filler lfiller@bobcatcdd.com
Subject: Pool House
Date: Mar 3, 2025 at 9:24:21 AM
To: Bill Hadovski bhadovski@bobcatcdd.com

Well, this is the original sales quote from the pool house area



ArtisTree
Irrigation # SCC131152027
Landscape # CGC1525297
Sarasota County, Florida

Phone: (941) 488-8897
Fax: (941) 484-0945
Web: www.artistree.com

Sales Quotation

Quotation Number: 26894
Quotation Date: 02/06/2025
Valid Until Date: 03/06/2025
Customer Number: C23101
Printed On: 2/6/2025
Contract Ref No:

Customer Information	Jobsite / Contract Information
Bobcat Trail CDD 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager	**Bobcat Trail CDD** 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager

Contract Description:

Quantity	Item Code	Description	Extended
Removal of plants and mulch in 3 gardens around pool/replace with new sod.			
1.00 Hours	LD105-GENL	General Labor	
2.00 Pallet	MN55007	MN-Sod Pallet(s) Floratam	
		Subtotal for Removal of plants and mulch in 3 gardens	**1,561.60**
Contract Total			**$1,561.60**

Job Summary:

ACCEPTED THIS _____ **DAY OF** _____

Salesperson signature **Owner/Client Signature**

Bobcat Trail Landscape Committee Meeting Minutes
Tuesday March 18, 2025
Bobcat Trail Community Center
1352 Bobcat Trail Boulevard
North Port Florida 34288

1. **Call to Order**

The meeting was called to order at 12:15 PM.

2. **Roll Call/Statement of Quorum**

Present at the meeting representing the Bobcat Trail Landscape Committee (BCTLC) were Jeff Brall, Bill Hadovski, and Laura Filler. Artis Tree was represented by Jeff Tamayo. There were no residents or members of the public present.

3. **Approval/Adoption of Agenda**

March 18, 2025, Bobcat Trail Landscape Committee Meeting Agenda was modified as follows, "Review Christmas Light Status" was included in section 8. Agenda was approved as modified. (See Attachment 1).

4. **Public Comment on Agenda Items**

There was no public comment.

5. Meeting Minute Approval

The meeting minutes for February 18, 2025, BCTLC meeting were approved as issued.

6. Old Business

A. Artis Tree Contract matrix review for March 2025. (See Attachment 2). Artistree made some clarification of the fertilizer and insecticide application schedule and indicated they had met the March matrix requirements.

B. Bobcat Trail Aquatic and Landscape Inspection Report dated February 25th, 2025, by Rizzetta & Company John Fowler Landscape Specialist (Landscape Section Only). (See Attachment 5). Artis Tree indicated due to the timing of the report and their Bobcat Trail schedule they had not had the opportunity to review and respond to the items.

C. The Guard House Landscape Plan providing actual plant count was provided. (See Attachement 3)

(1) Project will start on April 7, 2025

D. Commercial/Woodhaven/Toledo Blade/Under The Trees

(1) The areas are in good shape and being maintained per the Artis Tree contract. As previously noted, the turf along Bobcat Village Drive is in tough shape.

E. Tour of key Bobcat Trail areas

(1) Pool Area

- Reconsidered removing hedge by pool house as it blocks view of parking lot. After inspection of the area all present decided to keep the current contract scope and remove the hedge.

(2) Commercial side entrance

- Light in center island marque does not work.

(3) North and South Bobcat Village Road Bullnoses

- The spacing of the plants in the north and south bullnose are different. There is more room in the north bullnose. To fill in the additional space it was decided to add a second row of schefflera plants.
- The second row of schefflera and open spots in the remaining existing schefflera hedges will be created and filled with existing plants that are being removed per the approved plan.
- Artis Tree agreed to revise their quote to reflect using existing schefflera to replace gaps and provide second hedge.

(4) Back Gate

- Initial evaluation of adding plants to the back gate was placed on hold as spacing on the exit side is significantly less than that on the entrance side.
- Inspection of the outside area of the back gate identified several areas within the schefflera hedge that had gaps or other plants crowing among them. It was agreed that schefflera plants being removed from the Commercial side project could be used to fill in the gaps. Encroaching plants will be removed.

F. The tree down on Woodhaven has been removed and fence repaired. Work not done by Bobcat, most likely the town of North Port.

7. <u>New Business</u>

A. Shovel Ready Projects

(1) Sod enhancement

- Plan one more inspection tour of property and then finalize the scope.

B. Landscape lighting.

(1) Much of the contracted lighting has been installed/repaired. And has improved the Bobcat Trail after dark appearance.

(2) Lighting work on back gate has not been started.

(3) Bobcat Trail trial Community Center east bullnose.

- Landscape light still needs to be repaired, some consideration for replacing the tree is impacting effort.

(4) Christmas Lights

- Waterproofing approach to Christmas lights was discussed with sample equipment displayed.
- A small Christmas Lights test was proposed to verify waterproof equipment works prior to major purchase.
- Christmas lights electrical (cables and power distribution boxes) will be installed during the week of November 10th.
- It was estimated that the additional equipment needed for waterproofing Christmas lights would cost between three hundred and four hundred dollars. This assumes we can use the existing extension cords.

8. Budget

(1) General discussion related to current and proposed projects

9. Public Comment

(1) No public comment.

10. Adjournment

(1) Adjourned at 2:30 PM.

ATTACHMENTS

1. Approved Agenda for February 18, 2025, Bob Cat Trail Landscape Committee Meeting.
2. BCTLC Yearly Contract Schedule Grid.
3. Guard House Landscape Plan.
4. Revised Guard House Landscape Proposal.
5. Bobcat Trail Aquatic and Landscape Inspection Report dated January 28th, 2025, by Rizzetta & Company John Fowler Landscape Specialist (Landscape Section Only).

ATTACHMENT 1

From: Laura Filler lfiller@bobcatcdd.com
Subject: March 18,2025 BCTLC Agenda
Date: Mar 5, 2025 at 3:26:17 PM
To: BBlandon@rizzetta.com, Jeff Tamayo jefft@artistree.com, Scott Acton scotta@artistree.com, Jeffrey Brall jbrall@bobcatcdd.com, Bill Hadovski bhadovski@bobcatcdd.com, Valerie Duemmel vduemmel@bobcatcdd.com

All: Please see the attached Agenda for the March 18,2025 BCTLC meeting.
Thank you,
Laura

Bob2at Trail Landscape Committee
3/18/2025 BCT Community Center 12 PM
Agenda (revise as needed at meeting)

1. Call to Order
2. Roll Call/Statement of Quorum
3. Approval/Adoption of Agenda Items
4. Public Comment on Agenda Items
5. Reading/Approval of 2/18/2025 Meeting Minutes

Old Business

6A. - Commercial Side & Pool Area Site Visit

- Artistree's Matrix Report (Laura)

+Review "Fertilize, Insecticide, Weed Control" Turf

- Discussion of Current Landscape Status

+ Saw Palmetto in Commercial entryway bed

- John Fowler Report

6B. Street Monuments (Valarie)

- Discussion of Current Landscape Status of Street Monuments

6C. Commercial/Woodhaven/Toledo Blade/ Under The Trees (Bill)

- Discussion of Current Landscape Status of Above Areas

- Hard Cut Back Oaks

6D. Miscellaneous Items (Jeff)

7. **3 Shovel Ready Projects (Part of 5 Year Plan)**

Pool Area - scheduled for 4/7

Guard House Bed (Silver Buttonwood, Dwarf Ixora, Lariope, & Flowers) - scheduled for 4/7

Mulch/Sod Enhancement - areas identified

8. Landscape Lighting Status

- Discussion

- REVIEW CHRISTMAS LIGHT STATUS

9. Budget

10. Public Comment

11. Adjournment

ATTACHMENT 2

BCTLC YEARLY CONTRACT SCHEDULE GRID


TASK	January	February	March	April	May	June	July	August	Septemb	October	Novemb	Decemb	TOT
Mow Line Trim Blow	2	2	4	4	4	4	4	4	4	4	4	2	42
Hard Edge	2	2	4	4	4	4	4	4	4	4	4	2	42
Trash Pickup	2	2	4	4	4	4	4	4	4	4	4	2	42
Bed Edge	1	1	2	2	2	2	2	2	2	2	2	1	21
Fertilize Shrubs			1		1					1			3
Fertilize Palms			1		1					1			3
→ Fertilize Turf		1		1			1			1		1	5
Fertilize Trees			1		1					1			3
→ Insecticide Turf	1		1		1		1		1		1		6
Fire Ant Control	1	1	1	1	1	1	1	1	1	1	1	1	12
Insecticide Shrubs	1	1	1	1	1	1	1	1	1	1	1	1	12
Weed Control Beds	1	1	2	2	2	2	2	2	2	2	2	2	22
Pre-Emergent Beds		1				1							2
Prune Shrubs	1	1	1	1	1	1	1	1	1	1	1	1	12
Trim Palms 15' or <	1		1	1	1	1	1	1	1	1	1		10
Trim Palms >15'					1								1
Trim Oaks 17' Max	1		1	1	1	1	1	1	1	1	1	1	10
Soil Sample		1							1				2
Mulch Maintain 3" Depth										1			1
Weed Control Roads	1	1	1	2	2	2	2	2	2	2	2	1	20
Mow Woodhaven Schwb-Road	1	1	1	1	2	2	2	2	2	2	2	1	18
Mow "Under Trees"	1	1	1	1	2	2	2	2	2	2	2	2	18
Commercial Lake Tower @ Hospital			1	1	1	1	1	1	1	1	1	1	10
→ Weed Control Turf		1									1		2
Irrigation/ Distribution Components	1	1	1	1	1	1	1	1	1	1	1	1	12
Install Annuals 250 4"			1			1					1		3

ATTACHMENT 3

- 12 Silver button wood
- 17 Dwarf Ixora
- 14 Lariope

Jatropha

Shiffelera



ATTACHMENT 4

Sales Quotation

ArtisTree

Irrigation # SCC131152027
Landscape # CGC1525297
Sarasota County, Florida

Phone: (941) 488-8897
Fax: (941) 484-0945
Web: www.artistree.com

Quotation Number: 26886

Quotation Date: 02/06/2025
Valid Until Date: 03/06/2025
Customer Number: C23101
Printed On: 2/18/2025
Contract Ref No:

Customer Information	Jobsite / Contract Information
Bobcat Trail CDD 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager	**Bobcat Trail CDD** 3434 Colwell Avenue, Ste. 200 Tampa FL 33614 USA Attn: District Manager

Contract Description:

Quantity	Item Code	Description	Extended
Front Entrance Guard House Garden Revamp			
1.00 Hours	LD105-GENL	General Labor	
14.00 Each	SS61196	Silver Buttonwood - 3 GAL	
22.00 Each	SS60744	Ixora 'Petite Red'- 3 GAL	
13.00 Each	SS60834	Liriope 'Evergreen'- 3 GAL	
100.00 Per Foot	PT74035	Rainbird Dripline Per Foot	
12.00 Each	MH40025	Cocoa Brown-A-2-CU FT	
		Subtotal for Front Entrance Guard House Garden Rev:	**1,326.44**
Contract Total			**$1,326.44**

Job Summary:
Plants installed based on provided plan.

ACCEPTED THIS _____ **DAY OF** _____

Salesperson signature **Owner/Client Signature**

ATTACHMENT 5

Bobcat Trail

AQUATICS AND LANDSCAPE INSPECTION REPORT



February 25th, 2025
Rizzetta & Company
John Fowler – Landscape Specialist

Rizzetta & Company
Professionals in Community Management

General Updates, Recent & Upcoming Maintenance Events


- ❑ **Treat ant mounds throughout district.**
- ❑ **Some dead hanging Palm fronds starting to show.**

The following are action items for LMP to complete. Please refer to the item # in your response listing action already taken or anticipated time of completion. Red text indicates deficient from previous report. **Bold Red text** indicates deficient for more than a month. Green text indicates a proposal has been requested. Blue indicates irrigation. **Bold & Underlined** is info or a question for the BOS. Orange is items for Staff to address.

1. Noting it appears broadleaf turf weeds were treated on Bobcat Village Center Dr. Some pesky weeds may need retreatment.
2. Repair a small rut in the median island on Bobcat Village Center Dr. close to Toledo Club apartments. (Pic. 2)



3. Diagnose and treat a couple Jatrophas that have not flushed out new growth in the median island on Bobcat Village Center Dr. by the gas station. (Pic. 3>)
4. Noting a couple ant mounds in the beds on Bobcat Village Center Dr. Treat and once no longer active, smooth out to the surrounding grade.
5. Treat some weeds in the tree rings on Bobcat Village Center Dr. ROWs.
6. Remove a small dead hanging Oak branch in the median at Bobcat Village Center Dr. and Bobcat Trail W intersection.
7. Hand pull some weeds in the annual beds on the exit monument of Bobcat Trail and Toledo Blade intersection.
8. Diagnose and treat a couple declining Duranta 'Gold Mound' on the median island on Bobcat Trail E after entering through the gate.
9. Noting most of the Croton are starting to flush out new growth.



10. Need to improve the turf on the exit ROW of Bobcat Trail E by the guard house. Not sure if this is from irrigation being down or winter weeds dying off. (Pic. 10)



11. Diagnose and treat a few declining Red-Hot Hibiscus in the median beds on Bobcat Trail.

12. Remove low lying dead palm fronds in the roundabout bed of Solitary Palm Ct.

13. Diagnose and treat some declining Foxtail Ferns in the median beds on Bobcat Trail E. Remove any dead stalks within them.

14. There are a few palms with dead fronds in the median beds on Bobcat Trail E. Most notably the Pineapple Palm overhanging the road near the amenity center. As well as the Foxtail Palm at the amenity center intersection. (Pic. 14>)

15. There are a couple dead Red Sister Ti stalks that should be removed in the medians on Bobcat Trai E. from guard gate to amenities.

16. Noting most of the turf has recovered on Bobcat Trail E from the irrigation being down in the past. There are still a couple spots that need improvement.

17. Treat joint crack weeds in concrete culverts and asphalt in medians on Bobcat Trai.

18. Diagnose at treat a few declining Copperleaf on the entrance side of the road heading into the amenity center parking lot. (Pic. 18)



19. Diagnose and treat the Ornamental Grasses on the entrance side of the road heading into the amenity center parking lot. These should be cut back at the same time.

20. Diagnose and treat chlorotic 'Petit" Ixora on the entrance and exit side of the amenity center at Bobcat Trail intersection.

21. Treat a large ant mound in the bed of the parking lot by the pool.

22. Noting Woodhaven Dr. looks good, and the fence line has been sprayed out. Just a couple vines that should be pulled.



23. Noting the tree stumps still present on the entrance side of the road heading into the amenity center parking lot. Provide a proposal for removal. (Pic. 23)



24. Pull a large weed at the stop sign on the exit side of Bobcat Trail at Woodhaven intersection. (Pic. 24)



BOBCAT TRAIL COMMUNITY DEVELOPMENT DISTRICT

MEETING MINUTES

April 17, 2025

MINUTES OF INFRASTRUCTURE – ASSET WORKSHOP

Each person who decides to appeal any decision made by the Board with respect to any matter considered at the meeting is advised that the person may need to ensure that a verbatim record of the proceedings is made, including the testimony and evidence upon which such appeal is to be based.

The workshop of the infrastructure- Asset Committee of the Bobcat Trail Community Development District was held on Thursday, April 17, 2025 at 3:00 PM at the Bobcat Trail Community Center, 1352 Bobcat Trail Blvd, North Port, FL 34288.

Present and constituting a quorum:

Steven Ball	Board Supervisor, Chairman
Jeffrey Brall	Board Supervisor, Vice Chairman
Michael SanAntonio	Board Supervisor, Assistant Secretary
Paul Fisher	Board Supervisor, Assistant Secretary
Robert Branch	Board Supervisor, Assistant Secretary

Call to Order/Roll Call

The meeting was called to order at 3:00 PM by Steven Ball. Present were Steven Ball, Jeff Brall, Michael SanAntonio, Robert Branch and Paul Fisher.

Pledge of Allegiance

Approval of Agenda

No additions

The agenda was approved.

Public Comments

No public comments regarding the agenda.

Old Business

A. Try Marine: Supervisor Ball reviewed a proposal from Try Marine to treat driving range pond. The cost would be $89,733 for a 3-year program.
B. Handicapped Parking: Supervisor Ball reviewed the status of new parking spaces. Several members of the board are concerned about the cost to just add two spots. This will be reviewed in detail when the engineers report is completed. He reviewed the proposal for a survey costing $1,200.
C. Community Center Sign: Supervisor Branch ordered a new sign for $984.40.
D. Storm Drain Collapse: Supervisor Ball explained that Finn Outdoor will repair the collapse in the coming weeks. Finn Outdoor will also provide an estimate for repairing the wash out at 3394 Royal Palm due to irrigation break.

New Business

A. New Maintenance Employee: Supervisor Branch discussed the termination of the previous employee and he will be posting the position for a new employee.
B. Tennis Court Resurfacing Project: Supervisor SanAntonio and Branch reviewed two proposals for this project. City Wide is $11,717.50 and MOR Sports group is $15,496. This will be voted on at the Board Meeting on May 6th.
C. Pump House Break in: Supervisor Brall reviewed the break-in with the board. He did not see any damage. The lock on the door needed to be replaced. Supervisor SanAntonio stated new cameras will be installed inside and outside of the pump house.
D. ButterflyMX Discussion: A representative of Butterfly joined via Zoom to review their gate monitoring system and answer Board and resident questions regarding their solution. The board will continue to explore this option.

Resident Concerns

Supervisor Branch reviewed a resident's concern regarding people swimming and fishing in the ponds and any liability the CDD may have if someone gets injured. The Board will review the liability issue with the district attorney at the May 6th meeting.

Supervisor Updates

A. Supervisor Fisher requested any updates for the newsletter should be sent to him by end of day 4-18.
B. Supervisor Brall reviewed landscape improvements that have been completed as well as lighting upgrades that have been installed.
C. Supervisor Ball discussed that Solitude will be treating the weeds in the ponds to get them ready for the rainy season.
D. Supervisor SanAntonio reviewed that the key FOB for the tennis court is now active. Update will be in the newsletter. He also stated the importance of closing the gate after exiting the courts.
E. Supervisor Branch reviewed a new filter was ordered for PRV #13 cost will be $783. He also stated a new filter for the 3" PRV would be $1,356 each. They will not be ordered at this time.

Public Comments

A. Comment requesting clarification regarding the golf course Summary Judgement. Clarification was provided by the board.
B. Comment regarding Sunshine laws and discussing maintenance employee.

Adjournment

Adjournment at 3:54 PM.

Tab 6

Rizzetta & Company

UPCOMING DATES TO REMEMBER

- **Next Meeting:** June 3, 2025
- **FY 2023-2024 Audit Completion Deadline:** June 2025
- **Next Election (Seats 1, 2, and 4):** November 2026

District Manager's Report

April 25

2025

BOBCAT TRAIL CDD

FINANCIAL SUMMARY		3/31/2025
General Fund Cash Balance		$ 1,016,490.00
Investments Operating		$ 527,766.00
Debt Service Fund Investment Balance		$ 306,615.00
Total Cash and Investment Balances		**$ 1,850,871.00**
General Fund Expense Variance:	**$166,935**	**Under Budget**

Financial Statement Notes:

The District is currently underbudget. The line items reflecting variances in the financial statements are as follows:

Line Item	Variance
Employee Payroll Processing Fees	$ 1,561.00
Misc. Fees	$ 2,914.00
Access Control Maintenance and Repair	$ 4,809.00
Gate Maintenance and Repair	$ 7,273.00
Utility Pool	$ 688.00
Utility Street Lights	$ 1,120.00
Utility Services Guardhouse	$ 718.00
Aquatic Maintenance	$ 3,226.00
Landscape Maintenance	$ 12,355.00
Tree Trimming Services	$ 1,420.00
Sidewalk Maintenance and Repairs	$ 15,078.00
Employee Salaries	$ 6,631.00
Maint. and Repairs	$ 6,723.00
Misc. Operating Supplies	$ 1,759.00
Property Insurance	$ 2,181.00
Pool Service Contract	$ 2,237.00

Custom Reserves: Custom Reserves has revised the reserve study. It is included in the agenda for Board acceptance.

Budget workshop: Reminder the budget workshop will be held on May 6, 2025 at 1:00 pm.

Tab 7

Ron Turner
Supervisor *of* Elections
Sarasota County: Our **County**. Our **Vote**.

April 15, 2025

Belinda Blandon
Rizzetta & Company, Inc
9530 Marketplace Road
Suite 206
Ft. Myers, FL 33912

RE: Bobcat Trail CDD Registered Electors

Dear Ms. Blandon:

Listed below is the total number of registered electors for the Bobcat Trail Community Development District as of April 15, 2025.

Registered Electors: 798

Sincerely,

Ron Turner
Supervisor of Elections
Sarasota County

RT/tm