$$Vc = \frac{\pi * \emptyset * RPM}{1000}$$
 $RPM = \frac{(Vc * 1000)}{(\pi * \emptyset)}$ $\emptyset = \frac{(Vc * 1000)}{(\pi * RPM)}$