Summary of Expected Machines and Parameters:

- Generator:
 - Parameters: Rotational Speed, Torque
- Rotator:
 - Parameters: Rotational Speed, Torque
- Heater/Furnace:
 - o Parameters: Air Temperature, Process Temperature
- Machining Tool (Lathe, Mill, CNC):
 - o Parameters: Tool Wear, Torque
- Quality Control Machine:
 - o Parameters: ProductID, Machine Failure Label