## Design Notes (Consolidated) Team 6:

Matthew Schroeder
Todd Townsend
Tyson Fosdick
Ruben Maldonado

Date of review: 11/20/2019

Design reviewed by individuals from two teams:

Jeff Roman

Thomas Harris

## **Board Layout**

- Silk screen overlap throughout board.
- Silk screen is off the board in top left corner.
- Chunk of trace in DRC.
- Team name and date needs to be on board.
- Ground stitching vias are not present.
- ERC Warnings (Components that don't need values).
  - Ext. connectors and LEDs.
- Traces might need to be rounded out.
- Via 'fencing' or putting via's close to important grounds may be advantageous

## Schematic

- Pin 22 not grounded.
- AVCC and AREF are floating.
- User-Button not a very meaningful name.
- Labeling is done very well.
- Bypass capacitors lacking on VCC and likely 5V regulator.