<u>Girar y Aplicar Presión - T & AP</u> <u>Tabla III - A</u>

Tiempo en TMU para ángulos (en°) girados										
300	45"	60°	75°	90°	105	120	135	150	165	180
2.8	3.5	4.1	4.8	5.4	6.1	6.8	7.4	9.1	8.7	9.4
4.4	5.5	6.5	7.5	8.5	9.6	10.6	11.6	12.7	13.7	14.8
8.4	10.5	12.3	14.4	16.2	18.3	20.4	22.2	24.3	26.1	29.2
	30° 2.8 4.4	30° 45° 2.8 3.5 4.4 5.5	30° 45° 60° 2.8 3.5 4.1 4.4 5.5 6.5	30° 45° 60° 75° 2.8 3.5 4.1 4.8 4.4 5.5 6.5 7.5	30° 45° 60° 75° 90° 2.8 3.5 4.1 4.8 5.4 4.4 5.5 6.5 7.5 8.5	30° 45° 60° 75° 90° 105 2.8 3.5 4.1 4.8 5.4 6.1 4.4 5.5 6.5 7.5 8.5 9.6	30° 45° 60° 75° 90° 105 120 2.8 3.5 4.1 4.8 5.4 6.1 6.8 4.4 5.5 6.5 7.5 8.5 9.6 10.6	30° 45° 60° 75° 90° 105 120 135 2.8 3.5 4.1 4.8 5.4 6.1 6.8 7.4 4.4 5.5 6.5 7.5 8.5 9.6 10.6 11.6	30° 45° 60° 75° 90° 105 120 135 150 2.8 3.5 4.1 4.8 5.4 6.1 6.8 7.4 9.1 4.4 5.5 6.5 7.5 8.5 9.6 10.6 11.6 12.7	Tiempo en TMU para ángulos (en°) girad 30° 45° 60° 75° 90° 105 120 135 150 165 2.8 3.5 4.1 4.8 5.4 6.1 6.8 7.4 9.1 8.7 4.4 5.5 6.5 7.5 8.5 9.6 10.6 12.6 12.7 13.3 8.4 10.5 12.3 14.4 16.2 18.3 20.4 22.2 24.3 26.1